

MAY 25 1984

Docket No. 50-454
Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

Thank you for your letter dated May 17, 1984, informing us of your program for the reinspection of electrical conductor butt splices at the Byron Station, Units 1 and 2.

We concur with your planned approach to this reinspection program. It is our intent to have one or more NRC electrical inspectors at Byron to monitor your reinspection effort.

Upon completion of this reinspection effort for each unit, it is requested that you provide Region III with your analysis as to the safety significance of all defects identified.

Your cooperation with us is appreciated.

Sincerely,

"Original Signed by R. L. Spessard"

R. L. Spessard, Director
Division of Engineering

cc w/o ltr dtd 5/17/84:
Dennis L. Farrar, Director
of Nuclear Licensing
V. I. Schlosser, Project Manager
Gunner Sorensen, Site Project
Superintendent
R. E. Querio, Station
Superintendent

cc w/ltr dtd 5/17/84:
DMB/Document Control Desk (RIDS)
Resident, RIII
Byron, Braidwood
Diane Chevez, DAARE/SAFE
Jane M. Whicher
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division

8406010102 840525
PDR ADOCK 05000454
S PDR

R III
Love/lc
5/25/84

R III
Williams
8/25/84

R III
Hayes
5/25/84

R III
Littl
5/25/84

R III
Spessard
5/25

1E01