


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

BEC0 91- 138  
November 15, 1991

License DPR-35  
Docket 50-293

Report of Inservice Inspections  
Conducted During Refueling Outage (RFO) 8

The enclosed reports provide a summary of the inservice inspections conducted between the end of RFO-7 and the end of RFO-8. The reports encompass the time period from March 23, 1989 to August 14, 1991. This submittal fulfills the requirements of the ASME Boiler and Pressure Vessel Code Section XI, Paragraph IWA-6230.

  
G. W. Davis

RAH/cab/6415

- Enclosures:
- 1) Inservice Inspection Summary Report for Refuel Outage 8, Pilgrim Nuclear Power Station, dated 10/17/91
  - 2) In vessel Visual Inspection Eighth Refuel Outage, Final Report prepared by G.E. Inspection Services, August 1991
  - 3) Inservice Inspection Eighth Refuel Outage, Final Report prepared by GE Inspection Services

cc: See Page 2

A047  
11

9111190198 911115  
PDR ADOCK 05000293  
Q PDR

cc: Mr. R. Eaton, Project Manager  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation  
Mail Stop: 14D1  
U. S. Nuclear Regulatory Commission  
1 White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

U. S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Senior NRC Resident Inspector  
Pilgrim Nuclear Power Station

Mr. Fred P. Barton  
Supervising District Engineering Inspector  
Division of Inspection  
Department of Public Safety  
1 Ashburton Place  
Room 1301  
Boston, MA 02108

Authorized Nuclear Inservice Inspector (ANII)  
Mr. V. Iyer  
Pilgrim Nuclear Power Station