

POST OFFICE BOX 2951 . BEAUMONT, TEXAS 77704


AREA CODE 409 838 6631

May 22, 1984 RBG-17892 File Ncs. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-170



Gulf States Utilities Company has completed its investigation of DR-170 concerning the fuel oil pipe support on the standby diesel generator supplied by Transamerica Delaval Incorporated and has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

AnJ. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site