STONE AND WEBSTER MICHIGAN, INC. P.C. BOX 1963, MIDLAND, MICHIGAN 48640 PRINCIPAL STAFF 124/84 I O NO 14509 P. O. NO. RMS /RA SWM- /27 LTR NO VIA REF. DEAR SIRS: M FILE THE FOLLOWING ARE ATTACHED SENT SEPARATELY DISTRIBUTION TO X COPIES __ PRINTS _ REPRODUCIBLES EACH OF SPECIFICATIONS DRAWINGS NOTES OF CONFERENCE X DOCUMENTS STATUS PLEASE NOTE SENT FOR YOUR X APPROVED FINAL OMISSIONS APPROVAL COMMENT APPROVED AS REVISED AS DEFINED USE PRELIMINARY ADDITIONS CORRECTIONS INFORMATION NO COMMENT UNACCEPTABLE X FILES COMMENTS CONCURRENCE CLOSED SUGGESTIONS AS NOTED YOUR ATTENTION IS DIRECTED TO THE FOLLOWING RELEASED FOR: FABRICATION PURCHASE OF NECESSARY MATERIALS PLEASE REVISE AND SUBMIT ___ _ REPRODUCIBLES _ MICROFILM APERTURE CARDS _ MICROFILM APERTURE CARDS OF _ DOCUMENTS _ DRAWINGS _ SHOP DETAIL _ PRINTS _ REPRODUCIBLES ___ PLEASE RETURN ONE COPY EACH OF THIS MATERIAL BEARING YOUR APPROVAL OR COMMENTS PLEASE ACKNOWLEDGE RECEIPT OF THIS MATERIAL BY SIGNING AND RETURNING THE ENCLOSED COPY OF THIS FORM WE TRUST THAT THESE NOTES ARE IN ACCORDANCE WITH YOUR UNDERSTANDING IF NOT PLEASE ADVISE US SHOULD ANY REVISION TO DOCUMENTS OR DRAWINGS RETURNED HEREWITH INVOLVE A PRICE INCREASE. THE SUPPLIER MIJST NOTIFY STONE & WEBSTER PURCHASING DEPARTMENT WITHIN TEN HOLD DAYS EVEN THOUGH A DEFINITE ESTIMATE CANNOT BE GIVEN AT THE TIME. OTHERWISE, THE PURCHASER WILL CONSIDER THE REVISIONS MADE WITHOUT COST. IMPORTANT The following closed CIO NIR(s) is (are) forwarded for your information: 019

DISTRIBUTION:

Job File C.4.2 (orig + 1)

DLQuamme, CPCo NIReichel, CPCo RAWells, CPCo JGKeppler, NRC

8406010341 840524 PDR ADDCK 05000329 S PDR

JJHarrison, NRC BLBurgess, NRC (site)

APAmoruso (2)

KRArndt/Chrono/Vault w/o attach(2)

Initiator

JE01 11 MAY 29 1984

CIO Program Manager

STONE & WEBSTER MICHIGAN, INC.

NONCONFORMANCE IDENTIFICATION REPORT

DATE OF NONCONFORMANCE:	RY 22, 1984	NIR NUMBER 019
IDENTIFICATION/LOCATION OF ITEMS		
FDDL DISCREPANCIES (FEBRUAR)	V 13 1084 PRINTOUT)	
DESCRIPTION OF NONCONFORMANCE:	1 13, 1904 PRINTOUT)	
Bechtel Procedure No. FPD-3.000 R Control is responsible for the co Distribution List.		
During CIO Evaluation No. MP-MIS- discrepancies were identified in		act Document Control" several
Work print request were submitted No. M-1A and C-304. It was noted revised to reflect the change.		
FDDL Printout (Dated February 13, Distribution for Station No. 64 (had included unsolicited drawings	(Subcontracts). Subco	
Mill your	PROGR	RAM MGR 1/5 Kann
INITIATOR DATE 2-29-84 CORRECTIVE ACTION BY:	PROGR DATE_	2-29-84
DATE 2-29-84	PROGR DATE_	2-29-84
DATE 2-29-84- CORRECTIVE ACTION BY:	DATE_ ORGANIZATION TAKING	
DATE 2-29-84- CORRECTIVE ACTION BY:	ORGANIZATION TAKING QAR No's RA-00134 (A	CORRECTIVE ACTION
DATE 2-29-84 CORRECTIVE ACTION BY: IDENTIFY The response provided via CPCo's RA-00195 (Attachment 2) have been is considered closed.	ORGANIZATION TAKING QAR No's RA-00134 (An reviewed and is accompany)	CORRECTIVE ACTION Attachment 1) and ceptable. This NIR
DATE 2-29-84 CORRECTIVE ACTION BY: IDENTIFY The response provided via CPCo's RA-00195 (Attachment 2) have been is considered closed.	ORGANIZATION TAKING QAR No's RA-00134 (An reviewed and is accompany)	CORRECTIVE ACTION Attachment 1) and ceptable. This NIR

Closed Page 1 of 2

PFOCE (ASME Only)

Date



MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

QUALITY ACTION REQUEST

1. Requirement PPD 3.000 Rev. 11 ORIGINAL

Unecceptable

Acceptable

7. Date issued 3/7/84				8. Revision
9. Page	1	_ of	2	

Bechtel Proced Control is re- ution List.	dure No. sponsible aluation	for the	Paragraph No. ! control of work S-082-0001 "Sub	llowing deficiencies: 5.2.2 states in part, prints and the mainter Contract Document Cont	nance of a Distrib-
3. QAR Originated by CLS C. L. Spini			/Division/Section AD	5. Response Due Dete 3/15/84	12. Date Reported to MPQA Mgr N/A
13, Action Item No. 50 4910	15. Item Prio	rity	17. S/U Code PGM00	19. Action Organization Bechtel Field	F. Pointe
14. Discipline N/A	16. Trend Co G-5	de	18. Rest Code BCPCO STF-D	Document Control	21. Dete 3/8/84
BUTED TO BY	ALL DOC W DIE ADVERTE ENCTION	DEDICE OF THE DIGHTS	BEING DISTERS WE AS PART OF THE	CONTENCT DISTERNATION PROPERTY ACTION: SUBCONT	COTOCO COEFFCTIVE FORCE DEPARTMENT 1 000 15 THE CON- 6 DECUMENT TO CANCEL DEPUTTER
27. Disposition Action Take	The second second second second		Care	POAE (ASME Only)	Date
SAMPLING OF				29. QAR CIO	Le Ponto 4/12 kg

Superceding QAR RA-00195

QAR MO: RA-00134				
3/7/84	REY:			
PAGE 2 OF 2				

RIDIAND PROJECT		RA-00134	
QUALITY ASSURANCE DEPARTMENT	CONTINUATION SHEET	3/7/84	REY:
		PAGE 2 OF	2
Block 2 Continued			
° Work print request were	submitted on February 10, 1984 for sp	ecifications No.	M-1A
and C-304. It was noted	d that on February 22. 1984 the FDDL h	ad not been revi	sed to
reflect the change.			
• FDDL Printout (Dated Feb	bruary 13, 1984) indicated numerous me	chanical drawing	s on
Distribution for Station	No. 64 (Subcontracts). Subcontracts	stated recent F	DDI Le

had included unsolicited	d drawings in error.		
Coxt Block 22 CLER	ICAL ereor	The Lates of	
CONT. BLOCK 23: Proposed	Corrective Action		
Discrepancies identified	on RA-00134 were corrected at the time	of the evaluati	on.
The FDDL was updated to re	eflect the accurate distribution for s	ubcontracts docu	ment
the same day. Any errors	should be discovered during this veri notes. FDDL procedures were reviewed b	fication process	
and her shoervisor.			ra
implementation.	dures for changing the FDDL and unders	tand their	
BLOCK 24: FUDC DISTRIBUT BLOCK 25: 3-23-84	ION/D. BARSKY	1. Lun	4-1+8
		1. 2004	4 - 1 - 1

ORIGINAL



MIDLAND PROJECT QUALITY ASSURANCE DEPARTMENT

QUALITY ACTION REQUEST

Ī	6. QAR Number	
	RA-00195	
	7. Date issued 4-17-84	8. Revision
	9. Page 1 of 1	
-	10. ASME Related	

	_	_	_	_
-	-			
	- Filt and	26245	- m	warn t

FDD 3.000, Rev 11, Para 7.3 states in part . . . The document controller shall make necessary additions and/or deletions to the work print distribution from the previously established work print distribution in the FDDL.

2. Deficiency

To close QAR RA-00134, FDDL printout dated 4-7-84 was checked for accuracy with the results:

1. Station 324 has unsolicited drawing J-73 sheets 1 & 2.

2. Station 266 requested work print drawings C-117 Rev 8 and C-124 Rev 8 on 3-23-84. These drawings do not appear in FDDL dated 4-7-84. 11 Porential 60 55(a)

3. QAR Originated by JZalitis	57	4. Discip	pline/Division/Section PAD	5. Response Due Date 4-27-84	12. Date Reported to MPQA Mgr
13. Action Item No. S06751	15. Item Prid	prity	17. S/U Code PGMOO	19. Action Organization Bechtel Field	EPOINT Hant
N/A	16. Trend Code 2D-50003		18. Resb Code BPCO STF-D	Document Control	21. Date 4/17/84
22. Cause				23. Proposed Corrective Action	

STATION 266 PEQUESTED SEVERAL DOCUMENTS BE ADDED TO THE FOOL FOOL ADDED THE DUCK MENTS AS DESIGN DEAWINES, WHEN STATION ZLE REQUIRED SPECIFICATIONS STATION 324 WAS ERRONE OUSLY ADDED TO THE FOOL FOR DEALUING I +3 SHEETS 1,2.

U REVIEW THE FOOL WITH STATIONS 324 AND ZLL TO DETERMINE ACCURATE DISTRIBUTION

1) COCRECTTHE FOOL

I REVISE THE DISTRIBUTION CHANGE FORM TO DIFFERENTIATE BETWEEN DEALLINGS & SPECIFICATIONS.

Duzin

24. Responsible Organization/Person___

BROWN

25. Proposed Egmpletion Date 5/7/84

26. Disposition Conci

NA 8W 5/7/84

27. Disposition Action Taken

- 1. The FDDL has been reviewed with Stations 266 and 324.
- 2. The FDDL has been updated to reflect accurate distribution.
- The distribution change form has been revised.

28. Method of Disposition Verification

SEE ATTACHED FOR CLOSURE JUSTIFICATION .

29. QAR Closed by

Date

X Acceptable

Unacceptable

Superceding OAR

To LWWorley

FROM RVSudduth

DATE May 8, 1984

SUBJECT MIDLAND ENERGY CENTER PROJECT -

QAR RA-00195

FILE 16:17 SERIAL 27891

Consumers Power Company

INTERNAL CORRESPONDENCE

18-84

CC

During overview of QAR RA-00195, items 1 and 2 were found corrected.

Action implemented as a result of QAR RA-00195

- 1) The FDDL was reviewed with Stations 266 and 324 for distribution.
- 2) The FDDL was updated to reflect accurate distribution.
- 3) The distribution change form has been revised.

Action of Document Control Assurance Group

- 1. Station 324 did not have drawing J-73 sheets 1 and 2.
- 2. Document Control Assurance Grov reviewed FDDL for accurate distribution. No discrepancies found.

Recommend closure of QAR number RA-00195.

Ronald V. Judduth