IA 94-035

MEMORANDUM TO:

Michael T. Lesar, Acting Chief

Rules Review Section

Regulatory Publication Branch

FROM:

Joseph R. Gray, Deputy Director

Office of Enforcement

SUBJECT:

ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES AND

UNESCORTED ACCESS (EFFECTIVE IMMEDIATELY)

(Rex Allen Werts)

A signed original of the subject order is enclosed for your transmittal to the Office of the <u>Federal Register</u> for publication. Additional conformed copies (5) of the Order are attached for your use.


Attachment: As Stated

cc: J. Goldberg, OGC

DISTRIBUTION:
JGray, OE
RRosano, OE
Day File
EA File
OCS

OE (DO:04/				
RRosano	JGray				
12/6 2/94	12//2/94				

Doc Name: 6:\OECASES\94035FR.DR



Query: 1991 EVENT REPORTS:73.71

LICENSEE: OMAHA PUBLIC POWER DISTRICT

SITE: FT CALHOUN 1

DOCKET: 05000285

RX TYPE: PWR

VENDORS: CE

EMERGENCY CLASS: N/A REGION: 4 STATE: NE

EMERGENCY CLASS: N/A REGION: 4 STATE: NE

EMERGENCY CLASS: N/A REGION: 4 STATE: NE

TIME: 02:34

SECURITY DEGRADATION
CURR CURRENT MODE
UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR

CODE CRIT PWR

1 N N O HOT SHUTDOWN
O HOT SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION RELATED TO UNLOCKED, UNMONITORED AREA DOOR.
COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1 2

DOCKET: 05000424 05000425

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: GA

OPS OFFICER: STEVE SANDIN
10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM
CODE CRIT PWR

CODE CRIT PWR

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION
2 N Y 100 POWER OPERATION

DISCOVERY OF POTENTIAL COMPROMISE OF SAFEGUARDS INFORMATION. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAIDWOOD 1 2

DOCKET: 05000456 05000457

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 99 POWER OPERATION
2 N O COLD SHUTDOWN

COLD SHUTDOWN

ONUMBER: 20222

EVENT DATE: 01-08-91

EVENT TIME: 19:49

NOTIFY DATE: 01-08-91

UNSPECIFIED PARAGRAPH

CURR CURRENT MODE

PWR

OCOLD SHUTDOWN

O COLD SHUTDOWN

INSTRUMENT TECHNICIAN SHORTED OUT A CONTROL CIRCUIT CARD IN THEIR SECURITY SYSTEM. THEY LOST MONITORING CAPABILITIES VIA SOME CAMERAS AND THEY HAVE LOST CARD READING CAPABILITIES OF 11 DOORS.

IT TOOK 14 MINUTES TO GET ALL AREAS POSTED WITH SECURITY GUARDS. NOTHING UNUSUAL OR ABNORMAL WAS DISCOVERED. LICENSEE SAID IT WILL TAKE A FEW HOURS BEFORE THEY FULLY RECOVER THEIR SECURITY SYSTEM.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

*** UPDATE DATE :01/09/91 UPDATE TIME:12:31ET***FROM LICENSEE: PETELLE BY: HUFFMAN ***

LICENSEE IS RETRACTING THEIR ENS EVENT NOTIFICATION. BASED ON FURTHER REVIEW OF THE EVENT AND COMPUTER HISTORIES IT WAS DETERMINED THAT THE TIME OF DISCOVERY WAS 19:51CST AND COMPENSATORY MEASURES FULLY IMPLEMENTED BY 20:00CST. THIS IS LESS THAN 10 MINUTES AND DOES NOT MEET THE REPORTING CRITERIA OF 10 CFR 73.71. THE RESIDENT INSPECTOR HAS BEEN INFORMED. NOTIFIED R3DO (GREGER) .

LICENSEE: BALTIMORE GAS & ELEC CO. EN NUMBER: 20224 SITE: CALVERT CLIFFS 2 EVENT DATE: 01-09-91 DOCKET: 05000318 EVENT TIME: 03:40 RX TYPE: PWR NOTIFY DATE: 01-09-91 VENDORS: CE TIME: 04:39 EMERGENCY CLASS: N/A REGION: 1 STATE: MD OPS OFFICER: STEVE BLOOM

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

FITNESS FOR DUTY QUESTIONED DUE TO SLEEPING ON WATCH. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTH CAROLINA ELECTRIC & GAS CO.

EN NUMBER: 20237 SITE: SUMMER 1 EVENT DATE: 01-10-91 DOCKET: 05000395 EVENT TIME: 04:40 RX TYPE: PWR NOTIFY DATE: 01-10-91 VENDORS: W-3-LP EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 05:35 OPS OFFICER: STEVE BLOOM 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE PWR CODE CRIT PWR Y 47 POWER OPERATION 47 POWER OPERATION

POSSIBLE SAFEGUARDS SYSTEM DEGRADATION DUE TO AREA BOUNDARY. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1102 ON 1/10/91 BY RUSS HIGGINS ENTERED BY BLOOM SAFEGUARDS SYSTEM DEGRADATION DOES EXIST. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. NOTIFIED R2DO (MCALPINE) .

20238 01-10-91 POW DIABLO CANYON 1 2 LICENSEE: PACIFIC GAS & ELECTRIC CO. EN NUMBER: 20238 SITE: DIABLO CANYON 1 2

SITE: DIABLO CANYON 1 2

EVENT DATE: 01-10-91

EVENT TIME: 02:45 DOCKET: 05000275 05000323 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 02:45 NOTIFY DATE: 01-10-91 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 07:55

OPS OFFICER: BOB SPENCE

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

UNSPECIFIED PARAGRAPH

CURR CURRENT MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

N

EMPLOYEE LOST KEY CARD AT 0200 PST AND SEARCHED FOR IT FOR 45 MINUTES BEFORE REPORTING IT TO SECURITY. COMPENSATORY MEASURES WERE IMMEDIATELY TAKEN UPON SECURITY NOTIFICATION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 1354 EST 1/14/91 BY ARROYO TAKEN BY MACKINNON RETRACTING THIS EVENT BECAUSE LOST KEY CARD WAS NOT USED WHILE THE SECURITY COMPUTER WAS DOWN. RESIDENT INSPECTOR AND REGION 5 DOUG SCHAEFER CONCURRED WITH RETRACTING THIS EVENT. REGION 5 (HOWARD WONG) NOTIFIED.

LICENSEE: CAROLINA POWER & LIGHT CO. EN NUMBER: 20240 EVENT DATE: 01-10-91 SITE: ROBINSON 2 EVENT TIME: 15:15 DOCKET: 05000261 NOTIFY DATE: 01-10-91 RX TYPE: PWK EMERGENCY CTASS: N/A REGION: 2 STATE: SC TIME: 16:11

OPS OFFICER: WILLIAM MATTINGLY UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

VITAL AREA DOOR SUBMASTER KEY LOST.

IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

20253 01-12-91 POW DRESDEN 2 3

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 20253 SITE: DRESDEN 2 3 EVENT DATE: 01-12-91 DOCKET: 05000237 05000249

RX TYPE: BWR BWR EVENT TIME: 08:06 NOTIFY DATE: 01-12-91

VENDORS: GE-3 GE-3 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 10:02 OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

N 0 COLD SHUTDOWN
N 0 COLD SHUTDOWN
N 0 COLD SHUTDOWN
N 42 POWER OPERATION
V 42 POWER OPERATION

LOSS OF SECURITY CAMERA COVERAGE OF A SECTION OF THE PLANT PERIMETER ZONE.

COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1131 ON 01/16/91 BY MAYER ENTERED BY HOO JOLLIFFE

AT 1400 (CST) ON 01/14/91, UPON INVESTIGATION OF THIS EVENT, LICENSEE DETERMINED THAT NO LOSS OF ASSESSMENT HAD OCCURRED. THUS, LICENSEE DESIRES TO RETRACT THIS EVENT. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. HOO NOTIFIED R3 GREGER.

20254 01-12-91 POW DIABLO CANYON 1 2 LICENSEE: PACIFIC GAS & ELECTRIC CO. EN NUMBER: 20254 SITE: DIABLO CANYON 1 2 EVENT DATE: 01-12-91 DOCKET: 05000275 05000323 EVENT TIME: 12:20 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 01-12-91 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 15:56 OPS OFFICER: WILLIAM MATTINGLY UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR Y 92 POWER OPERATION 92 POWER OPERATION
Y 100 POWER OPERATION 100 POWER OPERATION N 2

PROTECTED AREA KEY CARD TEMPORARILY LOST.

IMMEDIATE COMPENSATORY ACTIONS TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 1354EST 01/14/91 BY ARROYO TAKEN BY MACKINNON AT 1030 PST LICENSEE DECIDED TO RETRACT THE ABOVE EVENT AFTER DISCUSSION WITH RESIDENT INSPECTOR AND REGION 5 SCHAEFER. R5DO (HOWARD WONG) NOTIFIED.

DAVIS BESSE 1 20262 01-16-91 POW

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1
DOCKET: 05000346
RX TYPE: PWR
VENDORS: B&W-R-LP

EN NUMBER:20262 EVENT DATE: 01-16-91 EVENT TIME: 09:15 NOTIFY DATE: 01-16-91 EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 10:02

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE DISCOVERED A POTENTIAL BOMB DEVICE IN A MAINTENANCE BUILDING IN A REMOTE LOCATION INSIDE THE PLANT PROTECTED AREA.

LICENSSE NOTIFIED LOCAL SHERIFF DEPARTMENT. LICENSEE IS INVESTIGATING THE DEVICE.

SEE HOO LOG FOR DETAILS.

UPDATE @ 1319 EST 01/16/91 BY FILITUCCI TAKEN BY MACKINNON THIS EVENT IS BEING RETRACTED BY THE LICENSEE AFTER LICENSEE INVESTIGATION REVEALED THAT THE SUSPICIOUS DEVICE WAS NOT A BOMB. SEE HOO LOG BOOK FOR FURTHER DETAILS. R3DO (MCCANN) , EO (ROSSI) , IAT NRR (MCPEEK) , IAT NMSS (YARDUMIAN) , R3 (JIM CREED) , AEOD (ZECH) , & AEOD (WEISS) NOTIFIED.

RESIDENT INSPECTOR NOTIFIED BY THE LICENSEE.

LICENSEE: SOUTHERN NUCLEAR OPERATING COMPANY

EN NUMBER: 20267 SITE: FARLEY 1 2

EVENT DATE: 01-17-91 DOCKET: 05000348 05000364 EVENT TIME: 12:26 RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP NOTIFY DATE: 01-17-91

EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 13:55

OPS OFFICER: CHAUNCEY GOULD

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF LOSS OF SAFEGUARDS INFORMATION. NO COMP MEASURES TAKEN. THE RI WAS INFORMED.

* * * UPDATE 1841EST 2/1/91 FROM J.OSTERHOLTZ BY S.SANDIN * * * TWO (2) ADDITIONAL SAFEGUARDS DOCUMENTS HAVE BEEN DETERMINED MISSING, NEITHER OF WHICH IS CONSIDERED SIGNIFICANT IN THAT THEY DO NOT PROVIDE ASSISTANCE FOR ACCESS TO THE PA. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. NOTIFIED R2DO (KENNETH BARR).

LICENSEE: HOUSTON LIGHTING & POWER CO.

EN NUMBER: 20276 SITE: SOUTH TEXAS 1

EVENT DATE: 01-18-91 DOCKET: 05000498

EVENT TIME: 09:20 RX TYPE: PWR NOTIFY DATE: 01-18-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:15

OPS OFFICER: WILLIAM MATTINGLY

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

0 REFUELING N N O REFUELING

PERIMETER SECURITY MEASURES DEGRADED DUE TO SEVERE WEATHER CONDITION.

NOT IMMEDIATELY COMPENSATED BUT COMPENSATED NOW. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: WISCONSIN PUBLIC SERVICE CORP.

EN NUMBER: 20309 SITE: KEWAUNEE 1

EVENT DATE: 01-23-91 DOCKET: 05000305 EVENT TIME: 15:50

RX TYPE: PWR NOTIFY DATE: 01-23-91 VENDORS: W-2-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 17:27

OPS OFFICER: WILLIAM MATTINGLY
10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO ACCESS AUTHORIZATION PROCESS.

IMMEDIATE COMPENSATORY MEASURE TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

20336 01-26-91 POW POINT BEACH 1 2

LICENSEE: WISCONSIN ELECTRIC POWER CO.

EN NUMBER: 20336 SITE: POINT BEACH 1 2

DOCKET: 05000266 05000301 EVENT DATE: 01-26-91

RX TYPE: PWR PWR EVENT TIME: 02:24

VENDORS: W-2-LP W-2-LP NOTIFY DATE: 01-28-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 20:56

OPS OFFICER: WILLIAM MATTINGLY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

PROTECTED AREA BOUNDARY SAFEGUARDS SYSTEM DEGRADATION.

IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

^{* * *} UPDATE ON 1/30/91 1643EST BY RON SEIZERT TO MATTINGLY * * *

EVENT RETRACTED AND DECLASSIFIED BY THE LICENSEE. SEE HOO LOG FOR DETAILS. LICENSEE WILL INFORM THE RESIDENT INSPECTOR. HOO NOTIFIED R3DO (JACKIW) .

LICENSEE: TENNESSEE VALLEY AUTHORITY

EN NUMBER: 20338 SITE: SEQUOYAH 1 2 DOCKET: 05000327 05000328
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP EVENT DATE: 01-29-91 EVENT TIME: 13:40 NOTIFY DATE: 01-29-91

EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 13:47

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR N Y 100 POWER OPERATION 100 POWER OPERATION

Y 100 POWER OPERATION 100 POWER OPERATION 2 N

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA MONITORING.

IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: GPU NUCLEAR CORP.

SITE: THREE MILE ISLAND 1 EN NUMBER: 20350 DOCKET: 05000289
RX TYPE: PWR
VENDORS: B&W-L-LP EVENT DATE: 01-31-91 EVENT TIME: 09:13 NOTIFY DATE: 01-31-91

EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 11:54

OPS OFFICER: JOHN MacKINNON

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N Y 93 POWER OPERATION 93 POWER OPERATION

SAFEGUARDS STITEM DEGRADATION RELATED TO DETECTION/MONITORING/ALARM OF AREA BOUNDARY FOR APPROXIMATELY THIRTY EIGHT MINUTES. SECURITY SEARCHED AREA AND FOUND NOTHING. LICENSEE WILL NOTIFY RESIDENT INSPECTOR.

LICENSEE: DUQUESNE LIGHT CO.

EN NUMBER: 20372 SITE: BEAVER VALLEY 1 2 DOCKET: 05000334 05000412 EVENT DATE: 02-02-91 RX TYPE: PWR PWR EVENT TIME: 16:45 VENDORS: W-3-LP NOTIFY DATE: 02-02-91 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 16:47

OPS OFFICER: STEVE SANDIN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION AT PRIMARY ACCESS FACILITY (PAF). COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: MAINE YANKEE ATOMIC POWER CO. EN NUMBER: 20389 SITE: MAINE YANKEE 1 EVENT DATE: 02-05-91 DOCKET: 05000309 EVENT TIME: 18:31 NOTIFY DATE: 02-05-91 RX TYPE: PWR VENDORS: CE TIME: 19:31 EMERGENCY CLASS: N/A REGION: 1 STATE: ME OPS OFFICER: CHAUNCEY GOULD UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE PWR CODE CRIT PWR Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEMS DEGRADATION RELATED TO THE SECURITY COMPUTER. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO I G FOR DETAILS. THE RI WILL BE INFORMED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI EN NUMBER: 20392 SITE: SAN ONOFRE 1 2 3 EVENT DATE: 02-05-91 DOCKET: 05000206 05000361 05000362 EVENT TIME: 16:00 RX TYPE: PWR PWR PWR NOTIFY DATE: 02-06-91 VENDORS: W-3-LP CE CE EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 11:48 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR N N 0 COLD SHUTDOWN 0 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION N 3

- LICENSEE RECEIVED A TELEPHONE BOMB THREAT TO THEIR ANSWERING MACHINE -

LICENSEE RECEIVED AN UNSUBSTANTIATED BOMB THREAT TELEPHONED TO THEIR ANSWERING MACHINE BETWEEN 1600 (PST) ON 02/05/91 & 0715 (PST) ON 02/06/91. LICENSEE AND LOCAL FBI ARE INVESTIGATING THE THREAT.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1306 ON 02/05/91 BY BEATTY ENTERED BY HOO JOLLIFFE * * *

AT 0950 (PST), LOCAL FBI HAS CLASSIFIED THE CALL AS A NUISANCE BOMB THREAT.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOC NOTIFIED R5 SCHUSTER, NMSS IAT DAVIDSON, NRR IAT MCPEEK.

LICENSEE: PHILADELPHIA ELECTRIC CO.

SITE: PEACH BOTTOM 2 3 EN NUMBER: 20396 DOCKET: 05000277 05000278
RX TYPF BWR BWR
VENDORS: GE-4 GE-4 EVENT DATE: 02-07-91 EVENT TIME: 13:30 NOTIFY DATE: 02-07-91 VENDORS: GE-4 GE-4

EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 14:16

OPS OFFICER: STEVE SANDIN 10 CFR SECTION: DDDD 73.71 10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N N 0 REFUELING 0 REFUELING
3 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION OF ACCESS TO PRIMARY CONTAINMENT, COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

20440 02-13-91 POW

LICENSEE: WISCONSIN PUBLIC SERVICE CORP.

SITE: KEWAUNEE 1 EN NUMBER: 20440 EVENT DATE: 02-13-91 DOCKET: 05000305 VENDORS: W-2-LP EVENT TIME: 10:20 NOTIFY DATE: 02-13-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 12:04

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

POTENTIAL SAFEGUARDS DEGRADATION DUE TO THE APPARENT INATTENTIVENESS

OF A SECURITY GUARD WHILE POSTED AT A VITAL AREA OPENING. COMPENSATORY MEASURES HAVE BEEN TAKEN. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 1543 3/19/91 REPORT BY NALEPKA (SCARFO) * * *

THIS EVENT HAS BEEN RETRACTED UPON REFERENCE TO GENERIC LETTER 9103 AND 10CFR7371, R3DO HAS BEEN INFORMED OF THIS RETRACTION.

DRESDEN 2 3 20446 02-14-91 POW

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3 EN NUMBER: 20446 DOCKET: 05000237 05000249 EVENT DATE: 02-14-91
RX TYPE: BWR BWR EVENT TIME: 04:33
VENDORS: GE-3 GE-3 NOTIFY DATE: 02-14-91

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 06:25

OPS OFFICER: STEVE BLOOM

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N N O COLD SHUTDOWN O COLD SHUTDOWN N Y 95 POWER OPERATION 95 POWER OPERATION 3

SAFEGUARDS DEGRADATION DUE TO AREA BOUNDARY. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 02/15/91 @ 1228EST BY JOSEFIK TAKEN BY MACKINNON LICENSEE IS RETRACTING THIS EVENT BECAUSE THE AREA UNDER CONCERN WAS NOT PART OF THE BARRIER. LICENSEE NOTIFIED THE RESIDENT INSPECTOR AND REGION 3 MADEDA. R3DO (BRUCE JORGENSEN) NOTIFIED.

LICENSEE: NUCLEAR FUEL SERVICES INC.

EN NUMBER: 20475 SITE: NUCLEAR FUEL SERVICES INC. EVENT DATE: 02-18-91 DOCKET: 07000143 EVENT TIME: 04:34 RX TYPE: NOTIFY DATE: 02-18-91 VENDORS: EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 05:31

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO SECURITY LIGHTING.

SEE HOO LOG FOR DETAILS. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY.

LICENSEE: FLORIDA POWER CORPORATION

SITE: CRYSTAL RIVER 3 EN NUMBER: 20493 DOCKET: 05000302 EVENT DATE: 02-19-91 RX TYPE: PWR EVENT TIME: 16:30 VENDORS: B&W-L-LP NOTIFY DATE: 02-19-91 EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 17:08

OPS OFFICER: JOHN MacKINNON

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N Y 99 POWER OPERATION 99 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA DOOR. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

20509 02-21-91 POW OYSTER CREEK 1

LICENSEE: GPU NUCLEAR CORP.

SITE: OYSTER CREEK 1 EN NUMBER: 20509 DOCKET: 05000219 EVENT DATE: 02-21-91 RX TYPE: BWR EVENT TIME: 12:01

NOTIFY DATE: 02-21-91 VENDORS: GE-2 EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 13:05

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

CODE CRIT PWR

N O REFUELING O REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION/ALARM OF VITAL AREA DOOR, COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. RI INFORMED.

* * * UPDATE AT 1029 ON 03/13/91 BY HELLER TAKEN BY HOO JOLLIFFE

* * *

LICENSEE HAS DOWNGRADED THIS EVENT FROM A REPORTABLE EVENT TO A LOGGABLE EVENT AND DESIRES TO RETRACT THIS EVENT BASED ON THE GUIDANCE INCLUDED IN NRC GENERIC LETTER #91-03 AND THE FOLLOWING.

THE BACKUP ADVISORY ALARM WAS TEMPORARILY INOPERABLE DUE TO MAINTENANCE ACTIVITIES AT THE TIME OF

THE EVENT. HAD THIS ALARM BEEN OPERABLE AT THE TIME OF THE EVENT,

IT WOULD HAVE ALERTED THE CAS & SAS OPERATORS OF THE ALARM CONDITION. LICENSEE WILL INFORM THE RESIDENT INSPECTOR. HOO NOTIFIED RIDO ANDERSON.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 EN NUMBER: 20513 EVENT DATE: 02-21-91 DOCKET: 05000275 EVENT TIME: 18:15 RX TYPE: PWR NOTIFY DATE: 02-21-91 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 21:36

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N O REFUELING O REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO ALARMING VITAL AREA ACCESS DOOR. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: CONNECTICUT YANKEE ATOMIC POWER CO.

EN NUMBER: 20515 SITE: HADDAM NECK 1 DOCKET: 05000213 EVENT DATE: 02-21-91

EVENT TIME: 22:58 RX TYPE: PWR NOTIFY DATE: 02-22-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 00:21

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY SYSTEM DEGRADATION DUE TO LOSS OF AC POWER TO THE PLANT SECURITY COMPUTERS. COMPENSATORY MEASURES WERE IN PLACE WITHIN 10 MINUTES OF THE POWER LOSS. POWER WAS RESTORED TO THE COMPUTERS AT 0010 ON 02/22/91.

SEE HOO LOG FOR DETAILS.

LICENSTE INFORMED THE NRC RESIDENT INSPECTOR.

POINT BEACH 1 20550 02-28-91 POW LICENSEE: WISCONSIN ELECTRIC POWER CO. SITE: POINT BEACH 1 EN NUMBER

SITE: POINT BEACH 1

DOCKET: 05000266

RX TYPE: PWR

VENDORS: W-2-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: WI

EN NUMBER: 20550

EVENT DATE: 02-28-91

NOTIFY DATE: 02-28-91

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA BOUNDARY. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 0928 EST 03/01/91 BY KOPETSKY TAKEN BY MACKINNON*

TO EVENT IS BEING RETRACTED AFTER FURTHER INVESTIGATION. SEE

HG 1 TO BOOK FOR FURTHER DETAILS. R3DO (M RING) NOTIFIED.

TROJAN 1 20561 03-01-91 POW

LICENSEE: PORTLAND GENERAL ELECTRIC CO.

SITE: TROJAN 1

DOCKET: 05000344

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 5 STATE: OR

EN NUMBER: 20561

EVENT DATE: 03-01-91

EVENT TIME: 19:05

NOTIFY DATE: 03-01-91

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY SYSTEM DEGRADATION RELATED TO PROTECTED AREA BOUNDARY.

IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE STATE AND THE RESIDENT INSPECTOR.

UPDATE AT 01:33 ON 03/12/91 BY FERGERSON THE LICENSEE IS RETRACTING THIS EVENT SINCE THEY HAVE DETERMINED THAT THIS REPORT IS ONLY LOGGABLE AND NOT REPORTABLE. THEY ARE BASING THIS ON GENERIC LETTER 91-03 AND THE FACT THAT OTHER COMPENSATORY MEASURES WERE IN PLACE AT TIME OF EVENT. THE RI WILL BE NOTIFIED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2

DOCKET: 05000254 05000265

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

VENDORS: GE-3 GE-3

NOTIFY DATE: 03-04-91

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWK

CODE CRIT PWK

PWR

1 N N 0 REFUELING

2 N Y 95 POWER OPERATION 95 POWER OPERATION

SECURITY SYSTEM DEGRADATION RELATED TO PROTECTED AREA GATE NOT BEING LOCKED PROPERLY. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY.
SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2

DOCKET: 05000295 05000304

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: STEVE BLOOM

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

2 N 99 POWER OPERATION 99 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION DUE TO AREA BOUNDARY. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

SEABROOK 1 20598 03-08-91 POW

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 20598

DOCKET: 05000443 EVENT DATE: 03-08-91

RX TYPE: PWR EVENT TIME: 08:55

VENDORS: W-4-LP NOTIFY DATE: 03-08-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 09:52

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION N

DISCOVERY OF POTENTIAL COMPROMISE OF SAFEGUARDS INFORMATION. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS.

UPDATE AT 14:27 BY STRICKLAND THE LICENSEE IS RETRACTING THIS EVENT SINCE THEY HAVE DETERMINED (08:45 ON 3/21), BASED ON CRITERIA IN GENERIC LETTER 91-03, THE IT IS ONLY LOGGABLE AND NOT REPORTABLE. THE RI WILL BE INFORMED. REG 1 GRAY NOTIFIED.

DIABLO CANYON 1 2 20614 03-10-91 POW LICENSEE: PACIFIC GAS & ELECTRIC CO. EN NUMBER: 20614 SITE: DIABLO CANYON 1 2 EVENT DATE: 03-10-91 DOCKET: 05000275 05000323 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 16:45 NOTIFY DATE: 03-10-91 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 20:35 OPS OFFICER: RUDY KARSCH 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CRIT PWR
N 0 REFUELING 0 REFUELING CODE CRIT PWR N N C REFUELING N Y 100 POWER OPERATION 100 POWER OPERATION N

SECURITY REPORT -- NRC INSPECTORS OBSERVED AN OFFICER WHO WAS INATTENTIVE TO DUTY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

UPDATE 03/14/91 @ 1206 EST BY HUBBLE TAKEN BY MACKINNON

LICENSEE IS RETRACTING THIS EVENT AFTER REVIEWING NRC LETTER 91-03 (REPORTING SAFEGUARDS EVENTS) WITH REGION 5 (DENNIS SCHAEFER). LICENSEE NOTIFIED THEIR RESIDENT INSPECTOR OF THIS RETRACTION. R5DO (GREGG YUHAS) NOTIFIED.

VERMONT YANKEE 1 20616 03-10-91 POW LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP. SITE: VERMONT YANKEE 1 EN NUMBER: 20616 DOCKET: 05000271 EVENT DATE: 03-10-91 RX TYPE: BWR EVENT TIME: 03:35 VENDORS: GE-4 NOTIFY DATE: 03-11-91 EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 09:50 OPS OFFICER: CHAUNCEY GOULD UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N

N Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY QUESTIONED DUE TO INATTENTIVENESS ON WATCH. IMMEDIATE COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR ADDITIONAL DETAILS. THE RI WAS INFORMED.

*** UPDATE DATE :04/10/91 UPDATE TIME:1044 ***FROM LICENSEE:J. MORIARITY

BY T. MCGINTY ***

THE LICENSEE IS RETRACTING THIS EVENT DUE TO GENERIC LETTER NRC 91-03, WHICH REDEFINES THE REPORTABILITY OF SUCH EVENTS. THE LICENSEE HAS DISCUSSED THE MATTER WITH THE RESIDENT INSPECTOR AND THE REGION. NOTIFIED RIDO (ESELGROTH).

20619 03-12-91 POW DIABLO CANYON 1

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 EN NUMBER: 20619

EVENT DATE: 03-12-91 DOCKET: 05000275 EVENT TIME: 07:32 RX TYPE: PWR

VENDORS: W-4-LP NOTIFY DATE: 03-12-91

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 11:29

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INI':IAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR

N 0 COLD SHUTDOWN 0 COLD SHUTDOWN N

SAFEGUARDS SYSTEM DEGRADATION RELATED TO THE AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WAS INFORMED.

UPDATE 03/14/91 @ 1206 EST BY HUBBLE TAKEN BY MACKINNON

LICENSEE IS RETRACTING THIS EVENT AFTER REVIEWING NRC LETTER 91-03 (REPORTING OF SAFEGUARDS EVENTS) WITH REGION 5 (DENNIS SCHAEFER). LICENSEE NOTIFIED RESIDENT INSPECTOR OF THIS RETRACTION.

R5DO (GREGG YUHAS) NOTIFIED.

20637 03-14-91 POW

LICENSEE: DETROIT EDISON CO.

EN NUMBER: 20637 SITE: FERMI 2 EVENT DATE: 03-14-91 DOCKET: 05000341 EVENT TIME: 03:35 RX TYPE: BWR NOTIFY DATE: 03-14-91 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 04:29

OPS OFFICER: DICK JOLLIFFE

1) CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N Y 27 POWER OPERATION 27 POWER OPERATION

SECURITY SYSTEM DEGRADATION DUE TO GUARD SLEEPING ON WATCH. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE ON 4/11/91 1145EDT BY MIKE HALL TO MATTINGLY * * * EVENT RETRACTED BASED ON NRC GENERIC LETTER 91-03 DATED 3/6/91. AN LER WILL NOT BE ISSUED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. THE HOO NOTIFIED R3DO (GARDNER).

INDIAN POINT 2 20654 03-16-91 POW LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW SITE: INDIAN POINT 2 EN NUMBER: 20654

 DOCKET: 05000247
 EVENT DATE: 03-16-91

 RX TYPE: PWR
 EVENT TIME: 12:19

 VENDORS: W-4-LP
 NOTIFY DATE: 03-16-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 13:24

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION RELATED TO IMPROPER SECURING OF THE FUEL STORAGE ROLLER DOOR. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

* * * UPDATE ON 3/18/91 0900EST BY TOM ELSROTH TO MATTINGLY * * *
EVENT RETRACTED AND DOWNGRADED TO A LOGGABLE EVENT AFTER
DISCUSSIONS WITH THE REGION. SEE HOO LOG FOR DETAILS. THE
LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. THE HOO
NOTIFIED R1DO(C ANDERSON).

ARKANSAS NUCLEAR 2 20671 03-20-91 POW

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 2 EN NUMBER: 20671

DOCKET: 05000368 EVENT DATE: 03-20-91

RX TYPE: PWR EVENT TIME: 13:30

VENDORS: CE NOTIFY DATE: 03-20-91

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 15:19

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

2 N N O REFUELING O REFUELING

ONE HOUR SECURITY REPORT DUE TO A DEGRADATION IN THE VITAL AREA BOUNDARY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1738EST ON 3/20/91 FROM HETCHENS TO KARSCH * * * RETRACTING THIS EVENT. UNDER THE GUIDANCE OF GL-91-03 THIS IS NOT REPORTABLE.

POINT BEACH 1 2

20672 03-20-91 POW

LICENSEE: WISCONSIN ELECTRIC POWER CO.

SITE: POINT BEACH 1 2 EN NUMBER: 20672 DOCKET: 05000266 05000301 EVENT DATE: 03-20-91 EVENT TIME: 12:06 RX TYPE: PWR PWR VENDORS: W-2-LP W-2-LP NOTIFY DATE: 03-20-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 16:05

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY REPORT DUE TO A DEGRADATION IN THE VITAL AREA BOUNDARY. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 1412 4/8/91 BY MCCULLUM (SCARFO) * * *

THE LICENSEE IS RETRACTING THIS EVENT NOTIFICATION DUE TO A RECLASSIFICATION OF THE REPORTABILITY OF THIS EVENT AS STATED IN NRC GENERIC LETTER DATED 3/6/91. UNDER THE REVAMPED REPORTING CRITERIA, THE EVENT BECOMES A LICENSEE LOG FNTRY AND NO LONGER REQUIRES AN EVENT NOTIFICATION. R3DO (GARDNER) HAS BEEN NOTIFIED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 2 EN NUMBER: 20700 DOCKET: 05000336 EVENT DATE: 03-25-91 RX TYPE: PWR EVENT TIME: 21:00 VENDORS: CE NOTIFY DATE: 03-25-91

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 21:25

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION

UNACCOUNTED KEYS. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR

DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 2 EN NUMBER: 20707 DOCKET: 05000220 05000410 EVENT DATE: 03-26-91 VENDORS: GE-2 GE-5 EVENT TIME: 13:55 NOTIFY DATE: 03-26-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 14:50

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 96 POWER OPERATION 96 POWER OPERATION N

2 N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF CRIMINAL ACT INVOLVING INDIVIDUAL GRANTED ACCESS. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

POINT BEACH 1 2

LICENSEE: WISCONSIN ELECTRIC POWER CO.

SITE: POINT BEACH 1 2

DOCKET: 05000266 05000301

RX TYPE: PWR PWR

VENDORS: W-2-LP W-2-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: WI

OPS OFFICER: TIM McGINTY

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY DEGRADATION RELATED TO PERIMETER MONITORING. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE 1412 4/8/91 BY MCCULLUM (SCARFO) * * *

THE LICENSEE HAS RETRACTED THIS EVENT DUE TO THE ADEQUACY OF THE COMPENSATORY MEASURES TAKEN AT THE TIME OF THE SECURITY DEGRADATION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R3DO (GARDNER) HAS BEEN INFORMED.

POINT BEACH 1 2 20760 04-04-91 POW LICENSEE: WISCONSIN ELECTRIC POWER CO. EN NUMBER: 20760 SITE: POINT BEACH 1 2 DOCKET: 05000266 05000301 EVENT DATE: 04-04-91 EVENT TIME: 15:23 RX TYPE: PWR PWR VENDORS: W-2-LP W-2-LP NOTIFY DATE: 04-05-91 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 08:48 OPS OFFICER: TIM McGINTY 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY DEGRADATION RELATED TO ACCESS CONTROL. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE 1412 4/8/91 BY MCCULLUM (SCARFO) * * *

THE LICENSEE IS RETRACTING THIS EVENT NOTIFICATION DUE TO A

RECLASSIFICATION OF THE REPORTABILITY OF THIS EVENT AS STATED IN NRC GENERIC LETTER DATED 3/6/91. UNDER THE REVAMPED REPORTING CRITERIA, THE EVENT BECOMES A LICENSEE LOG ENTRY AND NO LONGER REQUIRES AN EVENT NOTIFICATION. R3DO (GARDNER) HAS BEEN NOTIFIED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

DIABLO CANYON 1 2 20771 04-08-91 POW LICENSEE: PACIFIC GAS & ELECTRIC CO. EN NUMBER:20771 SITE: DIABLO CANYON 1 2 DOCKET: 05000275 05000323 EVENT DATE: 04-08-91 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 06:50 NOTIFY DATE: 04-08-91 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 10:44 OPS OFFICER: DICK JOLLIFFE UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR 1 N Y 50 POWER OPERATION 50 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N

ATTEMPTED INTRODUCTION OF A WEAPON INTO THE PLANT PROTECTED AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE @ 1717 ON 04/19/91 BY HUBBLE ENTERED BY HOO JOLLIFFE

LICENSEE INVESTIGATION REVEALED THAT THE EMPLOYEE'S ACTION WAS INADVERTENT WITH NO MALEVOLENT INTENT. LICENSEE HAS REINSTATED THE EMPLOYEE'S VITAL AREA ACCESS AUTHORIZATION AND HAS DOWNGRADED THIS EVENT FROM A REPORTABLE EVENT TO A LOGGABLE EVENT AND DESIRES TO RETRACT THIS EVENT.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. HOO NOTIFIED R5DO REESE.

LICENSEE: CAROLINA FOWER & LIGHT CO.

SITE: HARRIS 1 EN NUMBER: 20777 DOCKET: 05000400 EVENT DATE: 04-09-91 EVENT TIME: 14:00 RX TYPE: PWR NOTIFY DATE: 04-09-91 VENDORS: W-3-LP EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 14:50

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
1 N N 0 REFUELING 0 REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. COMPENSATORY MEASURES TAKEN. RI WILL BE INFORMED. SEE HOO LOG FOR DETAILS.

20792 04-11-91 POW

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: HARRIS 1 EN NUMBER: 20792 DOCKET: 05000400 EVENT DATE: 04-11-91 RX TYPE: PWR EVENT TIME: 08:23

VENDORS: W-3-LP NOTIFY DATE: 04-11-91

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 09:00

OPS OFFICER: TIM McGINTY

OPS OFFICER: TIM McGINTY

10 CFR SECTION: DDDD 73.71

APRE 50.72(b)(2)(vi)

UNIT SCRAM RX INIT INITIAL MODE

CURR CURRENT MODE

PWR CODE CRIT PWR

N N O REFUELING 0 REFUELING

MEDICAL EMERGENCY- HELICOPTER LANDING IN PROTECTED AREA.

AT 0823 EST, APRIL 11, 1991 A CAROLINA AIR CARE HELICOPTER LANDED WITHIN THE BOUNDARY OF THE PROTECTED AREA IN ORDER TO TRANSFER AN ELECTRICAL BURN VICTIM TO THE BURN CENTER AT CHAPEL HILL. THE AREA WAS CORDONED OFF BY A COMBINATION OF ARMED AND UNARMED SECURITY OFFICERS. THE CREW MEMBERS WERE UNDER CONSTANT ESCORT BY ARMED MEMBERS OF THE SECURITY FORCE. THE INJURED INDIVIDUAL WAS PLACED IN THE HELICOPTER AND TRANSPORTED OUT OF THE PROTECTED AREA.

ALL INDIVIDUALS WHO WERE IN CONTACT WITH THE HELICOPTER CREW MEMBERS WERE HAND SEARCHED BY SECURITY PERSONNEL PRIOR TO EXITING THE CORDONED AREA. THE MEDICAL PERSONNEL FROM APEX, NC RESCUE REQUESTED THE HELICOPTER TRANSPORT ON LOCATION DUE TO THE SEVERITY OF THE MEDICAL EMERGENCY.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * *UPDATE 04/12/91 AT 1445 EDT FROM CASE ENTERED BY KARSCH* * * THE LICENSEE IS RETRACTING THIS EVENT AND CONSIDERS IT TO BE NOT REPORTABLE. THE ACTIONS TAKEN IN RESPONSE TO THIS EVENT WERE IN ACCORDANCE WITH 10CFR73.55(d)(4) AND CHAPTER 3 OF THE HARRIS SECURITY PLAN. THIS REPORT WILL BE PLACED INTO THE QUARTERLY EVENT LOG. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R2DO (JAPE) NOTIFIED.

DIABLO CANYON 1 2 20818 04-13-91 POW

LICENSEE: PACIFIC GAS & ELECTRIC CO.

EN NUMBER: 20818 DOCKET: 05000275 05000323 EVENT DATE: 04-13-91 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 10:50 NOTIFY DATE: 04-13-91

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 14:49

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING ONE VITAL AREA DOOR DISCOVERED BY THE LICENSEE. IMMEDIATE COMPENSATORY MEASURE TAKEN ON DISCOVERY.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

* * * UPDATE @ 1717 ON C4/19/91 BY HUBBLE ENTERED BY HOO JOLLIFFE

WHILE INSPECTING OTHER VITAL AREA DOORS, SECURITY GUARDS OBSERVED THIS DOOR EVERY 10 MINUTES WHILE THE PLANT SECURITY COMPUTER WAS OUT OF SERVICE FOR MAINTENANCE. THUS, LICENSEE DOWNGRADED THIS EVENT FROM A REPORTABLE EVENT TO A LOGGABLE EVENT AND DESIRES TO RETRACT THIS EVENT DUE TO THE ABOVE INFORMATION AND THE CONTENTS OF NRC GENERIC LETTER #91-03.

SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R5DO REESE.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAIDWOOD 1 2 EN NUMBER: 20874

DOCKET: 05000456 05000457 EVENT DATE: 04-23-91

RX TYPE: PWR PWR EVENT TIME: 06:37

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 04-23-91

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 08:30

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71

APRE 50.72(b)(2)(vi)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

UNSPECIFIED PARAGRAPH

OFFSITE NOTIFICATION

CURR CURRENT MODE

PWR

1 N N O COLD SHUTDOWN O COLD SHUTDOWN 2 N Y 96 POWER OPERATION 96 POWER OPERATION

MISFIRED SECURITY WEAPON INJURED SECURITY GUARD. SEE LOG BOOK FOR DETAILS. NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

* * *UPDATE AT 1716 ON 5/3/91 BY TRUSHEIM AND ROONEY ENTERED BY BLOOM * * *
LICENSEE IS RETRACTING THIS EVENT AS A SECURITY REPORT SINCE IT DOES NOT MEET REPORTABILITY REQUIREMENTS. LICENSEE IS NOW CLASSIFYING THIS AS AN ACCIDENT THAT RESULTS IN A PRESS RELEASE. THE SECURITY CONTRACTOR WAS CONTACTED BY A LOCAL NEWSPAPER AND GAVE OUT DETAILS OF THE EVENT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. NOTIFIED R3DO(WRIGHT).

PALO VERDE 3 20905 04-28-91 POW

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 3 EN NUMBER: 20905

DOCKET: 05000530 EVENT DATE: 04-28-91

RX TYPE: PWR EVENT TIME: 16:10

VENDORS: CE80 NOTIFY DATE: 04-28-91

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 20:08

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

3 N N O REFUELING O REFUELING

SAFEGUARDS DEGRADATION RELATED TO UNMONITORED OPEN VITAL AREA DOOR.

IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. AFFECTED AREA WALKDOWN CURRENTLY IN PROGRESS. LICENSEE STATES THAT THIS EVENT MAY NOT BE REPORTABLE PER GENERIC LETTER 91-03 BUT IS CURRENTLY COMPLYING WITH REPORTING PROCEDURE PER THEIR EVENT REPORTING MANUAL. RESIDENT INSPECTOR WILL BE INFORMED.

*** UPDATE DATE :05/01/91 UPDATE TIME:1805 EDT ***FROM LICENSEE: KATHLEEN ROBERSON BY T. McGINTY ***
THIS EVENT IS BEING RETRACTED BASED ON A REVIEW OF GENERIC LETTER 91-03 REGARDING THE REPORTABILITY OF SAFEGUARDS EVENTS. BASED ON THAT REVIEW, THIS EVENT HAS BEEN REDUCED TO A LOGGABLE 73.71 EVENT. SPECIFICALLY, A VULNERABILITY IN A SAFEGUARD BARRIER THAT WAS COMPENSATED UPON DISCOVERY WITH NO ADVERSE CONSEQUENCES OR CONDITIONS DISCOVERED.

THE R5 SECURITY INSPECTOR (D. SCHUSTER) HAS BEEN NOTIFIED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R5DO (K. PERKINS) NOTIFIED BY HOO.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1 2

DOCKET: 05000424 05000425

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EVENT TIME: 19:08

NOTIFY DATE: 04-29-91

EMERGENCY CLASS: N/A PEGION: 3 STATE: GA TIME: 20:05

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 20:05

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

TORNADO TOUCHING DOWN IN THE OWNER CONTROLLED AREA CAUSED LICENSEE TO PULL BACK THEIR PERIMETER GUARDS IN AREAS NOT COVERED BY CAMERA SURVEILLANCE. INTRUSION ALARMS ARE OK. SEE HOO LOG BOOK FOR FURTHER DETAILS. RI NOTIFIED BY THE LICENSEE.

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 20916 SITE: WATERFORD 3 DOCKET: 05000382 EVENT DATE: 04-30-91 EVENT TIME: 04:14 RX TYPE: PWR NOTIFY DATE: 04-30-91 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 05:52

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SECURITY EVENT SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED

THE NRC RESIDENT INSPECTOR.

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 EN NUMBER: 20929 EVENT DATE: 05-02-91 DOCKET: 05000498 EVENT TIME: 10:38 RX TYPE: PWR NOTIFY DATE: 05-02-91 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 12:16

OPS OFFICER: STEVE BLOOM

10 CFR SECTION: DCTB 73.71(b)(1) CONTRABAND
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

ACTUAL INTRODUCTION OF CONTRABAND (PISTOL) INTO PA. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

RX TYPE: BWR PWR PWR EVENT TIME: 10:35
VENDORS: GE-3 CE W-4-LP NOTIFY DATE: 05-03-91 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 10:52

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
3 N Y 100 POWER OPERATION 100 POWER OPERATION

THE SECURITY PROGRAM COMPUTER HAS EXPERIENCED INTERMITTENT LOSS OF PROGRAM ACCESS CONTROL. COMPENSATORY MEASURES HAVE BEEN TAKEN. THE PROBLEM IS BEING ADDRESSED. SEE HOO LOG FOR DETAILS. THE NRC RESIDENT INSPECTOR, STATE AND LOCAL OFFICIALS WILL BE NOTIFIED OF THE EVENT.

CLINTON 1

20987 05-11-91 POW

LICENSEE: ILLINOIS POWER CO.

EN NUMBER: 20987 SITE: CLINTON 1 EVENT DATE: 05-11-91 DOCKET: 05000461 RX TYPE: BWR EVENT TIME: 11:09 NOTIFY DATE: 05-11-91 VENDORS: GE-6 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 12:40

OPS OFFICER: JOHN MacKINNON

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CUFRENT MODE
CODE CRIT PWR
N 99 POWER OPERATION 99 POWER OPERATION

A FIRE WATCH CONTRACT EMPLOYEE (WITH BURNS SECURITY) WITH UNESCORTED ACCESS TO CLINTON POWER STATION WAS ARRESTED AND CHARGED WITH SECOND DEGREE MURDER (WHICH OCCURRED LAST NIGHT) AND WEAPONS VIOLATION (GUN). THIS INCIDENT OCCURRED OFFSITE. EMPLOYEE'S ACCESS WAS REMOVED AT 1005 CDT, 5/11/91. DECATUR, ILLINOIS POLICE HAS SCHEDULED A NEWS RELEASE ON THIS INCIDENT FOR 5/13/91. THE LICENSEE DID NOT KNOW HOW LONG THIS EMPLOYEE HAS WORKED AT THEIR SITE. THE RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

* * * UPDATE RETRACTION FROM DENNIS SMITH AT 1019 EDT TAKEN BY KARSCH* * *

THE BASIS FOR THIS RETRACTION IS THAT ALTHOUGH THIS IS A NEWSWORTHY EVENT, IT DID NOT POSE A SECURITY THREAT TO THE CLINTON POWER STATION. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. THE R3DO (WIEDEMAN) HAS BEEN INFORMED.

20989 05-11-91 POW DRESDEN 2 3

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3 EN NUMBER: 20989 DOCKET: 05000237 05000249
RX TYPE: BWR BWR
VENDORS: GE-3 GE-3 EVENT DATE: 05-11-91 EVENT TIME: 12:56 NOTIFY DATE: 05-11-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:46

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR
PWR UNSPECIFIED PARAGRAPH CURR CURRENT MODE

2 N Y 85 POWER OPERATION 85 POWER OPERATION 3 N Y 75 POWER OPERATION 75 POWER OPERATION

MANHOLE (12" DIA PIPE) FROM OWNER CONTROLLED AREA TO THE PROTECTED AREA IN THE NORTH EAST CORNER OF PROPERTY FOUND UNSEALED. GUARD PLACED ON STATION UNTIL IT IS CORRECTED. LICENSEE DID NOT KNOW HOW LONG THIS CONDITION HAS EXISTED. SEARCH OF THE AREA FOUND NOTHING.

RESIDENT INSFECTOR WILL BE INFORMED BY THE LICENSEE.

*** UPDATE DATE :5/20/91***UPDATE TIME:09:53***FROM LICENSEE:T. JOSEFIK BY: HUFFMAN ***

BASED ON THE CRITERIA IN GENERIC LETTER 91-03, THE LICENSEE HAS DECIDED TO RETRACT THIS EVENT. IT HAS BEEN DETERMINED TO BE A 24 HOUR LOGGABLE EVENT. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED. R3DO (LANKSBURY)

NOTIFIED.

20994 05-07-91 POW POINT BEACH 1 2

LICENSEE: WISCONSIN ELECTRIC POWER CO.

EN NUMBER: 20994 SITE: POINT BEACH 1 2 DOCKET: 05000266 05000301 EVENT DATE: 05-07-91 VENDORS: W-2-LP W-2-LP EVENT TIME: 05:15 NOTIFY DATE: 05-12-91 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 23:27

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

CRIT PWR
N 0 REFUELING 0 REFUELING
Y 100 POWER OPERATION 100 POWER OPERATION 1 N N

FITNESS FOR DUTY DUE TO SECURITY GUARD FOUND ASLEEP AT POST. LICENSEE DID NOT FIND OUT ABOUT THIS EVENT UNTIL A FEW MINUTES AGO (2215 CDT 5/07/91). LICENSEE WILL INTERVIEW GUARD THAT WAS ASLEEP AT POST TOMORROW MORNING (5/13/91). LICENSEE HAS NOT SEARCHED THE AREA AND WILL NOT SEARCH THE AREA BECAUSE IN ORDER TO GET INTO THE AREA WHERE THE GUARD FEEL ASLEEP YOU NEED VITAL AREA ACCESS.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

**** 9:20 ET 05/15/91 BY JOAN MCCULLUM TAKEN BY THOMAS ANDREW.

THE OFFICER, UPON FURTHER INVESTIGATION WAS INATTENTIVE, NOT SLEEPING AS WAS ORIGINALLY REPORTED. IN LIGHT OF THE GUIDANCE IN GENERIC LETTER 91-03, THIS IS A LOGGABLE EVENT, RATHER THAN A REPORTABLE EVENT. THE RESIDENT INSPECTOR AND THE R3DO (WIEDEMAN) HAVE BEEN INFORMED.

LICENSEE: NORTHEAST UTILITIES SITE: MILLSTONE 1 2 3 EN NUMBER: 20995 DOCKET: 05000245 05000336 05000423 EVENT DATE: 05-13-91 RX TYPE: BWR PWR PWR VENDORS: GE-3 CE W-4-LP EVENT TIME: 11:30 NOTIFY DATE: 05-13-91 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 12:26 OPS OFFICER: STEVE SANDIN 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM FX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR 1 N N O REFUELING 0 REFUELING

Y 50 POWER OPERATION 50 POWER OPERATION Y 100 POWER OPERATION 100 POWER OPERATION N

UNIT 1 IS DEFUELED. SAFEGUARDS SYSTEM DEGRADATION RELATED TO PROTECTED AREA BOUNDARY AND VITAL AREA DOORS. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AND THE STATE OF CT.

LICENSEE: COMMONWEALTH EDISON CO.

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 12:21 OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
PWR CODE CRIT PWR

1 N N 0 HOT SHUTDOWN 0 HOT SHUTDOWN
2 N Y 92 POWER OPERATION 92 POWER OPERATION

EXPERIENCED LOSS OF MAIN SECURITY COMPUTER, REDUNDANT ACCESS CONTROL SYSTEM (BACKUP SECURITY COMPUTER), AND DEDICATED CAMERA MONITORS FOR LESS THAN 2 MINUTES WHEN AN UNINTERRUPTIBLE POWER SUPPLY INVERTER TROUBLE ALARM WOULD NOT RESET. THE LICENSEE DOES NOT KNOW WHAT CAUSED THE TROUBLE ALARM AT THIS TIME.

THE SYSTEM IS BACK TO NORMAL WITH THE EXCEPTION OF THE BACKUP SECURITY COMPUTER AND THE UNINTERRUPTIBLE POWER SUPPLY. THIS COMPUTER HAS TO BE REBOOTED WHICH REQUIRES CALLING IN PERSONNEL IN THE COMPUTER GROUP. FULL COMPENSATORY MEASURES ARE IN PLACE UNTIL ALL TESTING OF ALARM ZONES IS COMPLETED. TESTING OF THESE ZONES WILL TAKE ABOUT AN HOUR AFTER THE BACKUP SECURITY COMPUTER IS REBOOTED.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: B&W FUEL CO.

EN NUMBER: 21099 SITE: B&W FUEL CO. DOCKET: 07001201 EVENT DATE: 05-29-91 RX TYPE: EVENT TIME: 07:00 NOTIFY DATE: 05-29-91

EMERGENCY CLASS: N/A REGION: 2 STATE: VA TIME: 08:58

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DLOS 73.71(a) SHIPMENT LOST

AT 1420EDT ON 5/28/91 TWELVE (12) FUEL ASSEMBLIES IN SIX (6) CONTAINERS WERE SHIPPED VIA TRI-STATE TRUCKING (*) FROM THE B&W COMMERCIAL NUCLEAR FUEL FABRICATION FACILITY IN VIRGINIA TO THE DAVIS-BESSE FACILITY IN OAK HARBOR, OHIO. THE TRUCKERS LAST CALL IN WAS AT 2400EDT ON 5/28/91 FROM AMHEARST, OHIO WHICH IS APPROXIMATELY 60 MILES EAST OF THE PLANT. LICENSEE IS MAKING THIS REPORT TO INFORM THE NRC THAT THE FUEL HAD NOT ARRIVED AT 0700EDT AS 3CHEDULED. THE FUEL ASSEMBLIES CONTAIN >207,000 GRAMS URANIUM ENRICHED TO APPROX 3 W/O AND FOR REPORTING PURPOSES ARE DEFINED AS LOW STRATEGIC SPECIAL NUCLEAR MATERIAL, i.e. 10,000 GRAMS ENRICHED <10 W/O. AN ONSITE B&W REPRESENTATIVE (*) HAS DISPATCHED PERSONNEL TO LOCATE THE SHIPMENT ALONG THE ROUTE OF TRANSPORT. LICENSEE PLANS NO NOTI. ATION TO ANY LAW ENFORCEMENT OR OTHER OUTSIDE AGENCIES.

*SEE HOO LOG FOR CONTACT PERSONNEL AND TELEPHONE NUMBERS

HOONOTE: DAVIS-BEESE WAS CONTACTED AND IS AWARE OF THE SITUATION, HOWEVER BEW IS CONTRACTUALLY OBLIGATED TO MAINTAIN CUSTODY AND OBSERVE NRC REPORTING REQUIREMENTS UNTIL THE FUEL ARRIVES ONSITE.

* * * UPDATE 1134EDT 5/29/91 FROM LESTER BY S.SANDIN * * *
TRUCKER CONTACTED TRI-STATE TRUCKING DISPATCH AT APPROX 1115EDT
FROM THE AMHEARST, OHIO STOPOVER. THE PERSONNEL DISPATCHED FROM
THE SITE ARRIVED AT THE LOCATION AT APPROX THE SAME TIME.
PRELIMINARY INDICATION IS THAT THE TRUCKER DID NOT OBSERVE THE
WRITTEN B&W SHIPPING REQUIREMENTS WHICH HE HAD BEEN BRIEFED ON
PRIOR TO HIS DEPARTURE FROM THE D&W FACILITY IN VA, i.e.
CONTACTING B&W IF ANTICIPATED ARRIVAL WAS LATER THAN SCHEDULED.
NOTIFIED R2DO(VERRELLI), R3DO(CANIANO), EO(HICKEY),
IAT(YARDUMIAN), AEOD (SPESSARD), AND PAO(NEWLIN).

COMANCHE PEAK 1 2 21135 06-03-91 POW

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

SITE: COMANCHE PEAK 1 2 EN NUMBER: 21135

DOCKET: 05000445 05000446 EVENT DATE: 06-03-91

RX TYPE: PWR PWR EVENT TIME: 11:34

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 06-03-91

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 13:20

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0

AT 1040 (CDT) ON 06/03/91, A SECURITY GUARD DISCOVERED THE UNIT 2 CIRCULATION WATER DISCHARGE TUNNEL MANHOLE COVER HAD BEEN REMOVED AND NO SECURITY COMPENSATORY MEASURES HAD BEEN TAKEN. THE SECURITY GUARD IMMEDIATELY NOTIFIED THE CENTRAL ALARM STATION AND TOOK COMPENSATORY ACTIONS.

INVESTIGATION HAS REVEALED THAT UNIT 2 CONSTRUCTION PERSONNEL REMOVED THE MANHOLE COVER AT AROUND 0900 (CDT) ON 06/03/91. THE MANHOLE COVER WAS REPLACED AT 1130 (CDT) ON 06/03/91 AND A SWEEP OF THE PROTECTED AREA IS IN PROGRESS. THE LICENSEE DID NOT KNOW WHY THE CONSTRUCTION PERSONNEL REMOVED THE MANHOLE COVER.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

*** UPDATE DATE :06/17/9! UPDATE TIME:1342 EDT ***FROM LICENSEE:BROUGHTON BY T. McGINTY ***
THIS EVENT HAS BEEN RETRACTED AND DOWNGRADED TO A LOGGABLE EVENT. THIS IS BASED ON EVALUATION AND THE CONCLUSION WAS REACHED FOLLOWING DISCUSSIONS WITH C. CAIN OF REGION IV AND D. GRACE, THE RESIDENT INSPECTOR. SEE THE HOO LOG FOR DETAILS. HOO NOTIFIED R4DO (GAGLIARDO).

COMANCHE PEAK 1 2 21149 06-05-91 POW LICENSEE: TEXAS UTILITIES ELECTRIC CO. EN NUMBER: 21149 SITE: COMANCHE PEAK 1 2 DOCKET: 05000445 05000446 EVENT DATE: 06-05-91 EVENT TIME: 11:39 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 06-05-91 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 13:29 OPS OFFICER: TIM McGINTY 10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURRENT MODE
PWR N Y 100 POWER OPERATION 100 POWER OPERATION N 0 2 N

SAFEGUARDS SYSTEM DEGRADATION RELATED TO POSSIBLE BREACH OF PROTECTED AREA

DURING REVIEW OF WORK IN PROGRESS ON UNIT 2 CONSTRUCTION ACTIVITIES WITH REGARDS TO THE SECURITY VIOLATION OF 06/03/91 (SEE EVENT #21135), A POSSIBLE BREACH OF THE PROTECTED AREA BOUNDARY WAS DISCOVERED. IMMEDIATE COMPENSATORY MEASURE TAKEN UPON DISCOVERY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

*** UPDATE DATE :06/17/91 UPDATE TIME:1342 EDT ***FROM LICENSEE:BROUGHTON BY T. McGINTY ***
THIS EVENT HAS BEEN DOWNGRADED TO A LOGGABLE EVENT AFTER EVALUATION. THIS CONCLUSION WAS REACHED FOLLOWING DISCUSSIONS WITH C. CAIN OF REGION IV AND THE RESIDENT INSPECTOR (D. GRACE). SEE HOO LOG FOR DETAILS. HOO NOTIFIED R4DO (GAGLIARDO).

LICENSEE: STATE OF RHODE ISLAND

SITE: RHODE ISLAND ATOMIC ENERGY COM

DOCKET: 05000193

RX TYPE: POOL

VENDORS:

EMERGENCY CLASS: N/A REGION: 1 STATE: RI

OPS OFFICER: TIM McGINTY

10 CFR SECTION: DTHR 73.71(c)

EMERGENCY CLASS: STATE OF RHODE ISLAND

EVENT DATE: 06-10-91

EVENT TIME: 18:00

NOTIFY DATE: 06-11-91

SECURITY DEGRADATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO THE VITAL AREAS ALARM SYSTEM AT THE RHODE ISLAND NUCLEAR SCIENCE CENTER.

IMMEDIATE COMPENSATORY MEASURES WERE TAKEN AT THE TIME OF DISCOVERY.

THE RESEARCH REACTOR WAS SHUTDOWN DURING THE EVENT. SEE THE HOO LOG FOR DETAILS CONCERNING THIS EVENT. HOO NOTIFIED THE REGION (RIDO SHANBAKY).

21227 06-19-91 POW YANKEE ROWE 1

LICENSEE: VANKEE ATOMIC ELECTRIC CO.

EN NUMBER: 21227 SITE: YANKEE ROWE 1 EVENT DATE: 06-19-91 DOCKET: 05000029 EVENT TIME: 21:40 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 06-19-91 EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 22:28

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR PWR CODE CRIT PWR 1 N N O COLD SHUTDOWN O COLD SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION FOLLOWING LOSS OF POWER TO THE CENTRAL ALARM STATION (CAS) AND SECONDARY ALARM STATION (SAS). NOT COMPENSATED FOR UNTIL POWER WAS RESTORED 13 MINUTES LATER. SEE HOO LOG FOR DETAILS. NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

UPDATE ON 6/20/91 1241 EDT BY JAMES PALMIERI TAKEN BY MACKINNON

BASED ON NRC GENERIC LETTER 91-03 AND DISCUSSION WITH REGION 1 (RICK KEIMIG) THIS EVENT IS BEING DOWNGRADED TO A LOGGABLE EVENT (AS OF 1100 EDT). LICENSEE IS RETRACTING THIS EVENT. R1DO (DON HAVERKAMP) NOTIFIED.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: ARIZONA PUBLIC SERVICE CO. SITE: PALO VERDE 1 2 3

EN NUMBER: 21272 DOCKET: 05000528 05000529 05000530 EVENT DATE: 06-27-91 RX TYPE: PWR PWR PWR VENDORS: CE80 CE80 CE80 EVENT TIME: 09:00 NOTIFY DATE: 06-27-91 EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 12:30 OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION
3 N Y 100 POWER OPERATION 100 POWER OPERATION

⁻ LICENSEE SECURITY GUARD FORCE STRIKE PROBABLE IN NEXT THREE DAYS -

ON 06/26/91, LICENSEE SECURITY GUARD FORCE VOTED TO FORMALLY AUTHORIZE

A STRIKE. LICENSEE BELIEVES THAT A STRIKE IS IMMINENT WITHIN THE

3 DAYS. IF A STRIKE OCCURS, LICENSEE HAS AN ADEQUATE NUMBER OF TRAINED REPLACEMENT GUARDS AVAILABLE AS A CONTINGENCY MEASURE. LICENSEE HAS DETERMINED THAT A STRIKE WOULD HAVE NO EFFECT ON SAFE OPERATION OF THE PLANT.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

REGION V ISSUED PN #PNO-V-91-12.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BYRON 1 EN NUMBER:21283 DOCKET: 05000454 EVENT DATE: 06-29-91 RX TYPE: PWR EVENT TIME: 01:29 NOTIFY DATE: 06-29-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 03:36

OPS OFFICER: WILLIAM MATTINGLY 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 70 POWER OPERATION 70 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO A VITAL AREA BOUNDARY.

NOT IMMEDIATELY COMPENSATED AT DISCOVERY BUT COMPENSATED NOW. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 EN NUMBER: 21320 DOCKET: 05000245 EVENT DATE: 07-04-91 RX TYPE: BWR EVENT TIME: 00:50 VENDORS: GE-3 NOTIFY DATE: 07-04-91 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 01:56

OPS OFFICER: TIM McGINTY 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR

N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA DOOR. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. STATE AND LOCAL AUTHORITIES HAVE BEEN NOTIFIED. SEE HOO LOG FOR DETAILS.

LICENSEE: DUQUESNE LIGHT CO.
SITE: BEAVER VALLEY 1 2 EN NUMBER: 21359
DOCKET: 05000334 05000412 EVENT DATE: 07-11-91

RX TYPE: PWR PWR EVENT TIME: 10:03 VENDORS: W-3-LP W-3-LP NOTIFY DATE: 07-11-91

EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 11:04

OPS OFFICER: THOMAS ANDREWS UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN N Y 100 POWER OPERATION 100 POWER OPERATION N

SECURITY COMPUTER FAILED AT 1003 EDT FOR ABOUT 15 MINUTES.

THE LICENSEE WAS IN THE PROCESS OF DUMPING DATA FROM THE SECURITY COMPUTER WHEN THE COMPUTER FAILED. GUARDS WERE POSTED AT 0930 AS COMPENSATORY MEASURES DURING THE COMPUTER DUMP. ADDITIONAL COMPENSATORY MEASURES WERE TAKEN AS REQUIRED. LICENSEE IS INVESTIGATING PROBLEM WITH SECURITY COMPUTER.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

EN NUMBER:21379 SITE: COOK 1 2 DOCKET: 05000315 05000316 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 07-14-91 EVENT TIME: 01:37 NOTIFY DATE: 07-14-91

EMERGENCY CLASS: UNU REGION: 3 STATE: MI TIME: 01:50

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: AAEC 50.72(a)(1)(i) EMERGENCY DECLARED

DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 98 POWER OPERATION 98 POWER OPERATION

UNUSUAL EVENT DECLARED BECAUSE OF DISCOVERY OF SUSPICIOUS PACKAGE FOUND IN THE PROTECTED AREA WITH A THREATENING MESSAGE WRITTEN UPON IT. SEE HOO LOG FOR DETAILS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

**** UPDATE AT 0323 ET ON 07/14/91 BY R. SIEBER TAKEN BY T. ANDREWS ****

LICENSEE TERMINATED UNUSUAL EVENT AT 0320 AFTER DETERMINING THE PACKAGE DID NOT POSE A THREAT TO THE PLANT. THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR.

LICENSEE: WISCONSIN ELECTRIC POWER CO.

EN NUMBER:21387 SITE: POINT BEACH 1 2 DOCKET: 05000266 05000301 EVENT DATE: 07-15-91
RX TYPE: PWR PWR EVENT TIME: 14:15
VENDORS: W-2-LP W-2-LP NOTIFY DATE: 07-15-91 EVENT DATE: 07-15-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 15:51

OPS OFFICER: WILLIAM MATTINGLY 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 2 N

DISCOVERY OF POSSIBLE DRUG USE INVOLVING A CONTRACTOR PREVIOUSLY GRANTED UNESCORTED ACCESS.

AN HP CONTRACTOR WAS GRANTED UNESCORTED ACCESS FOR THE FALL 1990 AND SPRING 1991 OUTAGES. INFORMATION OBTAINED TODAY FROM CORPORATE HEADQUARTERS INDICATED THAT THE CONTRACTOR WAS DENIED ACCESS ON FOUR SEPARATE OCCASIONS IN 1987 (AT OTHER UTILITIES) FOR ALLEGEDLY FAILING THE INITIAL DRUG SCREENING. THE CONTRACTOR'S ACCESS WAS REMOVED FOLLOWING THE SPRING OUTAGE AND AN INVESTIGATION IS IN PROGRESS.

SEE SIMILAR EVENT 21390 AT PRAIRIE ISLAND.

THE LICENSEE INFORMED REGION III AND THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHERN STATES POWER CO.

EN NUMBER: 21390 SITE: PRAIRIE ISLAND 1 2 EVENT DATE: 07-15-91 DOCKET: 05000282 05000306 EVENT TIME: 16:30 RX TYPE: PWR PWR VENDORS: W-2-LP W-2-LP NOTIFY DATE: 07-15-91 EMERGENCY CLASS: N/A REGION: 3 STATE: MN TIME: 17:42

OPS OFFICER: WILLIAM MATTINGLY

OPS OFFICER: WILLIAM MATTINGET

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF POSSIBLE DRUG USE INVOLVING A CONTRACTOR PREVIOUSLY GRANTED UNESCORTED ACCESS.

AN HP CONTRACTOR WAS GRANTED UNESCORTED ACCESS FOR THE FALL 1990 OUTAGE, INFORMATION OBTAINED TODAY FROM CORPORATE HEADQUARTERS INDICATED THAT THE CONTRACTOR WAS DENIED ACCESS ON FOUR SEPARATE OCCASIONS IN 1987 (AT OTHER UTILITIES) FOR ALLEGEDLY FAILING THE INITIAL DRUG SCREENING. THE CONTRACTOR'S ACCESS WAS REMOVED FOLLOWING THE FALL OUTAGE ON 9/28/90 AND AN INVESTIGATION IS IN PROGRESS.

SEE SIMILAR EVENT 21387 AT POINT BEACH.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PHILADELPHIA ELECTRIC CO.

SITE: LIMERICK 1 2

EN NUMBER: 21401

DOCKET: 0 .00352 05000353 EVENT DATE: 07-18-91 EVENT TIME: 10:00 RX TYPE: BWR BWR NOTIFY DATE: 07-18-91 VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 10:39 OPS OFFICER: RUDY KARSCH 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION N

ONE HOUR SECURITY REPORT.

A FILE CABINET CONTAINING SAFEGUARDS INFORMATION WAS FOUND UNLOCKED. COMPENSATORY MEASURES WERE TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

EN NUMBER: 21583 SITE: VERMONT YANKEE 1 DOCKET: 05000271 EVENT DATE: 08-09-91 EVENT TIME: 16:20 RX TYPE: BWR NOTIFY DATE: 08-09-91 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 16:30

OPS OFFICER: TIM MCGINTY

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT DWR
N Y 100 PWR

Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACTOR ACCESSES REMOVED IN RESPONSE TO SECURITY INVESTIGATIONS

DEGRADATION OF SAFEGUARDS SYSTEMS BASED ON ACCESS GRANTED TO INDIVIDUALS SUBSEQUENTLY DETERMINED TO BE UNAUTHORIZED. IMMEDIATE COMPENSATORY MEASURES TAKEN BY REMOVING ACCESS UPON DISCOVERY. SPECIFICALLY, A CONTRACTOR EMPLOYEE WAS DISCOVERED TO HAVE MISREPRESENTED HIS CRIMINAL HISTORY BACKGROUND. AN AUDIT OF THE CONTRACTORS REVIEW OF SECURITY BACKGROUND INVESTIGATIONS DETERMINED SEVERAL CASES IN WHICH THE LICENSEES ACCEPTABLE CRITERIA WERE NOT MET. NINE ACCESSES WERE WITHDRAWN OVER THE PAST WEEK FOR THIS PARTICULAR CONTRACTOR IN RESPONSE TO THIS EVENT. NONE OF THE CONTRACTORS WERE OF THE FOREMAN OR MANAGEMENT LEVEL, AND THEIR CLEARANCE DID NOT INCLUDE ACCESS INTO ANY VITAL AREAS. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES EN NUMBER: 21599 DOCKET: 05000245 05000336 05000423 EVENT DATE: 08-12-91 EVENT TIME: 18:11 RX TYPE: BWR PWR PWR NOTIFY DATE: 08-12-91 VENDORS: GE-3 CE W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 18:30

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 STARTUP 0 STARTUP

2 N N 0 HOT STANDBY 0 HOT STANDBY

3 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

UNDETECTED ENTRY INTO VITAL AREA. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2

DOCKET: 05000315 05000316

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: MI

OPS OFFICER: WILLIAM HUFFMAN
10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PMP

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 98 POWER OPERATION 98 POWER OPERATION

INCOMPLETE PRE-EMPLOYMENT SECURITY SCREENING.

THE LICENSEE DETERMINED THAT AN INDIVIDUAL WHO HAD BEEN GRANTED UNESCORTED ACCESS TO THE SITE WOULD HAVE BEEN DENIED SUCH ACCESS BASED ON INFORMATION DEVELOPED DURING SUBSEQUENT INVESTIGATIONS INTO THE INDIVIDUAL'S BACKGROUND.

REVIEW OF THE BACKGROUND SCREENING PROCESS OF A CONTRACT EMPLOYEE WHO HAD RECENTLY BEEN INVOLVED IN A FITNESS FOR DUTY ISSUE REVEALED SEVERAL DEFICIENCIES: (A) THE CONTRACTOR (BARTLETT) FAILED TO PROVIDE DEROGATORY INFORMATION TO THE LICENSEE ON THE EMPLOYEE'S BACKGROUND; (B) THE LICENSEE FAILED TO MAINTAIN RECORDS WHICH INDICATED A PREVIOUS DENIAL OF ACCESS TO THE SPECIFIC INDIVIDUAL; (C) FAILURE OF THE EMPLOYEE TO IDENTIFY THAT HE HAD PREVIOUSLY BEEN DENIED ACCESS TO THE PLANT SITE ON THE SECURITY FORM.

THE LICENSEE IS REPORTING THIS PER THE LAST PARAGRAPH OF GENERIC LETTER 91-03.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: CONNECTICUT YANKEE ATOMIC POWER CO.

SITE: HADDAM NECK 1 EN NUMBER: 21720
DOCKET: 05000213 EVENT DATE: 08-27-91
RX TYPE: PWR EVENT TIME: 11:50

NOTIFY DATE: 08-27-91 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 12:00

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

A SECURITY GUARD LEFT HIS POST AT AN OPEN VITAL AREA DOOR UNATTENDED FOR APPROXIMATELY 20 SECONDS WHILE HE OPENED ANOTHER DOOR. SEE HOO LOG FOR THE COMPENSATORY MEASURES TAKEN. THE LICENSEE HAS NOTIFIED THE CONNECTICUT DEPARTMENT OF ENVIRONMENTAL PROTECTION AND WILL INFORM THE NRC RESIDENT INSPECTOR.

21724 08-27-91 POW VERMONT YANKEE 1

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

EN NUMBER: 21724 SITE: VERMONT YANKEE 1 EVENT DATE: 08-27-91 DOCKET: 05000271 RX TYPE: BWR EVENT TIME: 14:50

NOTIFY DATE: 08-27-91 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 14:59

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

UNAUTHORIZED ENTRY INTO THE VITAL AREA.

A LICENSEE OPERATIONS INSTRUCTOR HAD NINE CO-OP STUDENTS ON A TOUR OF THE RCIC. SECURITY RECEIVED AN ALARM AND FOUND THAT FOUR OF THE STUDENTS DIDN'T HAVE PROPER AUTHORIZATION TO BE IN THE RCIC AREA. SECURITY RESPONDED AND ESCORTED THE INDIVIDUALS OUT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

****UPDATE FROM LICENSEE: MORIARITY TO NRC: HUFFMAN ON9/10/91 AT 1204 EDT****

THIS REPORT IS BEING RETRACTED BASED ON FURTHER INVESTIGATION BY SECURITY. THE STUDENTS INVOLVED IN THIS INCIDENT DID NOT HAVE AUTHORIZATION DUE TO AN ADMINISTRATIVE OVER SITE. THERE WAS NO WILLFUL INTENT TO GAIN UNAUTHORIZED ENTRY INTO A VITAL AREA. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED. R1DO (ANDERSON) NOTIFIED.

21726 08-28-91 POW BRAIDWOOD 1 2

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAILWOOD 1 2 EN NUMBER:21726 SITE: BRAILWOOD 1 2 EN NUMBER: 21726

DOCKET: 05000456 05000457 EVENT DATE: 08-28-91

RX TYPE: PWR PWR EVENT TIME: 04:11

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 08-28-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 06:08

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DTHR 73.71(c)						SECURITY DEGRADATION		
UNIT				INITIAL MODE		CURR	CURRENT MODE	
1	CODE	CRIT	PWR 99	POWER	OPERATION	PWR 99	POWER	OPERATION
2	N	Y	71	The second second second	OPERATION	71	POWER	OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO BOTH PRIMARY AND SECONDARY SECURITY SYSTEMS. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

UPDATE FROM DORAZIO TO HUFFMAN AT 15:13EDT ON 9/3/91
LICENSEE IS RETRACTING THIS NOTIFICATION BASED ON REPORTABILITY
GUIDANCE PROVIDED IN NRC GENERIC LETTER 91-03. LICENSEE STATES
THAT COMPENSATORY ACTIONS WERE ESTABLISHED WITHIN EIGHT MINUTES
WHICH WERE EQUAL TO OR BETTER THAN THE DEGRADED SYSTEMS. NRC
RESIDENT INSPECTOR AND R3DO (BURDICK) INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 21734 SITE: ZION 1 2 EVENT DATE: 08-30-91 DOCKET: 05000295 05000304 VENDORS: W-4-LP W-4-LP EVENT TIME: 07:46 NOTIFY DATE: 08-30-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 09:43 OPS OFFICER: STEVE SANDIN 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING PROTECTED AREA FENCE ZONE. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: OMAHA PUBLIC POWER DISTRICT EN NUMBER: 21751 SITE: FT CALHOUN 1 DOCKET - 05000285 EVENT DATE: 09-01-91 EVENT TIME: 16:53 RX TYPE: PWR NOTIFY DATE: 09-01-91 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: NE TIME: 23:39 OPS OFFICER: TIM McGINTY UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING OF AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN UPON DISCOVERY. THE RESIDENT INSPECTOR HAS BEEN NOTIFIED. SEE HOO LOG FOR DETAILS.

21779 09-06-91 POW SAN ONOFRE 3

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 3 EN NUMBER: 21779 DOCKET: 05000362 EVENT DATE: 09-06-91 EVENT TIME: 00:00 RX TYPE: PWR NOTIFY DATE: 09-06-91 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 21:48

OPS OFFICER: THOMAS ANDREWS

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

Y 100 POWER OPERATION 100 POWER OPERATION

AT 1427 PDT, A FIRE PROTECTION DELUGE VALVE LOCATED IN THE REACTOR COOLANT PUMP "POO1" AREA LOCATED INSIDE CONTAINMENT ACTUATED. AS A RESULT, WATER WHICH WAS STANDING IN THE PIPE, DRAINED THROUGH THE VALVE INTO THE REACTOR COOLANT PUMP AREA. BASED UPON THE CONTAINMENT SUMP LEVEL INCREASE, THE LICENSEE ESTIMATES APPROXIMATELY 60 GALLONS OF WATER WAS IN THE PIPE. THE WATER WAS NOT PRESSURIZED OTHER THAN THAT CAUSED BY THE WEIGHT OF THE WATER ABOVE THE VALVE. THE FIRE PUMPS WERE NOT STARTED, SO A PRESSURIZED SPRAY DID NOT OCCUR.

THE LICENSEE DOES NOT BELIEVE THERE IS ANY DAMAGE TO THE REACTOR COOLANT PUMP MOTOR. NO PROBLEMS WERE NOTED AT THE TIME OF THE EVENT NOR HAVE ANY BEEN IDENTIFIED SINCE THE EVENT. THE LICENSEE IS STILL CHECKING OUT THE PUMP TO BE CERTAIN.

AT 1735 PDT, THE LICENSEE DETERMINED THAT THIS EVENT IS A RESULT OF POTENTIAL TAMPERING WITH THE DELUGE VALVE MANUAL ACTUATOR. THIS IS A "BREAK GLASS - PULL HANDLE" TYPE PULL STATION.

ALL PLANT SAFETY SYSTEMS ARE OPERABLE. THE ONLY OFF NORMAL CONDITION IS THE SECONDARY OFF SITE POWER SUPPLY IS OUT OF SERVICE UNTIL ABOUT 0600 PDT ON SEPTEMBER 7. THIS IS A PRE-PLANNED EVOLUTION. THE PRIMARY POWER SUPPLY IS AVAILABLE. BOTH EMERGENCY DIESEL GENERATORS ARE OPERABLE.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED OF THE DELUGE VALVE ACTUATION AND WILL BE INFORMED OF THIS NOTIFICATION.

**** UPDATE AT 2321 EDT ON 09/06/91 BY K. ECKMAN TAKEN BY T. ANDREWS ****

AT 1945 PDT, THE LICENSEE DETERMINED THAT THERE WERE TWO CLEANING PEOPLE IN THE AREA OF THE PULL STATION. THEY HAVE ADMITTED TO "WIPING" THE PULL STATION DOWN WITH DECON CLOTHS AND INADVERTENTLY TRIPPED THE PULL STATION. THEY THEN TRIED TO CLOSE THE PULL STATION. THE CLEANING PEOPLE THEN TRIED TO NOTIFY THEIR SUPERVISOR ABOUT THE INCIDENT. WHEN THIS WAS UNSUCCESSFUL, THEY FORGOT TO NOTIFY ANYONE ELSE.

SECURITY HAS PULLED THE PLANT ACCESS FOR THESE TWO INDIVIDUALS

PENDING FURTHER INVESTIGATION. THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. R5DO (HUEY), EO (ROSSI), IAT-NRR (BUSH), IAT-NMSS (DAVIDSON) NOTIFIED BY HOO.

**** UPDATE AT 1435 EDT ON 9/09/91 FROM B. PLAPPERT TAKEN BY HUFFMAN ****

BASED ON FURTHER INVESTIGATION, LICENSEE IS RETRACTING THIS EVENT. THE LICENSEE HAS DETERMINED THAT MANIPULATION OF THE DELUGE PULL STATION WAS PURELY ACCIDENTAL AND THAT NO INTENT TO TAMPER WAS INVOLVED. THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. R5DO(KIRSCH), IAT-NRR(BUSH), IAT-NMSS(DAVIDSON), AND EO(ROSSI) HAVE BEEN INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2 EN NUMBER:21806 DOCKET: 05000254 05000265 EVENT DATE: 09-11-91 RX TYPE: BWR BWR EVENT TIME: 05:15 NOTIFY DATE: 09-11-91 VENDORS: GE-3 GE-3 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 07:35 OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION N Y 90 POWER OPERATION 90 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING AREA BOUNDARY, IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY, SEE HOO LOG BOOK FOR DETAILS. THE RI WILL BE INFORMED.

LICENSEE: NEW YORK POWER AUTHORITY

SITE: FITZPATRICK 1 EN NUMBER: 21807 EVENT DATE: 09-11-91 DOCKET: 05000333 RX TYPE: BWR EVENT TIME: 08:20 VENDORS: GE-4 NOTIFY DATE: 09-11-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 09:14

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

LOST/UNACCOUNTED FOR SECURITY WEAPON. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE RI WILL BE INFORMED.

UPDATE AT 09:25 BY HORNING TO GOULD THE WEAPON WAS FOUND. THE RI WAS INFORMED.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1 EN NUMBER: 21819 DOCKET: 05000271 EVENT DATE: 09-12-91 RX TYPE: BWR

VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 1 STATE: VT

EMERGENCY CLASS: N/A REGION: 1 STATE: VT

TIME: 16:24

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SAFEGUARDS INFORMATION WHICH COULD HAVE SIGNIFICANTLY ASSISTED IN GAINING UNAUTHORIZED AND / OR UNDETECTED ACCESS WAS COMPROMISED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2

DOCKET: 05000334 05000412

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: PA

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO PERIMETER ALARM FOR PROTECTED AREA ACCESS. COMPENSATORY MEASURES HAVE BEEN TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

ZION 1 2

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2

DOCKET: 05000295 05000304

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DTHR 73.71(c)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 77 POWER OPERATION 77 POWER OPERATION
2 N Y 99 POWER OPERATION 99 POWER OPERATION

SECURITY AND BACKUP SECURITY COMPUTERS FAILED FOR UNKNOWN REASONS.

LICENSEE IMMEDIATELY POSTED SECURITY GUARDS AT VITAL AREA DOORS AND DISPATCHED ROVING PATROL GUARDS.

LICENSEE IS INVESTIGATING THE CAUSE OF THE FAILURES.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

*** UPDATE DATE :10/18/91 UPDATE TIME . 0936EDT ***FROM LICENSEE: MILNE BY SCARFO ***

THE LICENSEE INVESTIGATION DETERMINED THAT 1 OF 3 SECURITY COMPUTERS REMAINED FULLY FUNCTIONAL DURING THE FAILURE WHICH (ACCORDING TO GENERIC LETTER 9103) PROVIDES A BASIS FOR RETRACTING THIS EVENT. THE LICENSEE TOOK COMPENSATORY ACTION PRIOR TO SYSTEM REBOOT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R3DO (SCHUMACHER) HAS BEEN INFORMED.

LICENSEE: DUKE POWER CO.

SITE: MCGUIRE 1 2 EN NUMBER: 21923 DOCKET: 05000369 05000370 EVENT DATE: 09-30-91 EVENT TIME: 17:08 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 09-30-91 EMERCENCY CLASS: N/A REGION: 2 STATE: NC TIME: 17:56

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N 0 REFUELING 0 REFUELING

Y 100 POWER OPERATION 100 POWER OPERATION

INCOMPLETE SECURITY CHECK PERFORMED ON TEMPORARY EMPLOYEE.

A DUKE POWER TEMPORARY EMPLOYEE WAS ALLOWED PROTECTED AND VITAL AREA ACCESS WITHOUT A COMPLETE BACKGROUND INVESTIGATION. WHEN RESULTS OF THE BACKGROUND INVESTIGATION WERE FINALLY RECEIVED, IT WAS DETERMINED THAT THE INDIVIDUAL WAS UNRELIABLE AND HIS PLANT ACCESS WAS DENIED. THE INDIVIDUAL WAS ONSITE FOR A TOTAL OF THREE DAYS BEFORE HIS BADGE WAS PULLED. IT IS NOT KNOWN IF HE ENTERED ANY VITAL AREAS WHILE HE WAS ON PLANT.

REPORTABILITY OF THIS EVENT WAS NOT DETERMINED UNTIL 1708 EDT, 9/30/91. LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR.

SOUTH TEXAS 1 21984 10-10-91 POW

LICENSEE: HOUSTON LIGHTING & FOWER CO.

EN NUMBER:21984 SITE: SOUTH TEXAS 1 EVENT DATE: 10-10-91 DOCKET: 05000498 EVENT TIME: 21:22 RX TYPE: PWR NOTIFY DATE: 10-10-91 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 23:22

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR

THE SECURITY SYSTEM WAS LOST WHEN AUX BUS "1J" WAS LOST AND BACK UP POWER DIDN'T FICK UP THE LOADS. WHEN THE SECURITY SYSTEM IS LOST GUARDS MUST BE POSTED WITHIN 10 MINUTES. ONE GUARD POST WAS NOT POSTED FOR 25 MINUTES DUE TO HUMAN ERROR. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE ON 10/21/91 AT 1245 EDT FROM PINZON TAKEN BY KARSCH

THE LICENSEE IS RETRACTING THIS EVENT. FURTHER INVESTIGATION REVEALED THAT ONLY UNIT 2 SECURITY DEVICES WERE AFFECTED. THE UNMANNED POST WAS FOR UNIT 1 WHERE DEVICES REMAINED OPERATIONAL THROUGHOUT THE EVENT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ILLINOIS POWER CO.

EN NUMBER:21989 SITE: CLINTON 1 EVENT DATE: 10-11-91 DOCKET: 05000461 RX TYPE: BWR EVENT TIME: 15:10 NOTIFY DATE: 10-11-91 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 17:03

OPS OFFICER: RUDY KARSCH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

PART OF A MARIJUANA CIGARETTE WAS FOUND ON AN HVAC BRACKET INSIDE THE VITAL AREA. MAINTENANCE WAS GOING ON IN THE AREA AND PERSONNEL FOUND THE ITEM PARTIALLY COVERED BY DUST AND DEBRIS. IT APPEARED TO HAVE BEEN THERE FOR A LONG TIME. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY

EN NUMBER: 22020 SITE: WATTS BAR 1 EVENT DATE: 10-16-91 DOCKET: 05000390 RX TYPE: PWR EVENT TIME: 15:54 NOTIFY DATE: 10-16-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 16:18

OPS OFFICER: DICK JOLLIFFE

SHIPMENT LOST 10 CFR SECTION: DLOS 73.71(a)

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR

1 N N 0 UNDER CONSTRUCT 0 UNDER CONSTRUCT

- SPECIAL NUCLEAR MATERIAL (INCORE TIP DETECTORS) FOUND IN SITE WAREHOUSE -

A WESTINGHOUSE (NSSS SUPPLIER) REPRESENTATIVE NOTIFIED THE WATTS BAR SPECIAL NUCLEAR MATERIALS (SNM) CUSTODIAN, MR DELK, THAT 24 INCORE TIP DETECTORS (LESS THAN A TOTAL OF 1 GRAM OF HIGHLY

ENRICHED URANIUM) HAD BEEN RECEIVED AT WATTS BAR IN 1980.

AT 1554, THE SNM CUSTODIAN LOCATED 14 DETECTORS IN THE SITE WAREHOUSE BUT COULD NOT LOCATE THE OTHER 10 DETECTORS.

MR DELK IS REPORTING THE UNACCOUNTED FOR SNM IN ACCORDANCE WITH 10CFR73.67(g)(3)(iii).

AT 1640, THE SNM CUSTODIAN LOCATED THE OTHER 10 DETECTORS IN THE WAREHOUSE. THE DETECTORS ARE IN THEIR ORIGINAL UNDAMAGED SEALED SHIPPING CONTAINERS.

THE DETECTORS WILL BE MOVED AND PLACED UNDER THE CONTROL OF THE SNM CUSTODIAN IN ACCORDANCE WITH PLANT PROCEDURES.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

22034 10-17-91 POW VOGTLE 1 2

LICENSEE: GEORGIA POWER CO.

EN NUMBER: 22034 SITE: VOGTLE 1 2 DOCKET: 05000424 05000425 EVENT DATE: 10-17-91 EVENT TIME: 17:13 VENDORS: W-4-LP W-4-LP RX TYPE: PWR PWR NOTIFY DATE: 10-17-91 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 18:06

OPS OFFICER: CHAUNCEY GOULD

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N 0 REFUELING 0 REFUELING CODE CRIT PWR

100 POWER OPERATION 100 POWER OPERATION Y

ATTEMPTED INTRODUCTION OF CONTRABAND INTO THE PROTECTED AREA. COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WILL BE INFORMED.

* * * UPDATE ON 10/21/91 AT 1150EDT BY THOMAS HARGIS TO MATTINGLY * * *

EVENT RETRACTED. THE INVESTIGATION HAS DETERMINED THAT THERE WAS NO DELIBERATE ATTEMPT TO BRING CONTRABAND ONSITE. IN ACCORDANCE WITH NUREG 1304 THE EVENT IS RETRACTED AND WILL BE LOGGED. THE LICENSEE HAS DISCUSSED THIS EVENT WITH THE REGION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. THE HOO NOTIFIED RDO (AL BELISLE).

22054 10-20-91 POW DAVIS BESSE 1

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1 DOCKET: 05000346 RX TYPE: PWR

EVENT TIME: 11:39 VENDORS: B&W-R-LP NOTIFY DATE: 10-20-91

EN NUMBER: 22054 EVENT DATE: 10-20-91 EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 12:41

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION RELATED TO POWER SUPPLY FUNCTIONS. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WILL BE INFORMED.

UPDATE FROM LICENSEE:PITZEN TO NRC:HUFFMAN AT 0113 EDT ON 10/21/91

LICENSEE REPORTS THAT ALL SECURITY SYSTEMS WERE RETURNED TO SERVICE AND TESTED SATISFACTORILY BY 1902 EDT ON 10/20/91. THE RESIDENT INSPECTOR HAS BEEN INFORMED.

* * * UPDATE AT 1353 ON 11/14/91 BY NUTTER ENTERED BY HOO JOLLIFFE * * *

LICENSEE DESIRES TO RETRACT THIS EVENT SINCE COMPENSATORY MEASURES (SECURITY GUARDS POSTED AT VITAL AREA DOORS) WERE ALREADY IN PLACE PRIOR TO THE TRANSFORMER BEING TAKEN OUT OF SERVICE.

(SEE HOO LOG FOR ADDITIONAL DETAILS).

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R3DO DEFAYETTE.

Y

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3

DOCKET: 05000206 05000361 05000362

RX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71

NONR

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

EVENT DATE: 10-25-91

EVENT TIME: 10:35

NOTIFY DATE: 10-25-91

EVENT TIME: 10:35

NOTIFY DATE: 10-25-91

EVENT TIME: 10:35

NOTIFY DATE: 0-25-91

EVENT TIME: 10:35

NOTIFY DATE: 0-25-91

EVENT TIME: 10-25-91

EVENT TIME: 10:35

NOTIFY DATE: 0-25-91

EVENT TIME: 0-25-91

EVEN

RECEIVED UNSUBSTANTIATED BOMB THREAT CALL FROM OFFSITE. LICENSEE IS TAKING COMPENSATORY ACTIONS. NRC RESIDENT INSPECTOR WILL BE NOTIFIED. SEE HOO LOG FOR MORE DETAILS.

N Y 92 POWER OPERATION 92 POWER OPERATION N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

100 POWER OPERATION 100 POWER OPERATION

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3 DOCKET: 05000286 EN NUMBER: 221 EVENT DATE: 10-30-91 RX TYPE: PWR EVENT TIME: 09:15 VENDORS: W-4-LP NOTIFY DATE: 10-30-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 10:34

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N 0 HOT STANDBY 0 HOT STANDBY

AN AUDIT OF THE PREVIOUS DAY'S SECURITY ALARMS REVEALED THAT AN ALARM FOR A VITAL AREA DOOR WAS NOT RESPONDED TO DUE TO HUMAN ERROR. THIS COULD BE CONSTRUED AS AN UNCOMPENSATED FAILURE IN A SAFEGUARDS SYSTEM. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1 EN NUMBER: 22115 EVENT DATE: 10-30-91 DOCKET: 05000309 EVENT TIME: 12:52 RX TYPE: PWR NOTIFY DATE: 10-30-91 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 13:53

OPS OFFICER: WILLIAM MATTINGLY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N

1 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY DEGRADATION RELATED TO AUTHORIZING SECURITY CLEARANCES.

DURING A SECURITY REVIEW TO BADGE A CONTRACTED MAINTENANCE WORKER FOR THE 1992 REFUELING OUTAGE, IT WAS DISCOVERED THAT THE WORKER HAD A POSITIVE DRUG TEST WHILE WORKING AT PILGRIM IN 1987. SUBSEQUENT TO THE POSITIVE DRUG TEST, THE CONTRACTOR WAS EMPLOYED AT MAINE YANKEE FOR THE 1990 OUTAGE. MAINE YANKEE'S POLICY IS THAT THEY WILL NOT HIRE PEOPLE THAT HAVE TESTED POSITIVE FOR LRUGS. THE WORKER'S BADGE WAS REMOVED AND HE WAS TAKEN OFF SITE. THE LICENSEE PLANS TO INVESTIGATE THIS EVENT TO FIND OUT WHY A SECURITY CLEARANCE WAS GRANTED FOR THIS CONTRACTOR DURING THE 1990 OUTAGE AND WHETHER OR NOT OTHERS WERE GRANTED SECURITY CLEARANCE WITH SIMILAR BACKGROUNDS.

THE LICENSEE WILL INFORM THE STATE AND THE NRC RESIDEN1 INSPECTOR.

22116 10-30-91 POW FERMI 2

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 22116 DOCKET: 05000341 EVENT DATE: 10-30-91 EVENT TIME: 14:05 RX TYPE: BWR VENDORS: GE-4 NOTIFY DATE: 10-30-91 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 15:00

OPS OFFICER: JOHN MacKINNON

UNIT SCRAM

10 CFR SECTION: APRE 50.72(b)(2)(vi) OFFSITE NOTIFICATION DDDD 73.71 UNSPECIFIED PARAGRAPH RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

BETWEEN 0855 EST & 1255 EST THREATS DIRECTED TO THE FERM! SITE WERE RECEIVED BY MONROE DEPARTMENT OF MENTAL HEALTH & MERCY MEMORIAL HOSPITAL IN MONROE COUNTY.

AT 0855 EST MONROE DEPARTMENT OF MENTAL HEALTH RECEIVED ONE PHONE CALL AND TWO MORE THREAT PHONE CALLS WERE MADE TO MERCY MEMORIAL HOSPITAL. LICENSEE SAID THAT THESE THREATS ARE UNSUBSTANTIATED. THE CALLER SAID THAT THE PLANT WOULD BE DESTROYED, HAVE A MELT DOWN, & CERTAIN PEOPLE WOULD BE KILLED (THIS STATEMENT WAS DIRECTED TOWARDS THE PERSON HE WAS TALKING TO AND NOT AGAINST FERMI PLANT EMPLOYEES). LICENSEE SAID THAT THE PERSON MAKING THE PHONE CALLS IS MALE AND IN HIS FORTIES. AFTER LICENSEE LEARNED ABOUT THE FIRST THREAT CALL SECURITY MEASURES AROUND THE PLANT WERE INCREASED. AT 1450 EST AFTER LEARNING ABOUT THE OTHER TWO PHONE CALLS SECURITY STARTED SEARCHING PROTECTED AND VITAL AREAS. SEARCH IS STILL IN PROGRESS.

LICENSEE NOTIFIED LOCAL LAW INFORCEMENT AGENCIES AND INFORMED THE

RESIDENT INSPECTOR NOTIFIED BY THE LICENSEE.

UPDATE BY PAUL KIEL @ 1717 EST TAKEN BY MACKINNON ALL VITAL AREAS HAVE BEEN SEARCHED BY 1656 EST. NO INDICATION OF TAMPERING, NO SUSPICIOUS OBJECTS OR CONDITIONS FOUND. SECURITY WILL MAINTAIN HEIGHTENED POSTURE THROUGHOUT THE NIGHT. LICENSEE DID NOT CONSIDER THIS AS A CREDIBLE EVENT. R3DO (CANIANO) NOTIFIED. RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

JPDATE ON 11/13/91 AT 1707EST BY BOB GAILLEZ TO MATTINGLY * * * EVENT RETRACTED. THE COUNTY SHERIFF VERIFIED THAT THE SUSPECT COULD NOT HAVE MADE THE CALLS AND THAT THE THREAT WAS NOT CREDIBLE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. THE HOO NOTIFIED R3DO (DEFAYETTE) .

LICENSEE: NUCLEAR FUEL SERVICES INC.

EN NUMBER: 22192 SITE: NUCLEAR FUEL SERVICES INC. EVENT DATE: 11-07-91 DOCKET: 07000143 EVENT TIME: 15:43 RX TYPE: NOTIFY DATE: 11-07-91 VENDORS:

EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 18:45

OPS OFFICER: STEVE SANDIN

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71

UNAUTHORIZED ENTRY INTO PROTECTED AREA. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1 2

DOCKET: 05000424 05000425

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: GA

EN NUMBER: 22290

EVENT DATE: 11-21-91

RX TYPE: PWR PWR

EVENT TIME: 10:00

NOTIFY DATE: 11-21-91

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

CODE CRIT PWR

CODE CRIT PWR

1 N Y 8 POWER OPERATION 8 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING PERIMETER. NOT IMMEDIATELY COMPENSATED ON DISCOVERY BUT COMPENSATED NOW. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: BERTHOLD SYSTEMS

SITE: BERTHOLD SYSTEMS

DOCKET:
RX TYPE:
VENDORS:
EMERGENCY CLASS: N/A REGION: 1 STATE: PA

EN NUMBER: 22302
EVENT DATE: 11-22-91
EVENT TIME: 17:56

NOTIFY DATE: 11-22-91

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH DLOS 73.71(a) SHIPMENT LOST

TOM KUNY OF BERTHOLD SYSTEMS, CALLED TO REPORT THAT A SHIPMENT OF COBALT 60 ROD SOURCES DID NOT ARRIVE WHEN EXPECTED. HIS COMPANY ADDRESS IS:

BERTHOLD SYSTEMS, INC. 101 CORPORATION DRIVE ALIOUIPPA, PA 15001

THE ROD SOURCES ARE ABOUT FIVE YEARS OLD AND WERE ORIGINALLY RATED AT 2 MILLICURIES (SHIPMENT TOTAL). THE SOURCES ARE COBALTOUS CHLORIDE SOLID MATERIAL. THEY WERE PACKAGED IN TWO TYPE "A" SHIPPING CONTAINERS AND WERE SHIPPED FROM OLIN CHEMICAL CORPORATION IN LAKE CHARLES, LOUISIANA ON 11/14/91. THE SOURCES WERE BEING SHIPPED TO BERTHOLD SYSTEMS FOR DISPOSAL.

THE SHIPPER IS YELLOW FREIGHT. ACCORDING TO MR. KUNY, OLIN HAS PRIMARY RESPONSIBILITY FOR THE SHIPMENT.

BERTHOLD SYSTEMS RECEIVED DOCUMENTATION FOR THIS SHIPMENT WITH ANOTHER SHIPMENT FROM OLIN. THESE SOURCES WERE EXPECTED TO ARRIVE SOMETIME BETWEEN 11/18/91 AND 11/22/91. SINCE THESE SOURCES HAVE NOT ARRIVED, BERTHOLD SYSTEMS HAS NOTIFIED YELLOW FREIGHT AND THE SOURCES ARE BELIEVED TO STILL BE IN THE YELLOW FREIGHT SHIPPING SYSTEM.

SINCE THE SOURCES ARE IN TYPE "A" SHIPPING CONTAINER, THE POTENTIAL EXPOSURE HAZARD TO THE PUBLIC IS BELIEVED TO BE MINIMAL. BERTHOLD SYSTEMS' LICENSE NUMBER IS 37-21-226-01. MR. KUNY WAS ASKED TO NOTIFY REGION 1 ON 11/25/91 AND THE NRC OPERATIONS CENTER IF THE SHIPMENT IS LOCATED.

LICENSEE: ILLINOIS POWER CO.

EN NUMBER: 22341 SITE: CLINTON 1 EVENT DATE: 11-28-91 DOCKET: 05000461 EVENT TIME: 01:24 RX TYPE: BWR VENDORS: GE-6 NOTIFY DATE: 11-28-91

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 02:50

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

CODE CRIT PWR
N Y 29 POWER OPERATION 29 POWER OPERATION

VITAL AREA DOORS KEYS LOST.

A KEY RING CARRIED BY A CONTROL ROOM OPERATOR WAS REPORTED TO PLANT SECURITY AS LOST SOMEWHERE IN THE PROTECTED AREA AT 0124 CST. BECAUSE THE RING CONTAINED A KEY TO VITAL AREA DOORS, A SECURITY ALERT WAS IMMEDIATELY DECLARED. ALL VITAL AREA DOORS AND BARRIERS WELF CHECKED AND A THOROUGH SEARCH FOR THE KEY RING WAS CONDUCTED.

LICENSEE STATES THAT IF THE LOST RING IS NOT LOCATED BY FRIDAY, 11/29/91, ALL VITAL AREA DOOR AND BARRIER LOCKS WILL BE CHANGED-OUT.

THE RESIDENT INSPECTOR HAS BEEN NOTIFIED.

UPDATE FROM LICENSEE: LOWERS TO NRC: HUFFMAN AT 0336 EST, 11/28/91

KEY RING WAS FOUND AT 0210 CST WITH ALL KEYS INTACT ON THE RING. SECURITY ALERT WAS TERMINATED. RESIDENT INSPECTOR WILL BE NOTIFIED.

ARKANSAS NUCLEAR 1 2 22419 12-09-91 POW

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 2 EN NUMBER: 22419 DOCKET: 05000313 05000368 EVENT DATE: 12-09-91 VENDORS: B&W-L-LP CE EVENT TIME: 18:50 NOTIFY DATE: 12-09-91

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 20:44

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DUNE 73.71(b)(1) UNAUTHORIZED ENTRY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION N

N Y 100 POWER OPERATION 100 POWER OPERATION

UPON PLACING A VISITOR'S BADGE IN THE BADGE RACK IT WAS NOTED THAT THERE WAS NO ENTRY ON THE VISITOR'S LOG TO SHOW WHO THE BADGE WAS ISSUED TO OR WHO AUTHORIZED THE VISIT. A COMPUTER PRINT OUT REVEALED NO VITAL AREA ACCESS WITH THIS LADGE. THE LICENSEE IS CONTINUING TO INVESTIGATE. THE LICENSEE INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 2139 EST FROM HUTCHENS TAKEN BY KARSCH * * *

RETRACTION: ADMINISTRATIVE ERROR IN THE LOG-IN. SECURITY PERSONNEL WERE ABLE TO VERIFY WHO THE VISITOR WAS. R4DO (HOWELL) NOTIFIED.

DUANE ARNOLD 1 22448 12-13-91 POW

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 22448 DOCKET: 05000331 EVENT DATE: 12-13-91 RX TYPE: BUR EVENT TIME: 11:42

NOTIFY DATE: 12-13-91 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 13:24

OPS OFFICER: CHAUNCEY GOULD

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 000

Y 98 POWER OPERATION 98 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. RI WAS INFORMED. SEE HOO LOG FOR DETAILS.

* * * UPDATE 1727EST 12/18/91 FROM ST. JOHN BY S.SANDIN * * * AFTER FURTHER REVIEW OF THE SECURITY PLAN AND DISCUSSIONS WITH R3 (MEADEA), LICENSEE HAS DETERMINED THAT THIS EVENT IS LOGABLE AND NOT REPORTABLE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. NOTIFIED R3DO (PHILLIPS).

22489 12-18-91 POW PEACH BOTTOM 2 3 LICENSEE: PHILADELPHIA ELECTRIC CO.

SITE: PEACH BOTTOM 2 3 EN NUMBER: 22489 EVENT DATE: 12-18-91

DOCKET: 05000277 05000278
RX TYPE: BWR BWR
VENDORS: GE-4 GE-4 EVENT TIME: 19:10 NOTIFY DATE: 12-18-91

EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 20:44

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N Y 15 POWER OPERATION 15 POWER OPERATION 3 N N 0 REFUELING 0 REFUELING

ATTEMPTED INTRODUCTION OF FIREARM ON SITE BY CONTRACT EMPLOYEE. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED STATE POLICE AND WILL INFORM BOTH STATE/LOCAL AGENCIES AND THE NRC RESIDENT INSPECTOR.

* * * UPDATE ON 12/20/91 AT 1115 EST FROM FOSS TAKEN BY KARSCH *

THE LI ENSEE IS RETRACTING THIS EVENT BASED ON GUIDANCE IN GL 91-03. THF GUIDANCE STATES THAT THE INTRODUCTION OF CONTRABAND INTO THE PROTECTED AREA THAT DOES NOT POSE A THREAT TO PLANT SECURITY IS NOT REPORTABLE. THE LICENSEE CONSIDERS THAT SINCE THE WEAPON WAS BROUGHT ONTO THE SITE INADVERTENTLY AND WITHOUT MALICIOUS INTENT NO THREAT TO SECURITY EXISTED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. RIDO (JOHANSEN) NOTIFIED.

22520 12-24-91 POW COOK 1

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

EN NUMBER: 22520 SITE: COOK 1 DOCKET: 05000315 EVENT DATE: 12-24-91 EVENT TIME: 09:05 RX TYPE: PWR NOTIFY DATE: 12-24-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:07

OPS OFFICER: DICK JOLLIFFE

SECURITY DEGRADATION 10 CFR SECTION: DTHR 73.71(c) UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE DISCOVERED A SECURITY RELATED PIECE OF ELECTRICAL EQUIPMENT INSTALLED OUTSIDE A SEISMIC SECURITY FENCE. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE ON 12/31/91 AT 1710EST BY RON SIEBER TO MATTINGLY *

EVENT RETRACTED. SEE HOO LOG FOR DETAILS. HOO NOTIFIED R3DO (HASSE).

LICENSEE: HOUSTON LIGHTING & POWER CO.

EN NUMBER: 22537 SITE: SOUTH TEXAS 1 DOCKET: 05000498 EVENT DATE: 12-29-91 RX TYPE: PWR EVENT TIME: 07:50 NOTIFY DATE: 12-29-91 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 09:37

OPS OFFICER: RUDY KARSCH

SECURITY DEGRADATION 10 CFR SECTION: DTHR 73.71(c) UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

THE FRONT DOORS OF THE ESSENTIAL COOLING WATER STRUCTURE WERE NOT PROPERLY SECURED AGAINST UNAUTHORIZED ENTRY FOR APPROXIMATELY 10

HOURS DUE TO HUMAN ERROR.

THE FAILURE OF A MULTIPLEXER FOR THE INTRUSION DETECTION SYSTEM (IDS) NECESSITATED MANUAL COMPENSATORY MEASURES. THE NEED FOR THESE MEASURES WAS NOT ADEQUATELY COMMUNICATED TO THE GUARD PERSONNEL. CONSEQUENTLY THE FRONT DOORS OF THE ESSENTIAL COOLING WATER STRUCTURE WERE NOT PROPERLY ATTENDED. A RECHECK BY A SUPERVISOR 10 HOURS LATER REVEALED THE LAPSE. THE LICENSEE BELIEVES THERE WAS NO UNAUTHORIZED ENTRY INTO THE AREA, BECAUSE OTHER PERIMETER SECURITY DEVICES, WHICH REMAINED OPERABLE, DID NOT ALARM. A SEARCH OF THE PROTECTED AREA IS UNDER WAY. THE IDS WILL BE RESTORED BY 12/30/91. SEE HOO LOG FOR ADDITIONAL DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

SOUTH TEXAS 1 22542 12-31-91 POW

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 EN NUMBER: 22542

DOCKET: 05000498 EVENT DATE: 12-31-91

RX TYPE: PWR EVENT TIME: 13:45

VENDORS: W-4-LP NOTIFY DATE: 12-31-91

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 15:27
OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY OFFICER FALSIFIED A SECURITY PATROL LOG ENTRY.

A SECURITY OFFICER FALSELY DOCUMENTED THE SATISFACTORY COMPLETION OF A PATROL IN A DESIGNATED AREA WITHIN THE PROTECTED AREA. AN INVESTIGATION DETERMINED THAT NO UNAUTHORIZED ACCESS OCCURRED IN THE AREA. SEE HOO LOG FOR DETAILS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 12/31/91 AT 1606EST BY CHARLIE AYALA TO MATTINGLY *

EVENT RETRACTED. THE EVENT IS A LOGGABLE SECURITY EVENT NOT A ONE HOUR REPORTABLE EVENT. THIS INFORMATION WAS KNOWN AT THE TIME OF THE INITIAL REPORT, HOWEVER, THE INFORMATION WAS IMPROPERLY CONVEYED TO THE CONTROL ROOM WHERE THE ENS REPORT WAS INITIATED. THE HOO NOTIFIED R4DO (HARRELL).

Query: 1992 EVENT REPORTS: 73.71

LICENSEE: CONSUMERS POWER CO. EN NUMBER: 22636 SITE: PALISADES 1 EVENT DATE: 01-20-92 DOCKET: 05000255 EVENT TIME: 14:27 NOTIFY DATE: 01-20-92 RX TYPE: PWR VENDORS: CE EMERGENCY CLASS: UNU REGION: 3 STATE: MI TIME: 14:33 OPS OFFICER: JOHN MacKINNON 10 CFR SECTION: AAEC 50.72(a)(1)(i) EMERGENCY DECLARED UNSPECIFIED PARAGRA UNSPECIFIED PARAGRAPH CURR CURRENT MODE RX INIT INITIAL MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION UNIT SCRAM 1 N

A TOY EXPLOSIVE DEVICE WHICH HAD BEEN FORGOTTEN TO BE RETRIEVED AFTER A SECURITY DRILL CONDUCTED A FEW DAYS AGO WAS DISCOVERED BY AN INPO INSPECTOR WHILE PERFORMING CLEANLINESS INSPECTION. HE REPORTED DEVICE TO CONTROL ROOM. CONTROL ROOM IMPLEMENTED THEIR SAFEGUARDS CONTINGENCY PROCEDURES. UPON ON DISCOVERING THAT THIS WAS A TOY EXPLOSIVE DEVICE USED IN THEIR SECURITY DRILL CONDUCTED A COUPLE OF DAYS AGO THEY EXITED THE UNUSUAL EVENT AT 1427 EDT. LICENSEE HAD NOTIFIED STATE & LOCAL OFFICIALS OF THIS EVENT.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

EN NUMBER: 22656 SITE: VERMONT YANKEE 1 EVENT DATE: 01-22-92 DOCKET: 05000271 EVENT TIME: 14:30 RX TYPE: BWR NOTIFY DATE: 01-22-92 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 15:34

OPS OFFICER: THOMAS ANDREWS UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE PWR CODE CRIT PWR

Y 97 POWER OPERATION 97 POWER OPERATION

DISCOVERED SECURITY VULNERABILITY WHICH WAS NOT COMPENSATED FOR WITHIN 10 MINUTES. THE VULNERABILITY WAS COMPENSATED FOR AT 1430 EST ON 01/22/92. SEE HOO LOG FOR DETAILS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 22666 SITE: WATERFORD 3 EVENT DATE: 01-23-92 DOCKET: 05000382 EVENT TIME: 18:30 NOTIFY DATE: 01-23-92 RX TYPE: PWR VENDORS: CE

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 20:17

OPS OFFICER: GREG SCARFO UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71

UNIT SCRIM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
3 N Y 100 POWER OPERATION 100 POWER OPERATION

A PLANT CONTROLLED-AREA PATROL FOUND A SAFEGUARDS SAFE UNLOCKED AND UNATTENDED. THE SAFE WAS IMMEDIATELY SECURED AND LOCKED UPON DISCOVERY. THE LICENSEE IS INVESTIGATING THE CONTENTS FOR LOSS OR THEFT OF MATERIALS. THE LENGTH OF TIME THE SAFE WAS UNLOCKED IS UNDETERMINED AT THIS TIME.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

HUMBOLDT BAY 3 22683 01-25-92 POW

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: HUMBOLDT BAY 3

DOCKET: 05000133

RX TYPE: BWR

VENDORS: GE-1

EN NUMBER: 22683

EVENT DATE: 01-25-92

EVENT TIME: 09:17

NOTIFY DATE: 01-25-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 12:51

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N N DECOMMISSIONED O DECOMMISSIONED

SAFEGUARDS SYSTEM DEGRADATION RELATED TO
DETECTION/ALARM/MONITORING/AREA
DOORS/AREA BOUNDARY. NOT IMMEDIATELY COMPENSATED ON DISCOVERY
BUT COMPENSATED NOW. NO RI AT SITE TO NOTIFY. SEE HOO LOG FOR
DETAILS.

* * *RETRACTION AT 1410 1/30/92 FROM MCKENNA TO MILLER * * * BASED UPON DISCUSSIONS WITH REGION 5 (SCHUSTER) CONCERNING THE DETAILS OF THE EVENT, THIS NOTIFICATION IS BEING RETRACTED. IT WAS SUBSEQUENTLY DETERMINED THAT COMPENSATORY MEASURES TAKEN AT 0855 WERE ADEQUATE. REFERENCING GENERIC LETTER 91-03, NO MALEVOLENT INTENT WAS INVOLVED AND NO ADVERSE CONSEQUENCES RESULTED, PROMPTING THE LICENSEE TO DEEM THE EVENT LOGGABLE.

NO RESIDENT INSPECTOR TO NOTIFY ON SITE.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1

DOCKET: 05000424

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: GA

EN NUMBER: 22687

EVENT DATE: 01-25-92

EVENT TIME: 16:55

NOTIFY DATE: 01-25-92

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING/ALARM/AREA DOORS/AREA BOUNDARY/POWER SUPPLY FUNCTIONS. NOT IMMEDIATELY COMPENSATED ON DISCOVERY BUT COMPENSATED NOW. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

EN NUMBER: 22750 SITE: DUANE ARNOLD 1 EVENT DATE: 02-06-92 DOCKET: 05000331 EVENT TIME: 04:25 RX TYPE: BWR NOTIFY DATE: 02-06-92 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 06:09

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR
N Y 80 POWER OPERATION 80 POWER OPERATION

DISCOVERY OF COMPROMISE OF SAFEGUARDS INFORMATION. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR FURTHER DETAILS. THE RI WILL BE INFORMED.

**** UPDATE AT 1003 EST ON 3/5/92 FROM RICKELS/HENRY TAKEN BY KARSCH ****

LICENSEE IS RETRACTING THIS EVENT. THE COMPROMISED INFORMATION WAS REVIEWED AND WOULD NOT SIGNIFICANTLY ASSIST SOMEONE IN GAINING ACCESS TO THE FACILITY, SABOTAGE, OR THEFT OF SPECIAL NUCLEAR MATERIAL. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R3DO (SNELL) NOTIFIED.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 EN NUMBER: 22796 DOCKET: 05000275 05000323 EVENT DATE: 02-12-92 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 15:59 NOTIFY DATE: 02-12-92 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 20:52

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

1

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION/MONITORING/ALARM/AREA DOORS/AREA BOUNDARY/COMPUTER. NOT IMMEDIATELY COMPENSATED ON DISCOVERY BUT COMPENSATED NOW. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

MAINE YANKEE 1 22825 02-17-92 POW LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1 DOCKET: 05000309 RX TYPE: PWR EN NUMBER: 22825 EVENT DATE: 02-17-92 EVENT TIME: 13:10 NOTIFY DATE: 02-17-92 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 14:01

OPS OFFICER: STEVE SANDIN

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE

CURR CURRENT MODE

CODE CRIT PWR PWR

N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

LICENSEE DISCOVERED COMPROMISE OF SAFEGUARDS INFORMATION. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AND WILL INFORM THE STATE NUCLEAR INSPECTOR.

**** RETRACTION @1530 EST ON 02/20/92 BY P. EBERT, TAKEN BY T. ANDREWS ****

AFTER FURTHER REVIEW OF THIS EVENT BY THE MAINE YANKEE LICENSING DEPARTMENT, THE LICENSEE HAS DETERMINED THAT THIS EVENT IS NOT REPORTABLE SINCE THE INFORMATION IN QUESTION HAS BEEN DETERMINED NOT TO BE SAFEGUARDS INFORMATION.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFED OF THE RETRACTION.

HOO NOTIFIED RIDO (EAPEN).

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 22828 SITE: ROBINSON 2 EVENT DATE: 02-17-92 DOCKET: 05000261 VENDORS: W-3-LP EVENT TIME: 15:00 NOTIFY DATE: 02-17-92

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 15:55

OPS OFFICER: STEVE SANDIN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
2 N

2 N Y 100 POWER OPERATION 100 POWER OPERATION

UNACCOUNTED FOR SECURITY KEY TO ALL VITAL AREA ACCESS DOORS. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

22863 02-23-92 POW FERMI 2

LICENSEE: DETROIT EDISON CO.

DOCKET: 05000341 RX TYPE: BWR EN NUMBER: 22863 SITE: FERMI 2 EVENT DATE: 02-23-92 EVENT TIME: 10:56 NOTIFY DATE: 02-23-92

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 11:47

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING PROTECTED AREAS BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

* * * UPDATE AT 1130EST ON 3/6/91 FROM KIEL TAKEN BY KARSCH * * * THE LICENSEE IS RETRACTING THIS EVENT. REVIEW DETERMINED THAT IT IS A LOGGABLE EVENT NOT A REPORTABLE EVENT PER THE GUIDANCE OF GENERIC LETTER 91-03. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R3DO (SNELL) NOTIFIED.

22926 02-28-92 POW POINT BEACH 1 2 LICENSEE: WISCONSIN ELECTRIC POWER CO. EN NUMBER: 22926 SITE: POINT BEACH 1 2 EVENT DATE: 02-28-92 DOCKET: 05000266 05000301 VENDORS: W-2-LP W-2-LP EVENT TIME: 16:43 NOTIFY DATE: 03-02-92 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 22:10 OPS OFFICER: WILLIAM HUFFMAN UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE Y 100 POWER OPERATION 100 POWER OPERATION
Y 100 POWER OPERATION 100 CODE CRIT PWR N 2 N

VITAL AREA DOOR SECURITY DEGRADATION.

LOCKING DEVICE ON VITAL AREA DOOR FAILED. INITIAL COMPENSATION ADEQUATE BUT SUBSEQUENT MEASURES INADEQUATE. SEE HOO LOG FOR DETAILS.

LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1719 EST ON 3/3/92 FROM: McCULLUM TO: HUFFMAN * *

UPON FURTHER REVIEW OF THIS EVENT, THE LICENSEE HAS DETERMINED THAT IT IS NOT REPORTABLE PER CRITERIA IN GENERIC LETTER 91-03. THE LICENSEE IS THEREFORE RETRACTING THIS EVENT. THE NRC RESIDENT INSPECTOR AND R3DO(SNELL) HAVE BEEN INFORMED.

LICENSEE: WOLF CREEK NUCLEAR OPER. CORP.

SITE: WOLF CREEK 1 EN NUMBER:22944

DOCKET: 05000482 EVENT DATE: 03-05-92

RX TYPE: PWR EVENT TIME: 06:49

VENDORS: W-4-LP NOTIFY DATE: 03-05-92

EMERGENCY CLASS: N/A REGION: 4 STATE: KS TIME: 08:44

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAMUNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE UNSPECIFIED PARAGRAPH PWR CODE CRIT PWR N N O COLD SHUTDOWN 0 COLD SHUTDOWN

LICENSEE DISCOVERED POTENTIAL COMPROMISE OF SAFEGUARDS INFORMATION. SEE HOO LOG FOR DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

23009 03-13-92 POW CLINTON 1

LICENSEE: ILLINOIS POWER CO.

EN NUMBER: 23009 SITE: CLINTON 1 EVENT DATE: 03-13-92 DOCKET: 05000461 EVENT TIME: 17:40 RX TYPE: BWR VENDORS: GE-6 NOTIFY DATE: 03-13-92 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 19:22

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCHAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR CODE CRIT PWR CODE CRIT PWR PWR N 0 REFUELING 0 REFUELING

A SET OF SECURITY KEYS COULD NOT BE ACCOUNTED FOR. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * UPDATE @ 1451 ON 02/16/92 BY DENNIS SMITH ENTERED BY HOO JOLLIFFE * *

LICENSEE DESIRES TO RETRACT THIS EVENT AS A REPORTABLE EVENT AND DOWNGRADE THIS EVENT TO A LOGGABLE EVENT. SEE HOO LOG FOR DETAILS. LICENSEE NOTIFIED THE RESIDENT INSPECTOR. HOO NOTIFIED R3DO RING.

LICENSEE: TOLEDO EDISON CO.

EN NUMBER: 23106 SITE: DAVIS BESSE 1 DOCKET: 05000346 EVENT DATE: 03-26-92 EVENT TIME: 17:02 RX TYPE: PWR NOTIFY DATE: 03-26-92 VENDORS: B&W-R-LP EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 18:03

OPS OFFICER: THOMAS ANDREWS

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 INFORMATION ONLY NINF

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

A BOMB THREAT DIRECTED AGAINST DAVIS BESSE WAS LEFT ON AN EMPLOYEE'S PERSONAL ANSWERING MACHINE AT HIS HOME. THE MESSAGE WAS DISCOVERED AT 1655 EST. THERE IS NO INDICATION AS TO WHEN THE MESSAGE WAS LEFT OR IF THERE IS A DEADLINE INVOLVED. THE EMPLOYEE NOTIFIED DAVIS BESSE SECURITY AT 1702 EST.

THE LICENSEE HAS NOT DETERMINED IF THIS IS A CREDIBLE EVENT AT THIS TIME. COMPENSATORY ACTIONS ARE BEING TAKEN. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

* * * UPDATE @ 2114 BY TULLELLE ENTERED BY ANDREWS * * *

LICENSEE HAS DETERMINED THAT THE BOMB THREAT IS NOT CREDIBLE. SEE HOO LOG FOR DETAILS. HOO NOTIFIED R3DO JACOBSON.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2

DOCKET: 05000254 05000265

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

EN NUMBER: 23151

EVENT DATE: 04-02-92

NOTIFY DATE: 04-02-92

TIME: 03:58

OPS OFFICER: GREG SCARFO

10 CFR SECTION: AESF 50.72(b)(2)(ii) ESF ACTUATION
DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

SHUTDOWN COOLING WAS LOST FOR TWO HOURS AND TWENTY MINUTES WHEN A RESERVE AUXILIARY TRANSFORMER TRIPPED AND DE-ENERGIZED SEVERAL SAFETY BUSES (LOSS OF OFFSITE POWER).

AT 0037CST, RESERVE AUXILIARY TRANSFORMER "22" TRIPPED WHEN THE FIRE PROTECTION DELUGE SYSTEM ACTUATED FOR UNKNOWN REASONS. SAFETY BUSES WHICH DE-ENERGIZED INCLUDED BUSES "23", "23-1", "24", "24-1", AND "29" AS WELL AS BUSES "25", "26", "27", "28". THE RADIATION MONITORING SYSTEM AND RHR LOOP "A" LOST POWER AND EMERGENCY DIESEL GENERATOR (EDG) "1/2" AUTOSTARTED AS A RESULT OF THE TRIP. THE REACTOR BUILDING VENTILATION SYSTEM ISOLATED, THE CONTROL ROOM VENTILATION SYSTEM ISOLATED, AND THE STANDBY GAS TREATMENT SYSTEM ACTUATED ON THE LOSS OF POWER TO THE RADIATION MONITORING SYSTEM. THE RHR "A" TRAIN WAS IN SHUTDOWN COOLING MODE AT THE TIME OF THE TRANSFORMER TRIP WITH RCS TEMPERATURE AT 132 DEGREES F AS MEASURED AT THE RHR HEAT EXCHANGER DISCHARGE.

AT 0138CST, ALL AFFECTED BUSES WERE RE-ENERGIZED VIA EDG "1/2" AND A CROSS TIE CONNECTION FROM UNIT #1 BUS "14-1" TO "UNIT #2 BUS "24-1". EDG "2" DID NOT AUTOSTART BECAUSE THAT CAPABILITY WAS DISABLED WHILE A MODIFICATION WAS BEING IMPLEMENTED.

SHUTDOWN COOLING WAS RESTORED AT 0256CST WITH RCS TEMPERATURE AT

139 DEGREES F. SHUTDOWN COOLING WAS LOST FOR TWO HOURS AND NINETEEN MINUTES WITH A HEATUP OF ABOUT SEVEN DEGREES. THE UNIT HAD BEEN DOWN FOR 93 DAYS PRIOR TO THIS EVENT. EDG "1/2" AUTOSTARTED AS REQUIRED BUT RHR "A" WAS NOT LOADED ONTO THE RE-ENERGIZED "23-1" BUS DUE TO CONCERNS ABOUT OVERLOADING THE EDG.

THE LOSS OF THE RAT ALSO RESULTED IN A SECURITY DEGRADATION RELATED TO ALARM/AREA DOORS/AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY BUT NOT FULLY COMPENSATED. SEE HOO LOG FOR DETAILS.

CURRENTLY, POWER IS BEING SUPPLIED TO SAFETY BUSES "23" AND "23-1" BY EDG "1/2". A CROSSTIE FROM UNIT #1 BUS "14-1" TO BUS "24-1" IS SUPPLYING POWER TO SAFETY BUSES "24" AND "24-1". BUS "26" IS THE ONLY BUS WHICH REMAINS DE-ENERGIZED. A BACKUP OFFSITE POWER SUPPLY IS AVAILABLE TO UNIT #2 THROUGH A RAT ON UNIT #1. THERE IS NO BACK FEED CAPABILITY THROUGH UNIT AUXILIARY TRANSFORMER "21" AND NO INDEPENDENT BACKUP OFFSITE POWER SUPPLY TO UNIT #2. RHR "B" IS AVAILABLE FROM SAFETY BUS "24" WITH POWER FROM THE CROSSTIE CONNECTION OR EDG "2", IF NECESSARY. THE ISOLATIONS AND SGTS ACTUATION REMAIN IN EFFECT. THE ACTUATION OF THE FIRE PROTECTION SYSTEM IS UNDER INVESTIGATION. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 04/02/92 0733EST FROM:NOHR BY:SCARFO * * *
UPON REVIEW, UNIT #1 GROUP ONE PRIMARY CONTAINMENT ISOLATION
VALVES "1-20-44" AND "1-20-45" WERE FOUND TO BE CLOSED. IT IS
BELIEVED THAT THE LOSS OF THE RAT CAUSED AN ELECTRICAL
DISTURBANCE WHICH RESULTED IN THE ISOLATION VALVE CLOSURES. THE
VALVES WERE IMMEDIATELY OPENED UPON DISCOVERY. THIS HAD NO
EFFECT ON THE OPERATIONAL STATUS OF UNIT #1. THE LICENSEE
INFORMED THE NRC RESIDENT INSPECTOR. R3DO(MCCORMICKBARGER) AND
EO(ROSSI) NOTIFIED.

23213 04-10-92 POW SALEM 1 2 LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO. SITE: SALEM 1 2 EN NUMBER: 23213 DOCKET: 05000272 05000311 EVENT DATE: 04-10-92 VENDORS: W-4-LP W-4-LP EVENT TIME: 03:21 NOTIFY DATE: 04-10-92 EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 04:19 OPS OFFICER: RUDY KARSCH 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN N N 0 HOT STANDBY 0 HOT STANDBY

THE SECURITY COMPUTER WHICH MONITORS CARD READERS "LOCKED UP".
THIS FAILURE REQUIRES COMPENSATORY MEASURES TO BE IN PLACE WITHIN TEN MINUTES. THIS REQUIREMENT WAS NOT MET. COMPENSATORY MEASURES

ARE NOW IN PLACE, GUARDS POSTED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

**** RETRACTED AT 1018 EDT ON 04/10/92 BY SERWAN TAKEN BY ANDREWS

THE LICENSEE IS RETRACTING THIS EVENT. BASED ON DISCUSSIONS WITH THE SENIOR RESIDENT INSPECTOR AND THE NRC SAFEGUARDS SECTION THEY HAVE DETERMINED THAT THE EVENT IS LOGGABLE, NOT REPORTABLE.

HOO NOTIFIED RIDO (ROGGE) .

LICENSEE: SOUTHERN NUCLEAR OPERATING COMPANY

SITE: FARLEY 1 2

DOCKET: 05000348 05000364

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: AL

EN NUMBER: 23251

EVENT DATE: 04-16-92

NOTIFY DATE: 04-16-92

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

LICENSEE DISCOVERED THAT A CONTRACTOR EMPLOYEE HAD PROVIDED FALSE INFORMATION ON HIS APPLICATION.

SEE HOO LOG FOR DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1

DOCKET: 05000458

RX TYPE: BWR

VENDORS: GE-6

EVENT DATE: 04-16-92

EVENT TIME: 17:50

NOTIFY DATE: 04-16-92

EMERGENCY CLASS: N/A REGION: 4 STATE: LA

TIME: 19:23

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N N 0 REFUELING 0 REFUELING

LICENSEE DISCOVERED A SECURITY OPENING WITHOUT A PROPER BARRIER OR A POSTED SECURITY GUARD.

SEE HOO LOG FOR DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: UNIVERSITY OF VIRGINIA

SITE: UNIV OF VIRGINIA EN NUMBER: 23298

EVENT DATE: 04-22-92 DOCKET: 05000062 EVENT TIME: 12:10 RX TYPE: POOL NOTIFY DATE: 04-22-92 VENDORS: EMERGENCY CLASS: UNU REGION: 2 STATE: VA TIME: 13:00

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: AAEC 50.72(a)(1)(i) EMERGENCY DECLARED DDDD 73.71 UNSPECIFIED PARAGRAPH

SECURITY THREAT DIRECTED AT UNIVERSITY OF VIRGINIA NUCLEAR REACTOR FACILITY BUILDING CONTAINING THE TWO MW SWIMMING POOL RESEARCH REACTOR. THIS FACILITY IS LOCATED AT CHARLOTTESVILLE, VA.

THE LICENSEE HAS NOTIFIED STATE AND LOCAL OFFICIALS OF THE DECLARATION OF THE UNUSUAL EVENT

SEE HOO LOG FOR DETAILS.

**** UPDATE AT 1558 EDT ON 04/22/92 BY BENNECHE TAKEN BY ANDREWS

LICENSEE HAS DETERMINED THAT NO REAL THREAT CURRENTLY EXISTS AT THE REACTOR BUILDING. THEY ARE TERMINATING THE UNUSUAL EVENT AT 1558 EDT. THE LICENSEE WILL NOTIFY STATE AND LOCAL OFFICIALS OF THE TERMINATION OF THE UNUSUAL EVENT.

HOO NOTIFIED R2DO (CANTRELL), EO (ROSSI), IAT (BURNETT, MCPEEK) AND FEMA (LOUZANIS)

ZION 1 2 23357 04-28-92 POW

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 23357 SITE: ZION 1 2 DOCKET: 05000295 05000304 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 04-28-92 EVENT ME: 20:58 NOTIFY DATE: 04-28-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 22:58 OPS OFFICER: TIM McGINTY

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR

CODE CRIT PWR
N 0 REFUELING 0 REFUELING
N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN 2 N

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

* * * UPDATE AT 1221 ON 05/11/92 BY COMBS ENTERED BY HOO JOLLIFFE

LICENSEE DESIRES TO RETRACT THIS EVENT SINCE COMPENSATORY SECURITY

MEASURES WERE ESTABLISHED AND IN PLACE WITHIN 10 MINUTES. THUS, THIS

EVENT IS A LOGGABLE SECURITY EVENT AND NOT A REPORTABLE SECURITY EVENT.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R3DO JORGENSEN

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: ROBINSON 2

DOCKET: 05000261

RX TYPE: PWR

VENDORS: W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

EN NUMBER: 23358

EVENT DATE: 04-29-92

NOTIFY DATE: 04-29-92

TIME: 04:32

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N N O REFUELING O REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA DOORS. IMMEDIATE COMPENSATORY ACTIONS WERE TAKEN BY THE LICENSEE. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS NOTIFIED THE NRC RESIDENT INSPECTOR.

RIVER BEND 1 23457 05-14-92 POW

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 23457

DOCKET: 05000458 EVENT DATE: 05-14-92

RX TYPE: BWR EVENT TIME: 05:30

VENDORS: GE-6 NOTIFY DATE: 05-14-92

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 07:09

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N N O REFUELING O REFUELING

LICENSEE DISCOVERED A PATHWAY THAT EXISTS INTO THE PLANT PROTECTED AREA. LICENSEE TOOK COMPENSATORY MEASURES. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1528 EDT FROM BARKER TO MILLER * * *
THE LICENSEE IS RETRACTING THIS NOTIFICATION BASED UPON THE
DETERMINATION THAT ADEQUATE COMPENSATORY MEASURES WERE TAKEN IN
AN APPROPRIATE AMOUNT OF TIME. THE EVENT HAS BEEN DEEMED
LOGGABLE INSTEAD OF REPORTABLE. THE RESIDENT INSPECTOR WILL BE
INFORMED. R4DO (BARNES) INFORMED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3

DOCKET: 05000206 05000361 05000362

RX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 92 POWER OPERATION 92 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

3 N Y 65 POWER OPERATION 65 POWER OPERATION

THE LICENSEE WAS REPORTING THE CONFIRMED DISCOVERY OF THE REMAINS OF A MARIJUANA CIGARETTE IN THE PROTECTED AREA.

ON 5/13/92 @ 13:05 A SUSPECT MATERIAL WAS DISCOVERED BY CONTRACT PERSONNEL WHILE THEY WERE PERFORMING A ROUTINE MAINTENANCE TASK AT A REMOTE AREA ON THE UNIT #3 SAFETY EQUIPMENT BUILDING ROOF AT THE 50' ELEVATION. ON 05/14/92 @ 14:30 AN OFFSITE LAB CONFIRMED THAT IT WAS A CONTROLLED SUBSTANCE. NO INDIVIDUALS HAVE BEEN IDENTIFIED AS RESPONSIBLE FOR THE MATERIAL. THE RI WAS INFORMED

HARRIS 1 23497 05-20-92 POW

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: HARRIS 1 EN NUMBER: 23497

DOCKET: 05000400 EVENT DATE: 05-20-92

RX TYPE: PWR EVENT TIME: 11:35

VENDORS: W-3-LP NOTIFY DATE: 05-20-92

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 12:32

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTROL SUBSTANCE FOUND WHILE WORKERS WERE INSTALLING CONDUIT IN THE MEN'S LOCKER ROOM (WASTE PROCESSING BUILDING). LICENSEE IS TAKING IMMEDIATE COMPENSATORY MEASURES. LICENSEE NOTIFIED RESIDENT INSPECTOR AND LOCAL AUTHORITIES OF THIS EVENT.

SEE HOO LOG BOOK FOR FURTHER INFORMATION.

* * * UPDATE AT 1554 ON 06/16/92 BY CASE ENTERED BY HOO JOLLIFFE

LICENSEE DESIRES TO DOWNGRADE THIS EVENT FROM A REPORTABLE SECURITY EVENT TO A LOGGABLE SECURITY EVENT BASED ON A TEST CONDUCTED BY THE NORTH CAROLINA STATE CRIME LAB WHICH REVEALED THAT THE SUBSTANCE TESTED WAS NOT AN ILLEGAL CONTROLLED SUBSTANCE.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R2DO LANDIS.

RIVER BEND 1 23547 05-28-92 POW

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 23547
DOCKET: 05000458 EVENT DATE: 05-28-92

RX TYPE: BWR EVENT TIME: 11:03
VENDORS: GE-6 NOTIFY DATE: 05-28-92

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 12:58

OPS OFFICER: THOMAS ANDREWS

N

N

1

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

O REFUELING

CODE CRIT PWR PWR

0

DURING SELF-SCREENING CONTRACTOR QUALITY ASSURANCE AUDIT,

REFUELING

LICENSEE DISCOVERED 11 CONTRACT EMPLOYEES HAD BEEN GIVEN UNESCORTED ACCESS TO THE PROTECTED AREA THAT HAD NOT PASSED THE PSYCHOLOGICAL EVALUATION.

THE SUBJECT CONTRACT PERSONNEL FAILED THE WRITTEN TEST AND DID NOT SHOW UP FOR THE CLINICAL EVALUATION. THEIR UNESCORTED ACCESS WAS REVOKED, THE SECURITY KEY CARDS WERE PULLED AND DESTROYED. THESE PEOPLE HAVE BEEN INVOLVED IN THE CHEMICAL CLEANING OF THE SERVICE WATER AND STANDBY SERVICE WATER SYSTEMS. THE LICENSEE HAS PLACED THE CONTRACTOR ON PROBATION AND IS CONDUCTING A ROOT CAUSE EVALUATION.

THIS EVENT IS REPORTED UNDER 10-CFR-73.56(B)2-ii PER GENERIC LETTER 91-03.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED OF THIS EVENT. NO OTHER NOTIFICATIONS ARE REQUIRED OR ANTICIPATED.

**** UPDATE AT 1510 EDT ON 05/28/92 BY NORRIS TAKEN BY ANDREWS

THE LICENSEE HAS IDENTIFIED 2 ADDITIONAL CONTRACT EMPLOYEES FROM THE SAME CONTRACTOR WHO ALSO DID NOT PASS THE PSYCHOLOGICAL EVALUATION. THIS CONTRACTOR EMPLOYS 39 PEOPLE ONSITE. THIS INCIDENT IS BELIEVED TO BE ISOLATED TO THIS CONTRACTOR. THE SAME ADMINISTRATIVE ACTIONS FOR THESE 2 ADDITIONAL PEOPLE WILL BE TAKEN AS THE ORIGINAL 11.

THE RESIDENT INSPECTOR WILL BE INFORMED OF THIS UPDATE.

****RETRACTION 1028 EDT ON 06/29/92 BY MCQUIRTER TAKEN BY ANDREWS ****

LICENSEE HAS SINCE DETERMINED THAT THIS EVENT DOES NOT MET REG

GUIDE 5.62 REPORTING CRITERIA. THE INDIVIDUALS MENTIONED ABOVE HAVE BEEN SUCCESSFULLY REEXAMINED AND HAVE HAD THEIR UNESCORTED ACCESS RESTORED.

THIS IS DISCUSSED IN THE LICENSEE'S CONDITION REPORT CR-92-0391.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED OF THE RETRACTION.

HOO NOTIFIED R4DO (CAIN).

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: ROBINSON 2 EN NUMBER: 23570

DOCKET: 05000261 EVENT DATE: 06-03-92

RX TYPE: PWR EVENT TIME: 09:52

VENDORS: W-3-LP NOTIFY DATE: 06-03-92

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 10:47

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR CURRENT MODE
PWR

2 N N O COLD SHUTDOWN O COLD SHUTDOWN

SAFEGUARD SYSTEM DEGRADATION RELATED TO MONITORING OF A VITAL AREA DOOR.

IMMEDIATE COMPENSATORY MEASURES WERE TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1 EN NUMBER: 23646

DOCKET: 05000271 EVENT DATE: 06-13-92

RX TYPE: BWR EVENT TIME: 05:33

VENDORS: GE-4 NOTIFY DATE: 06-13-92

EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 06:33

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE RECEIVED AN UNCONFIRMED BOMB THREAT. IMMEDIATE COMPENSATORY ACTIONS TAKEN. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE VERNON POLICE DEPARTMENT, WINDHAM SHERIFF'S OFFICE, BRATTLEBORO POLICE DEPARTMENT AND THE VERMONT STATE POLICE AND WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE 0953EDT 6/13/92 FROM WRIGHT BY S.SANDIN * * *
SECURITY TERMINATED COMPENSATORY MEASURES AS OF 0949EDT AFTER
DETERMINING THAT THIS WAS NOT A CREDIBLE BOMB THREAT. LICENSEE
NOTIFIED FBI AT 0747EDT OF THIS INCIDENT AND WILL NOTIFY OTHER
LAW ENFORCEMENT AGENCIES OF TERMINATION. THE VERMONT STATE POLICE
ARE CONTINUING THEIR INVESTIGATION. THE LICENSEE INFORMED THE NRC

RESIDENT INSPECTOR. NOTIFIED R1DO (JOHANSEN) AND R1 (COOPER, JOYNER).

DIABLO CANYON 1 2 23689 06-20-92 POW

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 EN NUMBER: 23689 EVENT DATE: 06-20-92 DOCKET: 05000275 05000323 EVENT TIME: 21:21 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 06-21-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 01:14

OPS OFFICER: TIM McGINTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N

N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO RESPONDING TO AN ALARM CONDITION ON A VITAL AREA DOOR. COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL NOTIFY THE RESIDENT INSPECTOR. SEE THE HOO LOG FOR SPECIFIC DETAILS. SEE ALSO RELATED EVENT #23688.

* * * UPDATE 06/25/92 1433EDT FROM: RYAN BY: SCARFO * * * THE LICENSEE HAS RETRACTED THIS EVENT ON THE BASIS THAT IT DOES NOT MEET THE ONE-HOUR REPORTING CRITERIA. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R5DO (JOHNSON) NOTIFIED.

DIABLO CANYON 1 2 23765 07-01-92 POW

LICENSEE: PACIFIC GAS & ELECTRIC CO.

EN NUMBER: 23765 SITE: DIABLO CANYON 1 2 EVENT DATE: 07-01-92 DOCKET: 05000275 05000323 VENDORS: W-4-LP W-4-LP EVENT TIME: 06:03 NOTIFY DATE: 07-01-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 10:03

OPS OFFICER: TIM McGINTY

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO THE ALARM AND KEY CARD FUNCTIONS FOR THE SITES VITAL AREA DOORS AND PROTECTED AREA BOUNDARIES. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

* * * UPDATE 1729EDT 7/24/92 FROM RYAN BY S.SANDIN * * * LICENSEE IS RETRACTING THIS EVENT AS OF 1410PDT 7/24/92. UPON FURTHER REVIEW AND DISCUSSION WITH R5 SAFEGUARDS INSPECTOR (SCHAEFER), IT WAS DETERMINED THAT THIS EVENT DID NOT MEET THE CRITERIA FOR A 1 HOUR EVENT AND WOULD BE DOWNGRADED TO AN ENTRY IN THE SAFEGUARDS EVENT LOG. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. NOTIFIED R5 (SCHAEFER).

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 23864

DOCKET: 05000341 EVENT DATE: 07-14-92

RX TYPE: BWR EVENT TIME: 17:20

VENDORS: GE-4 NOTIFY DATE: 07-14-92

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 17:59

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO ALARM SYSTEM. NOT IMMEDIATELY COMPENSATED ON DISCOVERY BUT COMPENSATED NOW. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

BABCOCK & WILCOX CO. 23881 07-15-92 FUE

LICENSEE: BABCOCK & WILCOX CO.

SITE: BABCOCK & WILCOX CO.

DOCKET: 07000027

RX TYPE:

VENDORS:

EN NUMBER: 23881

EVENT DATE: 07-15-92

EVENT TIME: 18:40

NOTIFY DATE: 07-15-92

EMERGENCY CLASS: N/A REGION: 2 STATE: VA TIME: 19:40

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

DURING PERSONNEL EVACUATION DURING THE ALERT REPORTED IN EVENT #23879,

NO PERSONNEL WERE SEARCHED FOR SPECIAL NUCLEAR MATERIAL ON EXIT FROM THE SECURITY AREA. ALL EVACUATED PERSONNEL WERE UNDER CONTINUOUS OBSERVATION

AND ACCOMPANIED BY SECURITY GUARDS TO THE ASSEMBLY AREA.

NO SECURITY SYSTEMS WERE LOST AND THE LICENSEE IS FOLLOWING THEIR PROCEDURES. ALL COMPENSATORY ACTIONS HAVE BEEN TAKEN.

* * * UPDATE 12/03/92 0948EST FROM: CLAYBROOK BY: SCARFO * * * THE LICENSEE HAS DETERMINED THAT THIS EVENT IS LOGGABLE BUT NOT REPORTABLE. RII HAS BEEN NOTIFIED. R2DO(RANKIN) NOTIFIED.

SOUTH TEXAS 1 2 23882 07-15-92 POW

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 2

DOCKET: 05000498 05000499

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: TX

EN NUMBER: 23882

EVENT DATE: 07-15-92

EVENT 'LIML: 18:45

NOTIFY DATE: 07-15-92

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

*** UPDATE 07/17/92 @ 1520 EDT BY PINZON TAKEN BY SKAY ***

THIS EVENT WAS RETRACTED BASED ON THE FACT THAT THE COMPENSATORY MEASURE TAKEN WAS IN CONFORMANCE WITH GENERIC LETTER 91-03. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: WATERFORD 3 EN NUMBER: 23905 DOCKET: 05000382 EVENT DATE: 07-17-92 EVENT TIME: 17:35 RX TYPE: PWR NOTIFY DATE: 07-17-92 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 19:30

OPS OFFICER: DONNA SKAY

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING OF AREA BOUNDARY. NOT IMMEDIATELY COMPENSATED FOR ON DISCOVERY BUT COMPENSATED FOR 24 MINUTES LATER. THE NRC RESIDENT WILL BE NOTIFIED. SEE HOO LOG FOR DETAILS.

***UPDATE @2243 7/17/92 ***

MONITORING SYSTEM WAS RESTORED AT 2240.

WASHINGTON NUCLEAR 2 23922 07-22-92 POW

LICENSEE: WASHINGTON PUBLIC POWER SUPPLY SYST

SITE: WASHINGTON NUCLEAR 2 EN NUMBER: 23922 DOCKET: 05000397 EVENT DATE: 07-22-92

RX TYPE: BWR EVENT TIME: 11:52 VENDORS: GE-5 NOTIFY DATE: 07-22-92

EMERGENCY CLASS: N/A REGION: 5 STATE: WA TIME: 15:49

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CUFRENT MODE

CODE CRIT PWR PWR

N Y 37 POWER OPERATION 37 POWER OPERATION

DISCOVERED SECURITY DEGRADATION THAT EXISTED FORM 10:38 PDT TO

10:43 PDT AND FROM 10:46 PDT TO 11:00 PDT. COMPENSATORY ACTIONS TAKEN. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

**** RETRACTION AT 1408 ON 07/27/92 BY CORNAGEY TAKEN BY HAROLD

LICENSEE DETERMINED THAT THE EVENT WAS NOT AN ONE HOUR REPORTABLE EVENT BUT A LOGABLE EVENT BASED ON A CONVERSATION WITH THE REGION V STAFF. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. NOTIFIED R5DO PATE.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: ROBINSON 2 EN NUMBER: 23983

DOCKET: 05000261 EVENT DATE: 08-01-92

RX TYPE: PWR EVENT TIME: 19:20

VENDORS: W-3-LP NOTIFY DATE: 08-01-92

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 20:09

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO ALARM AND COMPUTER FAILURES. IMMEDIATE COMPENSATORY MEASURES TAKEN. THE RI WAS

INFORMED. SEE HOO LOG FOR DETAILS.

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 24019

DOCKET: 05000341 EVENT DATE: 08-10-92

RX TYPE: BWR EVENT TIME: 07:25

VENDORS: GE-4 NOTIFY DATE: 08-10-92

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 08:23

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DDDD 73.71
UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR
UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

WEAPON FOUND BY ENTRY SCREENING.

DURING SECURITY SEARCH ACTIVITIES IN THE PRIMARY ACCESS PORTAL, A WEAPON WAS OBSERVED BY THE X-RAY MACHINE. THE WEAPON WAS DETERMINED TO BE A .22 CAL PELLET PISTOL. THE EMPLOYEE WAS RESTRAINED BY THE GUARDS AND HIS KEY CARD WAS DEACTIVATED. THE EMPLOYEE CLAIMED HE HAD FORGOTTEN THE WEAPON WAS IN THE BAG. THE EMPLOYEE WAS COOPERATIVE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4 EN NUMBER: 24108

DOCKET: 05000250 05000251 EVENT DATE: 08-24-92

RX TYPE: PWR PWR EVENT TIME: 02:45

VENDORS: W-3-LP W-3-LP NOTIFY DATE: 08-24-92

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 02:53

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH ANHU 50.72(b)(1)(iii) HURRICANE

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

3 N N 0 HOT STANDBY 0 HOT STANDBY
4 N N 0 HOT STANDBY 0 HOT STANDBY

SAFEGUARDS MEASURES SUSPENDED DUE TO HURRICANE WEATHER CONDITIONS.

STAFFING REQUIREMENTS AT CERTAIN SAFEGUARDS LOCATIONS HAVE BEEN SUSPENDED DUE THE IMMINENT THREAT OF HURRICANE WEATHER CONDITIONS. THE NRC RESIDENT HAS BEEN NOTIFIED. SEE HOO LOG FOR DETAILS.

LICENSEE HAS ALSO SUSPENDED ALL OUTSIDE FIRE WATCHES AS REQUIRED BY TECH SPEC 3.7.9. LICENSEE INFORMED RI.

FERMI 2 24181 09-06-92 POW

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2

DOCKET: 05000341

RX TYPE: BWR

VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: MI

EN NUMBER: 24181

EVENT DATE: 09-06-92

EMERGENCY CLASS: N/A REGION: 3 STATE: MI

TIME: 07:15

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
2 N Y 98 POWER OPERATION 98 POWER OPERATION

BECAUSE OF AIR CONDITIONING PROBLEMS IN THE SECONDARY ALARM STATION, THE LICENSEE DECIDED TO SWITCH THE COMPUTER FROM THE SECONDARY ALARM STATION TO THE CENTRAL ALARM STATION. THIS DECISION WAS MADE BASED UPON CONCERN REGARDING IMPACT OF ELEVATED AREA TEMPERATURES ON THE COMPUTER IN THE SECONDARY ALARM STATION.

AFTER THE SWITCH WAS MADE, BOTH ALARM STATIONS BECAME INOPERABLE WITH NO ALARMS REPORTING IN. MAINTENANCE PERSONNEL ARE WORKING ON GETTING BOTH COMPUTERS RUNNING AGAIN. THE COMPUTER IN THE SECONDARY ALARM STATION WAS RESTORED AT 0634 EDT. THEY ARE IN THE PROCESS OF TESTING THE SYSTEM NOW.

COMPENSATORY ACTIONS WERE TAKEN PRIOR TO THE ATTEMPT TO SWITCH COMPUTERS. THESE ACTIONS WILL REMAIN IN EFFECT UNTIL THE TESTING

ON THE COMPUTER SYSTEM IS COMPLETED.

MAINTENANCE PERSONNEL ARE ALSO WORKING ON REPAIRING THE A. ' CONDITIONING IN THE SECONDARY ALARM STATION. THE LICENSER DOES NOT HAVE AN ESTIMATE WHEN THE REPAIRS ON THE AIR CONDITIONING WILL BE COMPLETE.

THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR, STATE, AND LOCAL OFFICIALS.

* * * UPDATE FROM PETERMAN TO SEBROSKY AT 16:31 ON 9/8/92 * * *

THE LICENSEE IS RETRACTING THIS EVENT.

THE ORIGINAL REPORT WAS MADE BECAUSE IT WAS THOUGHT THAT INADEQUATE COMPENSATORY ACTIONS WERE TAKEN FOR APPROXIMATELY 17 MINUTES WHILE BOTH SECURITY COMPUTERS WERE NOT OPERATING. SUBSEQUENT REVIEW OF THE EVENT DETERMINED THAT ADEQUATE VISUAL SURVEILLANCE OF THE PERIMETER WAS MAINTAINED DURING THE 17 MINUTES THAT BOTH SECURITY COMPUTERS WERE NOT OPERATING. THE LICENSEE DOES NOT BELIEVE THAT THIS EVENT MEETS THE CRITERIA FOR REPORTING PER 10CFR73.71 BECAUSE ADEQUATE SURVEILLANCE OF THE SITE PERIMETER WAS MAINTAINED.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. HOO NOTIFIED R3DO (SNELL).

24191 09-09-92 POW CLINTON 1

LICENSEE: ILLINOIS POWER CO.

SITE: CLINTON 1 DOCKET: 05000461

RX TYPE: BWR VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 3 STATE: IL OPS OFFICER: STEVE SANDIN 10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR Y

PWR

100 POWER OPERATION 100 POWER OPERATION

EN NUMBER: 24191

TIME: 07:10

UNSPECIFIED PARAGRAPH

CURR CURRENT MODE

EVENT DATE: 09-09-92

EVENT TIME: 05:00

NOTIFY DATE: 09-09-92

LICENSEE FOUND VITAL AREA KEY ADRIFT IN THE PA. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 0801EDT 9/9/92 FROM SMITH TO JOHN MacKINNON * * * LICENSEE IS RETRACTING THIS EVENT FOLLOWING A DISCUSSION WITH R3 (BELANGER) AFTER DETERMINING THAT THE VITAL AREA KEY WAS NOT USED IN ANY UNAUTHORIZED MANNER. LICENSEE WILL DOCUMENT AS A LOGGABLE EVENT AND WILL INFORM THE NRC RESIDENT INSPECTOR. NOTIFIED R3DO(SNELL).

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

SITE: HOPE CREEK 1

EN NUMBER: 24222 EVENT DATE: 09-13-92 DOCKET: 05000354 EVENT TIME: 18:36 RX TYPE: BWR NOTIFY DATE: 09-13-92 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 19:31

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DCTB 73.71(b)(1) CONTRABAND
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR
N 0 REFUELING 0 REFUELING

ATTEMPTED INTRODUCTION OF CONTRABAND INTO A PROTECTED AREA. IMMEDIATE COMPENSATORY TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS.

CRYSTAL RIVER 3 24249 09-16-92 POW

LICENSEE: FLORIDA POWER CORPORATION

EN NUMBER: 24249 SITE: CRYSTAL RIVER 3 EVENT DATE: 09-16-92 DOCKET: 05000302 EVENT TIME: 21:30 RX TYPE: PWR VENDORS: B&W-L-LP NOTIFY DATE: 09-16-92

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 22:30

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

CODE CRIT PWR

Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA ACCESS. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY, SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE AT 09:28 ON 9/17/92 BY BECK TO GOULD THE LICENSEE DETERMINED AT 09:00 THAT NO DEGRADATION EXISTED TO THE VITAL AREA ACCESS, SO THEY ARE RETRACTING THIS EVENT.

WASHINGTON NUCLEAR 2 24266 09-18-92 POW

LICENSEE: WASHINGTON PUBLIC POWER SUPPLY SYST

SITE: WASHINGTON NUCLEAR 2 EN NUMBER: 24266 DOCKET: 05000397 EVENT DATE: 09-18-92

RX TYPE: BWR EVENT TIME: 13:58

VENDORS: GE-5 NOTIFY DATE: 09-18-92

EMERGENCY CLASS: N/A REGION: 5 STATE: WA TIME: 19:57

OPS OFFICER: THOMAS ANDREWS

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

AT 1358 PDT, THE CENTRAL ALARM STATION DISCOVERED THAT THE VITAL AREA DIESEL DOORS HAD FAILED AND WERE NOT TRANSMITTING ALARMS. MAINTENANCE HAS BEEN WORKING ON THESE DOORS FOR THE PAST SEVERAL DAYS, SO COMPENSATORY MEASURES HAD BEEN TAKEN PRIOR TO THE EVENT. ADDITIONAL MEASURES WERE TAKEN TO ENSURE ADEQUATE COVERAGE. SEE HOO LOG FOR DETAILS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. NO OTHER NOTIFICATIONS ARE ANTICIPATED OR REQUIRED.

* UPDATE DATE/TIME:9/30/92 @ 1438EDT ***FROM LICENSEE: WARE BY MCGINTY * THE LICENSEE IS RETRACTING THIS EVENT AFTER A TELEPHONE CONVERSATION WITH LEROY NORDERHAUG OF REGION V. THE EVENT IS BEING DOWNGRADED TO A LOGGABLE EVENT AFTER FURTHER INVESTIGATION OF THE CIRCUMSTANCES. THE LICENSEE INFORMED THE RESIDENT INSPECTOR. HOO NOTIFIED RV (NORDERHAUG).

LICENSEE: GULF STATES UTILITIES CO.

EN NUMBER: 24331 SITE: RIVER BEND 1 EVENT DATE: 09-29-92 DOCKET: 05000458 EVENT TIME: 10:00 RX TYPE: BWR NOTIFY DATE: 09-29-92 VENDORS: GE-6 EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 12:13

OPS OFFICER: STEVE SANDIN UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N CODE CRIT PWR
N Y 80 POWER OPERATION 82 POWER OPERATION

LOSS OF SAFEGUARDS DOCUMENT CONTROL. IMMEDIATE COMPENSATORY

MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 EN NUMBER: 24336 EVENT DATE: 09-29-92 DOCKET: 05000498 EVENT TIME: 19:35 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 09-29-92 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 21:32

OPS OFFICER: TIM MCGINTY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N N O REFUELING 0 REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO A VITAL AREA DOOR. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

BRAIDWOOD 1 2 24430 10-15-92 POW

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAIDWOOD 1 2 EN NUMBER: 24430 DOCKET: 05000456 05000457 EVENT DATE: 10-15-92 RX TYPE: PWR PWR EVENT TIME: 11:30

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 10-15-92 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 13:18 OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: DTMP 73.71(b)(1) SABOTAGE INIT INITIAL MODE CURR CURRENT MODE UNIT SCRAM RX CODE CRIT PWR PWR COLD SHUTDOWN 0 COLD SHUTDOWN N N 0 100 POWER OPERATION 100 POWER OPERATION N Y 2

VANDALISM FOUND IN THE UPPER CABLE SPREADING ROOM COMMON TO BOTH UNITS.

THE FOLLOWING IS A TEXT FROM THE LICENSEE:
"ON 10/14/92 THE BRAIDWOOD FIRE PROTECTION SITE MANAGER
(CONTRACTED FIRE WATCH MANAGER) WAS NOTIFIED THAT ONE OF HIS
EMPLOYEES HAD CAUSED DAMAGE TO PLANT PROPERTY. ON 10/15/92 PLANT
MANAGEMENT BECAME AWARE OF FURTHER DETAILS OF THIS EVENT. THE
DAMAGE WAS INSIGNIFICANT IN RELATION TO PLANT OPERATIONS OR
SECURITY, BEING LIMITED TO MINOR DAMAGE TO AIR DUCT INSULATION,
MINOR DAMAGE TO FIRE PROOFING, AND OTHER MINOR INCIDENTS OF LESS
SIGNIFICANCE. THIS APPEARS TO BE VANDALISM WITHOUT THE INTENT TO
INTERRUPT NORMAL OPERATION OR SECURITY. THESE INCIDENTS WERE
LIMITED TO ONE AREA OF THE PLANT. THE INVESTIGATION IS
CONTINUING."
END OF TEXT.

A SECURITY BADGE CHECK WAS PERFORMED AND THE INDIVIDUAL'S ACCESS WAS LIMITED TO THE ONE AREA INVOLVED. THE INDIVIDUALS UNESCORTED ACCESS HAS BEEN DENIED. THE LICENSEE HAS DONE A PRELIMINARY REVIEW OF THE AREA INVOLVED AND PLANS TO DO A FURTHER REVIEW TO ENSURE THAT ALL DAMAGE IS IDENTIFIED.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

* * * UPDATE 10/26/92 1734EST FROM:BAL BY:SCARFO * * *
THE FOLLOWING IS THE TEXT OF A FACSIMILE SUBMITTED BY THE
LICENSEE:

"THE PURPOSE OF THIS CALL IS TO RETRACT AN ENS CALL MADE ON 10/15/92 AT 1318EDT (1218CDT) UNDER 73.71. THIS PREVIOUS CALL CONCERNED A CONTRACTED FIRE WATCH PERSON CAUSING DAMAGE TO PLANT PROPERTY. UPON COMPLETION OF THE INVESTIGATION, IT HAS BEEN DETERMINED THAT THE INDIVIDUAL DID NOT INTEND TO INTERRUPT THE OPERATION OF THE PLANT OR CAUSE ANY DAMAGE WHICH WAS INTENDED TO INTERRUPT THE FUNCTION OF ANY SAFETY-RELATED SYSTEM OR COMPONENT. FURTHER REVIEWS OF THE AREAS TO WHICH THE INDIVIDUAL HAD ACCESS HAVE SHOWN NO ADDITIONAL DAMAGE BEYOND THE MINOR DAMAGE DESCRIBED IN THE ORIGINAL NOTIFICATION."

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: UNIVERSITY OF TEXAS

SITE: UNIVERSITY OF TEXAS - AUSTIN EN NUMBER: 24439
DOCKET: EVENT DATE: 10-16-92 RX TYPE: EVENT TIME: 08:05 NOTIFY DATE: 10-16-92 VENDORS:

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:47

OPS OFFICER: THOMAS ANDREWS

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71

NOTIFIED BY: TOM BOWERS

UNIVERSITY OF TEXAS - AUSTIN FACILITY:

BALCONES RESEARCH CENTER

BUILDING 159

AUSTIN, TX 78712

LICENSE: R129

AT APPROXIMATELY 0805 CDT, THE LICENSEE DISCOVERED A DEGRADATION IN THEIR SECURITY SYSTEM WHICH WAS NOT IMMEDIATELY COMPENSATED FOR. THE SYSTEM DEGRADATION OCCURRED AT 0752 CDT. UPON DISCOVERY, THE SECURITY AREA WAS INSPECTED AND NOTHING UNUSUAL WAS NOTED. VISUAL CONTROL WAS IN AFFECT UNTIL THE SECURITY SYSTEM WAS RETURNED TO SERVICE AT 0852 CDT. THE LICENSEE IS INVESTIGATING THE CAUSE OF THE SECURITY DEGRADATION.

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

SITE: COMANCHE PEAK 1 EN NUMBER: 24467 EVENT DATE: 10-21-92 DOCKET: 05000445 RX TYPE: PWR EVENT TIME: 04:51 VENDORS: W-4-LP NOTIFY DATE: 10-21-92

EMERGENCY CLASS: UNU REGION: 4 STATE: TX TIME: 06:12

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: AAEC 50.72(a)(1)(i) EMERGENCY DECLARED DDDD 73.71 UNSPECIFIED PARAGRA UNSPECIFIED PARAGRAPH

SCRAM RX INIT INITIAL MODE CURR CURRENT MODE UNIT

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

UNUSUAL EVENT, SECURITY COMPROMISE, "SECON RED".

A SECURITY OFFICER WAS FOUND TIED UP AND UNCONSCIOUS IN THE TURBINE BUILDING WITH HER WEAPON MISSING. HER WEAPON WAS LATER FOUND, BUT INDICATIONS OF THE COMMISSION OF A FELONY EXIST. THE INDIVIDUAL HAS BEEN SENT TO A HOSPITAL FOR TREATMENT. SECURITY REMAINS IN "SECURITY CONDITION (SECON) YELLOW" AS OF 0526 CDT. THE UNUSUAL EVENT WILL TERMINATE WHEN SECURITY COMPLETES THEIR INVESTIGATION. LOCAL POLICE HAVE BEEN CALLED IN TO AUGMENT THE INVESTIGATIONS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR FURTHER DETAILS. IAT (MCPEEK, DAVIDSON & BUSH) NOTIFIED.

COMMISSIONERS ASSISTANTS BRIEFING NOTIFICATIONS (*INDICATES

OFFICE DID NOT PARTICIPATE): AEOD AND IRB (BROCKMAN), COMM SELIN (VIETTI-COOK), CURTISS (CONNAUGHTON), REMICK (*), ROGERS (KARMAN), DepLANQUE (SUMMERS), EDO (MITCHELL), EDO REGION (*), EO (CHAFFEE), RDO (REESE), PAO (INGRAM), CAO (MADDEN), SECY (HART), STATE (SCHWARTZ), IP (UPSHAW), BRIEFER (JAUDAN), OTHERS (BEACH).

* * * UPDATE AT 0948 EDT FROM KROSS TAKEN BY KARSCH * * * UNUSUAL EVENT TERMINATED AT 0847 CDT. PLANT SECURITY HAS COMPLETED APPLICABLE PROCEDURES AND HAS CONFIRMED NO SECURITY THREAT TO THE PLANT. PLANT OPERATION REMAINED UNAFFECTED THROUGH OUT THE EVENT. THE INJURED SECURITY GUARD HAS REGAINED CONSCIOUSNESS. THE LICENSEE HAS ISSUED A PRESS RELEASE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R4DO (PELLET), EO (CHAFFEE), AND FEMA (MUSE) NOTIFIED.

**** COMMISSIONERS ASSISTANT'S BRIEFING ****

A COMMISSIONERS ASSISTANT'S BRIEFING WAS CONDUCTED AT 1200 EST ON 11/23/92 BY JAUDON - REGION 4. DUE TO THE SENSITIVE NATURE OF THE DISCUSSION, PARTICIPATION WAS LIMITED TO THE FOLLOWING:

WILSON - COMMISSIONER SELIN'S OFFICE
CARMEN - COMMISSIONER ROGERS' OFFICE
TRIMBLE - COMMISSIONER CURTISS' OFFICE
COLLINS - COMMISSIONER REMICK'S OFFICE
SUMMERS - COMMISSIONER DE PLANQUE'S OFFICE
MCKENNA - COMMISSIONER DE PLANQUE'S OFFICE
BLACK - COMANCHE PEAK PROJECT MANAGER

DIABLO CANYON 1 2 24504 10-27-92 POW

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2

DOCKET: 05000275 05000323

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

EN NUMBER: 24504

EVENT DATE: 10-27-92

EVENT TIME: 02:38

NOTIFY DATE: 10-27-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 06:16 OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N Y 100 POWER OFERATION 100 POWER OPERATION

A UNIT 1 VITAL AREA DOOR ALARM WAS RESPONDED TO BY SECURITY GUARDS IN

1 HOUR INSTEAD OF WITHIN THE REQUIRED 3 MINUTES DUE TO A SECURITY GUARD RESPONDING TO THE CORRESPONDING DOOR IN UNIT 2 INSTEAD OF THE UNIT 1 DOOR.

COMPENSATORY MEASURES HAVE BEEN TAKEN TO RESPOND TO THE UNIT 1 DOOR ALARM.

LICENSEE IS DETERMINING CAUSE AND CORRECTIVE ACTIONS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

SEE HOO LOG FOR ADDITIONAL DETAILS.

- * * * UPDATE 10/28/92 1254EST FROM:RYAN BY:SCARFO * * *
 THE LICENSEE IS RETRACTING THIS EVENT REPORT ON THE FOLLOWING BASIS:
- 1. THE CAUSE FOR THE DOOR ALARM WAS ESTABLISHED AND NO MALEVOLENT

INTENT WAS INVOLVED.

2. A SEARCH OF THE AFFECTED AREA WAS COMPLETED WITH NO ADVERSE

FINDINGS.

3. THE ALARM WAS FUNCTIONING PROPERLY SO ATTEMPTS TO ENTER THE AREA

WOULD HAVE BEEN DETECTED.

4. THIS EVENT WILL BE LISTED IN THE QUARTERLY EVENT LOG.

THIS INFORMATION WAS REVIEWED WITH A REGION 5 SAFEGUARDS INSPECTOR. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R5DO(JOHNSTON) NOTIFIED.

MCGUIRE 1 24507 10-27-92 POW

LICENSEE: DUKE POWER CO.

SITE: MCGUIRE 1

DOCKET: 05000369

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: NC

EN NUMBER: 24507

EVENT DATE: 10-27-92

RVENT TIME: 13:25

NOTIFY DATE: 10-27-92

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

WHILE PERFORMING AN ENGINEERING REVIEW FOR SEISMIC CONCERNS ON VITAL FEEDWATER PUMPS AND ITS ASSOCIATED PIPING, THE LICENSEE IDENTIFIED A POTENTIAL SCENARIO WHICH WOULD RENDER THE PUMPS INOPERABLE FOR SAFE SHUTDOWN OF THE UNIT.

THE LICENSEE'S ENGINEERING DEPARTMENT PERFORMED A DESIGN REVIEW OF PIPING SYSTEM DRAWINGS WHEN THEY DETERMINED THE FOLLOWING: A BREACH OF NON-VITAL PIPE CAUSED BY A SEISMIC EVENT COULD RESULT IN THE INTRODUCTION OF AIR INTO A VITAL FEEDWATER PUMP RENDERING IT INOPERABLE FOR SAFE SHUTDOWN OF UNIT 1. THE LICENSEE HAS DETERMINED THAT THIS MAY POSE SECURITY CONCERN. AS COMPENSATORY ACTION, SECURITY WILL POST AN OFFICER TO KEEP THE PIPE UNDER OBSERVATION. THE LICENSEE WILL ALSO EVALUATE UNIT 2 FOR THIS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

UPDATE ON 11/17/92 @ 1505 FROM LICENSEE: SELLERS BY: McGINTY

THE LICENSEE IS RETRACTING THIS EVENT BASED ON A REVIEW PERFORMED BY THE DESIGN GROUP AND DISCUSSIONS WITH THE REGION. HOO NOTIFIED R2DO (CANTRELL).

MCGUIRE 2

24511 10-27-92 POW

LICENSEE: DUKE POWER CO.

EN NUMBER: 24511 SITE: MCGUIRE 2 EVENT DATE: 10-27-92 DOCKET: 05000370 EVENT TIME: 17:00 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 10-27-92 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 17:09

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR

100 POWER OPERATION 100 POWER OPERATION

WHILE PERFORMING AN ENGINEERING REVIEW FOR SEISMIC CONCERNS ON VITAL FEEDWATER PUMPS AND ITS ASSOCIATED PIPING, THE LICENSEE IDENTIFIED A POTENTIAL SCENARIO WHICH WOULD RENDER THE PUMPS INOPERABLE FOR SAFE SHUTDOWN OF THE UNIT.

SEE EVENT # 24507. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

***UPDATE 11/17/92 @ 1505 FROM LICENSEE: SELLERS BY:McGINTY *** THE LICENSEE IS RETRACTING THIS EVENT BASED ON A REVIEW PERFORMED BY THE DESIGN GROUP AND DISCUSSIONS WITH THE REGION. HOO NOTIFIED R2DO (CANTRELL).

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1 EN NUMBER: 24558 DOCKET: 05000309 EVENT DATE: 11-05-92 EVENT TIME: 13:00 RX TYPE: PWR NOTIFY DATE: 11-05-92 VENDORS: CE

TIME: 14:16 EMERGENCY CLASS: N/A REGION: 1 STATE: ME

OPS OFFICER: FRANK TALBOT

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CRIT PWR CODE PWR

Y 100 POWER OPERATION 100 POWER OPERATION

ON NOVEMBER 3, 1992, THE LICENSEE DISCOVERED SIX SECURITY BACKGROUND CHECKS THAT WERE NOT ADEQUATELY COMPLETED IN MARCH, 1990. ON NOVEMBER 5 AT 13:00, THE LICENSEE DETERMINED THAT THE EVENT WAS REPORTABLE PER 10 CFR 73, APPENDIX G, (C). THE LICENSEE TOOK COMPENSATORY MEASURES UPON DISCOVERY.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

FARLEY 1 24566 11-07-92 POW

LICENSEE: SOUTHERN NUCLEAR OPERATING COMPANY

EN NUMBER: 24566 SITE: FARLEY 1

EVENT DATE: 11-07-92 DOCKET: 05000348 EVENT TIME: 17:03 RX TYPE: PWR NOTIFY DATE: 11-07-92 VENDORS: W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 18:52

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

0 REFUELING 1 N N O REFUELING

PLANT SECURITY ACCESS SYSTEM DEGRADATION RELATED TO VITAL AREA DOOR ALARMS.

COMPENSATORY MEASURES TAKEN IMMEDIATELY UPON DISCOVERY 4 HOURS LATER. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. UNIT 2 WAS UNAFFECTED BY THIS EVENT.

* * * UPDATE 12/3/92 AT 15:54 FROM NESBITT TAKEN BY SEBROSKY * *

THE LICENSEE IS RETRACTING THIS EVENT. THE LICENSEE HAS DISCUSSED THIS EVENT WITH NRC HEADQUARTERS (ERVIN) AND REGION 2 (THOMPSON) PERSONNEL. BASED ON THESE DISCUSSIONS THE LICENSEE HAS DETERMINED THAT THE EVENT IS LOGGABLE BUT NOT REPORTABLE.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. HOO NOTIFIED R2DO (RANKIN).

DAVIS BESSE 1 24571 11-09-92 POW

LICENSEE: TOLEDO EDISON CO.

EN NUMBER: 24571 SITE: DAVIS BESSE 1 DOCKET: 05000346 EVENT DATE: 11-09-92 EVENT TIME: 12:50 RX TYPE: PWR VENDORS: B&W-R-LP NOTIFY DATE: 11-09-92

EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 13:48

OPS OFFICER: FRANK TALBOT

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE FOUND SAFEGUARDS INFORMATION UNSECURED AND OUTSIDE THE PROTECTED AREA. COMPENSATORY MEASURES ARE BEING TAKEN BY THE LICENSEE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR ADDITIONAL DETAILS.

** UPDATE DATE/TIME:11/16/92 @ 1349 *FROM LICENSEE:FILIPUCCI BY McGINTY**

THE LICENSEE IS RETRACTING THIS EVENT BASED ON A REVIEW OF THE DOCUMENTS FOUND WHICH DETERMINED THAT UNDETECTED OR UNAUTHORIZED ACCESS TO DAVIS BESSE COULD NOT OCCUR FROM THE INFORMATION THAT WAS FOUND. ADDITIONALLY, THE GUIDANCE FOUND IN GENERIC LETTER 91-03 WAS FOLLOWED IN DETERMINING CONTINUED REPORTABILITY. THE LICENSEE HAS NOTIFIED REGION III, AND WILL NOTIFY THE RESIDENT INSPECTOR. HOO NOTIFIED R3DO (PHILLIPS).

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2

DOCKET: 05000334 05000412

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: PA

OPS OFFICER: FRANK TALBOT

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 90 POWER OPERATION 90 POWER OPERATION

2 N Y 45 POWER OPERATION 45 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION DUE TO COMPUTER MALFUNCTION. THE LICENSEE TOOK THE NECESSARY COMPENSATORY MEASURES. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR MORE DETAILS. SEE EVENT # 24671 FOR RELATED EVENT.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2

DOCKET: 05000334 05000412

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: UNU REGION: 1 STATE: PA

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 90 POWER OPERATION

2 N Y 46 POWER OPERATION 46 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION OCCURRED WHILE TROUBLESHOOTING SECURITY COMPUTER TRANSFER FUNCTION. DEGRADATION INVOLVED LOSS OF SECURITY MONITORING ALARM SYSTEM AND CARD READER ACCESS CONTROL SYSTEM. SYSTEMS WERE LOST AT 1635 EST AND RESTORED AT 1645 EST. COMPENSATORY ACTIONS HAD ALREADY BEEN ESTABLISHED PRIOR TO THE EVENT DUE TO EARLIER PROBLEMS WITH THE COMPUTERS. BASED ON LICENSEE'S EMERGENCY ACTION LEVELS, LOSS OF SECURITY TO THIS EXTENT REQUIRED DECLARATION OF A UNUSUAL EVENT. LICENSEE DECLARED AND TERMINATED THE UE AT 1701 EST. STATE, LOCAL AGENCIES AND THE NRC RESIDENT INSPECTOR HAVE BEEN INFORMED. SEE HOO LOG FOR MORE DETAILS.

SEE SIMILAR EVENT #24669.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

EN NUMBER: 24734 SITE: SALEM 1 2 EVENT DATE: 12-11-92 DOCKET: 05000272 05000311 EVENT TIME: 13:55 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 12-11-92

EMERGENCY (LASS: N/A REGION: 1 STATE: NJ TIME: 14:33

OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE PWR CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

- SECURITY EVENT -

SECURITY GUARDS FOUND WEAPONS IN A SERVICE TRUCK DURING ROUTINE SEARCH AT GUARDHOUSE. GUARDS CONFISCATED THE WEAPONS AND CALLED THE LOCAL POLICE. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: GENERAL ATOMICS COMPANY SITE: GENERAL ATOMICS COMPANY

EN NUMBER: 24759 EVENT DATE: 12-15-92 DOCKET: 05000089 EVENT TIME: 08:00 RX TYPE: NOTIFY DATE: 12-15-92 VENDORS:

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 13:44

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DUNE 73.71(b)(1) UNAUTHORIZED ENTRY

UNAUTHORIZED ENTRY INTO A CONTROLLED ACCESS AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. A REGION 5 INSPECTOR (SCHUSTER) NOTIFIED.

* * * UPDATE 12/16/92 1100EST FROM: STOWE BY: HUFFMAN * * * THE LICENSEE REPORTS THAT THIS EVENT ACTUALLY OCCURRED ON 12/12/92. R5DO(GARCIA) NOTIFIED.

Query: 1993 EVENT REPORTS: 73.71

DRESDEN 2 3 24883 01-14-93 POW

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 24883 SITE: DRESDEN 2 3 DOCKET: 05000237 05000249 EVENT DATE: 01-14-93
RX TYPE: BWR BWR EVENT TIME: 14:05
VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:55

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE

CURR CURRENT MODE

PWR CODE CRIT PWR PWR

Y 72 POWER OPERATION 72 POWER OPERATION Y 98 POWER OPERATION 98 POWER OPERATION N

POTENTIAL LOSS OF SAFEGUARDS INFORMATION.

SAFEGUARDS INFORMATION FOUND MISSING DURING ROUTINE INVENTORY CHECK. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON FINDING THE SAFEGUARDS MISSING. SECURITY SEARCH IS IN PROGRESS.

SEE HOO LOG BOOK FOR FURTHER DETAILS

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

* * * UPDATE 02/09/93 1211EST FROM: JOSEFIK BY: SCARFO * * * THE LICENSEE HAS DETERMINED THAT THE LOSS OF SAFEGUARDS INFORMATION WAS NOT SIGNIFICANT ENOUGH TO BE CONSIDERED REPORTABLE. REGION III HAS APPROVED THIS RETRACTION. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R3DO (JACKIW) NOTIFIED.

LICENSEE: DUKE POWER CO.

EN NUMBER: 24906 SITE: MCGUIRE 1 2 DOCKET: 05000369 05000370 EVENT DATE: 01-19-93 EVENT TIME: 09:15 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 01-19-93 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 11:30

OPS OFFICER: TIM MCGINTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

UNACCOUNTED FOR SECURITY WEAPON INSIDE THE PROTECTED AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE HAS NOTIFIED THE RESIDENT INSPECTOR AND REGION 2 (D. THOMPSON). SEE HOO LOG FOR DETAILS.

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 24975 SITE: ROBINSON 2 EVENT DATE: 01-29-93 DOCKET: 05000261 EVENT TIME: 14:59 RX TYPE: PWR VENDORS: W-3-LP NOTIFY DATE: 01-29-93 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 15:52

OPS OFFICER: FRANK TALBOT

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR SECURITY GUARD REPORTED TO PLANT MANAGEMENT AN UNACCOUNTED FOR SECURITY MASTER KEY.

LICENSEE IS TAKING COMPENSATORY MEASURES.

SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: CLEVELAND ELECTRIC ILLUMINATING CO.

EN NUMBER 25015 SITE: PERRY 1 EVENT DATE: 02-04-93 DOCKET: 05000440 EVENT TIME: 13:45 RX TYPE: BWR NOTIFY DATE: 02-04-93 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 14:21

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR

N O REFUELING O REFUELING

LICENSEE DISCOVERED A SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. NOT IMMEDIATELY COMPENSATED ON DISCOVERY BUT COMPENSATED NOW.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED BY THE LICENSEE.

SEE HOO LOG FOR DETAILS.

LICENSEE: GPU NUCLEAR CORP.

SITE: THREE MILE ISLAND 1 EN NUMBER: 25035 DOCKET: 05000289 EVENT DATE: 02-07-93 EVENT TIME: 06:54 RX TYPE: PWR VENDORS: B&W-L-LP NOTIFY DATE: 02-07-93 EMERGENCY CLASS: SIT REGION: 1 STATE: PA TIME: 07:11

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: AAEC 50.72(a)(1)(i) EMERGENCY DECLARED DDDD 73.71 UNSPECIFIED PARAGRAPH SCRAM RX INIT INITIAL MODE CURR CURRENT MODE UNIT

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE DECLARED A SITE AREA EMERGENCY DUE TO AN UNAUTHORIZED FORCED ACCESS TO THE SITE AT 0705 EST.

AT 0654 EST AN UNAUTHORIZED VEHICLE CRASHED THROUGH THE NORTH GATE, INTO THE PROTECTED AREA. THE VEHICLE CAME TO A STOP INSIDE THE TURBINE BUILDING. THE DRIVER FLED FROM THE VEHICLE AND CANNOT BE LOCATED.

THE NRC MADE THE DECISION TO ENTER THE STANDBY RESPONSE MODE AT APPROXIMATELY 0725 EST. THE DECISION WAS MADE BY REGIONAL ADMINISTRATOR (MARTIN) AND EXECUTIVE TEAM MEMBER (JORDAN).

**** COMMISSIONERS ASSISTANT'S BRIEFING AT 1000 EST ON 02/07/93

BRIEFER: JORDAN (AEOD)

NOTIFIED: SELIN'S ASSISTANT (NEASE), ROGERS' ASSISTANT

(SCARBOROUGH),

REMICK'S ASSISTANT (DOOLITTLE), CURTISS'

ASSISTANT (GRAY),

de Planque's ASSISTANT (MCKENNA), CA (CALLAHAN), SECY (BATES), EDO (MCCREE), EO (RICHARDSON), IP

(UPSHAW),

SP (MILLER), PA (GAGNER), NMSS (CUNNINGHAM), IRB

(GIITTER) .

PARTICIPATED: EDO(McCREE), de Planque's ASSISTANT(McKENNA),

PA (HAYDEN)

IP(UPSHAW), CA(CALLAHAN), SELIN'S

ASSISTANT (NEASE)

SP(MILLER), EO(RICHARDSON), REMICK'S

ASSISTANT (DOOLITTLE),

CURTIS' ASSISTANT (GRAY), IRB (GIITTER), POGERS'

ASSISTANT

(SCARBOROUGH)

**** UPDATE AS OF 1100 EST ON 02/07/93 BY FACSIMILE ENTERED BY ANDREWS ****
PENNSYLVANIA STATE POLICE OFFICERS AND TMI SITE PROTECTION OFFICERS APPREHENDED AN INTRUDER INSIDE THE TMI-1 TURBINE BUILDING AT AROUND 1100 EST. OFFICIALS ARE IN THE PROCESS OF INTERVIEWING THE INTRUDER.

TMI-1 IS OPERATING AT FULL POWER. THE PLANT'S VITAL AREA WAS NOT PENETRATED. THERE HAS BEEN NO ABNORMAL RELEASE OF RADIOACTIVITY FROM THE PLANT.

THE INTRUDER GAINED ACCESS TO THE PLANT'S TURBINE BUILDING AFTER DRIVING A STATION WAGON THROUGH A FENCE AND A ROLL-UP DOOR EARLIER THIS MORNING.

ALL PLANT PERSONNEL HAVE BEEN ACCOUNTED FOR.

FEDERAL, STATE, AND LOCAL OFFICIALS HAVE BEEN KEPT NOTIFIED OF THE EVENT.

* * * COMMISSIONERS ASSISTANTS' BRIEFING AT 1240 EST ON 02/07/93

BRIEFER:

JORDAN (AEOD)

NOTIFIED:

AEOD (SPESSARD), IRB (GIITTER), PAO (HAYDEN),

SP(LANDAU),

IP(UPSHAW), EDO(SNIEZEK), EO(RICHARDSON),

SECY (BATES),

CA(CALLAHAN), CURTIS' ASSISTANT (TRIMBLE), ROGERS' ASSISTANT (FLEISHMAN), SELIN'S ASSISTANT (NEASE),

REMICK'S

ASSISTANT (CROCKETT), de Planque's

ASSISTANT (MCKENNA)

PARTICIPANTS: PA (HAYDEN), SP (LANDAU), IP (UPSHAW), LDO (SNIEZEK),

EO

(RICHARDSON), SECY(BATES), CA(CALLAHAN), CURTIS'

ASSISTANT

(TRIMBLE), ROGERS' ASSISTANT (FLEISHMAN), SELIN'S

ASSISTANT

(NEASE), REMICK'S ASSISTANT (CROCKETT), de

Planque's

ASSISTANT (MCKENNA)

**** UPDATE AS OF 1215 EST ON 02/07/93 BY FACSIMILE ENTERED BY ANDREWS ****

THE PENNSYLVANIA STATE POLICE HAVE CONFIRMED THAT THE INTRUDER WAS UNARMED. THE STATE POLICE APPREHENDED THE INTRUDER AND ESCORTED HIM OFFGITE AT ABOUT 1100 EST. THE STATE POLICE IS INTERROGATING THE INTRUDER.

PLANT OFFICIALS ARE CONDUCTING A THOROUGH INSPECTION OF ALL PLANT SYSTEMS TO ENSURE THE INTRUDER HAD NO IMPACT ON THE PLANT. THE INTRUDER WAS FOUND UNDER THE PLANT'S CONDENSER.

VITAL AREAS OF THE PLANT WERE LOCKED AND PROTECTED WHILE THE INTRUDER WAS IN THE PLANT.

THE PLANT CONTINUED TO OPERATE AT 100 % POWER DURING THE EMERGENCY. THE PLANT CONTINUED TO OPERATE AS A PRECAUTION TO PROTECT THE SAFETY OF WORKERS WHO MIGHT HAVE TO GO INTO THE TURBINE BUILDING DURING A SHUTDOWN.

THE PLANT HAS BEEN IN A SITE AREA EMERGENCY SINCE 0705 EST AND WILL REMAIN IN A STATE OF EMERGENCY UNTIL A COMPLETE INSPECTION OF THE PLANT IS MADE.

**** UPDATE AT 1640 EST ON 02/07/93 BY SHADEL TAKEN BY SCARFO ****

THE LICENSEE TERMINATED THE SITE AREA EMERGENCY AT 1635EST AFTER THE COMPLETION OF A SECURITY INSPECTION OF THE FACILITY BY THE STATE POLICE AND THE RE-ESTABLISHMENT OF ALL SECURITY BOUNDARIES. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. STATE AND LOCAL AGENCIES WILL BE NOTIFIED.

* * * COMMISSIONER'S ASSISTANTS' BRIEFING 02/08/93 1930EST * * * BRIEFER: BLOUGH (RI)

NOTIFIED:

JORDAN (AEOD) SPESSARD (AEOD) BROCKMAN (IRB)
GIITTER (IRB) FOUCHARD (PAO) LANDAU (SP)
HAUBER (IP) McCREE (EDO) HILL (SECY)

MADDEN(CA) TRIMBLE(CURTIS)

SCARBOROUGH (ROGERS)

NEASE (SELIN) DOOLITTLE (REMICK)

McKENNA (de Planque)

PARTICIPANTS:

KANE(R1) YOUNG(R1) COLLINS(R1)
ROGGE(R1) FISH(R1) HEHL(R1)
BROCKMAN(IRB) GIITTER(IRB) LANDAU(SP)
MCCREE(EDO) HILL(SECY) MADDEN(CA) KANE (R1)

GRAY (CURTISS) COPLAN (ROGERS) NEASE (SELIN)

McKENNA (de Planque)

**** COMMISSIONER'S ASSISTANTS' BREIFING - 02/18/93, 1630 EST ****

BRIEFER: COLLINS (IIT LEADER)

NOTIFIED:

JORDAN (AEOD) ROSS (AEOD) GIITTER (IRB)
KOPLCK (PA) SCHWARTZ (SP) UPSHAW (IP)
MCCKEE (EDO) ROGGE (R1DO) BATES (SECY)
KEELING (CA) TRIMBLE (CURTISS) SCARBOROUGH

(ROGERS)

Planque)

SHEDLOSKY (SELIN) DOOLITTLE (REMICK) MCKENNA (de

PARTICIPANTS:

JORDAN (AEOD) ROSS (AEOD)

COLLINS (IIT

LEADER)

MARTIN (R1) SHEDLOSKY (SELIN) UPSHAW (IP)
BATES (SECY) DROGITTIS (SP) KEELING (CA)
DOOLITTLE (REMICK) SCARBOROUGH (ROGERS) FOUCHARD (PA)
MCKENNA (de Planque) WIGGINS (R1) VIRGILIO (EO)

CATAWBA 1 2

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2

25079 02-16-93 POW

EN NUMBER: 25079

DOCKET: 05000413 05000414 EVENT DATE: 02-16-93 EVENT TIME: 06:40 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 02-16-93 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 07:36 OPS OFFICER: RUDY KARSCH UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 100 POWER OPERATION 100 POWER OPERATION N N O REFUELING O REFUELING

AN INDIVIDUAL WITH A PISTOL IN HIS COAT WAS STOPPED AT THE ENTRY PORTAL.

THE INDIVIDUAL HAD A .22 MAGNUM PISTOL IN HIS COAT POCKET. THE INDIVIDUAL STATED THAT HE PUT THE PISTOL INTO HIS POCKET THE NIGHT BEFORE AND FORGOT IT WAS THERE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

**** UPDATE AT 1536 EST ON 02/16/93 BY CLEMENTS TAKEN BY ANDREWS

LICENSEE IS RETRACTING THIS EVENT. THE WEAPON DID NOT ENTER THE PROTECTED AREA AND THERE WAS NO INTENT TO TAKE A WEAPON INTO THE PROTECTED AREA. AS SUCH, THE LICENSEE IS DOWNGRADING THIS REPORT TO A 24 HOUR LOGGABLE EVENT.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED OF THIS RETRACTION.

HOO NOTIFIED RD20 (BRANCH).

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI SITE: SAN ONOFRE 1 2 3 EN NUMBER: 25159 DOCKET: 05000206 05000361 05000362 EVENT DATE: 03-01-93 RX TYPE: PWR PWR PWR EVENT TIME: 04:00 VENDORS: W-3-LP CE CE NOTIFY DATE: 03-01-93 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 08:15 OPS OFFICER: GREG SCARFO UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
N Y 78 POWER OPERATION 78 POWER OPERATION
N Y 75 POWER OPERATION 75 POWER OPERATION 2 N

BOMB THREAT HAS BEEN RECEIVED AT THE PLANT. IMMEDIATE COMPENSATORY MEASURES HAVE BEEN TAKEN UPON DISCOVERY. THE BOMB THREAT HAS NOT BEEN DETERMINED TO BE CREDIBLE AT THIS TIME. THE FBI HAS BEEN NOTIFIED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

^{* * *} UPDATE AT 1303 BY DOBSON ENTERED BY HOO JOLLIFFE * * *

AT 1000 (PST), LICENSEE AND FBI DETERMINED THAT THE BOMB THREAT WAS NOT CREDIBLE AND SECURED FROM SECURITY CONDITION YELLOW. LICENSEE INFORMED

THE NRC RESIDENT INSPECTOR AND IS CONTINUING THEIR INVESTIGATION. HOO NOTIFIED R5DO YUHAS, EO CHAFFEE, AEOD SPESSARD / GIITTER, NRR IATM MCPEEK, NMSS IATM YARDUMIAN.

LICENSEE: PACIFIC GAS & ELECTRIC CO. SITE: DIABLO CANYON 1 2 EN NUMBER: 25199 EVENT DATE: 03-06-93 DOCKET: 05000275 05000323 RX TYPE: PWR PWR EVENT TIME: 03:10 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 03-06-93 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 06:51 OPS OFFICER: CHAUNCEY GOULD

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N N 0 HOT STANDBY 0 HOT STANDBY

SAFEGUARDS SYSTEM DEGRADATION RELATED TO SECURITY COMPUTER FUNCTIONS.

COMPENSATORY MEASURES TAKEN IMMEDIATELY. SEE HOO LOG FOR DETAILS. THE RI WILL BE NOTIFIED.

LICENSEE: FLORIDA POWER CORPORATION

EN NUMBER: 25240 SITE: CRYSTAL RIVER 3 EVENT DATE: 03-13-93 DOCKET: 05000302 EVENT TIME: 04:29 RX TYPE: PWR VENDORS: B&W-L-LP NOTIFY DATE: 03-13-93 EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 05:28 OPS OFFICER: TIM MCGINTY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N N O COLD SHUTDOWN O COLD SHUTDOWN

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION AND ALARMS. EVENT CAUSED BY SEVERE WEATHER BEING EXPERIENCED AT THE SITE. COMPENSATORY MEASURES IN PLACE. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR AND THE LOCAL SHERIFF.

UPDATE ON 03/13/93 @ 1126 EST FROM LICENSEE: CRABTREE BY: McGINTY THE LICENSEE REPORTED THAT ALL OF THE INTRUSION DETECTION SYSTEMS AND ALARMS HAVE BEEN RESTORED TO SERVICE. THE LICENSEE WILL NOTIFY THE RESIDENT INSPECTOR. HOO NOTIFIED R2DO (LITTLE) .

* * * UPDATE AT 1845 EST FROM CRABTREE TAKEN BY KARSCH * * * CONTINUES TO BE IN A SECURE MODE. ANTICIPATED TIDAL SURGE DIDN'T MATERIALIZE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R2DO (LITTLE) NOTIFIED.

LICENSEE: NORTHEAST UTILITIES

RX TYPE: BWR PWR PWR VENDORS: GE-3 CE W-4-LP NOTIFY DATE: 03-13-93

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 15:13 OPS OFFICER: RUDY KARSCH

10 CFR SECTION: ANIC 50.72(b)(1)(iii) ICE STORM/HAIL DTHR 73.71(c) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 3 N Y 100 POWER OPERATION 100 POWER OPERATION

HEAVY SNOW RENDERED PERIMETER SECURITY CAMERAS INOPERABLE. COMPENSATORY ACTIONS TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE FROM SHIMP TAKEN BY SEBROSKY 3/14/93 @ 21:00 * * * AT 20:52 ON 3/14/93 THE LICENSEE DETERMINED THAT ALL MOTION DETECTORS WERE OPERATING PROPERLY. COMPENSATORY ACTIONS ARE NO LONGER IN EFFECT. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. HOO NOTIFIED RIDO (HAVERKAMP) .

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

EN NUMBER: 25247 SITE: SEABROOK 1 EVENT DATE: 03-13-93 DOCKET: 05000443 EVENT TIME: 17:32 RX TYPE: PWR NOTIFY DATE: 03-13-93 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 18:02

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

PERIMETER SECURITY CAMERAS AND ALARM SYSTEM DEGRADED DUE TO SEVERE WEATHER.

COMPENSATORY MEASURES HAVE BEEN TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

EN NUMBER: 25302 SITE: RIVER BEND 1 EVENT DATE: 03-24-93 DOCKET: 05000458 EVENT TIME: 06:45 RX TYPE: BWR NOTIFY DATE: 03-24-93 VENDORS: GE-6 EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 12:03

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

CABINET CONTAINING SAFEGUARDS INFORMATION LOCATED OUTSIDE THE PROTECTED AREA WAS FOUND TO HAVE BEEN LEFT OPEN AND UNATTENDED FOR OVER SIX AND ONE HALF HOURS. COMPENSATORY ACTIONS TAKEN IMMEDIATELY UPON DISCOVERY. INVESTIGATION IN PROGRESS. SEE HOOLOG BOOK FOR FURTHER DETAILS.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2

DOCKET: 05000413 05000414

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

OPS OFFICER: RUDY KARSCH
10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION
2 N N 0 COLD SHUTDOWN

EVENT DATE: 03-25-93

EVENT TIME: 15:50

NOTIFY DATE: 03-25-93

EVENT TIME: 16:40

SECURITY DEGRADATION

CURR CURRENT MODE

PWR

1 N Y 100 POWER OPERATION
2 N O COLD SHUTDOWN

POTENTIAL COMPROMISE OF SAFEGUARDS MATERIAL. THE LICENSEE HAS CORRECTED THE CONDITION. ACTUAL COMPROMISE OF SAFEGUARDS INFORMATION IS DOUBTFUL. SEE HOO LOG FOR ADDITIONAL INFORMATION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO. EN NUMBER: 25344 SITE: OCONEE 1 2 3 DOCKET: 05000269 05000270 05000287 EVENT DATE: 04-01-93 RX TYPE: PWR PWR PWR EVENT TIME: 15:50 VENDORS: B&W-L-LP B&W-L-LP B&W-L-LP NOTIFY DATE: 04-01-93 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 16:12 OPS OFFICER: WILLIAM HUFFMAN 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 100 POWER OPERATION 100 POWER OPERATION 1 N 2 N N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

INADEQUATE CONTROL OF SAFEGUARDS MATERIAL.

LICENSEE REPORTS THAT SAFEGUARDS MATERIAL KEPT IN A CORPORATE OFFICE WAS NOT STORED IN ACCORDANCE WITH LICENSEE SAFEGUARDS PROTECTION CRITERIA. LICENSEE ORIGINALLY DISCOVERED THE PROBLEM ON MARCH 25, 1993 AND EVALUATED IT AS A LOGGABLE EVENT AT THAT TIME. SUBSEQUENT EVALUATION OF THE DOCUMENTATION FOUND HAS RESULTED IN THE EVENT BEING UPGRADED TO REPORTABLE. IMMEDIATE COMPENSATORY ACTIONS WERE TAKEN ON DISCOVERY. THE NRC RESIDENT

INSPECTOR WILL BE NOTIFIED. SEE HOO LOG FOR DETAILS.

LICENSEE: FLORIDA POWER CORPORATION

EN NUMBER: 25350 SITE: CRYSTAL RIVER 3 EVENT DATE: 04-03-93 DOCKET: 05000302 EVENT TIME: 14:16 VENDORS: B&W-L-LP NOTIFY DATE: 04-03-93

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 14:28

OPS OFFICER: WILLIAM HUFFMAN

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

0 COLD SHUTDOWN N N O COLD SHUTDOWN

LICENSEE REPORTED A SAFEGUARDS SYSTEMS DEGRADATION RELATED TO POSSIBLE METHOD BY WHICH UNDETECTED ENTRY INTO PROTECTED AREA COULD BE ACCOMPLISHED.

IMMEDIATE COMPENSATORY ACTIONS TAKEN UPON DISCOVERY. THE NRC RESIDENT WILL BE NOTIFIED. SEE HOO LOG FOR DETAILS.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 25363 SITE: DRESDEN 2 3 DOCKET: 05000237 05000249 EVENT DATE: 04-06-93
RX TYPE: BWR BWR EVENT TIME: 12:02
VENDORS: GE-3 GE-3 NOTIFY DATE: 04-06-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 13:56

OPS OFFICER: TIM McGINTY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
2 N N O REFUELING O REFUELING
3 N N O REFUELING O REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO A BREACH IN THE VITAL AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE RESIDENT INSPECTOR WILL BE NOTIFIED BY THE LICENSEE. SEE HOO LOG FOR DETAILS.

25416 04-19-93 POW SAN ONOFRE 1

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 EN NUMBER: 25416

DOCKET: 05000206 EVENT DATE: 04-19-93 EVENT TIME: 16:45 RX TYPE: PWR

VENDORS: W-3-LP NOTIFY DATE: 04-19-93

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 20:39

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DTHR 73.71(c)
UNIT SCRAM BY TAKE SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N O COLD SHUTDOWN O COLD SHUTDOWN

SECURITY DEGRADATION DISCOVERED. COMPENSATORY MEASURES TAKEN

UPON DISCOVERY. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL NOTIFY THE RESIDENT INSPECTOR.

* * * UPDATE 1620EDT 4/26/93 FROM WHALEY BY S.SANDIN * * *
LICENSEE IS RETRACTING THIS REPORT BASED ON FINDINGS OF THE
INVESTIGATION WHICH REVEALED THAT THE PORTAL WAS ADEQUATELY
COMPENSATED. THE LICENSEE HAS RECLASSIFIED THIS EVENT AS LOGABLE
RATHER THAN REPORTABLE AFTER COMPLETING THEIR EVALUATION AS
PREVIOUSLY DISCUSSED WITH THE NRC RESIDENT INSPECTOR AND
R5 (SCHUSTER). NOTIFIED R5 (SCHUSTER).

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: ROBINSON 2

DOCKET: 05000261

RX TYPE: PWR

VENDORS: W-3-LP

VENDORS: W-3-LP

NOTIFY DATE: 04-22-93

NOTIFY DATE: 04-22-93

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 11:18

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA ACCESS DOOR.

SECURITY DOOR "21" TO THE VITAL AREA WAS ACCESSED AND AN ARMED GUARD POSTED. AT 1027EDT THE GUARD LEFT HIS STATION WITH THE DOOR LOCKED BUT STILL IN ACCESS. IN THIS CONDITION NO ALARMS OR COMPUTER GENERATED ACCESS INFORMATION WOULD BE AVAILABLE. AT 1030EDT THE GUARD WAS OBSERVED BY THE CENTRAL ALARM STATION (CAS) OPERATOR IN ANOTHER AREA ON CLOSED CIRCUIT TV. THE CAS OPERATOR INFORMED SECURITY MANAGEMENT WHO IMMEDIATELY DISPATCHED A SECOND GUARD TO SECURE THE DOOR. A SEARCH OF THE VITAL AREA WAS CONDUCTED WITH NEGATIVE RESULTS. THE LICENSEE ATTRIBUTES THE CAUSE TO PERSONNEL ERROR AND HAS INFORMED THE NRC RESIDENT INSPECTOR.

WASHINGTON NUCLEAR 2 25457 04-28-93 POW

LICENSEE: WASHINGTON PUBLIC POWER SUPPLY SYST

SITE: WASHINGTON NUCLEAR 2 EN NUMBER: 25457
DOCKET: 05000397 EVENT DATE: 04-28-93

DOCKET: 05000397 EVENT DATE: 04-28-1

VENDORS: GE-5 NOTIFY DATE: 04-28-93

EMERGENCY CLASS: N/A REGION: 5 STATE: WA TIME: 14:09

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N Y 91 POWER OPERATION 91 POWER OPERATION

A SECURITY EVENT LOG LEFT UNATTENDED FOR 15 MINUTES ON 4/27/93

COULD HAVE RESULTED IN COMPROMISE OF SAFEGUARDS INFORMATION. SEE HOO LOG FOR ADDITIONAL DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 1049 EDT 05/05/93 BY Mr BALL TAKEN BY MACKINNON

LICENSEE IS RETRACTING REPORT AND CHANGING THIS EVENT TO A LOGABLE EVENT. SECURITY PATROLS WERE IN THE AREA OF THE SECURITY LOG BOOK AND THERE WAS NO COMPROMISE OF THIS MATERIAL. LICENSEE DISCUSSED THIS EVENT WITH NRC REGION 5 (LEE NORDERHAUG) ON 05/03/93. RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE. R5DO (BOB PATE) NOTIFIED.

LICENSEE: NEBRASKA PUBLIC POWER DISTRICT

SITE: COOPER 1 EN NUMBER: 25479

DOCKET: 05000298 EVENT DATE: 05-03-93

RX TYPE: BWR EVENT TIME: 14:30

VENDORS: GE-4 NOTIFY DATE: 05-03-93

EMERGENCY CLASS: N/A REGION: 4 STATE: NE TIME. 16:14

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N O COLD SHUTDOWN O COLD SHUTDOWN

A GENERAL ELECTRIC (GE) CONTRACT EMPLOYEE WHO HAD FAILED A RANDOM DRUG TEST AT THE LIMERICK FACILITY WAS ALLOWED ACCESS TO VITAL AND PROTECTED AREAS OF THE FACILITY.

AFTER COMPLETING AN EXTENDED BACKGROUND INVESTIGATION OF A GE CONTRACT EMPLOYEE, IT WAS DETERMINED THAT THE INDIVIDUAL SHOULD NOT HAVE RECEIVED ACCESS TO VITAL AND PROTECTED AREAS OF THE FACILITY. THE EXTENDED BACKGROUND INVESTIGATION FOUND THAT THE EMPLOYEE FAILED A RANDOM DRUG TEST AT THE LIMERICK GENERATING FACILITY PRIOR TO HIS ASSIGNMENT AT THE COOPER FACILITY. THE CONTRACT EMPLOYEE HAD ACCESS TO VITAL AND PROTECTED AREAS OF THE PLANT FROM 04/02/93 UNTIL 04/29/93.

CURRENTLY, THE CONTRACT EMPLOYEE HAS COMPLETED HIS TASKS AND EXITED THE SITE. THE LICENSEE IS SUSPENDING THE GE-APPROVED CLEARANCE PROGRAM AND NOTIFYING GE OF THE STATUS OF THIS CONTRACT EMPLOYEE. THE LICENSEE HAS INFORMED ANOTHER FACILITY OF THIS CONTRACT EMPLOYEE'S STATUS UPON INQUIRY. A WORK REVIEW IS IN PROGRESS.

REGION IV HAS BEEN INFORMED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1 EN NUMBER: 25529
DOCKET: 05000309 EVENT DATE: 05-18-93

RX TYPE: PWR

VENDORS: CE

EMERGENCY CLASS: N/A REGION: 1 STATE: ME

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF UNCONTROLLED PRINTS CONTAINING SAFEGUARLS INFORMATION.

PRINTS CONTAINING SAFEGUARDS INFORMATION WERE FOUND IN AN UNCONTROLLED AREA OF THE PLANT. IMMEDIATE COMPENSATORY ACTIONS WERE TAKEN CONCERNING THESE PRINTS. ADDITIONAL COMPENSATORY ACTION IS IN PROGRESS TO ENSURE NO ADDITIONAL SAFEGUARDS RELATED PRINTS ARE UNACCOUNTED FOR.

NRC RESIDENT INSPECTOR HAS BEEN INFORMED. SEE HOO LOG FOR DETAILS.

DUANE ARNOLD 1 25535 05-19-93 POW

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 25535

DOCKET: 05000331 EVENT DATE: 05-19-93

RX TYPE: BWR EVENT TIME: 18:01

VENDORS: GE-4 NOTIFY DATE: 05-19-93

EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 20:12

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 90 POWER OPERATION 90 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA DOOR ALARM MONITORING.
NOT IMMEDIATELY COMPENSATED UPON DISCOVERY BUT EVENTUALLY COMPENSATED FOR. SECURITY MONITORING WAS SUBSEQUENTLY FULLY RESTORED. SEE HOO LOG FOR DETAILS.

NRC RESIDENT WILL BE NOTIFIED.

* * * UPDATE AT 1737 EDT CN 5/21/93 FROM JOENS TAKEN BY KARSCH *

THE LICENSEE IS RETRACTING THIS EVENT REPORT. THEIR REVIEW OF THE DATA INDICATES THAT THE LOSS OF THE MULTIPLEXER WAS ONLY FOR THREE MINUTES VICE TWENTY, AND THAT ALL DOORS REMAINED LOCKED. BASED ON DISCUSSIONS WITH REGION 3 IT WAS DETERMINED THAT THIS IS LOGGABLE BUT NOT REPORTABLE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R3DO (JACOBSON) NOTIFIED.

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 25604 SITE: BRUNSWICK 1 2 DOCKET: 05000325 05000324 EVENT DATE: 06-03-93 EVENT TIME: 11:30 RX TYPE: BWR BWR NOTIFY DATE: 06-03-93 VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 12:24

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N 0 REFUELING 0 REFUELING
N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION , i.e., UNACCOUNTED FOR KEY CARDS, RELATED TO MONITORING OF VITAL AND PROTECTED AREA ACCESS DOORS.

COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

25623 06-08-93 POW POINT BEACH 1 2 LICENSEE: WISCONSIN ELECTRIC POWER CO.

EN NUMBER: 25623 SITE: POINT BEACH 1 2 DOCKET: 05000266 05000301 EVENT DATE, 06-08-93 EVENT TIME: 19:50

VENDORS: W-2-LP W-2-LP NOTIFY DATE: 06-09-93

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 01:10

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY MONITORING.

A PORTION OF THE PLANT PROTECTED AREA BOUNDARY WAS NOT MONITORED FROM

1950 CDT UNTIL 2348 CDT DUE TO CONSTRUCTION EQUIPMENT WHICH PREVENTED AN UNOBSTRUCTED VIEW OF THE AREA. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE NRC RESIDENT WILL BE NOTIFIED.

*** 6/09/93 @ 0841 EDT BY D MARCELLE TAKEN BY MACKINNON***

LICENSEE IS RETRACTING THIS EVENT BECAUSE THEY HAD A SECURITY PERSON CONTINUOUSLY OBSERVING THE AREA. LICENSEE IS MAKING THIS A LOGGABLE EVENT. LICENSEE TALKED TO R3DO (JIM KNICELEY) ABOUT REDUCING THIS EVENT TO A LOGGABLE EVENT. R3DO (BOB HASSE).

25639 06-11-93 POW ZION 1 2

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2 EN NUMBER: 25639 EVENT DATE: 06-11-93 DOCKET: 05000295 05000304

EVENT TIME: 13:36 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 06-11-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:24 OPS OFFICER: GREG SCARFO 10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR N Y 100 POWER CPERATION 100 POWER OPERATION N Y 69 POWER OPERATION 69 POWER OPERATION 2 N

MAJOR SAFEGUARDS SYSTEM DEGRADATION. COMPENSATORY MEASURES ARE IN AFFECT. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

***UPDATE FROM COMBS TO HUFFMAN ON 6/14/93 AT 1502 EDT *** BASED ON FURTHER REVIEW OF THIS EVENT AND DISCUSSIONS WITH NRC REGION III SECURITY PERSONNEL (KNICELEY), LICENSEE IS RETRACTING THIS EVENT. LICENSEE STATES THAT BECAUSE COMPENSATORY ACTIONS WERE COMPLETED WITHIN 10 MINUTES, THE EVENT IS ONLY LOGGABLE. THE NRC RESIDENT HAS BEEN INFORMED. R3DO(SHEAR) ALSO INFORMED.

LICENSEE: FLORIDA POWER & LIGHT CO.

EN NUMBER: 25704 SITE: SAINT LUCIE 1 2 EVENT DATE: 06-27-93 DOCKET: 05000335 05000389 RX TYPE: PWR PWR EVENT TIME: 15:05 NOTIFY DATE: 06-27-93 VENDORS: CE CE EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 15:42

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR CODE CRIT PWR PWR 1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

ONE HOUR REPORT PER APP. G.I. (c). LIGHTNING STRIKES AND HIGH WINDS COMPROMISE PERIMETER SECURITY.

SUBSEQUENT TO WEATHER INDUCED FAILURE OF THE ELECTRONIC SECURITY MONITORING SYSTEM, THE TEN MINUTE BACKUP POSTINGS TO DESIGNATED LOCATIONS WERE NOT POSSIBLE DUE TO THE ONGOING SEVERE WEATHER. VISUAL COVERAGE GAVE ASSURANCE THAT NO COMPROMISE OF PERIMETER SECURITY OCCURRED. POSTINGS SHOULD BE POSSIBLE SHORTLY. THE LICENSEE HAS NOT OBSERVED ANY GRID INSTABILITY NOR WAS THERE ANY WEATHER RELATED THREAT TO SAFETY SYSTEMS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 DOCKET: 05000275 05000323

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EN NUMBER: 25749 EVENT DATE: 07-07-93 EVENT TIME: 00:01 NOTIFY DATE: 07-07-93 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 03:49

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO COMPUTER FAILURE. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1

DOCKET: 05000458

RX TYPE: BWR

VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 4 STATE: LA

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

ATTEMPTED INTRODUCTION OF A WEAPON INTO A PROTECTED AREA.

IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG
FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 07/12/93 0956EDT FROM:McQUIRTER BY:SCARFO * * * THIS EVENT WAS RETRACTED ON THE BASIS OF THE LACK OF INTENT OF THE INDIVIDUAL INVOLVED IN THE INCIDENT. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R4DO(CONSTABLE) NOTIFIED.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2

DOCKET: 05000325 05000324

RX TYPE: BWR BWR

VENDORS: GE-4 GE-4

VENDORS: GE-4 GE-4

MOTIFY DATE: 07-22-93

EMERGENCY CLASS: N/A REGION: 2 STATE: NC

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DUNE 73.71(b)(1)

UNAUTHORIZED ENTRY

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

PWR

1 N N 0 COLD S. TOWN 0 COLD SHUTDOWN
2 N 98 POWER OPERAL ON 98 POWER OPERATION

A CONTRACT EMPLOYEE WAS GRANTED UNESCORTED ACCESS AND IT WAS LATER DETERMINED THAT HAD THE EMPLOYEE BEEN TRUTHFUL ON HIS EMPLOYMENT APPLICATION, THE EMPLOYEE WOULD NEVER HAD BEEN GRANTED THIS ACCESS.

THE FOLLOWING IS A TEXT OF A FACSIMILE FROM THE LICENSEE:

"ON 7/20/93 THE FBI FINGER PRINT RECORDS ON A CONTRACT EMPLOYEE WERE RECEIVED FROM THE NRC BY THE CORPORATE EMPLOYEE RELATIONS DEPARTMENT. INITIAL REVIEW INDICATED THAT THE WRONG CRIMINAL HISTORY WAS SENT BECAUSE OF THE NAME, AGE AND EMPLOYMENT HISTORY DISCREPANCIES. BRUNSWICK NUCLEAR POWER WAS NOTIFIED ABOUT THE PROBLEM AND THAT IT WAS A CASE OF AN INCORRECT FILE BEING SENT. ON 7/21/93 AT 08:45 THE CONTRACT EMPLOYEE WAS CONFRONTED AND ADMITTED FALSIFYING THE EMPLOYMENT APPLICATION. ON //21/93 THE CONTRACT EMPLOYEE'S BACKGROUND INVESTIGATION WAS OBTAINED FROM THE EMPLOYER (POWER PLANT MAINTENANCE, SOCIETY HILL, S.C.) A REVIEW OF THAT FILE BY THE NUCLEAR ASSESSMENT DEPARTMENT ON 7/22/93 DETERMINED, THAT BASED ON THE FBI CRIMINAL HISTORY, UNESCORTED ACCESS WOULD HAVE NEVER BEEN GRANTED HAD THE EMPLOYEE BEEN TRUTHFUL ON THE EMPLOYMENT APPLICATION.

THE INITIAL SAFETY SIGNIFICANCE IS CONSIDERED LOW. THE INDIVIDUAL WAS GRANTED UNESCORTED ACCESS ON 3/24/93. HE WAS EMPLOYED AS A PAINTER AND WAS ENGAGED IN PAINTING VARIOUS COMPONENTS WITHIN THE PROTECTED AREA. COMPUTER TRANSACTIONS SHOW HE WAS ONLY IN A VITAL AREA FOR APPROXIMATELY TWO MINUTES DURING THE TIME HE HAD UNESCORTED ACCESS ALL OTHER TIME WAS PROTECTED AREA ONLY.

UNESCORTED ACCESS WAS REVOKED AT 08:07 7/21/93. BACKGROUND SCREENING RECORDS OBTAINED FROM THE EMPLOYER ON LATE AFTERNOON OF 7/21/93. THE CORPORATE NUCLEAR ASSESSMENT DEPARTMENT IS REVIEWING THE INFORMATION AND THE INVESTIGATION IS CONTINUING." END OF TEXT

THE CRIMINAL HISTORY CONSISTED OF DRUG USE, DISTURBING THE PEACE, AND BURGLARY. THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1 EN NUMBER: 25828

DOCKET: 05000528 EVENT DATE: 07-23-93

RX TYPE: PWR EVENT TIME: 14:00

VENDORS: CE80 NOTIFY DATE: 07-23-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 18:02

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: NINF INFORMATION ONLY

DDDD 73.71 UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 85 POWER OPERATION 85 POWER OPERATION

UNSUBSTANTIATED BOMB THREAT RECEIVED BY ARIZONA PUBLIC SERVICE COMPANY REGARDING PALO VERDE UNIT 1. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN. COURTESY NOTIFICATION TO THE MERICOPA COUNTY SHERIFF'S OFFICE WAS MADE. SEE HOO LOG FOR DETAILS

LICENSEE: FLORIDA POWER & LIGHT CO.

EN NUMBER: 25861 SITE: SAINT LUCIE 1 2 DOCKET: 05000335 05000389 EVENT DATE: 07-30-93 EVENT TIME: 16:27 RX TYPE: PWR PWR NOTIFY DATE: 07-30-93 VENDORS: CE CE

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 18:35

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 65 POWER OPERATION 65 POWER OPERATION

A GUARD FOR BOTH UNIT'S CONTROL ROOM DOORS WAS NOT POSTED FOLLOWING THE FAILURE OF THE SECURITY COMPUTER.

A LIGHTNING STRIKE RENDERED THE SECURITY COMPUTER INOPERABLE. THE LICENSEE'S SECURITY PLAN REQUIRES POSTING GUARDS AT SPECIFIED LOCATIONS TO CONTROL VITAL AREA ACCESS WHEN COMPUTER CONTROL IS LOST. THE ENTRY DOORS TO BOTH UNIT'S CONTROL ROOMS REMAINED UNPOSTED FOR APPROXIMATELY ONE HOUR AND EIGHTEEN MINUTES FOLLOWING THE COMPUTER FAILURE DUE TO HUMAN ERROR. CUARDS WERE POSTED WITHIN TWO MINUTES OF THE DISCOVERY OF THE LAPSE IN COVERAGE. A SEARCH OF THE AFFECTED AREA WAS NEGATIVE. THE LICENSEE IS REPLACING THE FAILED COMPONENTS IN AN ATTEMPT TO RESTORE THE SYSTEM TO OPERABILITY. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

25875 08-03-93 POW KEWAUNEE 1

LICENSEE: WISCONSIN PUBLIC SERVICE CORP.

EN NUMBER: 25875 SITE: KEWAUNEE 1 EVENT DATE: 08-03-93 DOCKET: 05000305 EVENT TIME: 13:30 RX TYPE: PWR NOTIFY DATE: 08-03-93 VENDORS: W-2-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 15:25

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71
UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE
CURR CURRENT MODE

PWR CODE CRIT PWR

Y 100 POWER OPERATION 100 POWER OPERATION 1 N

MAJOR SAFEGUARDS SYSTEM DEGRADATION WHICH WAS COMPENSATED FOR BY THE TIME OF THE REPORT. COMPENSATORY MEASURES ARE IN EFFECT. NO ADVERSE CONSEQUENCES RESULTED TO THE PLANT NOR ARE ANY LIKELY. INITIALLY, THE EVENT WAS CONSIDERED LOGGABLE BUT NOT REPORTABLE. HOWEVER, THE EVENT WAS DETERMINED TO BE REPORTABLE AFTER FURTHER CONSULTATION WITH REGION III PERSONNEL. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE 08/30/93 1502EDT FROM: NALPKA BY: SCARFO * * * THE LICENSEE IS RETRACTING THIS EVENT ON THE BASIS THAT THE INFORMATION AVAILABLE IN THE CABINET WOULD NOT SIGNIFICANTLY ASSIST AN INDIVIDUAL IN GAINING ACCESS TO THE PROTECTED AREA. REGION III WAS INVOLVED IN DISCUSSIONS PRIOR TO THIS RETRACTION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. R3DO(RING) WAS NOTIFIED.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 3

DOCKET: 05000423

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: CT

EN NUMBER: 25889

EVENT DATE: 08-05-93

EVENT TIME: 20:30

NOTIFY DATE: 08-05-93

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71
UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

3 N N O COLD SHUTDOWN O COLD SHUTDOWN

LICENSEE DISCOVERED SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. COMPENSATORY ACTIONS TAKEN UPON DISCOVERY. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2

DOCKET: 05000413 05000414

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

EMUMBER: 25890

EVENT DATE: 08-05-93

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

TIME: 23:30

OPS OFFICER: JACK LEWIS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
PWR
100 POWER OPERATION

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

MALFUNCTION OF TURNSTILE ALLOWS UNAUTHORIZED ENTRY.

WHILE CLEANING AT THE ENTRY PORTAL A JANITOR INADVERTENTLY BACKED THOUGH THE EXIT TURNSTILE. THE TURNSTILE SHOULD NOT HAVE ALLOWED ENTRY.

IT WAS DISCOVERED THAT THE TURNSTILE WAS DEFECTIVE.

THE TURNSTILE IS CURRENTLY BEING REPAIRED, THE JANITOR WAS IMMEDIATELY ESCORTED OUTSIDE THE PROTECTED AREA.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 25914

DOCKET: 05000331 EVENT DATE: 08-13-93

RX TYPE: BWR EVENT TIME: 12:10

VENDORS: GE-4 NOTIFY DATE: 08-13-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 14:04

OPS OFFICER: WILLIAM HUFFMAN 10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR

1 N N O REFUELING

UNSPECIFIED PARAGRAPH CURR CURRENT MODE PWR

0 REFUELING

PROTECTED AREA ACCESS REVOKED FOR PLANT WORKER.

AN INDIVIDUAL WHO HAD PREVIOUSLY BEEN GRANTED UNESCORTED ACCESS TO THE SITE ON A TEMPORARY BASIS WAS DENIED ACCESS WHEN IT WAS DETERMINED HE HAD AN UNREPORTED CRIMINAL HISTORY. SPECIFIC DENIAL OF ACCESS WAS DUE TO WILLFUL OMISSION OF PERTINENT INFORMATION. THE INDIVIDUAL WAS A CONTRACT LABORER AND THE CRIMINAL HISTORY DID NOT INDICATE THAT HE WOULD HAVE DONE ANYTHING TO AFFECT PLANT OPERATIONS. HOWEVER, A WORK REVIEW IS IN PROGRESS.

THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1

DOCKET: 05000309

RX TYPE: PWR

VENDORS: CE

EN NUMBER: 25941

EVENT DATE: 08-18-93

EVENT TIME: 18:38

NOTIFY DATE: 08-18-93

EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 20:50

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N O REFUELING O REFUELING

UNIT IS CURRENTLY DEFUELED. SAFEGUARDS SYSTEM DEGRADATION RELATED TO UNCOMPENSATED SECURITY ACCESS FOR THE CIRCULATING WATER PUMP HOUSE. MAINTENANCE PERSONNEL WERE PERFORMING WORK ON A 24 INCH SERVICE WATER PIPE WHICH REQUIRED THAT A SECURITY GUARD BE POSTED SINCE ACCESS TO THE CIRC WATER PUMP HOUSE FROM THE PROTECTED AREA WAS POSSIBLE WITH THE PIPE OPEN. AT 1405 EDT MAINTENANCE PERSONNEL STOPPED WORK AND INSTALLED A FLANGE.
AT 1838 EDT DURING ROUTINE ROUNDS SECURITY PERSONNEL DISCOVERED THAT MAINTENANCE PERSONNEL HAD RESUMED WORK WITHOUT NOTIFYING

THAT MAINTENANCE PERSONNEL HAD RESUMED WORK WITHOUT NOTIFYING SECURITY PERSONNEL. A SEARCH OF THE PUMP HOUSE WHICH IS ALSO INSIDE THE PROTECTED REVEALED NOTHING UNUSUAL. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

RIVER BEND 1 25969 08-24-93 POW

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 25969

DOCKET: 05000458 EVENT DATE: 08-24-93

RX TYPE: BWR EVENT TIME: 16:42

VENDORS: GE-6 NOTIFY DATE: 08-24-93

EMERGENCY CLASS: N/A RECION: 4 STATE: LA TIME: 18:26

OPS OFFICER: JOHN MacKINNON

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF THE LOSS OF SAFEGUARDS INFORMATION WHILE PERFORMING SAFEGUARD INVENTORY. LICENSEE IS STILL SEARCHING FILES FOR THE MISSING MATERIAL. THIS EVENT HAS NOT BEEN COMPENSATED FOR BECAUSE THEY HAVE NOT FOUND THE MISSING MATERIAL. SEE HOO LOG BOOK FOR FURTHER DETAILS.

RESIDENT INSPECTOR HAS BEEN INFORMED BY THE LICENSEE.

* * * UPDATE AT 1450 ON 09/08/93 BY MCQUIRTER ENTERED BY HOO JOLLIFFE * * *

AFTER REVIEWING AN INVENTORY LIST OF THE MISSING DOCUMENTS, LICENSEE HAS DETERMINED THAT THE INFORMATION CONTAINED IN THE MISSING DOCUMENTS IS

NOT SIGNIFICANT ENOUGH TO ASSIST ANYONE IN GAINING ACCESS TO THE PLANT PROTECTED AREA.

BASED ON THIS DETERMINATION, LICENSEE DESIRES TO RETRACT THIS EVENT.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED RADO MURRAY.

LICENSEE: NORTHERN STATES POWER CO.

EN NUMBER: 25979 SITE: MONTICELLO 1 DOCKET: 05000263 EVENT DATE: 08-26-93 EVENT TIME: 15:45 RX TYPE: BWR VENDORS: GE-3 NOTIFY DATE: 08-26-93 EMERGENCY CLASS: N/A REGION: 3 STATE: MN TIME: 17:40

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS INFORMATION FOUND IN AN UNCONTROLLED AREA. COMPENSATORY ACTIONS TAKEN UPON DISCOVERY. NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. SEE HOO LOG FOR DETAILS.

POINT BEACH 1 2 26006 09-01-93 POW

LICENSEE: WISCONSIN ELECTRIC POWER CO.

SITE: POINT BEACH 1 2 EN NUMBER: 26006 DOCKET: 05000266 05000301 EVENT DATE: 09-01-93 RX TYPE: PWR PWR EVENT TIME: 12:15

VENDORS: W-2-LP W-2-LP NOTIFY DATE: 09-01-93 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 14:02

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE SECURITY DEGRADATION CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA DOORS. NOT IMMEDIATELY COMPENSATED BUT COMPENSATED NOW. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

* * * UPDATE AT 1254 ON 09/16/93 FROM FENCEL TAKEN BY LEWIS * *

UPON FURTHER REVIEW OF THIS EVENT, THE LICENSEE HAS DOWNGRADED THE EVENT FROM A REPORTABLE SECURITY EVENT TO A LOGGABLE SECURITY EVENT SINCE CONTROLLED ACCESS TO THE SAFEGUARDS AREA HAD BEEN MAINTAINED DURING THIS EVENT.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R3DO MCCORMICKBARGER.

LICENSEE: WASHINGTON PUBLIC POWER SUPPLY SYST

SITE: WASHINGTON NUCLEAR 2 EN NUMBER: 26030 EVENT DATE: 09-07-93 DOCKET: 05000397 EVENT TIME: 06:32 RX TYPE: BWR NOTIFY DATE: 09-07-93 VENDORS: GE-5

EMERGENCY CLASS: N/A REGION: 5 STATE: WA TIME: 16:50

OPS OFFICER: DICK JOLLIFFE

APRE 50.72(b)(2)(vi) OFFSITE NOTIFICATION
RX INIT INITIAL MODE CURR CURRENT MODE
CRIT PWR 10 CFR SECTION: DDDD 73.71

UNIT SCRAM

CODE CRIT PWR

Y 100 POWER OPERATION 100 POWER OPERATION

- PLANT EMPLOYEE ATTEMPTED TO BRING A LOADED WEAPON INTO THE PLANT -

AT 0632 (PDT), WHILE REPORTING TO THE PLANT FOR WORK, A PLANT EMPLOYEE PLACED HIS WAIST PACK ON THE X-RAY MACHINE CONVEYOR BELT AT THE GUARD STATION. THE X-RAY MACHINE DETECTED A WEAPON INSIDE THE WAIST PACK.

THE WEAPON WAS A SMITH & WESSON .38 REVOLVER LOADED WITH 4 SHELLS.

SECURITY GUARDS CONFISCATED THE WEAPON AND SEARCHED THE EMPLOYEE AND HIS POSSESSIONS. NO OTHER WEAPONS OR SHELLS WERE FOUND.

SECURITY GUARDS WITHDREW THE EMPLOYEE'S PLANT ACCESS AUTHORIZATION

AND NOTIFIED THE BENTON COUNTY SHERIFF'S DEPARTMENT DUE TO A POSSIBLE VIOLATION OF A COUNTY ORDINANCE.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

SEE HOO LOG FOR ADDITIONAL DETAILS.

RIVER BEND 1 26070 09-16-93 POW

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 26070

DOCKET: 05000458 EVENT DATE: 09-16-93

RX TYPE: BWR EVENT TIME: 14:04

VENDORS: GE-6 NOTIFY DATE: 09-16-93

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 17:34

OPS OFFICER: JACK LEWIS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE DISCOVERED THAT 12 PAGES OF SAFEGUARDS INFORMATION WAS MISSING FROM THE SECURITY TRAINING FACILITY.

LICENSEE IS PERFORMING AN INVESTIGATION TO LOCATE THE MISSING PAGES AND DETERMINE THE REASON WHY THEY ARE MISSING.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1212EDT ON 10/05/93 FROM McQUIRTER TAKEN BY KARSCH * * *

THE LICENSEE DETERMINED THAT THE MISSING MATERIAL IS NOT "SAFEGUARDS" SENSITIVE WHEN OUT OF CONTEXT. THIS IS LOGGABLE VS. REPORTABLE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

 SITE: RIVER BEND 1
 EN NUMBER: 26123

 DOCKET: 05000458
 EVENT DATE: 09-27-93

 RX TYPE: BWR
 EVENT TIME: 12:45

 VENDORS: GE-6
 NOTIFY DATE: 09-27-93

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 14:40

OPS OFFICER: JACK LEWIS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

-SAFEGUARDS INFORMATION FILE CABINET FOUND UNLOCKED DURING INVENTORY-

DURING A SAFEGUARDS INVENTORY IN THE ADMINISTRATION BUILDING, THE SAFEGUARDS FILE CABINET WAS FOUND TO BE UNLOCKED AND THE CONTAINER INSIDE THE FILE CABINET WHICH CONTAINED SAFEGUARDS

DRAWINGS WAS OPEN. THE CONTAINER AND FILE CABINET WERE SECURED.

THE LICENSEE WILL INVENTORY THE FILE CABINET TO INSURE NOTHING IS

THE LICENSEE WILL NOTIFY HOO IF ANYTHING IS MISSING.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE ON 10/05/93 AT 1212 EDT FROM McQUIRTER TAKEN BY KARSCH * * * THE LICENSEE DETERMINED THAT THE MISSING MATERIAL IS NOT "SAFEGUARDS" SENSITIVE WHEN OUT OF CONTEXT. THIS IS LOGGABLE VS. REPORTABLE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

ROBINSON 2 26132 09-28-93 POW

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 26132 SITE: ROBINSON 2 EVENT DATE: 09-28-93 DOCKET: 05000261 EVENT TIME: 09:54 RX TYPE: PWR NOTIFY DATE: 09-28-93 VENDORS: W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 10:48

OPS OFFICER: JOHN MacKINNON UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

0 COLD SHUTDOWN N 0 COLD SHUTDOWN

MAIN POWER SUPPLY TO SECURITY COMPUTER FAILED AND THE BACKUP POWER SUPPLY FAILED TO PICK UP LOADS (BACKUP SECURITY DIESEL STARTED, PICKED UP LOADS AND THEN DUMPED ITS LOADS). LICENSEE LOST CAS/SAS. COMPENSATORY MEASURES WERE TAKEN WITHIN TEN MINUTES. BACKUP POWER SOURCE TO THE SECURITY COMPUTER WAS RESTORED AT 1017EDT AND IT IS STILL SUPPLYING POWER TO THE SECURITY COMPUTER.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

* * * UPDATE 10/01/93 1332EDT FROM: COOK BY: SCARFO * * * THE LICENSEE IS RETRACTING THIS EVENT ON THE BASIS THAT COMPENSATORY ACTIONS WERE TAKEN WITHIN THE REQUIRED SECURITY PLAN MINIMUM TIME PERIOD. THEREFORE, THE EVENT IS NOT REPORTABLE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R2DO (PEEBLES) NOTIFIED.

DRESDEN 2 3 26166 10-04-93 POW

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3 EN NUMBER: 26166 DOCKET: 05000237 05000249
RX TYPE: BWR BWR
VENDORS: GE-3 GE-3 EVENT DATE: 10-04-93 EVENT TIME: 11:37 NOTIFY DATE: 10-05-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 02:08

24

OPS OFFICER: CHAUNCEY GOJLD

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

N Y 97 POWER OPERATION

N Y 98 POWER OPERATION

98 POWER OPERATION

98 POWER OPERATION

THE LICENSEE REPORTED A SAFEGUARDS SYSTEM DEGRADATION OCCURRED DUE TO AN INCIDENT RELATED TO A VITAL AREA DOOR. COMPENSATORY MEASURES WERE TAKEN WITHIN 5 MINS AFTER ITS DISCOVEDY. SEE HOO LOG BOOK FOR DETAILS. THE RI WAS INFORMED.

UPDATE DATE :10/05/93 @ 0904 EDT *FROM LICENSEE:KUCZYNSKI
BY:MCGINTY**
THE LICENSEE RETRACTED THIS EVENT BASED ON THE DOOR NOT ACTUALLY
BEING IN A DEGRADED CONDITION, AND THEREFORE WOULD NOT ALLOW
UNAUTHORIZED ACCESS. SEE HOO LOG FOR DETAILS. THE LICENSEE
UNAUTHORIZED THE RESIDENT INSPECTOR. HOO NOTIFIED THE R3DO (MADERA).

LICENSEE: UNIVERSITY OF CINCINATTI

SITE: UNIVERSITY HOSPITAL

DOCKET:

RX TYPE:

VENDORS:

EMERGENCY CLASS: N/A REGION: 3 STATE: OH

TIME: 11:48

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DTHF 73.71(b) (1)

THEFT OF SNM

UNIVERSITY OF CINCINNATI HOSPITAL, CINCINNATI, OHIO

THE LICENSEE DISCOVERED THAT A SEALED STRONTIUM 90 BRACHYTHERAPY SOURCE CONTAINING 20.4 MILLI CURIES WAS MISSING FROM ITS NORMAL STORAGE LOCATION. THE LICENSEE DETERMINED AT 0940 EDT TODAY THAT THE SOURCE WAS MISSING AND PROBABLY STOLEN. THE SOURCE IS IN A WOODEN BOX WITH THE REQUIRED RADIATION MARKINGS.

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1

DOCKET: 05000346

RX TYPE: PWR

VENDORS: B&W-R-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: OH

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF CRIMINAL ACT INVOLVING INDIVIDUAL GRANTED ACCESS. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WAS INFORMED.

* * * UPDATE FROM BRADLEY ON 10/29/93 AT 1625 TO LEWIS * * *

DISCOVERY OF CRIMINAL ACT OF SAME TYPE INVOLVING ANOTHER INDIVIDUAL. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WILL BE NOTIFIED

NOTIFIED R3DO PEDERSON

LICENSEE: BOSTON EDISON CO.

EN NUMBER: 26274 SITE: PILGRIM 1 EVENT DATE: 10-27-93 DOCKET: 05000293 EVENT TIME: 08:28 RX TYPE: BWR NOTIFY DATE: 10-27-93 VENDORS: GE-3 EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 09:22

OPS OFFICER: JOHN MacKINNON

OPS OFFICER: JOHN MACKINNON

10 CFR SECTION: DUNE 73.71(b)(1)

UNAUTHORIZED ENTRY

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

ATTEMPTED INTRODUCTION OF A WEAPON INTO PROTECTED AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY.

LICENSEE BELIEVES THAT THE INDIVIDUAL INVOLVED DID NOT KNOW THAT HE WAS CARRYING AN UNLOADED WEAPON IN HIS BAG WHEN IT WAS FOUND BY SECURITY WHEN THEY X-RAYED HIS CARRYING BAG BEFORE HE ENTER PROTECTED AREA. LONG TIME PLANT EMPLOYEE IS BEING INTERVIEWED OFFSITE BY PLANT SECURITY.

RESIDENT INSPECTOR WILL BE INFORMED BY LICENSEE.

26295 11-02-93 POW HATCH 1 2

LICENSEE: GEORGIA POWER CO.

EN NUMBER: 26295 SITE: HATCH 1 2 DOCKET: 05000321 05000366 EVENT DATE: 11-02-93 VENDORS: GE-4 GE-4 EVENT TIME: 06:50 NOTIFY DATE: 11-02-93

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 07:53 OPS OFFICER: TIM MCGINTY

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 96 POWER OPERATION 96 POWER OPERATION 2 N Y 85 POWER OPERATION 85 POWER OPERATION

ATTEMPTED INTRODUCTION OF CONTRABAND (LOADED PISTOL) INTO THE PROTECTED AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY AT THE PROTECTED AREA X-RAY MACHINE. THE LICENSEE INITIALLY DOES NOT CONSIDER THE OCCURRENCE TO BE SIGNIFICANT. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

* * * UPDATE AT 1405 ON 11/11/93 BY REED ENTERED BY HOO JOLLIFFE

LICENSEE HAS COMPLETED THE INVESTIGATION INTO THIS EVENT AND HAS DETERMINED THAT THERE IS NO EVIDENCE THAT THE INDIVIDUAL HAD ANY MALEVOLENT INTENT OR HAD ATTEMPTED TO POSE A THREAT TO PLANT SECURITY AND THAT NO SUCH THREAT HAD EXISTED.

LICENSEE HAS FURTHER DETERMINED THAT, IN ACCORDANCE WITH THE GUIDANCE CONTAINED IN NRC GENERIC LETTER 91-03, ENCLOSURE 1, THIS EVENT IS
NOT REPORTABLE TO THE NRC AND THUS DESIRES TO RETRACT THIS EVENT.

LICENSEE HAS RECORDED THIS EVENT IN THEIR PLANT LOG.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R2DO VIAS.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2

DOCKET: 05000373 05000374

RX TYPE: BWR BWR

VENDORS: GE-5 GE-5

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0

SAFEGUARDS SYSTEM DEGRADATION RELATED TO PERIMETER BOUNDARY. COMPENSATORY MEASURES WERE IMMEDIATELY TAKEN UPON DISCOVERY.

SEE HOO LOG BOOK FOR FURTHER DETAILS.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1 2 3 EN NUMBER: 26316

DOCKET: 05000528 05000529 05000530 EVENT DATE: 11-04-93

RX TYPE: PWR PWR PWR EVENT TIME: 14:30

VENDORS: CE80 CE80 CE80 NOTIFY DATE: 11-04-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 17:27

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

DSAF 73.71(b)(1) SECURITY DEGRADATION

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

COLE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N Y 85 POWER OPERATION 85 POWER OPERATION

TWO INDIVIDUALS WERE GRANTED UNESCORTED ACCESS BASED ON FALSIFIED RECORDS AND AN INCOMPLETE BACKGROUND INVESTIGATION.

THE LICENSEE HAS DETERMINED THAT UNESCORTED ACCESS WOULD NOT HAVE BEEN GRANTED IF A COMPLETE AND PROPER INVESTIGATION HAD BEEN COMPLETED. A PRELIMINARY INVESTIGATION BY THE LICENSEE INTO THE EMPLOYMENT CERTIFICATION PROGRAM USED BY THEIR SUBCONTRACTOR HAS REVEALED SEVERAL DISCREPANCIES. IN ADDITION, OTHER INDIVIDUALS (APPROX 15) CERTIFIED BY THE SUBCONTRACTOR HAVE HAD THEIR UNESCORTED ACCESS REVOKED AND HAVE BEEN ESCORTED OFF SITE. INDIVIDUALS WERE WORKING INSIDE THE UNIT 1 CONTAINMENT ON STEAM GENERATOR TUBE PLUGGING AND REMOVAL. THE LICENSEE WILL DETERMINE THE IMPACT THESE INDIVIDUALS MAY HAVE HAD ON PLANT SAFETY SO APPROPRIATE CORRECTIVE MEASURES CAN BE TAKEN. THE LICENSEE HAS INFORMED THE REGION 5 SAFEGUARDS BRANCH INSPECTOR (SCHAEFER) AND WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 EN NUMBER: 26349 DOCKET: 05000275 05000323 EVENT DATE: 11-10-93 VENDORS: W-4-LP W-4-LP EVENT TIME: 18:50 NOTIFY DATE: 11-10-93 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 22:49

OPS OFFICER: THOMAS ANDREWS 10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY DDDD 73.71 UNSPECIFIED PARAGRAPH
RX INIT INITIAL MODE CURR CURRENT MODE UNIT SCRAM CODE CRIT PWR PWR 1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

BASED ON AN ALLIGATION REGARDING A NON-LICENSED, NON-SUPERVISORY EMPLOYEE POSSESSING AN ILLEGAL DRUG INSIDE THE DIABLO CANYON PROTECTED AREA, A CORPORATE SECURITY INVESTIGATION WAS CONDUCTED. AT APPROXIMATELY 1850 PST, THE LICENSEE DETERMINED BASED ON AN INTERVIEW WITH THE SUBJECT EMPLOYEE AND AFTER CONSULTING WITH SECURITY MANAGEMENT THAT THE ALLEGATION WAS VALID.

THE EMPLOYEE ADMITTED TO POSSESSING A PRESCRIPTION MEDICATION (DARVOCET) WHILE IN THE PROTECTED AREA AND ADMITTED TO GIVING SOME OF THE DRUG TO A CO-WORKER. DARVOCET IS A SCHEDULE 4 CONTROLLED SUBSTANCE. THE LICENSEE FURTHER ADDED THAT THE EMPLOYEE HAD MULTIPLE PRESCRIPTIONS FOR DARVOCET.

THE SUBJECT EMPLOYEE AND THE CO-WORKER WHO RECEIVED THE DRUG FROM THE SUBJECT EMPLOYEE HAVE HAD THEIR ACCESS SUSPENDED PENDING FURTHER ACTION FROM THE LICENSEE.

THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR. NO OTHER NOTIFICATIONS ARE PLANNED AT THIS TIME.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1

DOCKET: 05000528

RX TYPE: PWR

VENDORS: CE80

EN NUMBER: 26351

EVENT DATE: 11-11-93

EVENT TIME: 07:00

NOTIFY DATE: 11-11-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ

TIME: 10:04

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N O COLD SHUTDOWN O COLD SHUTDOWN

INDIVIDUAL GRANTED ACCESS BASED ON FALSIFIED RECORDS AND INCOMPLETE BACKGROUND INVESTIGATION.

BASED ON PREVIOUS DEFICIENCIES IN THE EMPLOYMENT CERTIFICATION PROGRAM USED BY A PLANT VENDOR (B&W), THE LICENSEE (ARIZONA PUBLIC SERVICE) SENT AN AUDIT TEAM TO THE VENDOR'S SITE FOR FOLLOWUP INVESTIGATIONS. THE INVESTIGATION REVEALED THAT AN INDIVIDUAL CURRENTLY WORKING AT THE PLANT WOULD NOT HAVE BEEN GRANTED UNESCORTED ACCESS BASED ON HIS PREVIOUS WORK HISTORY AND THAT HE HAD FALSIFIED HIS EMPLOYMENT RECORDS.

THE INDIVIDUAL'S UNESCORTED ACCESS HAS BEEN REVOKED. THE INDIVIDUAL IS NOT CURRENTLY ON SITE AND HAS NOT YET BEEN INFORMED OF THE LICENSEE'S ACTION.

A WORK REVIEW OF THE INDIVIDUAL IS IN PROGRESS. THE LICENSEE NOTES THAT THIS INDIVIDUAL HAS WORKED AT A NUMBER OF NUCLEAR POWER PLANTS UNDER THE FALSIFIED RECORDS AND THAT THOSE UTILITIES HAVE BEEN NOTIFIED OF THESE FINDINGS.

THE NRC RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

SEE RELATED EVENT #26316.

* * * UPDATE ON 11/16/93 AT 2013 EST FROM NAPIER TAKEN BY KARSCH * * *

THE LICENSEE REVIEWED THE RESULTS OF AN AUDIT CONDUCTED AT THE VENDOR FACILITY. BASED ON THE PRELIMINARY FINDINGS AND THE INSTANCES PREVIOUSLY REPORTED, THE LICENSEE HAS CONCLUDED THAT OTHER INDIVIDUALS' ACCESS AUTHORIZATION BY THE VENDOR MAY HAVE SIMILAR DISCREPANCIES. THE LICENSEE IS IN THE PROCESS OF TERMINATING UNESCORTED ACCESS FOR THE REMAINING 75 INDIVIDUALS WHO WERE CERTIFIED BY THE VENDOR PENDING INDEPENDENT REVIEW. THESE INDIVIDUALS WILL BE ESCORTED OFF SITE AS NECESSARY. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR AND HAS REPORTED THE RESULTS OF THEIR AUDIT TO REGION 5. R5DO (WENSLAWSKI) NOTIFIED.

LICENSEE: SOUTHERN NUCLEAR OPERATING COMPANY

SITE: FARLEY 1 2 EN NUMBER: 26352

DOCKET: 05000348 05000364 EVENT DATE: 11-11-93 EVENT TIME: 11:20 VENDORS: W-3-LP W-3-LP NOTIFY DATE: 11-11-93 EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 12:57 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

UNSPECIFIED PARAGRAF UNSPECIFIED PARAGRAPH N Y 100 POWER OPERATION 100 POWER OPERATION N N 0 REFUELING 0 REFUELING

LICENSEE WITHDREW TEMPORARY PLANT ACCESS AUTHORIZATION OF A CONTRACTOR EMPLOYEE IN ACCORDANCE WITH THE REQUIREMENTS OF 10CFR73, APPENDIX G, DUE TO FALSIFICATION OF RECORDS.

SEE HOO LOG FOR DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

26386 11-18-93 POW ZION 1 2

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2 EN NUMBER: 26386 DOCKET: 05000295 05000304
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP EVENT DATE: 11-18-93 EVENT TIME: 22:11 NOTIFY DATE: 11-19-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 00:06

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

CODE CRIT PWR
N N 0 REFUELING 0 REFUELING
N N 0 REFUELING 0 REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR. NO OTHER LICENSEE NOTIFICATIONS ARE PLANNED AT THIS TIME. SEE HOO LOG FOR DETAILS.

UPDATE @ 1759EST 11/19/93 BY DAVID COMBS TAKEN BY MACKINNON

LICENSEE IS RETRACTING THIS EVENT. ON FURTHER REVIEW OF THE ABOVE EVENT THE BARRIER OPENING DID NOT EXCEED THE CRITERIA THAT WOULD ALLOW UNAUTHORIZED ACCESS. LICENSEE DISCUSSED THIS EVENT WITH REGION JIM CREED BEFORE RETRACTING THIS EVENT. R3DO (BRUCE JORGENSEN) NOTIFIED.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1

EN NUMBER: 26393

EVENT DATE: 11-19-93 DOCKET: 05000458 EVENT TIME: 20:57 RX TYPE: BWR NOTIFY DATE: 11-20-93 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 01:56

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR

N Y 99 POWER OPERATION 99 POWER OPERATION

POSSIBLE COMPROMISE OF SAFEGUARDS MATERIAL.

SAFEGUARDS MATERIAL WAS FOUND OPEN AND UNATTENDED IN A MAIL ROOM OUTSIDE OF THE PROTECTED AREA. AT 21:20 CST, AN INVENTORY WAS PERFORMED AND ALL MATERIAL WAS ACCOUNTED FOR. REPORTABILITY WAS DETERMINED AT 23:59 CST, IN ACCORDANCE WITH REG GUIDE 5.62, PARAGRAPH 17. AN INVESTIGATION HAS BEEN INITIATED. THE NRC RESIDENT WILL BE NOTIFIED BY THE LICENSEE.

SEE HOO LOG FOR DETAILS.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 2 3 EN NUMBER: 26408 DOCKET: 05000361 05000362 EVENT DATE: 11-22-93 EVENT TIME: 21:07 RX TYPE: PWR PWR NOTIFY DATE: 11-23-93 VENDORS: CE CE EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 01:21

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
2 N Y 100 POWER OPERATION 100 POWER OPERATION
3 N N 0 REFUELING 0 REFUELING

UNSUBSTANTIATED BOMB THREAT.

THE SAN DIEGO SHERIFF'S DEPARTMENT INFORMED THE LICENSEE OF A BOMB THREAT RECEIVED BY THE DEPARTMENT AND DIRECTED AT THE SAN ONOFRE NUCLEAR POWER PLANT. THE INDIVIDUAL CALLING IN THE THREAT GAVE HIS NAME AND PHONE NUMBER TO THE TELEPHONE DISPATCHER THAT RECEIVED THE CALL.

THE LICENSEE TOOK IMMEDIATE COMPENSATORY MEASURES AND CONTACTED THE LOCAL FBI. THE FBI WAS AWARE OF THE INDIVIDUAL AND NOTED THAT HE HAS PSYCHOLOGICAL PROBLEMS AND A PREVIOUS HISTORY OF MAKING FALSE BOMB REPORTS. THE LICENSEE CLASSIFIED THE THREAT AS UNSUBSTANTIATED AND SECURED FROM COMPENSATORY ACTIONS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEF: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3

DOCKET: 05000286

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NY

OPS OFFICER: RUDY KARSCH
10 CFR SECTION: DTHR 73.71(c)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

3 N N 0 COLD SHUTDOWN

EVENT DATE: 12-06-93

EVENT TIME: 11:04

NOTIFY DATE: 12-06-93

EVENT TIME: 11:14

NOTIFY DEGRADATION

CURR CURRENT MODE

PWR

PWR

O COLD SHUTDOWN

A CIVIL DISTURBANCE NEAR THE PLANT SITE WHICH MAY POSE A THREAT TO THE FACILITY.

A DEMONSTRATION BY ABOUT 25 PEOPLE AT THE SITE GATE IS PROTESTING A DECISION TO STORE ALL OF NEW YORK STATE'S LOW LEVEL RADIOACTIVE WASTE AT INDIAN POINT 3. THERE HAS BEEN NO THREAT OF VIOLENCE. LOCAL POLITICIANS ARE IN ATTENDANCE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: OCONEE 1 2 3

DOCKET: 05000269 05000270 05000287

RX TYPE: PWR PWR PWR

VENDORS: B&W-L-LP B&W-L-LP B&W-L-LP

VENDORS: B&W-L-LP B&W-L-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

3 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE DISCOVERED A COMPROMISE OF SAFEGUARDS INFORMATION. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN. SEE HOO LOG BOOK FOR DETAILS. THE RI WAS INFORMED.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2

DOCKET: 05000325 05000324

RX TYPE: BWR BWR

VENDORS: GE-4 GE-4

EVENT DATE: 12-25-93

EMERGENCY CLASS: UNU REGION: 2 STATE: NC

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: AAEC 50.72(a)(1)(i)

DTHR 73.71(c)

DTHR 73.71(c)

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

2 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY RECEIVED A BOMB THREAT PHONE CALL. SECURITY DECLARED A SECURITY ALERT PER THEIR CONTINGENCY PLANS AT 1409EST. LICENSEES EMERGENCY PLANS HAVE THEM ENTER AN UNUSUAL EVENT CLASSIFICATION WHEN SECURITY GOES INTO ALERT. ALL AREAS ARE BEING SEARCHED AT THIS TIME. INITIAL SAFETY SIGNIFICANCE OF THIS EVENT IS MINIMAL. LICENSE HAS NOTIFIED STATE AND LOCAL OFFICIALS OF THIS EVENT. THEY WILL INFORM THE FBI OF THE BOMB THREAT.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

UPDATE @ 1603EST BY DENISE GREENWALT TAKEN BY MACKINNON UNUSUAL EVENT TERMINATED AT 1555EST AFTER SEARCH OF PLANT FOUND

STATE & LOCAL OFFICIALS WERE NOTIFIED BY LICENSEE. R2DO (PIERCE SKINNER), EO (BRIAN GRIMES), & FEMA (MOSTELLER) NOTIFIED.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

26538 12-25-93 POW FERMI 2

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 26538 EVENT DATE: 12-25-93 DOCKET: 05000341 EVENT TIME: 14:45 RX TYPE: BWR NOTIFY DATE: 12-25-93 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 16:12

OPS OFFICER: JOHN MacKINNON 10 CFR SECTION: DTHR 73.71(c) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N 0 HOT SHUTDOWN 0 HOT SHUTDOWN N

SECURITY SUSPENDED ACCESS REQUIREMENTS AT 1445 EST DUE TO EVENT (SEE EVENT # 26536 FOR BACKGROUND INFORMATION). SOME PERSONNEL RESPONDING TO PLANT EMERGENCY MAY NOT HAVE BEEN SEARCHED. COMPENSATORY MEASURES ARE BEING TAKEN. SEE HOO LOG BOOK FOR DETAILS.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

* * * UPDATE 01/19/94 0917EST FROM: HOSKINS BY: SCARFO * * * THIS EVENT IS BEING RETRACTED ON THE BASIS THAT NO ACTUAL DEGRADATION OF PHYSICAL SECURITY AND THAT ALARMS FROM VITAL AREA DOORS WERE CAUSED BY RESPONDING TO EMERGENCY PERSONNEL. WITH NO DEGRADATION OF SECURITY, NO NOTIFICATION IS REQUIRED. REGION III HAS BEEN NOTIFIED. R3DO (DeFAYETTE) NOTIFIED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

Query: EN1994:73.71

26815 02-18-94 POW WATERFORD 3

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 26815 SITE: WATERFORD 3 EVENT DATE: 02-18-94 DOCKET: 05000382 RX TYPE: PWR EVENT TIME: 14:30 NOTIFY DATE: 02-18-94 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 16:28

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

NUCLEAR FUEL HANDLING EQUIPMENT RELATED PHYSICAL SECURITY EVENT REPORTED IN ACCORDANCE WITH 10CFR73.71(b)(1) & 10CFR73, APPENDIX G, PARAGRAPH I(a)(2).

SEE HOO LOG FOR DETAILS.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

UPDATE ON 3/9/94 @ 14:28 BY BECKER TO GOULD THE LICENSEE IS RETRACTING THIS EVENT SINCE AN INVESTIGATION DETERMINED THAT THERE WAS NO DAMAGE TO THE ENCAPSULATION TUBE OR TO ANY FUEL IN THE SPENT FUEL POOL AROUND THE THE STORAGE LOCATION OF THE ENCAPSULATION TUBE. THERE WAS ALSO NO EVIDENCE THAT THE UNAUTHORIZED LIFT WAS INTENTIONAL. AN INVENTORY OF THE SPENT FUEL POOL WAS PERFORMED AND ALL CONTENTS WERE ACCOUNTED FOR. THE LICENSEE WILL, HOWEVER, SUBMIT A VOLUNTARY LER. THE RI WILL BE INFORMED.

REG 4 WESTERMAN WAS NOTIFIED.

LICENSEE: ROCHESTER GAS & ELECTRIC CORP.

EN NUMBER: 26827 SITE: GINNA 1 DOCKET: 05000244 EVENT DATE: 02-22-94 EVENT TIME: 02:45 RX TYPE: PWR NOTIFY DATE: 02-22-94 VENDORS: W-2-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 03:15 OPS OFFICER: STEVE SANDIN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N Y 98 POWER OPERATION 98 POWER OPERATION

THE LICENSEE DISCOVERED THAT TWO OF THE FIVE OFFSITE ACCESS BADGES PROVIDED CLEANING PERSONNEL WOULD IMPROPERLY ALLOW ACCESS TO VITAL AREAS. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS.

FERMI 2

26836 02-24-94 POW

LICENSEE: DETROIT EDISON CO.

EN NUMBER: 26836 SITE: FERMI 2 DOCKET: 05000341 EVENT DATE: 02-24-94 RX TYPE: BWR EVENT TIME: 00:01 NOTIFY DATE: 02-24-94 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 00:49

OPS OFFICER: TIM MCGINTY UNSPECIFIED PARAGRAPH

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAMUNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N N O COLD SHUTDOWN O COLD SHUTDOWN

DEMONSTRATION AT SITE, ON ACCESS DRIVE TO THE MAIN GATE.

IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY.

LICENSEE MAY ISSUE A PRESS RELEASE, AND WILL INFORM THE RESIDENT "NSPECTOR.

SEE HOO LOG FOR DETAILS.

** UPDATE DATE/TIME:2/24/94 AT 0204 EST*FROM: HEITZENRATER ALL OF THE DEMONSTRATORS HAVE LEFT THE SITE. R3DO (SNELL) NOTIFIED.

* * * UPDATE 03/09/94 0914EST FROM: NADER BY: SCARFO * * * THE FOLLOWING IS A PORTION OF THE TEXT OF A FACSIMILE SUBMITTED BY THE LICENSEE:

"UPON FURTHER REVIEW OF 10CFR73 APPENDIX G PARAGRAPH I(a)(2) OR (3) AND REGULATORY GUIDE 5.62 SECTIONS 2.2.9 AND 2.2.10 IT WAS DETERMINED THAT BECAUSE THE PROTESTORS DID NOT POSE ANY THREAT TO THE OPERATION OF THE PLANT THAT THE EVENT DID NOT MEET THE CRITERIA ESTABLISHED FOR A ONE HOUR REPORT.

BASED ON THIS REVIEW, DETROIT EDISON IS RETRACTING THE ONE HOUR 10CFR73.71 NOTIFICATION MADE ON 2-24-94." END OF TEXT.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R3DO(HAGUE) NOTIFIED.

26878 03-04-94 POW WATERFORD 3

LICENSEE: ENTERGY OPERATIONS INC.

SITE: WATERFORD 3 EN NUMBER: 26878 EVENT DATE: 03-04-94 DOCKET: 05000382 RX TYPE: PWR EVENT TIME: 02:20 NOTIFY DATE: 03-04-94 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 04:23

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DCTB 73.71(b)(1) CONTRABAND

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRABAND FOUND IN A FILE CABINET IN THE PROTECTED AREA. THIS CONTRABAND WAS FOUND DURING A ROUTINE SAFETY TOUR. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN ON DISCOVERY. LICENSEE DOES NOT CONSIDER THE ABOVE EVENT TO BE A THREAT TO THE PLANT. SEE HOO LOG FOR FURTHEP DETAILS.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

RETRACTION FROM LICENSEE:SCOTT TO NRC:HUFFMAN AT 1503 EST ON 3/24/93
BASED ON REVIEW OF GENERIC LETTER 91-03, "REPORTING OF SAFEGUARDS EVENTS", THE LICENSEE HAS CONCLUDED THAT THE CONTRABAND FOUND WITHIN THE PROTECTED AREA WAS NOT REPORTABLE. THEREFORE, THE LICENSEE IS RETRACTING THIS EVENT. THE EVENT HAS BEEN LOGGED AND SHALL BE SUBMITTED TO THE NRC AS REQUIRED BY 10 CFR 73.71.C.2. SEE THE HOO LOG FOR ADDITIONAL DETAILS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. R4DO (MURRAY) INFORMED.

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1

DOCKET: 05000346

RX TYPE: PWR

VENDORS: B&W-R-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: OH

EN NUMBER: 26926

EVENT DATE: 03-11-94

EVENT TIME: 16:00

NOTIFY DATE: 03-11-94

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

A REVOLVER WAS DISCOVERED TO BE MISSING FROM THE ARMORY DURING A WEEKLY INSPECTION.

AT ABOUT 12:00 ET 3/11/94, A NUCLEAR SHIFT SECURITY SUPERVISOR, WHILE PERFORMING A WEEKLY OPERATING INSPECTION FOR REVOLVERS, DISCOVERED THAT ONE OF THE SPARE WEAPONS WAS MISSING. A SEARCH OF THE ARMORY WAS CONDUCTED WITHOUT LOCATING THE WEAPON. SECURITY WEAPONS HAVE BEEN VERIFIED AGAINST AN INVENTORY LIST. COMPENSATORY ACTIONS INCLUDE INCREASING THE SEARCH OF OUT GOING PACKAGES FROM THE PROTECTED AREA WITH A METAL DETECTOR. THE LAST INVENTORY WAS CONDUCTED ON 3/4/94 AND ALL WEAPONS WERE VERIFIED. THE LICENSEE HAS ALSO STATIONED A SECURITY GUARD IN THE CONTROL ROOM.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR AND REGION III PERSONNEL (PIRTLE AND CREED). THE LICENSEE WILL ALSO INFORM LOCAL LAW ENFORCEMENT AGENCIES IF THE WEAPON IS NOT FOUND.

LICENSEE: WISCONSIN ELECTRIC POWER CO.

SITE: POINT BEACH 1 2 EN NUMBER: 26982 DOCKET: 05000266 05000301
RX TYPE: PWR PWR
VENDORS: W-2-LP W-2-LP
EMERGENCY CLASS W/2 EVENT DATE: 03-23-94 EVENT TIME: 16:13 NOTIFY DATE: 03-23-94 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 21:17 OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE

CURR CURRENT MODE

PWR

CODE CRIT PWR N Y 98 POWER OPERATION 98 POWER OPERATION N Y 97 POWER OPERATION 97 POWER OPERATION

A SAFEGUARD SYSTEM DEGRADATION RELATED TO DETECTION EXISTED FOR APPROXIMATELY 26 MINUTES. THE PROBLEM WAS CORRECTED UPON DISCOVERY. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

FARLEY 1 2 27023 03-30-94 POW

LICENSEE: SOUTHERN NUCLEAR OPERATING COMPANY

SITE: FARLEY 1 2 EN NUMBER: 27023

DOCKET: 05000348 05000364 EVENT DATE: 03-30-94 EVENT TIME: 22:41

RX TYPE: PWR PWR VENDORS: W-3-LP W-3-LP NOTIFY DATE: 03-31-94

EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 00:34

OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 REFUELING 0 REFUELING
2 N Y 99 POWER OPERATION 99 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO DETECTION WAS DISCOVERED TO HAVE EXISTED FOR APPROXIMATELY 6 HOURS. COMPENSATORY ACTIONS TAKEN IMMEDIATELY UPON DISCOVERY. SEE HOO LOG FOR DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

* * * UPDATE AT 1614 EST ON 3/31/93 FROM JOHNSON TAKEN BY KARSCH

BASED ON DISCUSSIONS OF THIS EVENT WITH REGION 2 (TILLMAN) IT WAS DETERMINED THAT THIS EVENT NEED NOT HAVE BEEN REPORTED TO THE NRC OPERATIONS CENTER AS A ONE HOUR REPORT. THEREFORE, THE LICENSEE IS RETRACTING THIS REPORT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R2DO (HOSEY) NOTIFIED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2 EN NUMBER: 27088 DOCKET: 05000295 05000304 EVENT DATE: 04-12-94

EVENT TIME: 22:25 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 04-13-94 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 00:16 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

CONTRACTOR DISCOVERED UNESCORTED FOR 15 MINUTES IN THE PROTECTED AREA. COMPENSATORY MEASURES WERE IMMEDIATELY TAKEN. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

EN NUMBER: 27094 SITE: MAINE YANKEE 1 EVENT DATE: 04-14-94 DOCKET: 05000309 EVENT TIME: 12:15 RX TYPE: PWR NOTIFY DATE: 04-14-94 VENDORS: CE EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 12:42

OPS OFFICER: STEVE SANDIN UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

UNACCOUNTED FOR SECURITY ACCESS KEYS. NOT FULLY COMPENSATED. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER CORPORATION

EN NUMBER: 27099 SITE: CRYSTAL RIVER 3 EVENT DATE: 04-15-94 DOCKET: 05000302 EVENT TIME: 10:00 RX TYPE: PWR NOTIFY DATE: 04-15-94 VENDORS: B&W-L-LP EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 10:37

OPS OFFICER: DOUG WEAVER

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

N N O REFUELING 0 REFUELING

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AN AREA BOUNDARY. IMMEDIATE COMPENSATORY ACTIONS WERE TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

EN NUMBER: 27110 SITE: RIVER BEND 1 EVENT DATE: 04-17-94 DOCKET: 05000458 EVENT TIME: 16:43 RX TYPE: BWR NOTIFY DATE: 04-17-94 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 18:21

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 10 CFR SECTION: DDDD 73.71
UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

LICENSEE DISCOVERED THAT A CONTRACT EMPLOYEE WITH PROTECTED AREA ACCESS HAD FALSIFIED EMPLOYMENT APPLICATION. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS.

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 27126 SITE: HARRIS 1 EVENT DATE: 04-20-94 DOCKET: 05000400 EVENT TIME: 05:55 VENDORS: W-3-LP NOTIFY DATE: 04-20-94

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 10:45

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71

UNSPECIFIED PARAGRAPH
INFORMATION ONLY

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

N N 0 REFUELING

CODE CRIT PWR

REFUELING

O REFUELING

ATTEMPTED INTRODUCTION OF CONTRABAND INTO PROTECTED AREA.

A LOADED REVOLVER WAS FOUND IN THE LUNCH BOX OF A CONTRACT WORKER AS HE ATTEMPTED TO ENTER THE PROTECTED AREA. THE INDIVIDUAL WAS IMMEDIATELY APPREHENDED AND TURNED OVER TO THE WAKE COUNTY SHERIFF'S DEPARTMENT. THE LICENSEE BELIEVES THAT THERE WAS NO MALEVOLENT INTENT INVOLVED. THE INDIVIDUAL CLAIMS THAT HE FORGOT THAT THE WEAPON WAS IN HIS LUNCH BOX. HIS PROTECTED AREA ACCESS HAS BEEN REMOVED.

THE LICENSEE HAS NOTIFIED THE RESIDENT INSPECTOR AND THE REGION II SECURITY BRANCH.

SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2 EN NUMBER: 27220 EVENT DATE: 05-07-94 DOCKET: 05000295 05000304 RX TYPE: PWR PWR EVENT TIME: 21:55
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 05-07-94

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 23:47

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DDDD 73.71 10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N Y 100 POWER OPERATION 100 POWER OPERATION

A BUS DUCT PENETRATION COVER PLATE WAS REMOVED PROVIDING AN ENTRY PATH INTO THE TURBINE BUILDING. THE ENTRY PATH EXISTED WITHOUT A SECURITY GUARD POSTED FOR LESS THAN ONE HOUR. THE COVER PLATE WAS REPLACED AT 2236 CDT. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

27234 05-11-94 POW QUAD CITIES 1 2

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 27234 SITE: QUAD CITIES 1 2 DOCKET: 05000254 05000265 RX TYPE: BWR BWR EVENT DATE: 05-11-94 EVENT TIME: 20:51 NOTIFY DATE: 05-11-94 VENDORS: GE-3 GE-3 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 22:52

OPS OFFICER: JOSEPH SEBROSKY

OPS OFFICER: JOSEPH SEBROSKY
10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N 0 REFUELING 0 REFUELING
N Y 97 POWER OPERATION 97 POWER OPERATION

SAFEGUARDS SYSTEMS DEGRADATION RELATED TO DETECTION EXISTED FROM 20:51 TO 21:40. DURING THIS TIME COMPENSATORY ACTIONS WERE IN PLACE, HOWEVER, THE SECURITY ADMINISTRATOR HAS RAISED A QUESTION AS TO WHETHER OR NOT THE COMPENSATORY ACTIONS WERE OF AN EQUIVALENT LEVEL OF PROTECTION. SEE HOO LOG FOR FURTHER DETAILS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

* * * UPDATE @ 15:52 5/12/94 FROM LEECH TAKEN BY SEBROSKY * * * THE LICENSEE IS RETRACTING THIS EVENT. UPON FURTHER REVIEW THE LICENSEE HAS DETERMINED THAT THE EVENT IS A 24 HOUR LOGGABLE EVENT AND NOT A 1 HOUR REPORTABLE EVENT. THE LICENSEE HAS DISCUSSED THIS WITH REGION III (CREED) AND THE SENIOR RESIDENT INSPECTOR.

HOO NOTIFIED R3DO (GROBE) .

27272 05-19-94 POW DIABLO CANYON 1 2

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2
DOCKET: 05000275 05000323
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP EN NUMBER: 27272 EVENT DATE: 05-19-94 EVENT TIME: 02:07 NOTIFY DATE: 05-19-94

EMERGENCY CLASS: N/A REGION: 4 STATE: CA TIME: 05:27

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE IS INVESTIGATING THE ALLEGATION THAT A SECURITY

OFFICER WAS ASLEEP AT HIS POST ON 4/28/94. THERE IS NO EVIDENCE OF UNAUTHORIZED ENTRY AT THE SITE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

*** UPDATE DATE/TIME:06/03/94**FROM LICENSEE:HUBBLE BY: McGINTY***

THE LICENSEE IS RETRACTING THIS EVENT BASED ON THE INABILITY TO OBTAIN AN INDEPENDENT VERIFICATION THAT THE GUARD WAS ACTUALLY SLEEPING. THE LICENSEE HAS INFORMED BOTH THE REGION (DENNIS SCHAEFER) AND THE RESIDENT INSPECTOR. HOO NOTIFIED THE RADO (STETKA) .

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 2 EN NUMBER: 27291 DOCKET: 05000313 05000368

RX TYPE: PWR PWR

VENDORS: B&W-L-LP CE EVENT DATE: 05-23-94 EVENT TIME: 12:55 VENDORS: B&W-L-LP CE NOTIFY DATE: 05-23-94 EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 14:48

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DUNE 73.71(b)(1) UNAUTHORIZED ENTRY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED CONTRACT EMPLOYEE WAS DISCOVERED TO HAVE FALSIFIED HIS EMPLOYMENT APPLICATION. THE LICENSEE IS MAKING THIS REPORT IN ACCORDANCE WITH 10CFR 50.73 APPENDIX G PARAGRAPH 1.C.

FBI INFORMATION WAS RECEIVED THAT CONFLICTED WITH THE EMPLOYMENT APPLICATION. THE EMPLOYEE'S INFORMATION NOTED THAT THE EMPLOYEE HAD A MISDEMEANOR ARREST FOR NARCOTICS POSSESSION AND THE FBI RECORDS INDICATE THAT THE INDIVIDUAL WAS ARRESTED FOR A FELONY POSSESSION.

THE LICENSEE HAS REVOKED UNESCORTED ACCESS TO THE SITE AS OF TODAY. (THE INDIVIDUAL'S UNESCORTED ACCESS WAS ORIGINALLY GIVEN ON 3/29/94.) THE INDIVIDUAL WAS NOT INVOLVED IN SAFETY RELATED WORK. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 EN NUMBER: 27294 DOCKET: 05000275 05000323 EVENT DATE: 05-24-94 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 14:04 NOTIFY DATE: 05-24-94 EMERGENCY CLASS: N/A REGION: 4 STATE: CA TIME: 17:31

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: DUNE 73.71(b)(1) UNAUTHORIZED ENTRY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 48 POWER OPERATION 48 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED CONTRACT EMPLOYEE WAS DISCOVERED TO HAVE A PREVIOUS FELONY CONVICTION. THE LICENSEE IS MAKING THIS REPORT IN ACCORDANCE WITH 10 CFR 73.71(b) USING GENERIC LETTER 93-03 ENCLOSURE 1 AS GUIDANCE.

THE EMPLOYEE HAD ACCESS TO THE SITE FROM 3/17/94 TO 3/29/94 AND DID NOT PERFORM ANY SAFETY RELATED WORK. ON 3/10/94 THE EMPLOYEE FILLED OUT A PERSONNEL ACCESS QUESTIONNAIRE AND STATED IN THAT QUESTIONNAIRE THAT THERE WERE NO FELONY CONVICTIONS IN THE EMPLOYEE'S PAST. FBI INFORMATION RECEIVED IN APRIL OF 1994 REVEALED THAT THE EMPLOYEE HAD A PRIOR FELONY CONVICTION, HOWEVER, THE FBI RECORD DID NOT INDICATE THE DISPOSITION OF THE FELONY COUNTS.

THE LICENSEE CONTRACTED WITH A COMPANY (EQUIFAX) TO PERFORM A LOCAL AREA AGENCY CHECK TO DETERMINE THE DISPOSITION OF THE FELONY COUNTS. EQUIFAX INFORMED THE LICENSEE THAT THE EMPLOYEE ONLY HAD MISDEMEANOR CONVICTIONS AND NOT FELONY CONVICTIONS. THE LICENSEE DID NOT PURSUE ANY FURTHER ACTION BECAUSE THE CONVICTIONS WERE MISDEMEANOR AND NOT FELONY.

TODAY THE LICENSEE RECEIVED THE STATE OF CALIFORNIA DEPARTMENT OF JUSTICE CRIMINAL RECORDS CHECK THAT INDICATED THAT THE EMPLOYEE HAD FELONY CONVICTIONS. THE LICENSEE HAS CONTACTED EQUIFAX ABOUT THE PROBLEM. EQUIFAX STATED THAT THEIR ORIGINAL REPORT WAS IN ERROR.

THE LICENSEE HAS FLAGGED THE INDIVIDUAL'S RECORDS TO PREVENT THE EMPLOYEE FROM REGAINING ACCESS TO THE SITE. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2 EN NUMBER: 27304

DOCKET: 05000325 05000324 EVENT DATE: 05-26-94

RX TYPE: BWR BWR EVENT TIME: 14:00

VENDORS: GE-4 GE-4 NOTIFY DATE: 05-26-94

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 14:52

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

DISCOVERY OF CRIMINAL HISTORY OF CONTRACTOR GRANTED ACCESS.
IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG
FOR DETAILS. THE LICENSEE INFORMED THE NRC REGION 2 OFFICE AND
THE RESIDENT INSPECTOR.

27324 06-01-94 POW

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 27324 DOCKET: 05000443 EVENT DATE: 06-01-94

EVENT TIME: 07:10 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 06-01-94

EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 09:54

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR
N N 0 REFUELING 0 REFUELING

UNAUTHORIZED USE OF KEY CARD BY UNKNOWN INDIVIDUAL.

UNKNOWN INDIVIDUAL WAS MIS-ISSUED KEY CARD. CARD WAS USED TO ENTER PROTECTED AREA. REALIZATION OF MIS-ISSUE WAS MADE IN APPROXIMATELY 3 MINUTES AND ACCESS WAS CANCELED. CARD WAS RETURNED TO BADGE STATION IN APPROXIMATELY 30 MINUTES WITHOUT ACKNOWLEDGEMENT BY RETURNING INDIVIDUAL. CARD WAS NEVER USED TO ENTER A VITAL AREA. COMPENSATORY SEARCH OF NON-VITAL AREAS IN PROGRESS. EFFORTS TO IDENTIFY INDIVIDUAL THAT USED CARD ALSO BEING PURSUED.

NRC RESIDENT INSPECTOR WILL BE NOTIFIED BY LICENSEE. SEE HOO LOG FOR ADDITIONAL DETAILS.

*** RETRACTION FROM BEMIS TO HUFFMAN AT 16:30 EDT ON 6/1/94 *** AT 12:06 EDT, THE LICENSEE SECURITY STAFF LOCATED THE INDIVIDUAL THAT USED THE INCORRECT KEY CARD. BASED ON THEIR FINDINGS, IT WAS DETERMINED THE THE INCIDENT WAS INADVERTENT AND UNINTENTIONAL AND THAT THE INDIVIDUAL HAD UNESCORTED ACCESS UNDER HIS OWN BADGE. THIS INCIDENT IS CONSEQUENTLY ONLY LOGGABLE AND IS BEING RETRACTED. RIDO(WHITE) INFORMED. THE RESIDENT WILL BE NOTIFIED BY THE LICENSEE.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 27394 SITE: QUAD CITIES 1 2 DOCKET: 05000254 05000265 EVENT DATE: 06-14-94 EVENT TIME: 13:10 RX TYPE: BWR BWR NOTIFY DATE: 06-14-94 VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:41

OPS OFFICER: THOMAS ANDREWS

UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N N 0 REFUELING 0 REFUELING
N Y 95 POWER OPERATION 95 POWER OPERATION 2 N

THE LICENSEE CALLED TO REPORT A SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY FUNCTIONS. COMPENSATORY ACTIONS HAVE BEEN TAKEN. SEE HOO LOG FOR DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 27395 DOCKET: 05000341 EVENT DATE: 06-13-94 RX TYPE: BWR VENDORS: GE-4 EVENT TIME: 13:20 NOTIFY DATE: 06-14-94

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 16:20

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
2 N N 0 REFUELING 0 REFUELING

FITNESS FOR DUTY OF SECURITY ESCORT QUESTIONED DUE TO ALLEGATION OF INATTENTIVENESS / SLEEPING ON DUTY. SEE HOO LOG FOR DETAILS

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: GPU NUCLEAR CORP.

EN NUMBER: 27404 SITE: THREE MILE ISLAND 1 EVENT DATE: 06-16-94 DOCKET: 05000289 EVENT TIME: 03:44 RX TYPE: PWR VENDORS: B&W-L-LP NOTIFY DATE: 06-16-94 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 05:26

OPS OFFICER: STEVE SANDIN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT DWD

CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO VITAL AREA ACCESS. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

27437 06-23-94 POW

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

EN NUMBER: 27437 SITE: COOK 1 2 DOCKET: 05000315 05000316 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 06-23-94 EVENT TIME: 10:00 NOTIFY DATE: 06-23-94

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:59

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N Y 99 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

DISCOVERY OF CRIMINAL ACT INVOLVING INDIVIDUAL GRANTED ACCESS.

SEE HOO LOG FOR DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

* * * UPDATE AT 1243 ON 7/13/94 BY PTACEK LAKEN BY WEAVER * * *

THE LICENSEE HAS RETRACTED THIS EVENT BASED ON THE FOLLOWING. THE EVENT WAS OF AN HISTORIC NATURE AND DID NOT MEFT THE 1 HOUR REPORT NG CRITERIA. THE LICENSEE INFORMED THE NRC RESIDENT INSPLCTOR. HOO NOTIFIED RDO (PEDERSON).

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

EN NUMBER: 27510 SITE: MAINE YANKEE 1 EVENT DATE: 07-09-94 DOCKET: 05000309 EVENT TIME: 08:50 RX TYPE: PWR NOTIFY DATE: 07-09-94 VENDORS: CE EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 09:48

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

FEGUARDS SYSTEM DEGRADATION RELATED TO AN AREA BOUNDARY. PATEDIATE COMPENSATORY ACTIONS WERE TAKEN UPON DISCOVERY. SEE NO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2 DOCKET: 05000325 05000324 EN NUMBER: 27563 EVENT DATE: 07-21-94 EVENT TIME: 18:05 RX TYPE: BWR BWR NOTIFY DATE: 07-21-94 VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 18:40

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY PERSONNEL RECEIVED AND REVIEWED A BACKGROUND INVESTIGATION ON A CONTRACT PAINTER INDICATING A CRIMINAL HISTORY THAT WAS NOT IDENTIFIED WHEN THE INDIVIDUAL WAS INITIALLY EMPLOYED ON SITE. THE CONTRACTOR WAS GRANTED ACCESS BASED UPON A TEMPORARY CLEARANCE ON 5/31/94. THE INDIVIDUAL'S ACCESS TO THE PROTECTED AREA WAS TERMINATED ON 6/29/94, AT THE END OF THE OUTAGE. THE LICENSEE IS INVESTIGATING WHICH VITAL AREAS WERE ACCESSED AND WHETHER THAT WAS CONSISTENT WITH HIS ASSIGNED WORK ACTIVITIES. THERE HAS BEEN NO DETRIMENTAL IMPACT IDENTIFIED AS A RESULT OF HIS ACCESS TO THE PROTECTED AREA. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 2 EN NUMBER: 27564 DOCKET: 05000220 05000410 EVENT DATE: 07-22-94 VENDORS: GE-2 GE-5 EVENT TIME: 10:40 NOTIFY DATE: 07-22-94 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 11:28

OPS OFFICER: DOUG WEAVER

10 CFR SECTION: DDDD 73.71
UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE
CURR CURRENT MODE PWR CODE CRIT PWR

1 N Y 90 POWER OPERATION 90 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

- COMPROMISE OF SAFEGUARDS INFORMATION -

IMMEDIATE COMPENSATORY MEASURES HAVE BEEN TAKEN UPON DISCOVERY.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

DETAILS PROVIDED BY THE LICENSEE ARE CONTAINED IN THE HOO LOG.

LICENSEE: FLORIDA POWER & LIGHT CO.

EN NUMBER: 27574 SITE: SAINT LUCIE 1 2 EVENT DATE: 07-25-94 DOCKET: 05000335 05000389 RX TYPE: PWR PWR EVENT TIME: 16:07 NOTIFY DATE: 07-25-94 VENDORS: CE CE EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 16:36

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N

UNSPECIFIED PARAGRAPH

CURR CURRENT MODE

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION N

SAFEGUARDS SYSTEM DEGRADATION RELATED TO POWER SUPPLY FUNCTION(S) NOT FULLY COMPENSATED. THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. SEE HOO LOG FOR DETAILS.

**** UPDATE AT 1715 EDT ON 07/25/94 BY BAILEY TAKEN BY ANDREWS

COMPENSATORY ACTIONS HAVE NOW BEEN TAKEN. THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. SEE HOO LOG FOR DETAILS.

HOO NOTIFIED R2DO (CANTRELL), NO (CALVO), IAT (WARREN)

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 27635 SITE: ARKANSAS NUCLEAR 1 2 EVENT DATE: 04-07-94 DOCKET: 05000313 05000368 RX TYPE: PWR PWR EVENT TIME: 12:00
VENDORS: B&W-L-LP CE NOTIFY DATE: 08-05-94 EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 16:50

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACTOR WHO HAD A PREVIOUS FELONY CONVICTION WAS GRANTED UNESCORTED PLANT ACCESS. COMPENSATORY ACTIONS HAVE BEEN TAKEN UPON DISCOVERY.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

SEE HOO LOG FOR DETAILS.

LICENSEE: SOUTH CAROLINA ELECTRIC & GAS CO.

SITE: SUMMER 1

DOCKET: 05000395

RX TYPE: PWR

VENDORS: W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DUNE 73.71(b)(1)

UNIT SCRAM

RX INIT INITIAL MODE

CODE CRIT PWR

PWR

1 N Y 80 POWER OPERATION 80 POWER OPERATION

UNAUTHORIZED ENTRY INTO PROTECTED AREA. NOT IMMEDIATELY COMPENSATED BUT COMPENSATED NOW. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1

DOCKET: 05000313

RX TYPE: PWR

VENDORS: B&W-L-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: AR

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DUNE 73.71(b)(1)

UNAUTHORIZED ENTRY

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

UNAUTHORIZED ENTRY INTO THE PROTECTED AREA. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTH CAROLINA ELECTRIC & GAS CO.

SITE: SUMMER 1 EN NUMBER: 27727

DOCKET: 05000395 EVENT DATE: 08-30-94

RX TYPE: PWR EVENT TIME: 18:15

VENDORS: W-3-LP NOTIFY DATE: 08-30-94

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 18:55

OPS OFFICER: BOB STRANSKY

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 80 POWER OPERATION 80 POWER OPERATION

POTENTIAL FOR COMPROMISE OF SAFEGUARDS INFORMATION. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. RI WILL BE INFORMED.

LICENSEE: WOLF CREEK NUCLEAR OPER. CORP.

EN NUMBER: 27740 SITE: WOLF CREEK 1 EVENT DATE: 09-01-94 DOCKET: 05000482

RX TYPE: PWR VENDORS: W-4-LP EVENT TIME: 14:15

NOTIFY DATE: 09-01-94 EMERGENCY CLASS: N/A REGION: 4 STATE: KS TIME: 15:58

OPS OFFICER: GREG SCARFO

10 CFR SECTION: DDDD 73.71

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

CODE CRIT PWR
1 N Y 93 POWER OPERATION 93 POWER OPERATION

DISCOVERY OF CRIMINAL ACT INVOLVING INDIVIDUAL GRANTED ACCESS. IMMEDIATE COMPENSATORY MEASURES TAKEN ON DISCOVERY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 27803

DOCKET: 05000458 EVENT DATE: 09-20-94 RX TYPE: BWR EVENT TIME: 09:15

NOTIFY DATE: 09-20-94 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 11:02

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: D 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
1 N N 0 REFUELING 0 REFUELING

DISCOVERY OF A CRIMINAL ACT INVOLVING AN INDIVIDUAL GRANTED ACCESS TO THE SITE. IMMEDIATE COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE RI WAS INFORMED.

LICENSEE: WOLF CREEK NUCLEAR OPER. CORP.

SITE: WOLF CREEK 1 EN NUMBER: 27839

DOCKET: 05000482 EVENT DATE: 09-29-94 RX TYPE: PWR EVENT TIME: 14:20

NOTIFY DATE: 09-29-94 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: KS TIME: 15:34

OPS OFFICER: CHAUNCEY GOULD

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT DWD

CODE CRIT PWR

1 N N O REFUELING O REFUELING

DISCOVERY OF CRIMINAL ACT INVOLVING INDIVIDUAL GRANTED ACCESS. IMMEDIATE COMPENSATORY MEASURES TAKEN CN DISCOVERY. SEE HOO LOG FOR DETAILS. THE RI WILL BE INFORMED.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 EN NUMBER: 27863

DOCKET: 05000313 EVENT DATE: 10-04-94

RX TYPE: PWR EVENT TIME: 22:05

VENDORS: B&W-L-LP NOTIFY DATE: 10-05-94

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 00:06

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

SECURITY GUARD APON LOST INSIDE THE PLANT FOR 3 MINUTES.

COMPENSATORY ME. URES IMMEDIATELY TAKEN UPON DISCOVERY. SEE HOO
LOG FOR DETAILS. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

PALO VERDE 2 27913 10-17-94 POW

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 2

DOCKET: 05000529

RX TYPE: PWR

VENDORS: CE80

NOTIFY DATE: 10-17-94

NOTIFY DATE: 10-17-94

EMERGENCY CLASS: N/A REGION: 4 STATE: AZ TIME: 15:40 OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N Y 2 STARTUP 2 STARTUP

POTENTIAL TAMPERING OF SAFETY RELATED EQUIPMENT DISCOVERED.

THE NRC RESIDENT INSPECTOR FOUND SEVERAL INDICATING LIGHT LENSES FOR VARIOUS VALVES ON A REMOTE SHUTDOWN PANEL WERE SHOWING THE WRONG INDICATIONS. FURTHER INVESTIGATION DETERMINED THAT APPROXIMATELY

20 RED AND GREEN VALVE POSITION INDICATING LENSES ON THE "A" AND "B"

REMOTE SHUTDOWN PANELS WERE SWAPPED.

PLANT SECURITY WAS IMMEDIATELY NOTIFIED. INVESTIGATION IS IN PROGRESS

TO DETERMINE IF ANY MAINTENANCE HAS BEEN PERFORMED ON THE SHUTDOWN PANELS RECENTLY. THE SHUTDOWN PANELS ARE IN A VITAL AREA WHICH REQUIRES A KEY CARD FOR ENTRY. THEREFORE, A RECORD OF ALL PERSONNEL WHO HAVE BEEN IN

THE VICINITY OF THE PANELS IS AVAILABLE. CHECKS OF OTHER

EQUIPMENT
PANELS HAVE NOT DISCOVERED ANY SIMILAR CONDITION.

THERE IS NOT YET A BASELINE DATE OF WHEN THE LENSES WERE LAST CONFIRMED
TO BE CORRECT. THIS IS CONSIDERED ONLY A PRECAUTIONARY REPORT AT THIS TIME AND HAS NOT YET BEEN CLASSIFIED AS A TAMPERING EVENT.

* * * UPDATE 11/22/94 1245EDT FROM:HAZELWOOD BY:SCARFO * * *
THE LICENSEE IS RETRACTING THIS EVENT ON THE BASIS THAT THE
INVESTIGATION FOUND NO MALEVOLENT INTENT ON THE PART OF THE
INDIVIDUALS INVOLVED IN THIS EVENT AND NO OTHER ABNORMALITIES
WERE FOUND. THE SWITCHED INDICATOR LIGHTS DID NOT AFFECT THE
ABILITY OF THE REMOTE SHUTDOWN PANEL TO PERFORM ITS INTENDED
FUNCTION NOR DID CAUSE OF WOULD'VE CAUSED ESF SYSTEM ACTUATION.
THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R4DO (HARRELL)
NOTIFIED.

LICENSEE: BALTIMORE GAS & ELEC CO.

SITE: CALVERT CLIFFS 1 2

DOCKET: 05000317 05000318

RX TYPE: PWR PWR

VENDORS: CE CE

EN NUMBER: 27918

EVENT DATE: 10-18-94

EVENT TIME: 15:00

NOTIFY DATE: 10-18-94

EMERGENCY CLASS: N/A REGION: 1 STATE: MD

TIME: 15:50

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

FALSIFICATION OF PRE-EMPLOYMENT SCREENING.

THE LICENSEE HAS DETERMINED THAT A CONTRACT EMPLOYEE FALSIFIED HIS PRE-EMPLOYMENT SECURITY SCREENING. THE CONTRACTOR IS EMPLOYED BY BARLETT NUCLEAR AND WORKED ONSITE AS AN INSULATOR. HIS SITE ACCESS BADGE HAS BEEN SUSPENDED.

THE NRC RESIDENT INSPECTOR WILL BE INFORMED.

***UPDATE @ 06:26 ON 10/21/94 TO GOULD BY BURRELL(BG&E) *** THIS UPDATE IS TO CLARIFY THAT THE BACKGROUND INVESTIGATION WAS COMPLETED BY BG&E UNDER ALL THE RULE REQUIREMENTS. THE INDIVIDUAL AGAINST WHOM THE ACTION WAS TAKEN WAS EMPLOYED BY BARTLETT NUCLEAR, BUT BARTLETT NUCLEAR PLAYED NO PART IN THE ORIGINAL IN PROCESSING ACTIVITIES AND HAS ABSOLUTELY NO INVOLVEMENT IN THIS MATTER.

LASALLE 1 2 27920 10-18-94 POW

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2 EN NUMBER: 27920 DOCKET: 05000373 05000374 EVENT DATE: 10-18-94

RX TYPE: BWR BWR EVENT TIME: 18:55
VENDORS: GE-5 GE-5 NOTIFY DATE: 10-18-94

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 20:55

OPS OFFICER: WILLIAM HUFFMAN UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

N Y 99 POWER OPERATION 99 POWER OPERATION
N Y 97 POWER OPERATION 97 POWER OPERATION

LOSS OF PROTECTED AREA SECURITY LIGHTING.

THE PROTECTED AREA PERIMETER LIGHTING WAS LOST AT 1855 CDT. COMPENSATORY ACTION WAS IMMEDIATELY TAKEN PER STATION PROCEDURES AND IN PLACE WITHIN SEVERAL MINUTES. THE SPECIFIC CAUSE IS UNKNOWN BUT HAS BEEN TRACED TO A TRIPPED 480 VOLT MCC BREAKER. ALL PERIMETER ALARM ZONES REMAINED FUNCTIONAL.

THE RESIDENT INSPECTOR WILL BE NOTIFIED.

*** RETRACTION FROM COMBS TO HUFFMAN AT 12:41 EST ON 11/2/94 *** INVESTIGATION REVEALED THAT ONLY ONE SECTION OF THE PROTECTED AREA SECURITY LIGHTING WAS AFFECTED. BECAUSE COMPENSATORY ACTIONS WERE TAKEN WITHIN 10 MINUTES, THE EVENT IS ONLY LOGGABLE AND NOT REPORTABLE. THIS RETRACTION HAS ALREADY BEEN DISCUSSED WITH NRC REGION III AND THE RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 27922 SITE: BRAIDWOOD 1 DOCKET: 05000456 EVENT DATE: 10-19-94 EVENT TIME: 07:45 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 10-19-94

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 09:44

OPS OFFICER: DOUG WEAVER 10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO AREA BOUNDARY DUE TO IMPROPER COMPENSATORY MEASURES.

ALTERNATE COMPENSATORY ACTIONS WERE TAKEN UPON DISCOVERY. LICENSEE BELIEVES THERE WERE NO ADVERSE CONSEQUENCES DUE TO THE FAILED COMPENSATORY MEASURE BASED ON INSPECTION AND RECORDS REVIEW. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOF.

DETAILS OF THIS EVENT ARE AVAILABLE IN THE HOO LOG.

LICENSEE: CAROLINA POWER & LIGHT CO.

EN NUMBER: 27979 SITE: ROBINSON 2 DOCKET: 05000261 EVENT DATE: 11-03-94

EVENT TIME: 08:46 RX TYPE: PWR VENDORS: W-3-LP NOTIFY DATE: 11-03-94

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 09:41

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N Y 100 FOWER OPERATION 100 POWER OPERATION

FALSIFICATION OF PRE-EMPLOYMENT SCREENING RECORDS.

A CONTRACT PAINTER WAS DETERMINED TO HAVE PROVIDED FALSE INFORMATION CONCERNING PREVIOUS DRUG HISTORY. THE INDIVIDUAL'S SITE ACCESS HAS BEEN PERMANENTLY DENIED. THE NRC RESIDENT INSPECTOR WAS NOTIFIED.

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 27996 SITE: WATERFORD 3 DOCKET: 05000382 EVENT DATE: 11-04-94 EVENT TIME: 16:55 RX TYPE: PWR NOTIFY DATE: 11-04-94 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 19:23

OPS OFFICER: DOUG WEAVER

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

Y 100 POWER OPERATION 100 POWER OPERATION N

SITE ACCESS REVOKED FOR A CONTRACT EMPLOYEE

A CONTRACT EMPLOYEE'S UNESCORTED SITE ACCESS WAS REVOKED WHEN IT WAS DISCOVERED THE EMPLOYEE HAD FALSIFIED INFORMATION ON HIS EMPLOYMENT APPLICATION.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 2 EN NUMBER: 28024 DOCKET: 05000498 05000499 EVENT DATE: 11-12-94 RX TYPE: PWR PWR EVENT TIME: 09:59
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 11-12-94 RX TYPE: PWR PWR EVENT TIME: 09:59 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:54

OPS OFFICER: TIM MCGINTY

10 CFR SECTION: DSAF 73.71(b)(1) SECURITY DEGRADATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

SAFEGUARDS SYSTEM DEGRADATION RELATED TO MONITORING CAPABILITIES. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR

DETAILS.

LICENSEE: PACIFIC GAS & ELECTRIC CO. EN NUMBER:28041 SITE: DIABLO CANYON 1 2 DOCKET: 05000275 05000323 EVENT DATE: 11-17-94 EVENT TIME: 07:30 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 11-17-94 EMERGENCY CLASS: N/A REGION: 4 STATE: CA TIME: 11:08 OPS OFFICER: CHAUNCEY GOULD UNSPECIFIED PARAGRAPH 10 CFR SECTION: DDDD 73.71 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR CODE CRIT PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE DISCOVERED THAT AN INDIVIDUAL THAT HAD BEEN INVOLVED IN A CRIMINAL ACT WAS GRANTED UNESCORTED ACCESS. SEE HOO LOG FOR DETAILS. THE RI WILL BE NOTIFIED.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2 EN NUMBER: 28047 DOCKET: 05000315 05000316 RX TYPE: PWR PWR EVENT DATE: 11-18-94 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 14:45 NOTIFY DATE: 11-18-94 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 15:31 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: DDDD 73.71
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

UNSPECIFIED PARAGRAPH
CURR CURRENT MODE
PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N N O COLD SHUTDOWN O COLD SHUTDOWN

CONTRACTOR GRANTED PLANT ACCESS BASED ON FALSE BACKGROUND INFORMATION. IMMEDIATE COMPENSATORY MEASURES TAKEN UPON DISCOVERY. SEE HOO LOG FOR DETAILS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: TCLEDO EDISON CO.

EN NUMBER: 28077 SITE: DAVIS BESSE 1 DOCKET: 05000346 EVENT DATE: 11-28-94 EVENT TIME: 14:40 RX TYPE: PWR NOTIFY DATE: 11-28-94 VENDORS: B&W-R-LP EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 16:45

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR N Y 100 POWER OPERATION 10C POWER OPERATION

CONTRACT EMPLOYEE FAILED TO DISCLOSE PREVIOUS DRUG USAGE.

IT WAS DETERMINED ON 11/28/94 THAT A CONTRACT LABORER HAD FAILED

TO DISCLOSE PREVIOUS POSITIVE DRUG TESTS. THE INDIVIDUAL WAS GRANTED UNESCORTED ACCESS TO PLANT PROTECTED AND VITAL AREAS ON 10/06/94.

THE HISTORY OF PREVIOUS POSITIVE RESULTS FROM DRUG TESTING WAS DETERMINED ON 11/28/94 THROUGH ROUTINE BACKGROUND CHECKS. PLANT ACCESS HAS BEEN REVOKED. A SECURITY WORK REVIEW IS IN PROGRESS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1

DOCKET: 05000346

RX TYPE: PWR

VENDORS: B&W-R-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: OH

EN NUMBER: 28090

EVENT DATE: 11-30-94

EVENT TIME: 14:00

NOTIFY DATE: 11-30-94

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 98 POWER OPERATION 98 POWER OPERATION

CONTRACT EMPLOYEE FALSIFIED EMPLOYMENT RECORDS.

A CONTRACT LABORER WAS PERMITTED UNESCORTED ACCESS TO THE PROTECTED AND VITAL AREAS ON SITE ON SEPTEMBER 15, 1994, BASED ON RESPONSES TO A PRE-EMPLOYMENT QUESTIONNAIRE. UPON RECEIPT OF A ROUTINE FOLLOW-UP SECURITY CHECK ON NOVEMBER 29, 1994, THE LICENSEE DETERMINED THAT THE INITIAL INFORMATION PROVIDED BY THE EMPLOYEE WAS FALSE. THE INDIVIDUAL'S SITE ACCESS HAS BEEN TERMINATED. THE LICENSEE WILL ALSO REVIEW WORK PERFORMED BY THE INDIVIDUAL.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: WASHINGTON PUBLIC POWER SUPPLY SYST

SITE: WASHINGTON NUCLEAR 2 EN NUMBER: 28148

DOCKET: 05000397 EVENT DATE: 12-09-94

RX TYPE: BWR EVENT TIME: 15:52

VENDORS: GE-5 NOTIFY DATE: 12-14-94

EMERGENCY CLASS: N/A REGION: 4 STATE: WA TIME: 16:08

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

WEAPON IN VITAL AREA LEFT UNATTENDED FOR ABOUT 5 MINUTES.

ON 12/09/94 A SECURITY WEAPON WAS LEFT UNATTENDED INSIDE A VITAL AREA WHEN A SECURITY OFFICER INADVERTENTLY LEFT THE WEAPON AFTER REMOVING HIS COAT. THE WEAPON WAS FOUND BY AN EQUIPMENT OPERATOR

APPROXIMATELY FIVE MINUTES LATER. THE EVENT WAS REVIEWED FOR REPORTABILITY AT THAT TIME, SINCE THE LOCATION OF THE WEAPON WAS VERIFIABLE FOR THE FIVE MINUTE PERIOD AND NOT LOST, AND SINCE ACCESS TO THE VITAL AREA IN QUESTION WAS REVIEWED AND THE PERSONNEL IN THE AREA DURING THE TIME PERIOD THAT THE WEAPON WAS UNATTENDED WERE AUTHORIZED FOR ACCESS, IT WAS DETERMINED TO BE NON-REPORTABLE BUT LOGGABLE. THE EVENT WAS LOGGED ON 12/09/94. AN ATTEMPT WAS MADE TO CONTACT THE REGION SECURITY STAFF AND THE SITE SENIOR RESIDENT TO NOTIFY THEM OF THE EVENT, BUT BECAUSE IT WAS NOT REGULAR BUSINESS HOURS THEY WERE NOT READILY AVAILABLE ON 12/09/94 (FRIDAY). THE SENIOR RESIDENT INSPECTOR WAS NOTIFIED ON 12/10/94, AND THE REGION WAS NOTIFIED ON 12/12/94 (MONDAY). WNP-2 CONTACTED SEVERAL OTHER PLANTS THAT HAVE HAD SIMILAR EVENTS. THOSE PLANTS CONTACTED HAD NOT REPORTED THOSE EVENTS. HOWEVER, BASED ON DISCUSSIONS WITH REGIONAL PERSONNEL, AND BASED ON THEIR DISCUSSIONS WITH NRR, IT HAS BEEN DETERMINED THAT THE NRCs EXPECTATION IS THAT THIS TYPE OF EVENT BE REPORTED. THIS ADDITIONAL GUIDANCE IS THE BASIS FOR THIS REPORT.

FOR ADDITIONAL DETAILS REFER TO HEADQUARTERS OPERATIONS OFFICERS LOG BOOK.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 28182 SITE: ZION 1 2 DOCKET: 05000295 05000304 EVENT DATE: 08-22-94 VENDORS: W-4-LP W-4-LP EVENT TIME: 07:15 NOTIFY DATE: 12-23-94 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:45

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: DDDD 73.71 UNSPECIFIED PARAGRAPH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION N Y

CONTRACTOR EMPLOYEE ADMITTED TO SITE WITHOUT PREAUTHORIZATION.

A LICENSEE INVESTIGATION OF AN ALLEGATION RECEIVED 12/22/94 REVEALED THAT SECURITY HAD IMPROPERLY AUTHORIZED ENTRY INTO THE PA ON 8/19, 8/22, AND 8/23/94 OF A CONTRACTOR ON THE ACCESS DENIED LIST. THE CONTRACTOR WAS ESCORTED AT ALL TIMES AND DID NOT ENTER ANY VITAL AREAS. THE SECURITY OFFICER INVOLVED, AN EMPLOYEE OF BURNS SECURITY, MAY HAVE DESTROYED SECURITY RECORDS IN AN ATTEMPT TO CONCEAL HIS FAILURE TO CHECK THE ACCESS DENIED LIST. THE SECURITY GUARD RESIGNED EFFECTIVE 12/23/94. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AND WILL INFORM R3 (JIM CREED) ON TUESDAY 12/27/94.

Query: 1991 EVENT REPORTS: hfit

LICENSEE: CONSUMERS POWER CO.

EN NUMBER: 20242 SITE: PALISADES 1 DOCKET: 05000255 EVENT DATE: 01-10-91 EVENT TIME: 09:30 RX TYPE: PWR NOTIFY DATE: 01-10-91 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 16:30

OPS OFFICER: WILLIAM MATTINGLY

FITNESS FOR DUTY

26 73

FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

CODE CRIT PWR
N 0 REFUELING 0 REFUELING

CE CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE.

A COMBUSTION ENGINEERING CONTRACT SUPERVISOR TESTED POSITIVE DURING A RANDOM DRUG TEST. THE CONTRACTOR'S ACCESS WAS IMMEDIATELY REVOKED AND ALL OF HIS WORK WAS REVIEWED. THERE WAS NO INDICATION OF ANY ADVERSE AFFECT ON THE PLANT RESULTING FROM THIS EVENT.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

EN NUMBER: 20249 SITE: COOK 1 2 DOCKET: 05000315 05000316 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 01-11-91 EVENT TIME: 09:00 NOTIFY DATE: 01-11-91 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 14:19

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 HOT STANDBY 0 HOT STANDBY
2 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACT SUPERVISOR UNABLE TO REPORT TO DUTY DUE TO ALCOHOL CONSUMPTION.

A CONTRACT SUPERVISOR (TECHNICAL REPRESENTATIVE FOR TURBINE MAINTENANCE) WAS UNABLE TO REPORT TO DUTY (REPORTED TO WORK BUT WAS DENIED ACCESS) DUE TO ALCOHOL CONSUMPTION. THE CONTRACTOR'S WORK WAS REVIEWED AND HE WAS SUSPENDED FOR 14 DAYS. THE LICENSEE DOES NOT BELIEVE THIS EVENT HAD ANY ADVERSE AFFECT ON THE PLANTS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2 EN NUMBER: 20250 DOCKET: 05000254 05000265 EVENT DATE: 01-11-91

EVENT TIME: 10:00 RX TYPE: BWR BWR

VENDORS: GE-3 GE-3 NOTIFY DATE: 01-11-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:43 OPS OFFICER: WILLIAM MATTINGLY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N 0 REFUELING PWR
O REFUELING CODE CRIT PWR 100 POWER OPERATION 100 POWER OPERATION Y

CONTRACT SUPERVISOR TESTED POSITIVE FOR DRUG USE.

A CONTRACTOR SUPERVISOR (SITE SUPERINTENDENT FOR PAINTERS) TESTED POSITIVE FOR DRUG USE (SPECIFIC DRUG NOT KNOWN). THE SUPERVISOR'S ACCESS WAS DENIED AND A WORK PERFORMANCE EVALUATION IS IN PROGRESS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2 EN NUMBER: 20266 DOCKET: 05000315 05000316 EVENT DATE: 01-16-91 RX TYPE: PWR PWR EVENT TIME: 18:47
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 01-17-91 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:24 OPS OFFICER: WILLIAM MATTINGLY
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N N 0 HOT SHUTDOWN 0 HOT SHUTDOWN

CONTRACTOR CONSTRUCTION SUPERVISOR TESTED "FOR CAUSE" FOR ALCOHOL.

A SECURITY LIEUTENANT DETECTED ALCOHOL ON THE BREATH OF A CONTRACTOR CONSTRUCTION SUPERVISOR WHILE MAKING A ROUTINE TOUR OF THE AUXILIARY BUILDING. A BREATHALYZER TEST CONFIRMED AN ALCOHOL CONCENTRATION OF 0.04%. THE SUPERVISOR'S ACCESS WAS IMMEDIATELY REVOKED, HE WAS SUSPENDED FOR 14 DAYS AND A "FOR CAUSE" URINALYSIS SAMPLE WAS OBTAINED TO CONFIRM BLOOD ALCOHOL CONCENTRATION. THE LICENSEE DOES NOT BELIEVE THIS EVENT HAD ANY ADVERSE AFFECT ON THE PLANTS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2 SITE: BRUNSWICK 1 2
DOCKET: 05000325 05000324
RX TYPE: BWR BWR
VENDORS: GE-4 GE-4 EN NUMBER: 20271 EVENT DATE: 01-17-91 EVENT TIME: 11:15 VENDORS: GE-4 GE-4 NOTIFY DATE: 01-17-91 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 16:23

OPS OFFICER: CHAUNCEY GOULD

10 CH	PR SECTI	ON: HF	IT 26	. 73	FITNE	SS FOR DUTY
UNIT	SCRAM			INITIAL MODE	CURR PWR	CURRENT MODE
1	N	N	0	REFUELING	0	REFUELING
2	N	Y	100	POWER OPERATION	100	POWER OPERATION

A CONFIRMED POSITIVE DRUG URINALYSIS LAB REPORT CONCERNING A LICENSEE SUPERVISOR. THE PERSON IN QUESTION HAS BEEN ESCORTED FROM THE SITE AND HIS ACCESS BADGE PULLED TO SUSPEND HIS ACCESS TO THE PLANT. THE MAN WORKED AS A TRAVELING MAINTENANCE FOREMAN WHOSE AREA OF RESPONSIBILITY IS THE TURBINE BUILDING (A NON-VITAL AREA). THEY WILL MAKE A REVIEW OF HIS WORK ASSIGNMENTS TO DETERMINE IF ANY ADVERSE CONDITIONS COULD HAVE BEEN CREATED BY ACTIVITIES AT WORK. THE RI WAS INFORMED.

LICENSEE: PUBLIC SERVICE CO. OF COLORADO SITE: FT SAINT VRAIN 1 EN NUMBER: 20298 DOCKET: 05000267 EVENT DATE: 01-21-91 RX TYPE: HTGR EVENT TIME: 15:07 NOTIFY DATE: 01-22-91 VENDORS: GAC-2 EMERGENCY CLASS: N/A REGION: 4 STATE: CO TIME: 12:15 OPS OFFICER: WILLIAM MATTINGLY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N 0 REFUELING 0 REFUELING

MANAGER (AND LICENSED OPERATOR) REPORTED TO WORK AFFECTED BY ALCOHOL.

DURING A RANDOM ALCOHOL SCREENING, A MANAGER (AND LICENSED OPERATOR) TESTED BELOW THE BAC LIMIT OF .04%, HOWEVER, THE MANAGER WAS LATE FOR HIS TEST WITHOUT A REASON. THE PLANT MEDICAL REVIEW OFFICER DETERMINED THAT THE MANAGER WOULD HAVE EXCEEDED THE BAC LIMIT IF HE WOULD HAVE REPORTED TO HIS TEST ON TIME. THE MANAGER'S ACCESS WAS REMOVED AND HE WAS REFERRED TO THE EAP. THIS EVENT IS PRUDENTLY BEING REPORTED IAW NUREG 13-85.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3

DOCKET: 05000206 05000361 05000362

EX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

CODE CRIT PWR

1 N

N

O REFUELING

O REFUELING

O REFUELING

O POWER OPERATION

3 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED REACTOR OPERATOR TESTED POSITIVE DURING RANDOM DRUG SCREENING.

A NUCLEAR ASSISTANT CONTROL OPERATOR (AND LICENSED REACTOR OPERATOR) TESTED POSITIVE DURING A RANDOM DRUG SCREENING. THE EMPLOYEE'S UNESCORTED ACCESS WAS TERMINATED, HE WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM AND PLACED ON INVESTIGATIVE SUSPENSION PENDING FURTHER MANAGEMENT REVIEW.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: BOSTON EDISON CO.

SITE: PILGRIM 1 EN NUMBER: 20315 DOCKET: 05000293 EVENT DATE: 01-23-91 RX TYPE: BWR EVENT TIME: 15:15 VENDORS: GE-3 NOTIFY DATE: 01-24-91

EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 10:17

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

SUPERVISOR IN PROCUREMENT DEPARTMENT WAS SENT TO BE TESTED FOR ALCOHOL LEVEL AFTER SECURITY DETECTED ALCOHOL ON HIS BREATH. THIS SUPERVISOR WHEN TESTED WAS IN ACCESS OF THEIR 0.04 LIMIT. THIS PERSON HAD PREVIOUSLY FAILED AN ALCOHOL TEST LAST NOVEMBER 20 . 1990. THIS PERSON DOES NOT WORK IN ANY SAFETY RELATED AREA OF THE PLANT AND HE ENTERED THE PLANTS EAP PROGRAM AT 0900 EST 01/24/91.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 EN NUMBER: 20326 DOCKET: 05000245 EVENT DATE: 01-25-91 RX TYPE: BWR EVENT TIME: 12:25 VENDORS: GE-3 NOTIFY DATE: 01-25-91 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 12:40

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR/SUPERVISOR WAS CAUGHT BY A RANDOM DRUG SCREENING. HE HAD PA ACCESS, BUT HAD NOT WORKED ON NOR HAD CONTACT WITH SAFETY RELATED EQUIPMENT. COMPENSATORY ACTION WAS TAKEN BY THE LICENSEE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EN NUMBER: 20347

EVENT DATE: 01-30-91

EVENT TIME: 10:10

NOTIFY DATE: 01-30-91 EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 17:47 OPS OFFICER: WILLIAM MATTINGLY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

3 N N O REFUELING O REFUELING
4 N N O REFUELING O REFUELING

CONTRACTOR ELECTRICAL FOREMAN TESTED POSITIVE FOR COCAINE.

A CONTRACTOR ELECTRICAL FOREMAN TESTED POSITIVE FOR COCAINE USE DURING A RANDOM URINALYSIS. HIS ACCESS WAS IMMEDIATELY REVOKED AND HIS COMPANY TERMINATED HIS EMPLOYMENT. A REVIEW OF ANY SAFETY RELATED WORK HE MAY HAVE PERFORMED IS IN PROCEESS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: WATTS BAR 1 2 EN NUMBER: 20401 DOCKET: 05000390 05000391 EVENT DATE: 02-08-91
RX TYPE: PWR PWR EVENT TIME: 03:00
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 02-08-91 EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 10:59

OPS OFFICER: STEVE BLOOM

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 UNDER CONSTRUCT 0 UNDER CONSTRUCT
2 N N 0 UNDER CONSTRUCT 0 UNDER CONSTRUCT

LICENSEE RECEIVED AN ANONYMOUS TIP THAT A CONTRACT EMPLOYEE WAS NOT PART OF THE RANDOM DRUG PROGRAM. THE INDIVIDUAL WAS SUPPOSED TO BE A HEAVY MARIJUANA USER. THE INDIVIDUAL WAS TESTED FOR CAUSE AND TESTED POSITIVE. THE INDIVIDUAL MAY HAVE BEEN ASSISTED IN STAYING OUT OF THE SYSTEM FROM INSIDE TVA. THE INDIVIDUAL HAS BEEN REMOVED FROM THE SITE. LICENSEE IS INVESTIGATING. LICENSEE INFORMED LOCAL LAW ENFORCEMENT AND WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: OMAHA PUBLIC POWER DISTRICT

EN NUMBER: 20410 SITE: FT CALHOUN 1 DOCKET: 05000285 EVENT DATE: 02-09-91 RX TYPE: PWR EVENT TIME: 15:45 VENDORS: CE NOTIFY DATE: 02-09-91 EMERGENCY CLASS: N/A REGION: 4 STATE: NE TIME: 23:45

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

SHIFT SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM TEST.

SHIFT SUPERVISOR (AND LICENSED SRO) TESTED POSITIVE FOR ALCOHOL DURING RANDOM TEST WHEN REPORTING FOR DUTY (BOTH BRFATHALYZER AND BAC). HIS ACCESS WAS AUTOMATICALLY SUSPENDED FOR 14 DAYS AND HE WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2

DOCKET: 05000295 05000304

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN
2 N Y 100 POWER OPERATION 100 POWER OPERATION

- COCAINE POWDER FOUND INSIDE CONTRACTOR'S DESK INSIDE VITAL AREA

A SECURITY GUARD FOUND A WHITE POWDERY SUBSTANCE INSIDE A FIRE WATCH CONTRACTOR'S DESK INSIDE THE TURBINE BUILDING (VITAL AREA). SECURITY DEPARTMENT WITHDREW THE CONTRACTOR'S PLANT PROTECTED AREA ACCESS AUTHORIZATION. THE SUBSTANCE HAS BEEN DETERMINED BY FIELD TEST BY THE LOCAL POLICE TO BE COCAINE. THE SUBSTANCE WILL BE SENT TO AN OUTSIDE LAB FOR FURTHER TESTING.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

SITE: HOPE CREEK 1 EN NUMBER: 20512

DOCKET: 05000354 EVENT DATE: 02-21-91

RX TYPE: BWR EVENT TIME: 09:08

VENDORS: GE-4 NOTIFY DATE: 02-21-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 18:17

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 24 POWER OPERATION 24 POWER OPERATION

LICENSED OPERATOR ACCESS TERMINATED DUE TO EXTRAPOLATED BLOOD ALCOHOL CONCENTRATION (BAC) > .04.

A LICENSED NUCLEAR CONTROL OPERATOR WAS ADMINISTERED A BLOOD ALCOHOL TEST FOR CAUSE DURING A SCHEDULED PHYSICAL EXAMINATION. EXTRAPOLATING THE BAC BACK TO HIS SCHEDULED START TIME OF 0700EST RESULTS IN A BAC OF APPROX. .045. THE OPERATOR ATTENDED THE PRESHIFT BRIEFING BUT IS NOT BELIEVED TO HAVE RELIEVED THE WATCH DUE TO HIS 0815EST SCHEDULED PHYSICAL EXAM. THE INDIVIDUAL'S ACCESS HAS BEEN TERMINATED AND HE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM (EAP). THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 EN NUMBER: 20524

DOCKET: 05000220 EVENT DATE: 02-23-91

RX TYPE: BWR EVENT TIME: 09:31

VENDORS: GE-2 NOTIFY DATE: 02-23-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 18:10

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

NINE MILE POINT SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING RANDOM TESTING.

AN I&C SUPERVISOR SELECTED FOR RANDOM TESTING THIS MORNING HAD A MEASURED BLOOD ALCOHOL CONCENTRATION (BAC) OF .057 AT 0931EST. LICENSEE IMMEDIATELY REVOKED THE INDIVIDUAL'S ACCESS AND SENT HIM HOME. AN INVESTIGATION IS CURRENTLY UNDERWAY TO DETERMINE INDIVIDUAL'S REPORTING TIME AND WHETHER HE PERFORMED ANY WORK. A MEETING WITH THE INDIVIDUAL AND THE MEDICAL REVIEW OFFICER WILL BE SCHEDULED TO DETERMINE APPROPRIATE COURSE OF ACTION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: OMAHA PUBLIC POWER DISTRICT

SITE: FT CALHOUN 1 EN NUMBER: 20555

DOCKET: 05000285 EVENT DATE: 02-28-91

RX TYPE: PWR EVENT TIME: 15:27

VENDORS: CE NOTIFY DATE: 03-01-91

EMERGENCY CLASS: N/A REGION: 4 STATE: NE TIME: 10:33

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 70 POWER OPERATION 70 POWER OPERATION

CONTRACTOR FAILED A DRUG TEST.

LICENSEE REPORTED THAT A CONTRACTOR FAILED A DRUG TEST. THE

CONTRACTOR

WAS PERFORMING VERIFICATION AND VALIDATION OF NEW PROCEDURES.

IS ASSURED THAT THE CONTRACTOR'S ACTIVITIES COULD NOT COMPROMISE THE

SAFETY OF THE PLANT OR ITS OPERATION. THE CONTRACTOR HAS BEEN TERMINATED. LICENSEE DID NOT REVEAL THE NATURE OR CUANTITY OF THE SUBSTANCE DETECTED. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2 EN NUMBER: 20635 DOCKET: 05000413 05000414 EVENT DATE: 03-13-91 EVENT TIME: 13:15 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 03-13-91

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 17:45

OPS OFFICER: WILLIAM MATTINGLY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 2 N

CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE DURING RANDOM SCREENING.

A MECHANICAL VENDOR SUPERVISOR TESTED POSITIVE FOR COCAINE USAGE DURING A RANDOM DRUG SCREENING. THE CONTRACTOR'S ACCESS WAS IMMEDIATELY REVOKED AND A QA/QC VERIFICATION OF HIS WORK IS BEING PERFORMED.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2 EN NUMBER: 20650 DOCKET: 05000315 05000316 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 03-15-91 EVENT TIME: 14:30 NOTIFY DATE: 03-15-91

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 15:52 OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N N 0 HOT STANDBY 0 HOT STANDBY

CONTRACT FIRE WATCH SUPERVISOR TESTED POSITIVE FOR OPIATES TODAY AFTER TAKING A RANDOM DRUG SCREEN TEST ON 03/06/91. MEDICAL REVIEW OFFICER INTERVIEWED THIS PERSON AND CONCLUDED THAT THIS

PERSON HAD USED OPIATES. CONTRACT SUPERVISOR ACCESS HAS BEEN SUSPENDED AND HE MIGHT BE TERMINATED.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: DUKE POWER CO.

EN NUMBER: 20680 SITE: MCGUIRE 1 2 SITE: MCGUIRE 1 2 EN NUMBER: 20680

DOCKET: 05000369 05000370 EVENT DATE: 03-21-91

RX TYPE: PWR PWR EVENT TIME: 08:40

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 03-21-91

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 16:49

OPS OFFICER: THOMAS ANDREWS

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

Y 100 POWER OPERATION 100 POWER OPERATION

EMPLOYEE TESTED POSITIVE FOR ALCOHOL DURING PRE-BADGING TESTING.

A MAINTENANCE SUPERVISOR WHO HAS NOT PREVIOUSLY BEEN BADGED TO WORK IN THE PROTECTED AREA, WAS BEING TESTED FOR DRUG/ALCOHOL USE AS PART OF THE PRE-BADGING PROCESS. AT 0729, BREATHALYZER INDICATED 0.032 ALCOHOL CONTENT; AT 0732, INDICATED 0.033. ON A SEPARATE BREATHALYZER, THE RESULTS WERE 0.028 AT 0750 AND 0753. WHILE THIS IS BELOW THE NRC LIMIT OF 0.04, THE MEDICAL REVIEW OFFICER DETERMINED THAT THIS WAS A POSITIVE TEST RESULT. THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM AND HIS ACCESS TO THE PROTECTED AREA WILL BE REVIEWED AT A LATER DATE.

THE NRC SENIOR RESIDENT INSPECTOR HAS BEEN NOTIFIED BY THE LICENSEE.

LICENSEE: PHILADELPHIA ELECTRIC CO.

SITE: LIMERICK 1 2 EN NUMBER: 20763 DOCKET: 05000352 05000353 EVENT DATE: 04-05-91 EVENT TIME: 14:20 RX TYPE: BWR BWR VENDORS: GE-1 GE-4 NOTIFY DATE: 04-05-91 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 17:30

OPS OFFICER: RAY SMITH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

A VENDOR EMPLOYEE WAS DETERMINED TO BE UNFIT FOR SCHEDULED WORK DUE TO ALCOHOL CONSUMPTION.

DURING A RANDOM TEST, A VENDOR EMPLOYEE TESTED POSITIVE FOR ALCOHOL AND THIS WAS THEN CONFIRMED POSITIVE BY ANOTHER BREATH ANALYSIS TEST. THE VENDOR EMPLOYEE IS CONSIDERED AS NON-SUPERVISORY BY THE LICENSEE, HOWEVER, THE INDIVIDUAL DOES PERFORM PERFORMANCE AND SALARY REVIEW ACTIVITIES FOR VENDOR PURPOSES ONLY. THE INDIVIDUAL DID HAVE PROTECTED AREA ACCESS BUT DOES NOT NORMALLY WORK IN THE PROTECTED AREA AND WAS NOT IN THE PROTECTED AREA AT ALL TODAY.

THE INDIVIDUAL HAS BEEN REMOVED FROM THE SITE AND TAKEN HOME. THE INDIVIDUAL'S PROTECTED AREA ACCESS HAS BEEN REMOVED.

THE NRC RESIDENT HAS BEEN NOTIFIED.

LICENSEE: WISCONSIN PUBLIC SERVICE CORP.

SITE: KEWAUNEE 1 EN NUMBER: 20793 DOCKET: 05000305 EVENT DATE: 04-10-91 RX TYPE: PWR EVENT TIME: 12:05 VENDORS: W-2-LP NOTIFY DATE: 04-11-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 09:57

OPS OFFICER: TIM MCGINTY

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

PWR PWR 0 REFUELING 0 REFUELING N

INDIVIDUAL UNFIT FOR SCHEDULED WORK DUE TO ALCOHOL CONSUMPTION.

A CONTRACTOR SUPERVISOR WAS DETERMINED TO BE UNFIT FOR DUTY DUE TO ALCOHOL CONSUMPTION. DISCOVERED DURING A PRE-EMPLOYMENT SCREENING FOR WORK BY THE LICENSEE, HOWEVER THE INDIVIDUAL WAS ALREADY BADGED AS A CONTRACTOR. IMMEDIATE COMPENSATORY MEASURES TAKEN IN THAT THE EMPLOYEES BADGE WAS IMMEDIATELY DEACTIVATED. THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

SITE: COMANCHE PEAK 1 2 EN NUMBER: 20795 DOCKET: 05000445 05000446 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 04-11-91 EVENT TIME: 10:00 NOTIFY DATE: 04-11-91 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:41 OPS OFFICER: WILLIAM HUFFMAN 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN N 0

CONTRACTOR INSIDE PROTECTED AREA WITH DETECTABLE ALCOHOL LEVEL.

A HEATING AND VENTILATION CONTRACTOR WAS DISCOVERED BY PLANT PERSONNEL TO HAVE ALCOHOL ON HIS BREATH. THE INDIVIDUAL WAS ESCORTED OUT OF THE PROTECTED AREA FOR BREATHALYZER ANALYSIS. THE RESULTS OF THE ANALYSIS INDICATED AN ALCOHOL BLOOD LEVEL OF J.06%. THE INDIVIDUAL'S ACCESS BADGE HAS BEEN DEACTIVATED.

THE LICENSEE WILL BE DETERMINING IF ANY WORK BY THE CONTRACTOR HAS BEEN AFFECTED. THE NRC RESIDENT INSPECTOR WILL BE INFORMED.

LICENSEE: NORTHERN STATES POWER CO.

SITE: PRAIRIE ISLAND 1 2 EN NUMBER: 20805 DOCKET: 05000282 05000306 EVENT DATE: 04-12-91 RX TYPE: PWR PWR EVENT TIME: 11:00 VENDORS: W 2-LP W-2-LP NOTIFY DATE: 04-12-91 EMERGENCY CLASS: N/A REGION: 3 STATE: MN TIME: 14:26 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 98 POWER OPERATION 98 POWER OPERATION 2 N

SUPERVISOR WITHIN PROTECTED AREA UNDER INFLUENCE OF ALCOHOL.

A NORTHERN STATES POWER COMPANY NON-LICENSED SUPERVISOR WAS FOUND TO BE UNDER THE INFLUENCE OF ALCOHOL WHILE WORKING INSIDE THE PROTECTED AREA. HE WAS OBSERVED TO HAVE SLURRED SPEECH AND SMELLED OF ALCOHOL. HE TESTED POSITIVE AT THE SITE MEDICAL FACILITY AND WAS SENT TO A MEDICAL CENTER FOR A MORE EXTENSIVE FITNESS FOR DUTY EXAM. THE INDIVIDUAL'S SITE ACCESS HAS BEEN TERMINATED. UPPER MANAGEMENT IS AWARE OF THE SITUATION AND IS MAKING AN ASSESSMENT OF WHAT AFFECT THE INDIVIDUAL'S ACTIONS COULD HAVE HAD ON THE PLANTS.

THE LICENSEE HAS INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2 EN NUMBER: 20841 DOCKET: 05000373 05000374 EVENT DATE: 04-17-91 RX TYPE: BWR BWR EVENT TIME: 14:48 VENDORS: GE-5 GE-5 NOTIFY DATE: 04-17-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:48

OPS OFFICER: RAY SMITH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT DWD CODE CRIT PWR PWR 1 N N 0 REFUELING 0 REFUELING 2 N Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY REPORT INVOLVING A LICENSED UNIT SHIFT FOREMAN (LICENSED SRO).

A UNIT SHIFT FOREMAN RECEIVED A PRESUMED POSITIVE ON A RANDOM TEST CONDUCTED ON 4/10/91. THIS WAS CONFIRMED POSITIVE BY THE MEDICAL REVIEW OFFICER TODAY, 04/17/91. THE SUBSTANCE INVOLVED WAS NOT MADE AVAILABLE IN THE REPORT TO THE SITE PERSONNEL.

INFORMATION ON THE SUBSTANCE WILL HAVE TO BE OBTAINED FROM THE CORPORATE OFFICE.

THE INDIVIDUAL'S ACCESS HAS BEEN DENIED. A WORK PERFORMANCE INVESTIGATION IS BEING STARTED TO DETERMINE THE RECENT ACTIVITIES OF THE INDIVIDUAL. THE INDIVIDUAL HAD BEEN IN TRAINING FOR THE PAST COUPLE OF WEEKS BUT MORE RECENT ACTIVITIES ARE STILL BEING INVESTIGATED. THE PROCESS OF REFERRING THE INDIVIDUAL TO THE EMPLOYEE ASSISTANCE PROGRAM IS BEING STARTED.

THERE ARE NO KNOWN ADVERSE AFFECTS TO THE PLANT FROM THIS EVENT.

THE NRC RESIDENT HAS BEEN NOTIFIED.

FERMI 2 20842 04-17-91 POW

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2

DOCKET: 05000341

RX TYPE: BWR

VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: M1

EN NUMBER: 20842

EVENT DATE: 04-17-91

EVENT TIME: 13:15

NOTIFY DATE: 04-17-91

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
2 N N 0 REFUELING 0 REFUELING

CONTRACTOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

UPON ENTERING THE PROTECTED AREA, SECURITY PERSONNEL DETECTED ALCOHOL ON THE BREATH OF A CONTRACTOR SUPERVISOR (FOR THE TECHNICAL GROUP). THE SUPERVISOR WAS DETAINED AND TESTED "FOR CAUSE" FOR ALCOHOL. THE TEST WAS POSITIVE FOR ALCOHOL AND HE WAS ALSO SCREENED FOR DRUGS (RESULTS NOT YET AVAILABLE). THE SUPERVISOR'S UNESCORTED ACCESS WAS TERMINATED AND EVALUATION OF THE HIS SAFETY RELATED WORK IS IN PROGRESS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

* * * UPDATE AT 1329 ON 04/19/91 BY HALL ENTERED BY HOO JOLLIFFE

THE SUBJECT INDIVIDUAL OF THIS REPORT WAS A CONTRACTOR EMPLOYEE WORKING AT FERMI AND NOT A CONTRACTOR SUPERVISOR. LICENSEE WILL INCLUDE THIS INCIDENT IN THEIR NEXT SEMIANNUAL FITNESS FOR DUTY PERFORMANCE DATA REPORT TO THE NRC.

THUS, LICENSEE DESIRES TO RETRACT THIS EVENT.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

HOO NOTIFIED R3DO GREGER.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2

DOCKET: 05000373 05000374

RX TYPE: BWR BWR

VENDORS: GE-5 GE-5

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: RAY SMITH

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

EN NUMBER: 20887

EVENT DATE: 04-24-91

EVENT TIME: 16:25

NOTIFY DATE: 04-24-91

FITNESS FOR DUTY

CURR CURRENT MODE

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
N Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY REPORT INVOLVING A MECHANICAL MAINTENANCE SUPERVISOR.

A MECHANICAL MAINTENANCE SUPERVISOR RECEIVED A CONFIRMED POSITIVE TEST TODAY FOLLOWING A RANDOM TEST ON 04/22/91. THP INDIVIDUAL HAS BEEN ESCORTED OFFSITE, ACCESS HAS BEEN DENIED, AND A MEETING HAS BEEN SET UP WITH MEDICAL AND EMPLOYEE ASSISTANCE STAFF. A PERFORMANCE INVESTIGATION WILL BE CONDUCTED.

THE SUBSTANCE INVOLVED IS NOT DISCLOSED TO THE SITE PERSONNEL MAKING THIS REPORT.

THE NRC RESIDENT WILL BE NOTIFIED.

LICENSEE: TENNESSEE VALLEY AUTHORITY

EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 17:13
OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 REFUELING 0 REFUELING
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
3 N N 0 REFUELING 0 REFUELING

3 N N O REFUELING O REFUELING

UNITS 1 AND 3 ARE DEFUELED. INTRODUCTION OF CONTROLLED SUBSTANCE BY PERSON OR PERSONS UNKNOWN INTO PROTECTED AREA CONFIRMED BY LAB ANALYSIS.

ON 3/16/91 A BREWING COFFEE MAKER IN THE RADIATION PROTECTION OFFICE WHICH IS LOCATED IN THE TURBINE BUILDING WAS SUSPECTED OF CONTAINING THC, THE ACTIVE INGREDIENT OF MARIJUANA. THE LOCAL POLICE DEPARTMENT WAS NOTIFIED AND PROVIDED A SAMPLE FOR ANALYSIS AT THEIR ALABAMA FORENSIC LABORATORY. THE LAB REPORT RECEIVED TODAY CONFIRMED THE PRESENCE OF THC. LICENSEE HAS NOTIFIED THE

TVA OFFICE OF INSPECTOR GENERAL WHO WILL BE CONDUCTING THE INVESTIGATION. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

UPDATE 4/9/91 @ 1500ET BY PAM HAMILTON TAKEN BY MACKINNON LICENSEE IS UNSURE AT THE PRESENT TIME IF THE SUBSTANCE REPORT THAT THEY GOT BACK FROM THE SHERIFF DEPARTMENT WAS FOR AN EVENT THAT OCCURRED ON 02/22/91 OR THE EVENT ABOVE WHICH HAPPENED ON 03/16/91. LICENSEE IS INVESTIGATING THIS PROBLEM AT THE PRESENT TIME. LICENSEE RECEIVED THIS INFORMATION ON 4/8/91 AROUND 1645ET. R2DO (PAUL FREDRICKSON) NOTIFIED.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2 EN NUMBER: 20910 DOCKET: 05000413 05000414 EVENT DATE: 04-29-91 RX TYPE: PWR PWR EVENT TIME: 16:30 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 04-29-91 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 18:52

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N N 0 REFUELING 0 REFUELING 2 N Y 100 POWER OPERATION 100 POWER OPERATION

EMPLOYEE ARRESTED AT SITE ON CONTROLLED SUBSTANCES VIOLATIONS.

LOCAL POLICE SERVED AN ARREST WARRANT AT THE PLANT SITE FOR AN EMPLOYEE FOR USE, SALE AND POSSESSION OF A CONTROLLED SUBSTANCE (COCAINE). THE EMPLOYEE WAS BADGED BUT WAS IN A NON-SUPERVISORY CAPACITY, HE WAS ASSIGNED TO SECONDARY CHEMISTRY MONITORING AND DID NOT PERFORM ANY SAFETY RELATED WORK. ALL HIS WORK WAS ROUTINELY CHECKED. AT THE TIME OF THE ARREST, HE DID NOT APPEAR INTOXICATED AND A SEARCH OF HIS WORK AREA REVEALED NO DRUGS. HIS PLANT ACCESS HAS BEEN TERMINATED AND THE LICENSEE IS AWAITING FURTHER INFORMATION FROM LAW ENFORCEMENT AUTHORITIES BEFORE TAKING ADDITIONAL ADMINISTRATIVE ACTIONS.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED. NO OTHER NOTIFICATIONS HAVE BEEN MADE BY THE LICENSEE.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: GRAND GULF 1 EN NUMBER: 20922 DOCKET: 05000416 EVENT DATE: 05-01-91 RX TYPE: BWR EVENT TIME: 15:31 VENDORS: GE-6 NOTIFY DATE: 05-01-91 EMERGENCY CLASS: N/A REGION: 2 STATE: MS TIME: 15:31

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 50 POWER OPERATION 50 POWER OPERATION

NON-LICENSED OPERATOR ARRESTED FOR POSSESSION OF DRUG PARAPHERNALIA.

ON 4/27/91, A NON-LICENSED OPERATOR FROM GRAND GULF WAS ARRESTED IN VICKSBURG, MISSISSIPPI, FOR POSSESSION OF DRUG PARAPHERNALIA. ON 4/29/91, A CONFIDENTIAL CALL WAS PLACED TO PLANT MANAGEMENT INFORMING THEM OF THE SITUATION. THE LICENSEE IMMEDIATELY TERMINATED THE EMPLOYEE'S ACCESS TO THE PLANT AND CALLED HIM IN FOR TESTING. TESTING WAS NEGATIVE, HOWEVER, THE EMPLOYEE ADMITTED TO COCAINE USE. THE EMPLOYEE WAS PLACED IN AN EMPLOYMENT ASSISTANCE PROGRAM AND HIS FUTURE STANDING DEPENDS ON THE RESULT OF THE PROGRAM EVALUATION.

THE EMPLOYEE STATED THAT HE HAD NOT EVER REPORTED TO WORK UNDER THE INFLUENCE. LICENSEE IS CURRENTLY EXAMINING WORK RECORDS OF THE EMPLOYEE.

THE LICENSEE STATED THAT A POTENTIAL FOR ADVERSE PUBLICITY EXISTS BASED ON A INQUIRY TODAY FROM THE VICKSBURG EVENING POST CONCERNING THE CIRCUMSTANCES OF THE ARREST AND DUTIES OF THE OPERATOR.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 2

DOCKET: 05000247

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A PEGION: 1 STATE: NY

EVENT DATE: 05-13-91

EMERGENCY CLASS: N/A PEGION: 1 STATE: NY

TIME: 16:00

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 16:00

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N N O COLD SHUTDOWN O COLD SHUTDOWN

A TEMPORARY HEALTH PHYSICS SUPERVISOR TESTED POSITIVE FOR DRUGS DURING A RANDOM DRUG TEST.

"AT 1500EDT ON 5/13/91 THE SECURITY SUPERINTENDENT RECEIVED A CALL FROM THE CON ED MEDICAL REVIEW OFFICER REPORTING THAT A CON ED EMPLOYEE, A HEALTH PHYSICS TEMPORARY SUPERVISOR, TESTED POSITIVE FOR DRUGS AS A RESULT OF A RANDOM TEST TAKEN ON 5/6/91. THIS EMPLOYEE WILL BE ENROLLED IN THE COMPANY SUBSTANCE ABUSE PROGRAM. HIS UNESCORTED ACCESS HAS BEEN SUSPENDED AND WILL NOT BE

REINSTATED UNTIL SUCCESSFUL COMPLETION OF THE PROGRAM REQUIREMENTS." THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: CLEVELAND ELECTRIC ILLUMINATING CO.

SITE: PERRY 1 EN NUMBER: 21006

DOCKET: 05000440 EVENT DATE: 05-13-91

RX TYPE: BWR EVENT TIME: 14:45

VENDORS: GE-6 NOTIFY DATE: 05-14-91

EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 12:21

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

CORPORATE SUPERVISOR WITH SITE ACCESS TO BOTH PERRY AND DAVIS-BESSE TESTED POSITIVE FOR CONTROLLED SUBSTANCE.

AT 1445 ON 5/13/91 THE ACCESS AUTHORIZATION SUPERVISOR WAS NOTIFIED BY THE MEDICAL REVIEW OFFICER (MRO) OF A CONFIRMED POSITIVE DRUG TEST RESULT FROM A SAMPLE PROVIDED BY A COMPANY MANAGEMENT REPRESENTATIVE (SUPERVISOR) IN THE PROCUREMENT ORGANIZATION. THIS INDIVIDUAL'S PRIMARY REPORTING POINT IS AT THE CORPORATE FACILITY IN INDEPENDENCE, OHIO, BUT HE HAS A FIELD OFFICE ONSITE AT BOTH PERRY AND DAVIS-BESSE FACILITIES OUTSIDE THE PROTECTED AREAS. THE INDIVIDUAL'S TEST SAMPLE WAS COLLECTED ON 5/9/91 AND THE MRO HAS MEET WITH THE INDIVIDUAL AND DETERMINED THAT THIS IS A CONFIRMED POSITIVE TEST. AN INVESTIGATION IS CONTINUING OF THE CIRCUMSTANCES OF THIS AND OF THE INDIVIDUAL'S WORK ACTIVITIES TO DETERMINE ANY SAFETY RELATED IMPLICATIONS. THE INDIVIDUAL'S ACCESS HAS BEEN SUSPENDED AND A MEETING WITH THE MRO IS PLANNED TO DISCUSS THE COMPANY SUBSTANCE ABUSE PROGRAM THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AT PERRY AND WILL INFORM THE NRC RESIDENT INSPECTOR AT DAVIS-BESSE. ALSO, LICENSEE HAS DISCUSSED THIS REPORT WITH REGION 3 (JIM CREED) .

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: SAINT LUCIE 1 2

DOCKET: 05000335 05000389

RX TYPE: PWR PWR

VENDORS: CE CE

VENDORS: CE CE

NOTIFY DATE: 05-30-91

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR CONTROLLED SUBSTANCE DURING RANDOM TESTING.

AT 1200EDT ON 5/29/91 THE CONTROL ROOM WAS INFORMED BY THE SITE FITNESS COORDINATOR OF A POSITIVE DRUG TEST ON A LICENSED OPERATOR. THE LICENSED OPERATOR WAS IN THE REQUALIFICATION PROGRAM WHEN RANDOMLY TESTED ON 5/22/91. PRIOR TO THE RECEIVING THE TEST RESULTS, HE STOOD TWO (2) SHIFTS. OFFSITE MANAGEMENT WAS NOTIFIED BY 1300EDT ON 5/29/91 AND THE OPERATOR'S BADGE HAS BEEN PULLED WITH SITE ACCESS DENIED. PER LICENSEE PROCEDURE, THE OPERATOR HAS BEEN REFERRED TO THEIR EMPLOYEE ASSISTANCE PROGRAM (EAP) AND ADMINISTRATIVELY SUSPENDED FROM WORK FOR 14 DAYS. LICENSEE WILL REVIEW OPERATORS PAST SIXTY (60) DAY WORK HISTORY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 21211

DOCKET: 05000443 EVENT DATE: 06-17-91

RX TYPE: PWR EVENT TIME: 13:15

VENDORS: W-4-LP NOTIFY DATE: 06-17-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 16:21

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RK INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE.

A CONTRACT SUPERVISOR (UNITED ENGINEERING AND CONSTRUCTION)
TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST. THE
CONTRACTOR'S SITE AND PROTECTED AREA ACCESS WERE IMMEDIATELY
SUSPENDED. THE CONTRACTOR SUPERVISED CRAFT PERSONNEL OUTSIDE THE
PROTECTED AREA (MOVING DESKS, REPAIRING PARKING LOTS, ETC.) AND
THERE IS NO INDICATION THAT HIS WORK COULD HAVE ANY AFFECT ON
PLANT OPERATION. THE CONTRACTOR HAS BEEN GIVEN THE OPTION TO
ENTER THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 EN NUMBER: 21212

DOCKET: 05000313 EVENT DATE: 06-17-91
RX TYPE: PWR EVENT TIME: 15:10
VENDORS: B&W-L-LP NOTIFY DATE: 06-17-91

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 16:50

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR DRUG USE.

A LICENSED SENIOR REACTOR OPERATOR (SRO) TESTED POSITIVE FOR DRUG USE FOLLOWING A RANDOM DRUG TEST. THE LICENSEE DID NOT KNOW THE SPECIFIC SUBSTANCE THAT HAD BEEN DETECTED. THE EMPLOYEE, WHO WAS NOT ON DUTY AT THE TIME, HAD HIS PLANT ACCESS IMMEDIATELY SUSPENDED. A WORK QUALITY REVIEW HAS BEEN INITIATED BY PLANT MANAGEMENT TO ASSURE NO ACVERSE AFFECT ON PLANT OPERATION. THE EMPLOYEE WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM FOR EVALUATION AND RECOMMENDATIONS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: MAINE YANKEE ATOMIC POWER CO.

SITE: MAINE YANKEE 1 EN NUMBER: 21214

DOCKET: 05000309 EVENT DATE: 06-17-91

RX TYPE: PWR EVENT TIME: 16:00

VENDORS: CE NOTIFY DATE: 06-18-91

EMERGENCY CLASS: N/A REGION: 1 STATE: ME TIME: 14:10

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE.

A CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE FOLLOWING A RANDOM DRUG TEST. THE RESULTS WERE CONFIRMED POSITIVE BY THE MEDICAL REVIEW OFFICER. THE INDIVIDUAL'S PLANT ACCESS HAS BEEN PERMANENTLY DENIED. THE INDIVIDUAL SUPERVISED CONTRACT JANITORIAL SERVICES AND THE LICENSEE CONSIDERS THAT THERE WERE NO SAFETY RAMIFICATIONS INVOLVED.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: BOSTON EDISON CO.

SITE: PILGRIM 1

DOCKET: 05000293

EVENT DATE: 06-25-91

RX TYPE: BWR

VENDORS: GE-3

NOTIFY DATE: 06-26-91

EMERGENCY CLASS: N/A PEGION: 1 STATE: M3

EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 09:00

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N N O REFUELING O REFUELING

TRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A CONTRACT SUPERVISOR (WITH NATIONAL FIRE AND MEDICAL) TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG TEST. ALCOHOL CONTENT AS MEASURED BY BREATHALYZER WAS 0.049%. A BLOOD SAMPLE WAS WITHDRAWN FOR CONFIRMATION. THE INDIVIDUAL'S PLANT ACCESS WAS

TERMINATED. THE INDIVIDUAL WORKED WITH THE FIRE WATCH GROUP AND MANAGEMENT CONSIDERS THAT NO SAFETY RELATED WORK WAS INVOLVED. THE INDIVIDUAL WILL BE PARTICIPATING IN THE EMPLOYEE ASSISTANCE PROGRAM AND SUITABILITY FOR FURTHER EMPLOYMENT WILL BE EVALUATED UPON COMPLETION.

THE NRC RESIDENT INSPECTOR WILL BE INFORMED.

LICENSEE: TLORIDA POWER & LIGHT CO.

EN NUMBER:21298 SITE: TURKEY POINT 3 4
DOCKET: 05000250 05000251 SITE: TURKEY POINT 3 4 EVENT DATE: 06-30-91 VENDORS: W-3-LP W-3-LP EVENT TIME: 21:20 NOTIFY DATE: 07-01-91 EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 18:12 OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: **RFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR
3 N N 0 REFUELING 0 REFUELING
4 N N 0 REFUELING 0 REFUELING CODE CRIT PWR

-PAINTING CONTRACTOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL ON HIS BREATH-

A PAINTING CONTRACTOR SUPERVISOR WHO HAD BEEN CLEANING AND PAINTING THE UNIT 4 CONTAINMENT WALLS EXITED THE PLANT. WHILE ATTEMPTING TO REENTER THE PLANT A SHORT TIME LATER, SECURITY GUARDS SMELLED ALCOHOL ON HIS BREATH. SECURITY GUARDS PERFORMED AN ALCOHOL TEST ON THE INDIVIDUAL.

AT 2049 ON 06/30/91, THE ALCOHOL TEST RESULTS WERE CONFIRMED POSITIVE.

THE INDIVIDUAL STATED THAT HE HAD NOT CONSUMED ANY ALCOHOL WHILE ON SITE AND THAT HE DID NOT WISH TO APPEAL THE TEST RESULTS.

LICENSEE WITHDREW THE INDIVIDUAL'S PLANT ACCESS AUTHORIZATION.

AT 2120 ON 06/30/91, LICENSEE DETERMINED THIS EVENT TO BE REPORTABLE TO THE NRC.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: MCGUIRE 1 2 EN NUMBER:21358 DOCKET: 05000369 05000370 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 07-10-91 EVENT TIME: 14:03 NOTIFY DATE: 07-11-91 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 09:00

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

A FOOD VENDING COMPANY CONTRACTOR SUPERVISOR TESTED POSITIVE FOR COCAINE. THE INDIVIDUAL DID NOT WORK ON ANY PLANT EQUIPMENT. LICENSEE WITHDREW HIS PLANT ACCESS AUTHORIZATION. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4 EN NUMBER: 21366

DOCKET: 05000250 05000251 EVENT DATE: 07-11-91
RX TYPE: PWR PWR EVENT TIME: 09:31

VENDORS: W-3-LP W-3-LP NOTIFY DATE: 07-11-91

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 19:03

OPS OFFICER: WILLIAM MATTINGLY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

3 N N O REFUELING O REFUELING
4 N N O REFUELING O REFUELING

PAINTING CONTRACTOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A PAINTING CONTRACTOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL (BAC 0.04). SECURITY PERSONNEL RECEIVED AN ANONYMOUS CALL THAT SOMEONE INSIDE THE UNIT 3 CONTAINMENT SMELLED OF ALCOHOL. SECURITY PERSONNEL DETERMINED THAT THE PAINTING CONTRACTOR SUPERVISOR SMELLED OF ALCOHOL AND TESTED HIM FOR CAUSE. THE SUPERVISOR'S ACCESS HAS BEEN DENIED FOR AT LEAST 14 DAYS AND A WORK CHECK DETERMINED THAT HE WAS NOT WORKING ON VITAL EQUIPMENT.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 2

DOCKET: 05000247

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NY

OPS OFFICER: GREG SCARFO

EN NUMBER: 21472

EVENT DATE: 07-26-91

EVENT TIME: 10:45

NOTIFY DATE: 07-26-91

TIME: 21:27

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
2 N N 0 HOT SHUTDOWN 0 HOT SHUTDOWN

CONTRACT EMPLOYEE TESTED POSITIVE DURING RANDOM DRUG TEST.

AT 1045, A CONTRACT EMPLOYEE TESTED POSITIVE FOR AN UNREPORTED DRUG DURING A RANDOM DRUG TEST. THIS EMPLOYEE HAD ACCESS TO THE PRIMARY AUXILIARY BUILDING AND OTHER UNOCCUPIED VITAL AREAS BUT THERE ARE NO INDICATIONS OF ANY ADVERSE AFFECT IN THESE AREAS.

THE LICENSEE REVOKED THE EMPLOYEE'S UNESCORTED ACCESS PASS AT 1050. (HOO NOTE: IT IS CUSTOMARY FOR THIS LICENSEE TO TERMINATE AN EMPLOYEE WHO TESTS POSITIVELY DURING A RANDOM DRUG TEST.) THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GPU NUCLEAR CORP. SITE: THREE MILE ISLAND 1 DOCKET: 05000289 EN NUMBER: 21486 EVENT DATE: 07-29-91 RX TYPE: PWR VENDORS: B&W-L-LP EVENT TIME: 10:30 NOTIFY DATE: 07-29-91 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 14:58 OPS OFFICER: WILLIAM MATTINGLY 10 CFR SECTION: HFIT 26.73 10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR 1 N Y 96 POWER OPERATION 96 POWER OPERATION PWR

LICENSED REACTOR OPERATOR TESTED POSITIVE FOR DRUGS.

A LICENSED REACTOR OPERATOR TESTED POSITIVE FOR DRUGS DURING A RANDOM DRUG SCREENING. THE RO WAS IMMEDIATELY SUSPENDED FOR 14 DAYS AND REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

**** UPDATE @ 1012 07/30/91 BY HENRY SHIPMAN TAKEN BY THOMAS

LICENSEE PLANS TO MAKE A PRESS RELEASE ON THIS EVENT. THE RESIDENT INSPECTOR HAS BEEN NOTIFIED AND WILL BE PROVIDED A COPY OF THE PRESS RELEASE.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: WATTS BAR 1 2

DOCKET: 050 0390 05000391

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN

CPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 UNDER CONSTRUCT

2 N N 0 UNDER CONSTRUCT

2 UNDER CONSTRUCT

0 UNDER CONSTRUCT

A LICENSED WATTS BAR EMPLOYEE TESTED POSITIVE TO ALCOHOL. THE EMPLOYEE WAS TAKEN HOME AND WILL BE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. THE EMPLOYEE WAS BEING TESTED BECAUSE HE WAS GOING TO VISIT ANOTHER UTILITY. WATTS BAR DOES NOT HAVE A FORMAL UNESCORTED ACCESS PROGRAM SINCE THEY DO NOT HAVE AN OPERATING LICENSE.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

3 N N 0 COLD SHUTDOWN

4 N N 0 COLD SHUTDOWN

COLD SHUTDOWN

6 EVENT DATE: 08-06-91

EVENT TIME: 11:41

NOTIFY DATE: 08-06-91

FITNESS FOR DUTY

CURR CURRENT MODE

PWR

O COLD SHUTDOWN

O COLD SHUTDOWN

A CONTRACT SUPERVISOR WAS CONFIRMED POSITIVE ON A FOR CAUSE ALCOHOL TEST. THIS PERSON HAD JUST HAD HIS BADGE MADE AT THE TURKEY POINT PLANT AND NEVER ENTERED THE PLANT.

THIS PERSON DID HAVE AN ACTIVE BADGE AT THE ST. LUCIE PLANT. THIS BADGE WAS REACTIVATED ON JULY 24, 1991. THE INDIVIDUAL ENTERED THE ST. LUCIE PLANT FOR A SHORT MEETING ON JULY 24.

THIS PERSON HAS BEEN DENIED ACCESS AT BOTH TURKEY POINT AND ST. LUCIE. THE TURKEY POINT NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. THE ST. LUCIE NRC RESIDENT INSPECTOR HAS NOT BEEN NOTIFIED.

LICENSEE: BALTIMORE GAS & ELEC CO.

SITE: CALVERT CLIFFS 1 2

DOCKET: 05000317 05000318

RX TYPE: PWR PWR

VENDORS: CE CE

EMERGENCY CLASS: N/A REGION: 1 STATE: MD

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER

A NUCLEAR SECURITY SUPERVISOR WAS ARRESTED BY THE CALVERT COUNTY SHERIFF'S DEPARTMENT IN POSSESSION OF MARIJUANA ON COMPANY PROPERTY OUTSIDE THE PROTECTED AREA. THE PRELIMINARY INVESTIGATION REVEALS THAT HE HAD PERSONALLY GROWN THE MARIJUANA ON REMOTE COMPANY PROPERTY IN THE WOODS ABOUT 1 MILE SE OF THE PLANT. THE INDIVIDUAL HAS BEEN SUSPENDED AND HIS ACCESS TERMINATED. THE PARENT COMPANY FOR CALVERT CLIFFS IS INVESTIGATING THE EVENT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR, STATE AND LOCAL AUTHORITIES AND MADE A PRESS RELEASE.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4 DOCKET: 05000250 05000251

EN NUMBER:21582 EVENT DATE: 08-09-91 RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

3 N N 0 REFUELING

4 N N 0 REFUELING

0 REFUELING

0 REFUELING

A CONTRACTOR FOREMAN FAILED AN ALCOHOL TEST AT THE MAIN ENTRY STATION. THE INDIVIDUAL HAD NOT ENTERED THE OWNER CONTROLLED AREA AT ANY TIME ON 8/9/91. THE INDIVIDUAL WAS AN INSULATION INSTALLER FOR FIRE BARRIERS AND THE WORK IS COVERED BY A QC INSPECTION PROGRAM. THE INDIVIDUALS ACCESS HAS BEEN REVOKED FOR TURKEY POINT AND ST. LUCIE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: BALTIMORE GAS & ELEC CO.

SITE: CALVERT CLIFFS 1 2

DOCKET: 05000317 05000318

RX TYPE: PWR PWR

VENDORS: CE CE

EMERGENCY CLASS: N/A REGION: 1 STATE: MD

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

EN NUMBER: 21611

EVENT DATE 08-13-91

EVENT TIME: 11:20

NOTIFY DATE: 08-13-91

FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

A SENIOR NUCLEAR SECURITY OFFICER FAILED A DRUG TEST ADMINISTERED FOR CAUSE.

ON 8/13/91, AT APPROXIMATELY 1100EDT, THE ASSISTANT GENERAL SUPERVISOR NUCLEAR SECURITY ELECTED TO REFER A SEMIOR NUCLEAR SECURITY OFFICER FOR A FITNESS FOR DUTY EXAMINATION DUE TO FREQUENT PATTERNS OF TARDINESS. THE SEMIOR OFFICER CALLED IN PRIOR TO ARRIVING ON-SITE TO REPORT THAT HE WOULD BE LATE FOR WORK. IMMEDIATELY UPON ARRIVING FOR WORK AND PRIOR TO ASSUMING ANY SECURITY RELATED RESPONSIBILITIES, HE WAS REFERRED FOR THE FITNESS FOR DUTY EXAMINATION.

FREQUENT OR RECURRING PATTERNS OF TARDINESS ARE IDENTIFIED AS UNUSUAL OR ABERRANT JOB PERFORMANCE INDICATORS UNDER BG&Es CONTINUED BEHAVIORAL OBSERVATION PROGRAM.

THE SENIOR NUCLEAR SECURITY OFFICER IN QUESTION WAS SCHEDULED TO PERFORM IN THE CAPACITY AS THE SECURITY SHIFT SUPERVISOR ON 8/13/91.

AT 1120EDT A BREATH ALCOHOL SCREENING ANALYSIS INDICATED A

CONFIRMED A POSITIVE TEST ABOVE THE CUT-OFF LEVEL OF .04%. THE MEDICAL REVIEW OFFICER EVALUATED AND CONFIRMED THE RESULTS.

THE SENIOR NUCLEAR SECURITY OFFICER'S ACCESS WAS SUSPENDED AND HE WAS ESCORTED OFF-SITE TO HIS HOME BY SECURITY SUPERVISION.
FURTHER ACTIONS AND DISPOSITION WILL BE DETERMINED AS NECESSARY AFTER REVIEW BY THE APPROPRIATE COMPANY PERSONNEL IN ACCORDANCE WITH BG&E FITNESS FOR DUTY AND APPLICABLE PORTIONS OF 10CFR26.

AT NO TIME WAS THE SENIOR OFFICER PERMITTED TO PERFORM IN ANY SECURITY RELATED CAPACITY UNTIL THE RESULTS OF THE FITNESS FOR DUTY EXAMINATION WERE OBTAINED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW SITE: INDIAN POINT 2 EN NUMBER: 21617 DOCKET: 05000247 EVENT DATE: 08-14-91 RX TYPE: PWR EVENT TIME: 07:28 VENDORS: W-4-LP NOTIFY DATE: 08-14-91 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 11:46 OPS OFFICER: THOMAS ANDREWS 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY CURR CURRENT MODE UNIT SCRAM RX INIT INITIAL MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED EMPLOYEE FAILED A RANDOM ALCOHOL TEST. THE INDIVIDUAL WAS SELECTED AT RANDOM PRIOR TO ENTRY AT 0658 EDT ON 08/14/91. POSITIVE RESULTS OF GREATER THAN 0.04% BAC WERE OBTAINED ON THE ALCOHOL BREATHALYZER TEST. THE EMPLOYEE HAS REQUESTED CONFIRMATION OF THE RESULTS VIA BLOOD TEST. THE RESULTS OF THE BLOOD TEST ARE PENDING. EMPLOYEE ACCESS HAS BEEN SUSPENDED PENDING FURTHER MEDICAL REVIEW.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI SITE: SAN ONOFRE 1 2 3 EN NUMBER: 21625 DOCKET: 05000206 05000361 05000362 EVENT DATE: 08-15-91 RX TYPE: PWR PWR PWR VENDORS: W-3-LP CE CE EVENT TIME: 13:00 NOTIFY DATE: 08-15-91 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 18:32 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 91 POWER OPERATION 91 POWER OPERATION Y 100 POWER OPERATION 100 POWER OPERATION N N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

⁻ LICENSED SENIOR REACTOR OPERATOR FAILED A RANDOM TEST FOR ALCOHOL -

AT 1910 (PDT) ON 08/14/91, A LICENSED SENIOR REACTOR OPERATOR REPORTING FOR DUTY FAILED A RANDOM BREATH ANALYZER TEST FOR ALCOHOL. LICENSEE WITHDREW THE EMPLOYEE'S PLANT PROTECTED AND VITAL AREA UNESCORTED ACCESS AUTHORIZATION.

AT 1300 (PDT) ON 08/15/91, LICENSEE RECEIVED LABORATORY BLOOD ANALYSIS RESULTS THAT CONFIRMED THE PRESENCE OF ALCOHOL.

THE EMPLOYEE HAS BEEN PLACED ON INVESTIGATORY SUSPENSION, AWAITING FURTHER LICENSEE MANAGEMENT REVIEW.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 21721

DOCKET: 05000443 EVENT DATE: 08-27-91

RX TYPE: PWR EVENT TIME: 06:35

VENDORS: W-4-LP NOTIFY DATE: 38-27-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 12:27

OPS OFFICER: RUDY KARSCH 10 CFR SECTION: HFIT 26.73

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N O REFUELING O REFUELING

A 12 OUNCE CAN OF BEER WAS FOUND IN A CONTRACT CRAFT EMPLOYEE'S (FOREMAN) LUNCH BOX AS HE WAS ENTERING THE PROTECTED AREA. THE INDIVIDUAL TESTED NEGATIVE FOR ALCOHOL. HE HAS BEEN SUSPENDED. THE LICENSEE WILL ISSUE A RUSS RELEASE AND HAS INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: WISCOMSIN PUBLIC SERVICE CORP.

SITE: KEWAUNEE 1 EN NUMBER: 21793

DOCKET: 05000305 EVENT DATE: 09-06-91

RX TYPE: PWR EVENT TIME: 12:00

VENDORS: W-2-LP NOTIFY DATE: 09-09-91

EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 15:39

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 99 POWER OPERATION 99 POWER OPERATION

SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

LICENSEE REPORTS THAT A PLANT ENGINEERING SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM TEST. ALCOHOL LEVEL WAS MEASURED AT 0.055% USING A BREATHALYZER. THE EMPLOYEE'S PLANT ACCESS WAS IMMEDIATELY TERMINATED. MANAGEMENT IS CURRENTLY CONDUCTING A WORK REVIEW BACK TO 8/01/91 TO ENSURE THAT THERE IS NO POTENTIAL FOR DEGRADED PERFORMANCE. DECISION ON RE-ACCESS WILL

DEPEND ON EVALUATION FROM AN EMPLOYEE ASSISTANCE PROGRAM.

THE LICENSEE ACKNOWLEDGED THE LATENESS OF THE REPORT DUE TO THE NORMALLY RESPONSIBLE PERSON BEING OFF WORK THE DAY OF THE EVENT. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: VIRGINIA POWER CO.

EN NUMBER: 21794 SITE: SURRY 1 2
DOCKET: 05000280 05000281
RX TYPE: PWR PWR
VENDORS: W-3-LP W-3-LP SITE: SURRY 1 2 EVENT DATE: 09-09-91 EVENT TIME: 10:00 NOTIFY DATE: 09-09-91

EMERGENCY CLASS: N/A REGION: 2 STATE: VA TIME: 16:25

OPS OFFICER: WILLIAM HUFFMAN

OPS OFFICER: WILLIAM HUFFMAN

FITNESS FOR DUTY

CURRENT MO UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N N COLD SHUTDOWN 0 COLD SHUTDOWN 2

SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A VIRGINIA POWER RADIATION PROTECTION SHIFT SUPERVISOR WAS ON COMPANY BUSINESS AT PLANT VOGTLE WHEN ALCOHOL WAS DETECTED ON HIS BREATH. THE INDIVIDUAL WAS SENT TO THE VOGTLE FITNESS FOR DUTY FACILITY WHERE HE TESTED POSITIVE FOR ALCOHOL. THE INDIVIDUAL HAD A BACKUP BLOOD SAMPLE DRAWN BUT THE RESULTS HAVE NOT YET BEEN RECEIVED. VOGTLE DENIED HIM FURTHER PLANT ACCESS AND HE IS RETURNING TO THE SURRY POWER STATION. HIS BADGE ACCESS TO BOTH SURRY AND NORTH ANNA HAS ALSO BEEN TERMINATED. HIS FUTURE STATUS WITH VIRGINIA POWER WILL BE BASED ON THE EVALUATION OF AN EMPLOYEE ASSISTANCE PROGRAM AND A REPORT FROM THE MEDICAL REVIEW OFFICER. THE LICENSEE CONSIDERS THAT A WORK REVIEW IS UNNECESSARY.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

UPDATE 09/26/91 @ 10:20 BY PRICE TO GOULD THE LICENSEE CALLED TO CLASSIFY THE TYPE OF ALCOHOL TEST THAT WAS CONDUCTED ON THE INDIVIDUAL AS A PRE-ACCESS TEST AND NOT A "FOR CAUSE TEST". THE RI WILL BE INFORMED.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP EN NUMBER: 21849 EVENT DATE: 09-17-91 EVENT TIME: 08:19 NOTIFY DATE: 09-17-91 EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 19:00

OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: HFIT 26.73

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR 3 N N O COLD SHUTDOWN O COLD SHUTDOWN 4 N N O REFUELING O REFUELING

A FLORIDA POWER & LIGHT SUPERVISOR WAS CONFIRMED POSITIVE ON A "FOR CAUSE" ALCOHOL TEST.

THE RESULTS OF THIS TEST WERE . 07. THE AROMA OF ALCOHOL HAD BEEN DETECTED ON THE INDIVIDUAL AT THE MAIN ENTRY STATION BY PLANT SECURITY. HE STATED THAT HIS LAST CONSUMPTION OF ALCOHOL WAS 21:00 ON 9/16 AND IT WAS A HALF BOTTLE OF VODKA. THE INDIVIDUAL WORKS IN THE AREA OF BUDGET AND COST CONTROL. HE DID NOT GAIN PLANT ACCESS AND HE HAS BEEN DENIED PLANT ACCESS AND DID NOT WANT TO APPEAL. HE WILL BE PUT INTO THE EMPLOYEES ASSISTANCE PROGRAM. THE RI WAS INFORMED.

LICENSEE: ILLINOIS POWER CO.

SITE: CLINTON 1 EN NUMBER:21903 DOCKET: 05000461 EVENT DATE: 09-26-91 RX TYPE: BWR EVENT TIME: 09:50 VENDORS: GE-6 NOTIFY DATE. 09-26-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:56

OPS OFFICER: RUDY KARSCH 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR PWR CODE CRIT PWR

N Y 95 POWER OPERATION 95 POWER OPERATION

A SUPERVISOR WAS TESTED FOR CAUSE BASED UPON ALCOHOL ON THE BREATH. THE TEST CAME BACK POSITIVE AND THE INDIVIDUAL WAS ESCORTED OFF THE SITE. THE INDIVIDUAL HAD VITAL AREA ACCESS, BUT HIS WORK DID NOT AFFECT NUCLEAR OPERATIONS. THE INDIVIDUAL WAS SUBJECTED TO DISCIPLINARY ACTION AND OFFERED AN OPPORTUNITY TO ENROLL IN AN EMPLOYEE ASSISTANCE PROGRAM. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 21905 DOCKET: 05000443 EVENT DATE: 09-26-91 RX TYPE: PWR VENDORS: W-4-LP EVENT TIME: 14:00 NOTIFY DATE: 09-26-91 EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 16:56 OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
1 N N 0 REFUELING 0 REFUELING

A CRAFT CONTRACTOR SUPERVISOR TESTED POSITIVE FOR COCAINE. THIS WAS A RANDOM FOLLOW UP ON A PREVIOUS POSITIVE TEST. ACCESS FOR THIS INDIVIDUAL HAS BEEN REVOKED PERMANENTLY. THE INDIVIDUAL'S LAST ACCESS TO THE PROTECTED AREA WAS ON 8/20/91, AND NEVER HAD

ENTRY TO THE VITAL AREA. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2 EN NUMBER: 21920 DOCKET: 05000254 05000265 EVENT DATE: 09-30-91 RX TYPE: BWR BWR EVENT TIME: 02:38 VENDORS: GE-3 GE-3 NOTIFY DATE: 09-30-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 13:38 OPS OFFICER: WILLIAM HUFFMAN
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

CONTRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A CONTRACT FIRE PROTECTION INSPECTION SUPERVISOR WAS TESTED FOR CAUSE WITH A POSITIVE BREATHALIZER ALCOHOL LEVEL OF 0.09%. HIS ACCESS WAS IMMEDIATELY DENIED AND A WORK PERFORMANCE EVALUATION IS UNDERWAY. POTH LICENSEE CORPORATE MANAGEMENT AND THE NRC RESIDENT INSPECTOR HAVE BEEN INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

DOCKET: 05000237 05000249
RX TYPE: BWR BWR
VENDORS: GE-3 GE-3 EN NUMBER: 21922 EVENT DATE: 09-23-91 EVENT TIME: 15:00 NOTIFY DATE: 09-30-91 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 17:35 OPS OFFICER: WILLIAM HUFFMAN

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

2 N Y 99 POWER OPERATION 99 POWER OPERFTION
3 N N 0 REFUELING 0 REFUELING

CONTRACT SUPERVISOR FAILED RANDOM DRUG TEST.

A RANDOM DRUG TEST WAS GIVEN TO A CONTRACT SUPERVISOR (MILLWRIGHT GENERAL FOREMAN WORKING FOR HUNTER CORPORTATION) ON 9/23/91. AT 14:45 CDT ON 9/30/91, THE LICENSEE WAS INFORMED THAT TEST RESULTS WERE POSITIVE (THE LICENSEE WAS UNABLE TO IDENTIFY THE DRUG INVOLVED). PLANT ACCESS FOR THE INDIVIDUAL WAS IMMEDIATELY TERMINATED. A WORK PERFORMANCE INVESTIGATION IS UNDERWAY.

LICENSEE HAS NOTIFIED THE RESIDENT INSPECTOR.

LICENSEE: NEW YORK POWER AUTHORITY

SITE: FITZPATRICK 1 DOCKET: 05000333

EN NUMBER: 21938 EVENT DATE: 10-03-91 RX TYPE: BWR EVENT TIME: 07:45 NOTIFY DATE: 10-03-91 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 10:45

OPS OFFICER: THOMAS ANDREWS UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE WAS NOTIFIED THAT A NON-LICENSED SUPERVISOR HAD TESTED POSITIVE FOR COCAINE AT 0745 EDT ON 10/03/91. THE RANDOM DRUG TEST WAS ADMINISTERED ON 09/30/91. THE EMPLOYEE HAS ADMITTED TO THE USE.

THE INDIVIDUALS BADGE HAS BEEN PULLED AND HE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. FURTHER ACTIONS WILL BE BASED UPON HIS PROGRESS IN THE EMPLOYEE ASSISTANCE PROGRAM.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: GEORGIA POWER CO.

EN NUMBER: 22015 SITE: VOGTLE 1 2 DOCKET: 05000424 05000425 EVENT DATE: 10-14-91
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP
NOTIFY DATE: 10-15-91

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 17:22 OPS OFFICER: TIM MCGINTY

OPS OFFICER: TIM MCGINII

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N N 0 REFUELING 0 REFUELING
N Y 100 POWER OPERATION 100 POWER OPERATION CODE CRIT PWR

FITNESS FOR DUTY QUESTIONED DUE TO FALSIFICATION OF TESTING RECORDS

A NON-SUPERVISORY EMPLOYEE OF THE UTILITY'S FITNESS FOR DUTY TESTING CENTER WAS DISCOVERED TO HAVE FALSIFIED TESTING RECORDS. THE EMPLOYEE WAS TERMINATED UPON DISCOVERY OF THE RECORDS FALSIFICATION. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: WISCONSIN ELECTRIC POWER CO.

EN NUMBER: 22035 SITE: POINT BEACH 1 2 DOCKET: 05000266 05000301 EVENT DATE: 10-17-91 RX TYPE: PWR PWR VENDORS: W-2-LP W-2-LP EVENT TIME: 17:00 NOTIFY DATE: 10-17-91 EMERGENCY CLASS: N/A REGION: 3 STATE: WI TIME: 18:31

OPS OFFICER: CHAUNCEY GOULD

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

THE LICENSEE REPORTED THE UNINTENTIONAL ATTEMPT TO INTRODUCE ALCOHOL INTO THE PROTECTED AREA.

A PLANT MAINTENANCE PERSON HAD TWO LUNCH BOXES IN HIS CAR AND HE TOOK THE WRONG ONE (THE ONE WITH THE CAN OF BEER) INTO THE PROTECTED AREA AND MADE IT ABOUT 15-20FT PAST THE NOATH GATE HOUSE (HIS POINT OF ENTRY) WHEN HE REALIZED THAT HE GRABBED THE WRONG LUNCH BOX, SO HE CAME BACK TO THE GATE HOUSE AND REPORTED IT TO SECURITY. THE LUNCH BOX WAS X-RAYED WHEN HE CAME ON THE SITE, BUT IT JUST SHOWED UP AS A CAN. NO ALCOHOL TEST WAS REQUIRED. HE WAS ALLOWED TO RETURN THE LUNCH BOX TO THE CAR AND ALLOWED REENTRY TO THE SITE. THE RI WILL BE INFORMED.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 EN NUMBER: 22100 DOCKET: 05000313 EVENT DATE: 10-28-91 EVENT TIME: 09:00 RX TYPE: PWR VENDORS: B&W-L-LP NOTIFY DATE: 10-28-91

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 18:02

OPS OFFICER: JOHN MacKINNON 10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

Y 51 POWER OPERATION 51 POWER OPERATION

LICENSEE SENIOR REACTOR OPERATOR ACCESS IMMEDIATELY SUSPENDED UPON CONFIRMING POSITIVE FOR MARIJUANA FOR THE SECOND TIME IN LAST 4.5 MONTHS.

SEE HOO LOG BOOK FOR FURTHER DETAILS. RESIDENT INSPECTOR INFORMED BY THE LICENSEE.

LICENSEE: ILLINOIS POWER CO.

EN NUMBER: 22122 SITE: CLINTON 1 EVENT DATE: 10-31-91 DOCKET: 05000461 RX TYPE: BWR EVENT TIME: 09:57 NOTIFY DATE: 10-31-91 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:00

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

THE RESIDENT INSPECTOR SMELLED ALCOHOL IN THE AREA OF FIVE INDIVIDUALS WHILE FILLING OUT A RADIATION WORK PERMIT. HE OBTAINED THE NAMES OF THE INDIVIDUALS AND REPORTED THEM TO SECURITY. IN ACCORDANCE WITH LICENSEE PROCEDURES, THESE FIVE INDIVIDUALS WERE TESTED USING A BREATHALYZER. ONE INDIVIDUAL TESTED POSITIVE TO ALCOHOL AT 0.085 BAC. SEE HOO LOG FOR

ADDITIONAL DETAILS REGARDING LICENSEE ACTIONS.

THE NRC FOR LENT INSPECTOR HAS BEEN INFORMED OF THIS EVENT.

LICENTE: ARIZONA PUBLIC SERVICE CO.

EN NUMBER: 22220 SITE: PALO VERDE 2 DOCKET: 05000529 EVENT DATE: 11-12-91 EVENT TIME: 08:00 RX TYPE: PWR NOTIFY DATE: 11-12-91 VENDORS: CE80 EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 16:32

OPS OFFICER: WILLIAM MATTINGLY

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR

N 0 REFUELING

0 REFUELING

A SMALL BAG OF MARIJUANA SEEDS WERE FOUND IN THE PROTECTED AREA.

A FIRE WATCH FOREMAN FOUND A SMALL BAG (1.5"x2") CONTAINING MARIJUANA SEEDS WITHIN THE PROTECTED AREA (THE 140' ELEVATION OF THE AUXILIARY BUILDING NEAR THE ACCESS TO THE TURBINE BUILDING BREEZEWAY). THE LICENSEE DOES NOT KNOW HOW THE SEEDS GOT THERE OR WHO THEY BELONG TO.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 2 3 EN NUMBER: 22221 EVENT DATE: 11-12-91 DOCKET: 05000245 05000336 05000423 EVENT TIME: 15:30 RX TYPE: BWR PWR PWR VENDORS: GE-3 CE W-4-LP NOTIFY DATE: 11-12-91 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 17:13 OPS OFFICER: WILLIAM MATTINGLY FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73

UNIT	CODE	CRIT	PWR	INITIAL MODE	PWR	CURRENT MODE
1	N	N	0	COLD SHUTDOWN	0	COLD SHUTDOWN
2	N	N	0	HOT STANDBY	0	HOT STANDBY
3	N	N	0	COLD SHUTDOWN	0	COLD SHUTDOWN

SCAFFOLDING CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE.

A SCAFFOLDING ERECTION CONTRACT SUPERVISOR, WITH ACCESS TO THE VITAL AREA, TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG SAMPLE. THE SUPERVISOR WAS ESCORTED OFFSITE AND HIS ACCESS WAS TERMINATED. AN INVESTIGATION OF THE SUPERVISOR'S WORK IS UNDERWAY.

THE LICENSEE INFORMED THE STATE AND THE NRC RESIDENT INSPECTOR.

LICENSEE: WOLF CREEK NUCLEAR OPER. CORP.

SITE: WOLF CREEK 1 EN NUMBER: 22249 DOCKET: 05000482

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: KS

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

EVENT DATE: 11-15-91

EVENT TIME: 11:25

NOTIFY DATE: 11:25

NOTIFY D

LICENSEE DISCOVERED BAG OF SUSPECTED CONTRABAND MATERIAL INSIDE THE PA. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE INFORMED THE LOCAL SHERIFFS DEPARTMENT AND THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3 EN NUMBER: 22255

DOCKET: 05000206 05000361 05000362 EVENT DATE: 11-15-91
RX TYPE: PWR PWR PWR EVENT TIME: 12:15
VENDORS: W-3-LP CE CE NOTIFY DATE: 11-15-91
EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 19.40
OPS OFFICER: DICK JOLLIFFE
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 91 POWER OPERATION 91 POWER OPERATION
2 N N 0 HOT SHUTDOWN 0 HOT SHUTDOWN
3 N Y 100 POWER OPERATION 100 POWER OPERATION

PLANT EMPLOYEE TESTED POSITIVE FOR ALCOHOL. SEE HOO LOG FOR DETAILS. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1

DOCKET: 05000220

EVENT DATE: 11-22-91

RX TYPE: BWR

VENDORS: GE-2

EMERGENCY CLASS: N/A REGION: 1 STATE: NY

COPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 93 POWER OPERATION 93 POWER OPERATION

NON-LICENSED SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING RANDOM DRUG TEST. THE INDIVIDUAL HAD PERFORMED WORK WITHIN THE PROTECTED AREA PRIOR TO THE TEST. THE LICENSEE IS CHECKING INTO THE ACTIVITIES PERFORMED BY THIS INDIVIDUAL TO DETERMINE IF THERE WAS ANY SAFETY SIGNIFICANCE.

THE LICENSEE HAS PULLED THE SUPERVISOR'S UNESCORTED ACCESS. THE INDIVIDUAL HAS BEEN SUSPENDED AND REFERRED TO THE EMPLOYEE

ASSISTANCE PROGRAM. THIS IS THE FIRST POSITIVE TEST FOR THIS PERSON.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3

DOCKET: 05000206 05000361 05000362

RX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

WOTIFY DATE: 11-22-91

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

OF3 OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

TODE

OFFICER: THOMAS ANDREWS

1 N Y 91 POWER OPERATION 91 POWER OPERATION

2 N Y 67 POWEL OPERATION 67 POWER OPERATION

3 N Y 100 POWER OPERATION 100 POWER OPERATION

AT 1605 PST ON 11/22/91, THE LICENSEE'S MEDICAL REVIEW OFFICER DETERMINED THAT AN EMPLOYEE, WHO IS A LICENSED REACTOR OPERATOR ASSIGNED TO UNITS 2 AND 3, HAD TESTED POSITIVE ON A DRUG SCREEN URINALYSIS TEST. THIS IS THE FIRST POSITIVE DRUG TEST RESULT FOR THIS EMPLOYEE. THE EMPLOYEE HAS BEEN PLACED ON INVESTIGATORY SUSPENSION PENDING FURTHER MANAGEMENT REVIEW. THE DRUG SCREEN URINALYSIS TEST WAS ADMINISTERED AS PART OF THE RANDOM TESTING PROGRAM ON 11/15/91.

THE EMPLOYEE'S PROTECTED AND VITAL AREA UNESCORTED ACCESS AUTHORIZATION WAS TERMINATED WITHIN 10 MINUTES. THE EMPLOYEE WAS PERFORMING DUTIES AS A LICENSED OPERATOR WITHIN THE PLANT PROTECTED AND VITAL AREAS ON THE DAY OF THE TEST AND HAS CONTINUED TO PERFORM THESE DUTIES UNTIL TODAY.

THERE HAS BEEN NO MEDIA INTEREST IN THIS EVENT NOR HAVE OTHER OFFSITE AGENCIES BEEN NOTIFIED. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED BY THE LICENSEE.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3

DOCKET: 05000237 05000249

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

PWR

2 N N 0 REFUELING

N N 0 COLD SHUTDOWN

EVENT DATE: 11-26-91

EVENT TIME: 10:25

NOTIFY DATE: 11-26-91

FITNESS FOR DUTY

CURR CURRENT MODE

PWR

0 REFUELING
0 REFUELING

CONTRACT SUPERVISOR TESTED POSITIVE DURING RANDOM DRUG TESTING.

A CONTRACT SUPERVISOR INVOLVED IN NON-SAFETY RELATED WORK HAD HIS ACCESS DENIED AS OF 1055CST ON 11/26/91 AFTER TESTING POSITIVE FOR DRUGS (DATE TEST ADMINISTERED NOT KNOWN BY INDIVIDUAL MAKING REPORT). THE INDIVIDUAL HAS DISCUSSED THE FINDINGS WITH THE MEDICAL REVIEW OFFICER AND BEEN REFERRED TO THE CONTRACTOR'S EMPLOYEE ASSISTANCE PROGRAM (EAP). LICENSEE IS CONDUCTING A WORK PERFORMANCE INVESTIGATION PER PROCEDURE AND HAS INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: BOSTON EDISON CO.

SITE: PILGRIM 1 EN NUMBER: 22371

DOCKET: 05000293 EVENT DATE: 12-03-91

RX TYPE: BWR EVENT TIME: 10:34

VENDORS: GE-3 NOTIFY DATE: 12-03-91

EMERGENCY CLASS: N/A .EGION: 1 STATE: MA TIME: 15:55

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR ALCOHOL DURING RANDOM FITNESS FOR DUTY TEST.

A LICENSED OPERATOR WHO WAS ON DUTY IN THE CONTROL ROOM WAS CALLED FOR A RANDOM FITNESS FOR DUTY TEST. BREATHALYZER RESULTS AT 1034 EST WERE .104 BAC. A SECOND BREATHALYZER LEST AT 1043 EST YIELDED .121 BAC. THE LIMIT IS .040 BAC. THIS IS THIS INDIVIDUAL'S FIRST POSITIVE TEST.

THE LICENSEE SEARCHED THE CONTROL ROOM AREA, THE OPERATORS PERSONAL LOCKER AND VEHICLE FOR CONTRABAND. NONE WAS FOUND.

THE OPERATOR WAS ADMITTED TO THE PROTECTED AREA AT 0623 EST. THE INDIVIDUAL WAS NOT DIRECTLY INVOLVED IN ANY SAFETY RELATED ACTIVITY DURING THE TIME HE WAS IN THE PROTECTED AREA. CONTROL ROOM PERSONNEL WHO WORKED IN THE AREA OF THE INDIVIDUAL AS WELL AS SECURITY GUARDS WHO ADMITTED HIM TO THE PROTECTED AREA OBSERVED NO UNUSUAL ACTIONS NOR DETECTED ANY SMELL OF ALCOHOL AROUND THE INDIVIDUAL.

THE INDIVIDUALS ACCESS TO THE PROTECTED AREA HAS BEEN PULLED PENDING FURTHER INVESTIGATION. THE INDIVIDUAL IS SCHEDULED TO MEET WITH THE LICENSEE MEDICAL REVIEW OFFICER ON 12/04/91. THE INDIVIDUAL AGREED TO SUBMIT TO A BLOOD TEST. THE RESULTS ARE EXPECTED BACK ON 12/04/91.

THE LICENSEE DOES NOT PLAN TO ISSUE A PRESS RELEASE AT THIS TIME. THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

**** COMMISSIONERS ASSISTANT'S BRIEFING @ 1700 EST ON 12/03/91

BRIEFER:

ROGGE - REGION 1

NOTIFIED:

AEOD (JORDAN, ROSS) IRB (WEISS, ZECH)

NRR-EO (ROSSI, THOMAS)

NMSS (HICKEY)

CONGRESSIONAL AFFAIRS (CALLAHAN)

STATE PROGRAMS (MILLER)

INTERNATIONAL PROGRAMS (UPSHAW)

SECY (BATES)

EDO (BATEMAN, WECHSELBERGER) PUBLIC AFFAIRS (FOUCHARD) CURTIS' OFFICE (CONNAUGHTON) ROGERS' OFFICE (SCARBOROUGH) REMICK'S OFFICE (CROCKETT) SELIN'S OFFICE (BROCKMAN)

PARTICIPATED: NRR-EO (THOMAS)

CONGRESSIONAL AFFAIRS (CALLAHAN)

STATE PROGRAMS (COMBS)

INTERNATIONAL PROGRAMS (UPSHAW)

SECY (BATES) EDO (STETKA)

PUBLIC AFFAIRS (FOUCHARD) CURTIS' OFFICE (CONNAUGHTON) ROGERS' OFFICE (BILHORN) REMICK'S OFFICE (CROCKETT) SELIN'S OFFICE (BROCKMAN)

REGION 1 (LINVILLE, MILLER, ROGGE)

LICENSEE: GEORGIA POWER CO.

EN NUMBER: 22426 SITE: VOGTLE 1 2 DOCKET: 05000424 05000425 EVENT DATE: 12-10-91 EVENT TIME: 16:30 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 12-10-91

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 17:32

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 98 POWER OPERATION 98 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE REPORTED A PROBABLE INCIDENT OF SAMPLE TAMPERING AT THE FITNESS FOR DUTY FACILITY AT VOGTLE.

SECURITY INVESTIGATION INDICATES THAT THERE IS REASON TO BELIEVE A CONTRACT PARAMEDIC EMPLOYEE, AND MEMBER OF THE FITNESS FOR DUTY TESTING STAFF, SUBSTITUTED A DRUG FREE SAMPLE FOR HER OWN RANDOMLY COLLECTED SPECIMEN. COMPENSATORY MEASURES HAVE BEEN TAKEN. ADDITIONAL INFORMATION IS AVAILABLE IN THE HOO LOG. THE

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: LONG ISLAND LIGHTING CO

EN NUMBER: 22475 SITE: SHOREHAM 1 DOCKET: 05000322 EVENT DATE: 12-16-91 EVENT TIME: 09:36 RX TYPE: BWR VENDORS: GE-4 NOTIFY DATE: 12-16-91

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 15:27

OPS OFFICER: GREG SCARFO UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N

N N O REFUELING 0 REFUELING

AN I&C SUPERVISOR TESTED POSITIVE FOR ALCOHOL LEVELS ABOVE THE .04 LIMIT DURING A RANDOM TEST. THE SUPERVISOR WAS ESCORTED OFFSITE FOR FURTHER TESTING. THIS PERSON HAD ACCESS TO VITAL AREAS AND SAFETY SYSTEM BUT HAD NOT LEFT THE OFFICE BEFORE BEING EXPELLED FROM THE SITE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 22527 EVENT DATE: 12-26-91 DOCKET: 05000331 EVENT TIME: 10:15 RX TYPE: BWR NOTIFY DATE: 12-26-91 VENDORS: GE-4

EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 12:23

OPS OFFICER: TIM MCGINTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR CODE CRIT PWR
N 95 POWER OPERATION 95 POWER OPERATION

A LICENSED OPERATOR WAS CONFIRMED TO HAVE TESTED POSITIVE FOR COCAINE. THE OPERATOR WAS ON DUTY AT THE TIME OF THE RANDOM TEST. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN TO REMOVE THE PERSONS UNESCORTED ACCESS. THE LICENSEE WILL BE CONDUCTING A FOLLOWUP INVESTIGATION TO DETERMINE ADDITIONAL CIRCUMSTANCES RELATIVE TO THIS EVENT. THE LICENSEE WILL ALSO BE DETERMINING IF ANY PAST EVENTS WERE EITHER INITIATED OR EXACERBATED BY THIS PERSONS ACTIVITIES. THE SECURITY DIVISION WILL BE NOTIFYING THE PUBLIC RELATIONS DIVISION, WHICH WILL DETERMINE IF A PRESS RELEASE WILL BE MADE. THE LICENSEE NOTIFIED THE RESIDENT INSPECTOR AND WILL BE NOTIFYING STATE AGENCIES AS PROCEDURALLY REQUIRED. SEE THE HOO LOG FOR ADDITIONAL DETAILS.

Ouery: 1992 EVENT REPORTS: hfit

LICENSEE: CONSUMERS POWER CO.

EN NUMBER: 22556 SITE: PALISADES 1 EVENT DATE: 01-03-92 DOCKET: 05000255 EVENT TIME: 13:00 RX TYPE: PWR NOTIFY DATE: 01-03-92 VENDORS: CE

TIME: 13:39 EMERGENCY CLASS: N/A REGION: 3 STATE: MI

OPS OFFICER: THOMAS ANDREWS 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR 100 POWER OPERATION 100 POWER OPERATION

LICENSEE RECEIVED NOTIFICATION FROM AN EMPLOYEE FAMILY MEMBER THAT THE EMPLOYEE (AN UNLICENSED SUPERVISOR) VOLUNTARILY CHECKED INTO THE HORIZON TREATMENT CENTER FOR ALCOHOL ABUSE.

THE LICENSEE HAS REVOKED THE EMPLOYEE'S UNESCORTED ACCESS. THE EMPLOYEE WAS AT WORK THIS MORNING, BUT NOTHING UNUSUAL WAS OBSERVED BY THE SUPERVISOR'S SUPERINTENDENT. THE EMPLOYEE TESTED POSITIVE UNDER THE LICENSEE'S TESTING PROGRAM IN 1987. THE LICENSEE PLANS TO ALLOW THE EMPLOYEE TO RETURN TO WORK AFTER TREATMENT WITH FOLLOWUP TESTING PER 10-CFR-26.73

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2 EN NUMBER: 22557 DOCKET: 05000334 05000412
RX TYPE: PWR PWR
VENDORS: W-3-LP W-3-LP EVENT DATE: 12-04-91 EVENT TIME: 11:30 NOTIFY DATE: 01-03-92 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 16:15

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSEE DETERMINED AT 1610 EST ON 01/03/92 THAT A POSITIVE DRUG TEST RESULT INVOLVING A SHIFT TECHNICAL ADVISOR WAS POTENTIALLY REPORTABLE.

ON 11/27/91, A RANDOM FITNESS FOR DUTY TEST WAS PERFORMED ON AN ON-DUTY SHIFT TECHNICAL ADVISOR. ON 12/04/91, THE LICENSEE RECEIVED THE RESULTS FROM THE TEST AND ON 12/05/91, DETERMINED THAT THE RESULTS WERE POSITIVE FOR MARIJUANA. THE EMPLOYEE WAS SUSPENDED ON 12/05/91 AND SUBSEQUENTLY TERMINATED.

THE LICENSEE INITIALLY DETERMINED THAT THIS EVENT WAS NOT REPORTABLE UNDER 10-CFR-26.73. THIS EVENT WAS LOGGED FOR INCLUSION IN THE LICENSEE'S SEMI-ANNUAL FITNESS FOR DUTY REPORT.

AFTER FURTHER REVIEW BY THEIR LICENSING DEPARTMENT, THE LICENSEE DISCOVERED THAT THE EMPLOYEE HAD OBTAINED A LIMITED LICENSE UNDER PART 55 FOR FUEL MOVEMENT. BASED UPON THIS DISCOVERY, THE LICENSEE HAS DETERMINED THAT THIS EVENT WAS POTENTIALLY REPORTABLE. THE LICENSEE IS INVESTIGATING THE WORK PERFORMED BY THIS INDIVIDUAL TO SEE IF HE WAS INVOLVED IN ANY SAFETY RELATED ACTIVITY DURING THE TIME BETWEEN 11/27 AND 12/05/91.

THE NRC RESIDENT HAS BEEN INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2

DOCKET: 05000373 05000374

RX TYPE: BWR BWR

VENDORS: GE-5 GE-5

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N REFUELING

CONTRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL ON A FOR CAUSE TEST. THE TEST WAS PERFORMED USING A BREATHALYZER. THE INDIVIDUAL REFUSED TO ALLOW A BLOOD TEST TO BE PERFORMED. THE INDIVIDUAL'S SITE ACCESS HAS BEEN PULLED AND THE CONTRACTOR HAS SUSPENDED THE SUPERVISOR PENDING THE RESULTS OF THE LICENSEE'S / CONTRACTOR'S INVESTIGATION. SEE HOO LOG FOR MORE DETAILS.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: NEW YORK POWER AUTHORITY SITE: FITZPATRICK 1 EN NUMBER: 22654 DOCKET: 05000333 EVENT DATE: 01-21-92 RX TYPE: BWR EVENT TIME: 15:00 VENDORS: GE-4 NOTIFY DATE: 01-22-92 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 14:55 OPS OFFICER: JOHN MacKINNON 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

LICENSED OPERATOR TESTED POSITIVE FOR COCAINE LAST 05/02/91 AND ON THIS DATE HIS OPERATORS LICENSE WAS SUSPENDED AND IT HAS BEEN SUSPENDED SINCE THIS DATE. YESTERDAY (01/21/92) THIS INDIVIDUAL WAS CALLED IN FOR A FOLLOW UP DRUG TEST. THIS INDIVIDUAL LEFT THE SITE AND DID NOT SHOW UP FOR THE DRUG TEST. LICENSEE CONSIDERED THIS INDIVIDUALS ACTION OF NOT SHOWING UP FOR THE DRUG TEST AND

LEAVING THE SITE AS AN INDICATION THAT HE WAS TAKING SOME ILLEGAL SUBSTANCE. THIS INDIVIDUALS SITE ACCESS & HIS UNESCORTED ACCESS TO THE PLANT WAS REVOKED ON 01/21/92. LICENSEE IS REVIEWING FURTHER ACTIONS THAT THEY WILL TAKE AGAINST THIS INDIVIDUAL.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: BOSTON EDISON CO.

SITE: PILGRIM 1 EN NUMBER: 22673 EVENT DATE: 01-23-92 DOCKET: 05000293 EVENT TIME: 13:11 RX TYPE: BWR VENDORS: GE-3 NOTIFY DATE: 01-24-92

EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 12:17

OPS OFFICER: GREG SCARFO

FITNESS FOR DUTY CURR CURRENT MODE 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

A PLANT EMPLOYEE FAILED A RANDOM DRUG TEST FOR ALCOHOL.

THE RESULTS OF RANDOM DRUG TESTS PERFORMED BETWEEN 1311 EST AND 1328 EST ON A CONTRACTOR/SUPERVISOR INDICATE A BLOOD-ALCOHOL LEVEL ABOVE THE .04 BAC LIMIT EXTRAPOLATED TO 0745 EST WHEN HE ENTERED A PROTECTED AREA FOR WORK. HIS ACCESS TO PROTECTED AREAS WAS DENIED AT 1350 EST AFTER THE RESULTS OF THE TESTING WERE DETERMINED. NO ALCOHOL CONSUMPTION OCCURRED WITHIN THE PROTECTED AREA AND ALL WORK PERFORMED BY THE EMPLOYEE HAS BEEN IDENTIFIED AND RE-CHECKED. FURTHER MANAGEMENT ACTIONS ARE YET TO BE DETERMINED.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

EN NUMBER: 22702 SITE: MCGUIRE 1 2 DOCKET: 05000369 05000370 EVENT DATE: 01-27-92 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 09:35 NOTIFY DATE: 01-28-92 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 08:23

OPS OFFICER: RUDY KARSCH

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
1 N

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN N N 0 REFUELING 0 REFUELING

A SUPERVISOR WHO HAD VITAL AREA ACCESS TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG SCREENING. THE INDIVIDUAL HAS BEEN REMOVED FROM SERVICE. THE LICENSEE IS STILL INVESTIGATING THE SITUATION TO DETERMINE CORRECTIVE ACTION. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1 EN NUMBER: 22724 DOCKET: 05000528 EVENT DATE: 01-31-92 EVENT TIME: 09:25 RX TYPE: PWR VENDORS: CE80 NOTIFY DATE: 01-31-92

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 15:36

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

NON-LICENSED SUPERVISOR TESTED POSITIVE FOR COCAINE.

A POSITIVE DRUG TEST FOR COCAINE WAS CONFIRMED FOR A UNIT 1 RADIATION PROTECTION SUPERVISOR. SECURITY WAS IMMEDIATELY NOTIFIED AND THE INDIVIDUAL'S PROTECTED AREA ACCESS WAS CANCELED. THE INDIVIDUAL WAS NOT IN THE PROTECTED AREA AT THE TIME. THE LICENSEE HAS TERMINATED THE INDIVIDUAL'S EMPLOYMENT. THE LICENSEE STATES THAT A WORK HISTORY SAFETY IMPACT REVIEW FOR THIS INDIVIDUAL IS UNNECESSARY. THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. NO OTHER AGENCY NOTIFICATION OR PRESS RELEASE IS ANTICIPATED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 2 3 EN NUMBER: 22747 DOCKET: 05000361 05000362 EVENT DATE: 02-05-92 RX TYPE: PWR PWR EVENT TIME: 09:30 VENDORS: CE CE NOTIFY DATE: 02-05-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 18:13 OPS OFFICER: MARK MILLER

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

CODE CRIT PWR PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 0 STARTUP 0 REFUELING

CONTRACT EMPLOYEE FOUND UNFIT FOR DUTY.

AFTER BEING OBSERVED TO BE POTENTIALLY UNFIT FOR DUTY, A NON-SCE EMPLOYEE SUBMITTED TO A FOR-CAUSE/IMPAIRMENT TEST WITH POSITIVE RESULTS FOR ALCOHOL. THE EMPLOYEE'S PROTECTED AND VITAL AREA UNESCORTED ACCESS AUTHORIZATION WAS IMMEDIATELY TERMINATED BASED UPON RESULTS OF THE BREATH TEST POSITIVE RESULTS AT 1814 PST ON 2/4/92. THE DAY OF THE POSITIVE TEST, THE INDIVIDUAL WAS REPORTING TO WORK AND HAD NOT ENTERED THE PROTECTED AREA.

AT 0930 PST ON 2/5/92, FOLLOWING EVALUATION OF RECORDS IN SUPPORT OF THE BREATH TEST RESULTS, THE TEST WAS DECLARED TO BE POSITIVE FOR ALCOHOL. AS A RESULT OF THE TEST RESULTS, THE WORKER'S SITE ACCESS HAS BEEN PERMANENTLY DENIED, IN ACCORDANCE WITH SCE'S

POLICY. THE INDIVIDUAL HAS BEEN EMPLOYED ON-SITE SINCE 1/22/92.

THE RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1 2 EN NUMBER: 22762 DOCKET: 05000424 05000425 EVENT DATE: 02-07-92 RX TYPE: PWR PWR RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 14:10 NOTIFY DATE: 02-07-92

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 15:18

OPS OFFICER: WILLIAM HUFFMAN

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR MARIJUANA.

A LICENSED REACTOR OPERATOR RECEIVED A CONFIRMED POSITIVE FOR MARIJUANA FOLLOWING A RANDOM DRUG SCREENING TEST. THE INDIVIDUAL'S ACCESS HAS BEEN DENIED. A SAFETY WORK PERFORMANCE REVIEW IS IN PROGRESS. THE INDIVIDUAL WAS NOT ON SITE AT THE TIME BUT HAS BEEN CONTACTED BY THE LICENSEE'S MEDICAL REVIEW OFFICER.

THE NRC SENIOR RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: CONSUMERS POWER CO.

SITE: PALISADES 1 EN NUMBER: 22830 DOCKET: 05000255 EVENT DATE: 02-18-92 RX TYPE: PWR EVENT TIME: 07:38 VENDORS: CE NOTIFY DATE: 02-18-92 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 08:14

OPS OFFICER: MARK MILLER

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

CONTRACT WORKER TESTED POSITIVE FOR MARIJUANA.

A CONTRACT WORKER, ON SITE FOR THE CURRENT OUTAGE, TESTED POSITIVE FOR MARIJUANA DURING AN IN-PROCESSING DRUG SCREENING. DUE TO AN ADMINISTRATIVE ERROR, THE WORKER HAD BEEN GRANTED ACCESS TO THE PROTECTED AREA PRIOR TO THE RESULTS OF HIS DRUG SCREEN BEING KNOWN TO THE LICENSEE. THE WORKER ENTERED THE PROTECTED AREA AT 0658, HIS POSITIVE TEST RESULTS WERE OBTAINED AT 0738, AND HE WAS REMOVED FROM THE PROTECTED AREA AT 0757. THE WORKER DID NOT ENTER A VITAL AREA.

THE RESIDENT INSPECTOR AND REGION 3 HAVE BEEN INFORMED.

SITE: SAN ONOFRE 1 2 3 EN NUMBER: 22894
DOCKET: 05000206 05000361 05000362 EVENT DATE: 02-26-92 RX TYPE: PWR PWR PWR EVENT TIME: 14:18
VENDORS: W-3-LP CE CE NOTIFY DATE: 02-27-92 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 16:06 OPS OFFICER: RUDY KARSCH

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N Y 93 POWER OPERATION 93 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION 3 N N 0 REFUELING 0 REFUELING

FITNESS FOR DUTY 24 HOUR REPORT: A CONTRACT EMPLOYEE SUPERVISING PIPEFITTER FAILED A SCHEDULED SUBSTANCE SCREENING.

THE EMPLOYEE HAD VITAL AREA ACCESS TO ALL THREE SONGS UNITS. VITAL AREA ACCESS HAS BEEN CANCELED. THE LICENSEE HAS NOT YET DETERMINED THE NECESSITY FOR A REVIEW OF THE INDIVIDUALS WORK. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AND REGION 5 (DOUG SCHUSTER). SEE HOO LOG FOR FURTHER DETAILS.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: SAINT LUCIE 1 2 EN NUMBER: 22921 DOCKET: 05000335 05000389
RX TYPE: PWR PWR
VENDORS: CE CE EVENT DATE: 03-02-92 EVENT TIME: 10:00 VENDORS: CE CE NOTIFY DATE: 03-02-92

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 14:17 OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY

LICENSEE SUPERVISOR TESTED POSITIVE FOR MARIJUANA.

FLORIDA POWER AND LIGHT MECHANICAL MAINTENANCE FOREMAN TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG TEST CONDUCTED ON 2/25/92. THE TEST WAS CONFIRMED POSITIVE TODAY BY THE MEDICAL REVIEW OFFICER. THE INDIVIDUAL INVOLVED WAS TERMINATED PER COMPANY POLICY. A SAFETY AND QUALITY WORK REVIEW IS IN PROGRESS. THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BYRON 1 EN NUMBER: 22979 DOCKET: 05000454 EVENT DATE: 03-06-92 RX TYPE: PWR EVENT TIME: 10:00 VENDORS: W-4-LP NOTIFY DATE: 03-10-92 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 10:18

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR CODE CRIT PWR
N 0 REFUELING 0 REFUELING

AN INDIVIDUAL TESTED FOR CAUSE WAS NOT PROPERLY SCREENED DUE TO A PROCEDURAL DEFICIENCY.

ON MARCH 6, 1992 AN INDIVIDUAL WAS GIVEN A BREATH TEST FOR ALCOHOL BECAJSE OF SYMPTOMS OF INTOXICATION. HE WAS BELOW THE ACTION THRESHOLD AND RETURNED TO DUTY. AT THAT TIME A TEST FOR OTHER DRUGS SHOULD ALSO HAVE BEEN PERFORMED TO COMPLY WITH CORPORATE POLICY. THE ADDITIONAL TESTING WAS NOT DONE DUE TO A DEFICIENCY IN THE SITE PROCEDURE. THE REQUIREMENT WAS OMITTED.

THE INDIVIDUAL HAS NOW HAD THE ADDITIONAL TESTS AND IS ON ADMINISTRATIVE HOLD PENDING RECEIPT OF THE TEST RESULTS. A PROCEDURE REVISION IS BEING PROCESSED. SITE SECURITY WILL CONFIRM THAT THIS PROBLEM DOES NOT EXIST AT OTHER COMMONWEALTH EDISON SITES. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

DOCKET: 05000237 05000249
RX TYPE: BWR BWR
VENDORS: GE-3 GE-3 EN NUMBER: 23050 SITE: DRESDEN 2 3 EVENT DATE: 03-19-92 EVENT TIME: 11:20 NOTIFY DATE: 03-19-92 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:13 OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

2 N Y 73 POWER OPERATION 73 POWER OPERATION
3 N N 0 REFUELING 0 REFUELING

THE LICENSEE REPORTED A FITNESS FOR DUTY REPORT ON A LICENSED OPERATOR.

A LICENSED OPERATOR TESTED POSITIVE ON A RANDOM ALCOHOL/DRUG TEST ON 03/18/92 (THE LICENSEE COULD NOT TELL ME WHAT HE WAS TESTED POSITIVE FOR). UPON DISCOVERY, HIS ACCESS WAS DENIED AND HE IS SCHEDULED TO MEET WITH THE EMPLOYEE ASSISTANCE PROGRAM. THEY ARE ALSO INVESTIGATING HIS WORK PERFORMANCE. THE RI WAS INFORMED.

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 23097 DOCKET: 05000341 EVENT TIME: 11:38 NOTIFY DATE: 03-26-92 EVENT DATE: 03-25-92 RX TYPE: BWR VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:13

OPS OFFICER: DICK JOLLIFFE

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73

UNIT		RX	-	INITIAL MODE	CURR	CURRENT MODE	
2	The same and the			POWER OPERATION		POWER OPERATION	

- SUPERVISOR TESTED POSITIVE FOR DRUGS A SECOND TIME SINCE JUNE 1987 -

A SUPERVISOR WITH UNESCORTED PLANT ACCESS AUTHORIZATION WHO WORKS ON NONSAFETY RELATED EQUIPMENT TESTED POSITIVE FOR DRUGS. THE POSITIVE RESULTS ARE FROM A FOLLOWUP DRUG / ALCOHOL SCREENING TEST CONDUCTED ON 03/20/92.

LICENSEE SUSPENDED THE SUPERVISOR'S SITE ACCESS AUTHORIZATION AT 1145

ON 03/25/92. LICENSEE DETERMINED THAT THE SUPERVISOR HAD NOT ENTERED

THE SITE SINCE 12/19/91. LICENSEE HAS REFERRED THE SUPERVISOR TO THE EMPLOYEE ASSISTANCE PROGRAM FOR FURTHER EVALUATION.

THIS WAS THE SUPERVISOR'S SECOND POSITIVE TEST FOR DRUGS. THE FIRST POSITIVE TEST WAS IN JUNE 1987.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: OCONEE 1 2 3 EN NUMBER: 23100 DOCKET: 05000269 05000270 05000287 EVENT DATE: 03-26-92 RX TYPE: PWR PWR PWR EVENT TIME: 07:15 VENDORS: B&W-L-LP B&W-L-LP B&W-L-LP NOTIFY DATE: 03-26-92 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 11:28 OPS OFFICER: THOMAS ANDREWS FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 1 2 N

A CORPORATE OFFICE SUPERVISOR WITH UNESCORTED ACCESS AT OCONEE TESTED POSITIVE FOR COCAINE.

100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE PERFORMED A RANDOM DRUG SCREEN TEST OF THE INDIVIDUAL ON 03/17/92 AND RECEIVED NOTIFICATION AT 0715 ON 03/26/92 THAT THE RESULTS ARE A CONFIRMED POSITIVE RESULT. THE EMPLOYEE'S ACCESS HAS BEEN PUT ON HOLD. THE EMPLOYEE HAS BEEN PULLED FROM SERVICE AND REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: VIRGINIA POWER CO.

SITE: SURRY 1 2

DOCKET: 05000280 05000281

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EVENT TIME: 10:55

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: VA

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 REFUELING
2 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACT FOREMAN TESTED POSITIVE FOR ALCOHOL DURING RANDOM ALCOHOL BREATH TEST.

THE INDIVIDUAL REPORTED TO WORK AT 0600 EST AND WAS TESTED AT 1055 EST. THE BREATHALYZER RESULTS AT 1055 EST WERE 0.050 AND 0.056 BLOOP ALCOHOL CONTENT. THE LIMIT IS 0.040 BLOOD ALCOHOL CONTENT. A BLOOD TEST WAS NOT PERFORMED. THE INDIVIDUAL WAS ESCORTED OFFSITE AND HIS ACCESS HAS BEEN PULLED. THIS PERSON WAS NOT PERFORMING WORK NOR SUPERVISING PEOPLE RESPONSIBLE FOR PERFORMING WORK THAT WAS SAFETY RELATED.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2

DOCKET: 05000315 05000316

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: MI

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

EVENT DATE: 03-29-92

EVENT TIME: 06:25

NOTIFY DATE: 03-29-92

FITNESS FOR DUTY

CURR CURRENT MODE

CODE CRIT PWR

PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

A CONTRACT SUPERVISOR ASSIGNED TO PERFORM DUTIES WITHIN THE SCOPE OF 10 CFR PART 26 WAS DETERMINED TO BE UNFIT FOR SCHEDULED WORK DUE TO CONSUMPTION OF ALCOHOL.

ON MARCH 29, 1992, AT 0625 EST, AS A CONTRACT SUPERVISOR REQUESTED HIS PHOTO BADGE FOR ACCESS TO THE PLANT PROTECTED AREA, A SECURITY OFFICER DETECTED AN ODOR NORMALLY ASSOCIATED WITH INTOXICANTS. THE INDIVIDUAL WAS DENIED ACCESS. AT 0651, A TEST WAS CONDUCTED USING A BREATH ANALYZER DEVICE. THE TEST REFLECTED A BLOOD ALCOHOL CONCENTRATION [BAC] OF 0.051%. A SUBSEQUENT TEST WITH THE SAME DEVICE AT 0657 EST REFLECTED 0.050% BAC. CONFIRMATORY TESTS USING ANOTHER BREATH ANALYZER DEVICE WERE CONDUCTED AT 0710 AND 0716 EST. THE RESPECTIVE BAC READINGS WERE 0.045% AND 0.042%. AS A RESULT OF THIS POSITIVE ALCOHOL TEST,

THE TEST WAS ELEVATED TO "FOR CAUSE" AND URINE WAS COLLECTED FOR TESTING FOR OTHER SUBSTANCES.

ALTHOUGH THE SUBJECT WAS A SUPERVISOR, HE HAS NOT WORKED ON SAFETY RELATED SYSTEMS OR PERFORMED ANY CRITICAL WORK THAT MIGHT AFFECT THE SAFETY OR SECURITY OF THE PLANT. IN ACCORDANCE WITH THE LICENSEE FITNESS FOR DUTY PROGRAM, THE INDIVIDUAL WILL BE DENIED ACCESS FOR A MINIMUM OF 14 DAYS. AFTER THIS TIME, HE MUST AT MINIMUM, PROVIDE PROOF OF COUNSELLING, SUBMIT TO OBSERVED -CONTROLLED SUBSTANCE TESTING, AND PARTICIPATE IN AN ACCELERATED FOLLOW UP RANDOM TESTING PROGRAM.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED OF THIS EVENT. NO OTHER NOTIFICATIONS ARE REQUIRED OR ANTICIPATED AT THIS TIME.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1 EN NUMBER: 23216

DOCKET: 05000271 EVENT DATE: 04-10-92 RX TYPE: BWR EVENT TIME: 08:33

VENDORS: GE-4 NOTIFY DA.E: 04-10-92

EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 12:47

OPS OFFICER: MARK MILLER

OPS OFFICER: MARK MILLER

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N 0 REFUELING 0 0 REFUELING

EMPLOYEE TESTED POSITIVE FOR ALCOHOL.

A 'FOR CAUSE' TEST FOR ALCOHOL WAS ADMINISTERED TO AN EMPLOYEE AFTER A SUPERVISOR CONCLUDED THAT THE INDIVIDUAL'S BEHAVIOR INDICATED POTENTIAL SUBSTANCE ABUSE. THE CONFIRMATORY TEST INDICATED A BLOOD ALCOHOL LEVEL OF .160 PERCENT ALCOHOL, WHICH EXCEEDED THE LICENSEE'S ADMINISTRATIVE LIMIT OF .040 PERCENT.

THE INDIVIDUAL'S SITE ACCESS HAS BEEN REVOKED FOR A MINIMUM OF 14 DAYS AND THE INDIVIDUAL HAS BEEN REFERRED TO THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM. PLANT MANAGER APPROVAL WILL BE REQUIRED PRIOR TO THE INDIVIDUAL RESUMING DUTIES. THE INDIVIDUAL'S INVOLVEMENT IN PLANT ACTIVITIES FOR THE TIME PERIOD PRIOR TO THE TEST HAS BEEN REVIEWED.

THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2 EN NUMBER: 23311 DOCKET: 05000254 05000265 EVENT DATE: 04-22-92

RX TYPE: BWR BWR EVENT TIME: 18:10 VENDORS: GE-3 GE-3 NOTIFY DATE: 04-23-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:20

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT	SCRAM	RX		INITIAL MODE	CURR	CURRENT MODE
1	N	Y	100	POWER OPERATION	100	POWER OPERATION
2	N	N	0	COLD SHUTDOWN	0	COLD SHUTDOWN

CONTRACT EMPLOYEE TESTED POSITIVE FOR ALCOHOL.

A CONTRACTOR/SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A FOLLOW-UP DRUG TEST. THE EMPLOYEE WAS IMMEDIATELY DENIED ACCESS TO VITAL AREAS AND ESCORTED OFFSITE. HIS PERMANENT STATUS IS BEING REVIEWED BY THE LICENSEE. THE LICENSEE INITIATED A WORK PERFORMANCE INVESTIGATION AND THE RESULTS ARE PENDING. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 1 2 3 EN NUMBER: 23340

DOCKET: 05000010 05000237 05000249 EVENT DATE: 04-27-92

RX TYPE: BWR BWR BWR EVENT TIME: 10:40

VENDORS: GE-1 GE-3 GE-3 NOTIFY DATE: 04-27-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 17:28

OPS OFFICER: MARK MILLER

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 0
2 N Y 70 POWER OPERATION 70 POWER OPERATION
3 N Y 26 FOWER OPERATION 26 POWER OPERATION

FITNESS FOR DUTY.

POSITIVE RESULTS WERE OBTAINED FROM A RANDOM FITNESS FOR DUTY (FFD) TEST ADMINISTERED TO A CONTRACT SUPERVISOR. THE TEST WAS ADMINISTERED ON 4/20/92. THE LICENSEE HAS COMMENCED A WORK PERFORMANCE EVALUATION FOR THE SUBJECT INDIVIDUAL. THE INDIVIDUAL'S ACCESS TO THE PROTECTED AREA HAS BEEN REVOKED. THE LICENSEE DID NOT HAVE INFORMATION REGARDING THE SUBSTANCE AT THE TIME OF THIS NOTIFICATION. THE LICENSEE COULD NOT STATE WHAT FURTHER ACTIONS WOULD BE TAKEN WITH RESPECT TO THIS INDIVIDUAL. ACCORDING TO THE LICENSEE, THE DISPOSITION OF THIS CASE (e.g. EMPLOYEE ASSISTANCE, TERMINATION) IS THE RESPONSIBILITY OF THE CONTRACTOR.

THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: SACRAMENTO MUNICIPAL UTILITY DISTRI

SITE: RANCHO SECO 1 EN NUMBER: 23362

DOCKET: 05000312 EVENT DATE: 04-28-92

RX TYPE: PWR EVENT TIME: 14:25

VENDORS: B&W-L-LP NOTIFY DATE: 04-29-92

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 14:38

OPS OFFICER: TIM MCGINTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
1 N N 0 DECOMMISSIONED PWR 0 DECOMMISSIONED

THE LICENSEE OBTAINED A CONFIRMED POSITIVE TEST REGARDING FITNESS FOR DUTY ON A SUPERVISORY PERSON. THE EMPLOYEE WAS IMMEDIATELY DENIED ACCESS TO THE PROTECTED AREA AND WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE LICENSEE RECEIVED NOTIFICATION ON 4/28/92, HOWEVER THE EMPLOYEE ACTUALLY TOOK THE TEST ON 4/21/92. RANCHO SECO'S POSSESSION ONLY LICENSE BECAME EFFECTIVE AT MIDNIGHT ON 4/27/92. SINCE THE SAMPLE WAS OBTAINED WHILE THE OPERATING LICENSE WAS STILL EFFECTIVE, THE LICENSEE CONSIDERS THAT PART 26 STILL APPLIED IN THIS INSTANCE. THE LICENSEE NOTIFIED REGION V (SCHUSTER). SEE HOO LOG FOR DETAILS.

LICENSEE: FLORIDA POWER & LIGHT CO.

EN NUMBER:23425 SITE: SAINT LUCIE 1 2 DOCKET: 05000333 05000389
RX TYPE: PWR PWR EVENT DATE: 05-08-92 EVENT TIME: 09:10 NOTIFY DATE: 05-00-92 VENDORS: CE CE EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 14:08

OPS OFFICER: GREG SCARFO

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE 1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N N 0 REFUELING

A CONTRACT FOREMAN TESTED POSITIVE DURING A RANDOM DRUG TEST.

A CONTRACT FOREMAN TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST.

THE WORKER SUPERVISED PAINTERS WHO HAD ACCESS TO VITAL AREAS OF THE PLANT. AT 0914EDT, THE WORKER'S UNESCORTED ACCESS WAS REVCKED AND A WORK REVIEW IS UNDERWAY FOR ALL WORK PERFORMED FROM 04/29/92 UNTIL THE PRESENT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: GULF STATES UTILITIES CO.

SITE: RIVER BEND 1 EN NUMBER: 23427 DOCKET: 05000458 EVENT DATE: 05-08-92 EVENT TIME: 09:17 RX TYPE: BWR NOTIFY DATE: 05-08-92 VENDORS: GE-6

EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 16:26 OPS OFFICER: GREG SCARFO

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
N 0 REFUELING 0 REFUELING

A CONTRACT FOREMAN TESTED POSITIVE DURING A RANDOM DRUG TEST.

A CONTRACT FOREMAN TESTED POSITIVE FOR BENZODIAZENPINES (A DERIVATIVE OF VALIUM) DURING A RANDOM DRUG TEST. THE WORKER SUPERVISED A CLEANING CREW WHO HAD ACCESS TO VITAL AREAS OF THE PLANT. THE WORKER'S UNESCORTED ACCESS WAS REVOKED AND HIS KEYCARD DESTROYED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

UPDATE 1400EDT 05/12/92 BY V CARLSON TAKEN BY MACKINNON

LICENSEE HAS FOUND OUT THAT THE ABOVE MENTIONED CONTRACT FOREMAN WAS TAKING MEDICATION PRESCRIBED BY HIS DOCTOR. THEREFORE, THIS INDIVIDUAL'S RECORD HAS BEEN CHANGED TO SHOW THAT HE TESTED NEGATIVE ON THE RANDOM DRUG TEST.
RESIDENT INSPECTOR WILL BE NOTIFIED BY THE LICENSEE. R4DO

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 2

DOCKET: 05000220 05000410

RX TYPE: BWR RWR

VENDORS: GE-2 GE-5

EMERGENCY CLASS: N/A REGION: 1 STATE: NY

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

EN NUMBER: 23499

EVENT DATE: 05-20-92

EVENT TIME: 10:10

NOTIFY DATE: 05-20-92

FITNESS FOR DUTY

CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

RADIATION PROTECTION SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A FOLLOWUP TEST. HIS BLOOD ALCOHOL COUNT WAS 0.53 & LATER IT WAS 0.41. CUPERVISORS UNESCORTED ACCESS WAS REMOVED AND QUALITY ASSURANCE WILL CHECK HIS WORK THAT HE PERFORMED TODAY. SUPERVISOR HAS BEEN REFERRED TO LICENSEE EMPLOYEES ASSISTANCE PROGRAM.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

*** 05/21/92 UPDATE *** BASED ON A CHECK OF THE ORIGINAL REPORT IT APPEARS THAT THE ACTUAL ALCOHOL COUNTS WERE 0.053 AND 0.041

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI
SITE: SAN ONOFRE 1 2 3

DOCKET: 05000206 05000361 05000362

RX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

CPS OFFICER: TIM MCGINTY

EVENT DATE: 05-20-92

EVENT TIME: 08:15

NOTIFY DATE: 05-20-92

TIME: 16:28

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

FITNESS FOR DUTY

CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1	N	Y	92	POWER	OPERATION	92	POWER	OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
3	N	Y	65	POWER	OPERATION	65	POWER	OPERATION

AT 0815 PDT ON 05/20/92, IT WAS DETERMINED FOLLOWING A MEDICAL REVIEW OFFICERS REVIEW, THAT AN EMPLOYEE WHO IS A LICENSED RX OPERATOR HAD TESTED POSITIVE ON A DRUG SCREEN URINALYSIS TEST. THE EMPLOYEE'S PROTECTED AND VITAL AREA UNESCORTED ACCESS AUTHORIZATION WAS TERMINATED WITHIN TEN MINUTES. EMPLOYEE CURRENTLY UNDER INVESTIGATIVE SUSPENSION AWAITING FURTHER MANAGEMENT REVIEW. THE LICENSEF WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 2 3 EN NUMBER: 23537

DOCKET: 05000245 05000336 05000423 EVENT DATE: 05-26-92

RX TYPE: BWR PWR PWR EVENT TIME: 13:00

VENDORS: GE-3 CE W-4-LP NOTIFY DATE: 05-26-92

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 16:16

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION
3 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

CONTRACT SUPERVISOR TESTED POSITIVE FOR CONTROLLED SUBSTANCE ABUSE.

THE SUPERVISOR WAS TESTED ON MAY 18 AND THE RESULTS WERE CONFIRMED ON MAY 26. THE INDIVIDUAL'S BADGE WAS PULLED AT 1300 EDT ON MAY 26. THE INDIVIDUAL HAS NOT BEEN INVOLVED IN ANY SAFETY RELATED ACTIVITIES.

THE NRC RESIDENT INSPECTOR AND STATE OFFICIALS HAVE BEEN NOTIFIED. A PRESS RELEASE IS NOT ANTICIPATED AT THIS TIME.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2

DOCKET: 05000413 05000414

EVENT DATE: 06-05-92

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON LICENSED SUPERVISOR WHO HAD VITAL AREA ACCESS WAS ARRESTED FOR POSSESSION OF A CONTROLLED SUBSTANCE. ACCESS TO VITAL AREAS HAS BEEN WITHDRAWN. THE LICENSEE IS STILL INVESTIGATING THE SITUATION TO DETERMINE CORRECTIVE ACTION. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED. SEE HOO LOG FOR DETAILS.

LICENSEE: SOUTH CAROLINA ELECTRIC & GAS CO.

SITE: SUMMER 1 EN NUMBER: 23586

DOCKET: 05000395 EVENT DATE: 06-05-92

RX TYPE: PWR EVENT TIME: 12:45

VENDORS: W-3-LP NOTIFY DATE: 06-05-92 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 14:42

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

A PLANT EMPLOYEE SUPERVISOR TESTED POSITIVE FOR DRUGS (FIRST OFFENSE) DURING A RANDOM DRUG TEST. LICENSEE WITHDREW EMPLOYEE'S PLANT ACCESS AUTHORIZATION. LICENSEE IS DETERMINING TURTHER APPROPRIATE ACTIONS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

BRAIDWOOD 1 2 23592 06-05-92 POW

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAIDWOOD 1 2 EN NUMBER: 23592

DOCKET: 05000456 05000457 EVENT DATE: 06-05-92

RX TYPE: PWR PWR EVENT TIME: 15:33

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 06-05-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 19:48

OFS OFFICER: DICK JOLLIFFE

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 95 POWER OPERATION 95 POWER OPERATION

CONTRACTOR SECURITY GUARD SUPERVISOR TESTED POSITIVE FOR AN ILLEGAL DRUG.

LICENSEE WITHDREW THE SUPERVISOR'S PLANT ACCESS AUTHORIZATION.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

*** RETRACTED AT 1730 EDT ON 7/15/92 BY TRUSHEIM TAKEN BY DONNA SKAY ***

THE POSITIVE DRUG TEST SHOULD NOT HAVE BEEN REPORTED BECAUSE THE DRUG TEST WAS NOT CONDUCTED UNDER A TESTING PROGRAM APPROVED UNDER THE REQUIREMENTS OF 10 CFR 26. THE DRUG TEST WAS CONDUCTED AS PART OF THE SECURITY CONTRACTORS ANNUAL PHYSICAL EXAM REQUIREMENT FOR SECURITY GUARDS. THIS RETRACTION IS BEING MADE

BASED ON THE RECOMMENDATION OF GENE MCPEAK OF NRR. DESPITE THE FACT THAT THE DRUG TEST WAS NOT PERFORMED UNDER A PROGRAM MEETING 10CFR26 REQUIREMENTS, THE INDIVIDUAL'S UNESCORTED ACCESS WAS IMMEDIATELY DENIED AND THE INDIVIDUAL WAS TERMINATED. THE RESIDENT INSPECTOR AND R3DO (HAGUE) WERE NOTIFIED OF THE RETRACTION.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: SAINT LUCIE 1 2

DOCKET: 05000335 05000389

RX TYPE: PWR PWR

VENDORS: CE CE

NOTIFY DATE: 06-17-92

NOTIFY DATE: 06-17-92

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 09:58

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 85 POWER OPERATION 85 POWER OPERATION 2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

A CONTRACT EMPLOYEE TESTED POSITIVE FOR AN ILLEGAL SUBSTANCE.

A CONTRACT SECURITY SUPERVISOR TESTED POSITIVE FOR MARIJUANA DURING A DRUG TEST PERFORMED ON 06/07/92. THE RESULTS CONFIRMING THE POSITIVE DRUG TEST WERE RECEIVED AT 1452EST ON 06/16/92. THE CONTRACT EMPLOYEE'S UNESCORTED ACCESS TO VITAL AREAS WAS IMMEDIATELY RESCINDED AND THE CONTRACT EMPLOYEE WAS TERMINATED. A WORK REVIEW WAS INITIATED BY THE LICENSEE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER CORPORATION

SITE: CRYSTAL RIVER 3

DOCKET: 05000302

RX TYPE: PWR

VENDORS: B&W-L-LP

EN NUMBER: 23680

EVENT DATE: 06-19-92

RVENT TIME: 08:44

NOTIFY DATE: 06-19-92

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 11:47

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

3 N N O REFUELING O REFUELING

PLANT EMPLOYEE CALLED IN FOR A RANDOM DRUG & ALCOHOL TEST AT THEIR MAIN OFFICE (ST PETERSBURG, FL) WAS FOUND TO HAVE A HIGH BLOOD ALCOHOL LEVEL. INDIVIDUAL WAS SENT HOME. THIS INDIVIDUAL IS NOT BADGED. DURING AN EMERGENCY HE WOULD ONLY WORK IN THE CRYSTAL RIVER EOF WHICH IS LOCATED IN DOWNTOWN CRYSTAL RIVER.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

J.ICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: SEQUOYAH 1 2 EN NUMBER: 23703

DOCKET: 05000327 05000328

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSEE SUPERVISOR FOUND A QUANTITY OF ILLEGAL SUBSTANCE IN HIS DESK DRAWER OUTSIDE THE PLANT PROTECTED AREA. SUPERVISOR'S UNESCORTED SITE ACCESS AUTHORIZATION WAS WITHDRAWN. SEE HOO LOG FOR DETAILS.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1

DOCKET: 05000271

RX TYPE: BWR

VENDORS: GE-4

EMERGENCY CLASS N/A REGION: 1 STATE: VT

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

EMERGENCY CURRENT MODE

DWR

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

A PLANT EMPLOYEE TESTED POSITIVE FOR AN ILLEGAL SUBSTANCE DURING A RANDOM DRUG TEST. LICENSEE WITHDREW THE EMPLOYEE'S PLANT UNESCORTED ACCESS AUTHORIZATION, SUSPENDED THE EMPLOYEE FOR 14 DAYS, AND REFERRED HIM TO THE EMPLOYEE ASSISTANCE PROGRAM.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

SEE HOO LOG FOR DETAILS.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 2 3

DOCKET: 05000245 05000336 05000423

EVENT DATE: 06-25-92

RX TYPE: BWR PWR PWR

VENDORS: GE-3 CE W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: CT

TIME: 16:49

CPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N N 0 COLD SHUTDOWN

3 N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR/SUPERVISOR TESTED POSITIVE FOR MARIJUANA.

A DRUG TEST PERFORMED ON A CONTRACTOR/SUPERVISOR PRIOR TO THE ISSUANCE OF AN UNESCORTED BADGE RESULTED IN A POSITIVE READING FOR MARIJUANA. THE CONTRACTOR EMPLOYEE HAD ACCESS TO VITAL AREAS WITH AN ESCORT. HOWEVER, THE CONTRACTOR DID NOT ACTUALLY PERFORM WORK IN ANY VITAL AREAS. HIS ESCORTED ACCESS BADGE HAS BEEN REVOKED. THE LICENSEE BELIEVES NO VITAL EQUIPMENT WAS AFFECTED AND NO WORK REVIEW IS NECESSARY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. CONNECTICUT DEPARTMENT OF ENVIRONMENTAL PROTECTION AND THE TOWN OF WATERFORD HAVE BEEN NOTIFIED.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2

DOCKET: 05000315 05000316

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: MI

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

2 N N 0 HOT STANDBY

EVENT DATE: 06-26-92

EVENT TIME: 17:00

NOTIFY DATE: 06-26-92

EVENT TIME: 17:00

FITNESS FOR DUTY

CURR CURRENT MODE

PWR

1 N N 0 COLD SHUTDOWN
0 COLD SHUTDOWN
0 HOT STANDBY

A LICENSED EMPLOYEE TESTED POSITIVE FOR COCAINE FOLLOWING A TEST FOR CAUSE. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

POINT BEACH 1 2

23769 07-01-92 POW

LICENSEE: WISCONSIN ELECTRIC POWER CO.

SITE: POINT BEACH 1 2

EN NUMBER: 23769

EVENT DATE: 07-01-92

RX TYPE: PWR PWR

EVENT TIME: 06:45

VENDORS: W-2-LP W-2-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: WI

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE REPORTED AN UNINTENTIONAL ATTEMPT TO INTRODUCE ALCOHOL INTO THE PROTECTED AREA.

AT 0645 CDT ON 07/01/92, WHILE CONDUCTING A SEARCH OF A CONTRACTOR PAINTING VEHICLE AWAITING ENTRY INTO THE PROTECTED AREA, SECURITY DISCOVERED A SEALED LITER (MANUFACTURERS SEAL) OF

BRANDY IN THE CAB AREA. THE DRIVER, WHO REQUIRES AN ESCORT ON THE SITE, STATED THAT HE HAD PURCHASED THE BEVERAGE THE PREVIOUS EVENING. THE DRIVER HAD BEEN WORKING ON SITE FOR ABOUT A WEEK, HAD CHECKED OUT OF HIS HOTEL AND EXPECTED TO COMPLETE WORK AT THE SITE TODAY. THEREFORE, HE STATED THAT HE HAD THE BEVERAGE IN HIS TRUCK SINCE HE HAD NO OTHER PLACE TO PUT IT.

THE LICENSEE TOOK COMPENSATORY MEASURES BY CONFISCATING THE BRANDY AND ISSUING A PERSONAL PROPERTY TICKET TO THE DRIVER FOR RETURN UPON EXITING. THE LICENSEE WILL NOTIFY THE RESIDENT INSPECTOR.

* * * UPDATE 7/10/92 AT 1125 FROM KOPETSKY TAKEN BY SEBROSKY * *

THE LICENSEE IS RETRACTING THIS EVENT. AFTER FURTHER DISCUSSIONS WITH REGION III THE LICENSEE HAS DETERMINED THAT THIS EVENT DOES NOT MEET THE CRITERIA FOR BEING REPORTABLE. THE LICENSEE HAS NOTIFIED THE RESIDENT INSPECTOR. HOO NOTIFIED R3DO (CREED).

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: BRUNSWICK 1 2

DOCKET: 05000325 05000324

RX TYPE: BWR BWR

VENDORS: GE-4 GE-4

EMERGENCY CLASS: N/A REGION: 2 STATE: NC

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

EN NUMBER: 23819

EVENT DATE: 07-07-92

EVENT TIME: 19:30

NOTIFY DATE: 07-08-92

FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR
PWR
COLD SHUTDOWN

1 N N O COLD SHUTDOWN O COLD SHUTDOWN 2 N N O COLD SHUTDOWN O COLD SHUTDOWN

A PLANT EMPLOYEE REPORTING FOR WORK ON 07/07/92, PRIOR TO STARTING WORK, NOTIFIED HIS SUPERVISOR THAT HE HAD SMOKED MARIJUANA AT A PARTY OVER THE PAST WEEKEND.

LICENSEE WITHDREW THE EMPLOYEE'S SITE ACCESS AUTHORIZATION BADGE.

SENT THE EMPLOYEE HOME, AND REFERRED THE EMPLOYEE TO THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM.

ON 07/08/92, LICENSEE CALLED THE EMPLOYEE BACK TO THE SITE TO TAKE A

DRUG TEST. LICENSEE IS DETERMINING THE DATE OF THE EMPLOYEE'S LAST RANDOM DRUG TEST. LICENSEE IS REVIEWING THE EMPLOYEE'S WORK ACTIVITIES FOR A PERIOD TO BE DETERMINED.

THIS IS THE EMPLOYEE'S FIRST DRUG OFFENSE AND THERE IS NO PRIOR INDICATION OF ANY PROBLEMS WITH THIS EMPLOYEE.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

EN NUMBER: 23821 SITE: MILLSTONE 2 EVENT DATE: 07-08-92 DOCKET: 05000336 RX TYPE: PWR EVENT TIME: 20:18 NOTIFY DATE: 07-08-92 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 20:24

OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR

CODE CRIT PWR
N 0 REFUELING 0 REFUELING

A CONTRACTOR WORKING ON UNIT 2 TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG / ALCOHOL TEST. LICENSEE WITHDREW THE CONTRACTOR'S SITE ACCESS AUTHORIZATION BADGE. LICENSEE NOTIFIED STATE OFFICIALS AND THE NRC RESIDENT INSPECTOR.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3 EN NUMBER: 23851 DOCKET: 05000286 EVENT DATE: 07-14-92 EVENT TIME: 08:45 RX TYPE: PWR VENDORS: W-4-LP NOTIFY DATE: 07-14-92

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 13:12

OPS OFFICER: GREG SCARFO 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

A LICENSED REACTOR OPERATOR TESTED POSITIVE FOR MARIJUANA.

RESULTS OF A RANDOM DRUG TEST CONFIRMED THE EXISTENCE OF MARIJUANA IN A SAMPLE TAKEN FROM A LICENSED REACTOR OPERATOR. THE INITIAL TEST WAS PERFORMED ON 07/09/92 WHOSE RESULTS WERE AVAILABLE TO THE LICENSEE ON 07/13/92. AT THE TIME OF THE INITIAL RESULTS, THE LICENSEE REVOKED THE OPERATOR'S ACCESS BADGE. A 30-DAY WORK REVIEW HAS BEEN INITIATED AND THE OPERATOR HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANT PROGRAM. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 2 EN NUMBER: 23863 DOCKET: 05000529 EVENT DATE: 07-14-92 RX TYPE: PWR EVENT TIME: 08:34 VENDORS: CE80 NOTIFY DATE: 07-14-92 EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 13:56

OPS OFFICER: GREG SCARFO

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT DWD CODE CRIT PWR PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

A WORK CONTROL SCHEDULING SUPERVISOR TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST.

A SUPERVISOR FOR WORK CONTROL SCHEDULING TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST ON 07/06/92. SECURITY WAS IMMEDIATELY NOTIFIED AND THE EMPLOYEE'S ACCESS BADGE WAS REVOKED AT 0838MST. THE EMPLOYEE WAS NOT IN THE PROTECTED AREA AT THE TIME OF THE TESTING AND HIS WORK AREA WAS OUTSIDE OF THE PROTECTED AREA. THE LICENSEE BELIEVES THAT THIS EVENT DID NOT DIRECTLY AFFECT PLANT SAFETY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 2 DOCKET: 05000498 05000499 EN NUMBER: 23923 EVENT DATE: 07-22-92 VENDORS: W-4-LP W-4-LP EVENT TIME: 13:50 NOTIFY DATE: 07-22-92 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 18:01 OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED EMPLOYEE WITH UNESCORTED ACCESS WAS DETERMINED TO BE UNDER THE INFLUENCE OF ALCOHOL. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 2 EN NUMBER: 23935 DOCKET: 05000336 EVENT DATE: 07-24-92 RX TYPE: PWR EVENT TIME: 21:00 NOTIFY DATE: 07-24-92 VENDORS: CE EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 21:21 OPS OFFICER: STEVE SANDIN

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR CODE CRIT PWR
N 0 REFUELING 0 REFUELING

CONTRACT SUPERVISOR FAILED RANDOM ALCOHOL TEST.

A CONTRACT SUPERVISOR WORKING ON STEAM GENERATOR REPLACEMENT FOR UNIT 2 INSIDE THE PROTECTED AREA FAILED A RANDOM ALCOHOL TEST ADMINISTERED SHORTLY BEFORE 2100EDT ON 7/24/92. THE INDIVIDUAL WAS ESCORTED OFFSITE WITH THE LICENSEE REVOKING ACCESS AND NOTIFYING THE CONTRACT COMPANY MANAGEMENT. LICENSEE IS EVALUATING WHETHER A WORK REVIEW WILL BE PERFORMED. THE LICENSEE INFORMED STATE/LOCAL AGENCIES AND THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

DOCKET: 05000325 05000324
RX TYPE: BWR BWR
VENDORS: GE-4 GE-4 EN NUMBER: 23974 EVENT DATE: 07-30-92 EVENT TIME: 09:30 NOTIFY DATE: 07-31-92 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 08:58 OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

A NON-LICENSED CONTRACT SUPERVISOR WAS SUSPECTED TO BE UNDER THE INFLUENCE OF ALCOHOL WHEN THE INDIVIDUAL REPORTED TO WORK ON 7/30/92. A BREATH TEST WAS ADMINISTERED FOR CAUSE AND THE RESULTS INDICATED THAT THE INDIVIDUAL WAS ABOVE THE FITNESS FOR DUTY LIMITS FOR ALCOHOL. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: GEORGIA POWER CO.

SITE: HATCH 1 2 EN NUMBER: 23992 DOCKET: 05000321 05000366 RX TYPE: BWR BWR VENDORS: GE-4 GF-4 EVENT DATE: 08-04-92 EVENT TIME: 10:40 NOTIFY DATE: 08-04-92 VENDORS: GE-4 GF-4 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 14:48

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: EFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 95 POWER OPERATION 95 POWER OPERATION

A NON-LICENSED SUPERVISOR WAS TESTED FOR ALCOHOL FOR CAUSE. THE EMPLOYEE TESTED POSITIVE FOR ALCOHOL AND THE EMPLOYEE'S UNESCORTED ACCESS HAS BEEN REMOVED. THE EMPLOYEE HAS BEEN REFERRED TO AN EMPLOYEE ASSISTANCE PROGRAM.

THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: PHILADELPHIA ELECTRIC CO.

DOCKET: 05000277 05000278
RX TYPE: BWR BWR
VENDORS: GE-4 GE-4 SITE: PEACH BOTTOM 2 3 EN NUMBER: 23998 EVENT DATE: 08-05-92 EVENT TIME: 11:12 NOTIFY DATE: 08-05-92 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 15:10

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 95 POWER OPERATION 95 POWER OPERATION N Y 95 POWER OPERATION 95 POWER OPERATION

HP SUPERVISOR TESTED POSITIVE DURING RANDOM DRUG TEST.

THE LICENSEE RECEIVED A CONFIRMED POSITIVE DRUG TEST FOR A HEALTH PHYSICS SHIFT SUPERVISOR AT 1112 EDT ON 08/05/92. THE EMPLOYEE WAS TESTED VIA THE RANDOM DRUG TEST PROGRAM, AND THE SUBSTANCE DETECTED WAS COCAINE. THE EMPLOYEES SECURITY STATUS WAS DROPPED AND HE WAS SENT TO THE CORPORATE MEDICAL OFFICE FOR FURTHER EVALUATION AND TREATMENT. A REVIEW IS CURRENTLY BEING CONDUCTED OF THE INDIVIDUALS PREVIOUS WORK ACTIVITIES TO ENSURE THERE ARE NO UNPIVIEWED SAFETY QUESTIONS OR CONCERNS. THE LICENSEE WILL INFOL THE RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

EN NUMBER: 24004 SITE: CATAWBA 1 2 EVENT DATE: 08-06-92 DOCKET: 05000413 05000414 RX TYPE: PWR PWR EVENT TIME: 07:50 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 08-06-92 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 11:53

OPS OFFICER: MARK MILLER 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 REFUELING 0 REFUELING
2 N Y 100 POWER OPERATION 100 POWER OPERATION

VENDOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING RANDOM FITNESS FOR DUTY TEST.

A VENDOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM FITNESS FOR DUTY TEST. THE INDIVIDUAL'S BADGE AND KEY CARD WAS TERMINATED. THE INDIVIDUAL HAD NOT PERFORMED DUTIES ON SITE FOR OVER 24 HOURS AND WAS ONLY ON SITE FOR A FINAL DOSIMETRY CHECK PRIOR TO LEAVING THE SITE AND RETURNING TO HIS COMPANY'S HOME BASE.

THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3 EN NUMBER: 24007 DOCKET: 05000286 EVENT DATE: 08-06-92

VENDORS: W-4-LP EVENT TIME: 10:30 NOTIFY DATE: 08-06-92

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 12:38

OPS OFFICER: JOSEPH SEBROSKY
10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
3 N Y 2 STARTUP 2 STARTUP

A LICENSED REACTOR OPERATOR TESTED POSITIVE FOR MARIJUANA. THE SAME INDIVIDUAL HAS TESTED POSITIVE FOR MARIJUNIA IN THE PAST. (SEE EVENT NUMBER 23861). THE LICENSEE CAN NOT DETERMINE IF THE POSITIVE RESULT IS FROM RESIDUAL OR REUSE OF THE DRUG. THE LICENSEE HAS TERMINATED THE EMPLOYEE'S ACCESS TO THE PLANT AND IS STILL INVESTIGATING THE PROBLEM.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

EN NUMBER: 24034

EVENT DATE: 08-12-92

EVENT TIME: 11:50

NOTIFY DATE: 08-12-92

FITNESS FOR DUTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

N Y 70 POWER OPERATION 70 POWER OPERATION 4 N Y 66 POWER OPERATION 66 POWER OPERATION

A CONTRACT SUPERVISOR WAS DETERMINED TO BE UNDER THE INFLUENCE OF MARIJUANA DURING A RANDOM TEST. THE INDIVIDUAL'S ACCESS TO FP&L'S FACILITIES HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: HARRIS 1 EN NUMBER: 24049

DOCKET: 05000400 EVENT DATE: 08-14-92

RX TYPE: PWR EVENT TIME: 08:34

VENDORS: W-3-LP NOTIFY DATE: 08-14-92

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 14:57

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

DURING ROUTINE RANDOM DRUG & ALCOHOL TESTING OF A SITE CONTRACTOR EMPLOYEE

WHO HAS SUPERVISORY DUTIES (PLANT SERVICES FOREMAN PAINTER), TESTED POSITIVE FOR ALCOHOL [AVERAGE TEST RESULTS MEASURED A BLOOD/ALCOHOL CONTENT

(BAR) OF 0.041}. EMPLOYEE HAS BEEN REMOVED FROM THE PROTECTED AREA AND HIS UNESCORTED ACCESS AUTHORIZATION HAS BEEN WITHDRAWN. EMPLOYEE WAS TERMINATED.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEP

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: STEVE SANDIN

EN NUMBER: 24067

EVENT DATE: 08-17-92

EVENT TIME: 11:40

NOTIFY DATE: 08-17-92

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

3 N Y 70 POWER OPERATION 70 POWER OPERATION

4 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR WAS DETERMINED TO BE UNDER THE INFLUENCE OF MARIJUANA DURING A RANDOM TEST. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: HARRIS 1 EN NUMBER: 24154

DOCKET: 05000400 EVENT DATE: 08-31-92

RX TYPE: PWR EVENT TIME: 15:20

VENDORS: W-3-LP NOTIFY DATE: 08-31-92

EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 17:40

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 96 POWER OPERATION 96 POWER OPERATION

THE LICENSEE HAS DETERMINED THAT THE RESULTS OF A RANDOM DRUG AND ALCOHOL TEST (SUBSTANCE UNSPECIFIED) OF A 1ST LINE SECURITY

SUPERVISOR WAS POSITIVE FOR AN ILLEGAL CONTROLLED SUBSTANCE AND DECLARED A FITNESS FOR DUTY VIOLATION.

THE INDIVIDUAL REQUESTED TESTING OF THE SPLIT SAMPLE. PENDING RESULTS OF THE SUBSEQUENT SAMPLE ANALYSIS, HIS UNESCORTED ACCESS AUTHORIZATION HAS BEEN SUSPENDED. IT WAS NOT KNOWN IF THIS CONDITION AFFECTED HIS PERFORMANCE OR CONTRIBUTED TO ANY DEGRADATION TO THE LEVEL OF SAFETY OF THE PLANT. THE RI WAS INFORMED BUT NO OTHER NOTIFICATIONS WILL BE MADE.

LICENSEE: GPU NUCLEAR CORP.

SITE: OYSTER CREEK 1

DOCKET: 05000219

RX TYPE: BWR

VENDORS: GE-2

EMERGENCY CLASS: N/A REGION: 1 STATE: NJ

EN NUMBER: 24189

EVENT DATE: 09-08-92

RVENT TIME: 10:00

NOTIFY DATE: 09-08-92

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR DRUGS DURING A RANDOM DRUG TEST. THE INDIVIDUAL'S SITE ACCESS HAS BEEN TERMINATED AND THE INDIVIDUAL HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 24214 SITE: BYRON 1 2 DOCKET: 05000454 05000455 EVENT DATE: 09-12-92
RX TYPE: PWR PWR EVENT TIME: 07:45
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 09-12-92 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 11:58

OPS OFFICER: GREG SCARFO

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 94 POWER OPERATION 94 POWER OPERATION 2 N

A LICENSED REACTOR OPERATOR TESTS POSITIVE FOR ALCOHOL.

A LICENSED REACTOR OPERATOR (RO) REPORTING FOR DUTY AT 0745 ON 09/12/92 WAS QUESTIONED REGARDING HIS FITNESS FOR DUTY. A BREATHALYZER TEST AND URINALYSIS WERE PERFORMED. THE RESULTS OF THE BREATHALYZER TEST WERE POSITIVE FOR ALCOHOL WHILE THE URINALYSIS RESULTS ARE STILL PENDING. THE RO DID NOT HAVE ACCESS TO THE CONTROL ROOM, VITAL EQUIPMENT, OR ANY VITAL AREAS PRIOR TO FITNESS-FOR-DUTY TESTING.

THE LICENSED REACTOR OPERATOR'S PLANT ACCESS HAS BEEN WITHHELD PENDING EVALUATION AND REFERENCE TO THE PLANT EMPLOYEE ASSISTANCE PROGRAM (EAP). THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: LONG ISLAND LIGHTING CO

SITE: SHOREHAM 1 EN NUMBER: 24226 DOCKET: 05000322 EVENT DATE: 09-14-92 EVENT TIME: 11:45 RX TYPE: BWR VENDORS: GE-4 NOTIFY DATE: 09-14-92

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 14:43

OPS OFFICER: STEVE SANDIN

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR
1 N N 0 DECOMMISSIONED 0 DECOMMISSIONED

AT 1145EDT ON 9/14/92 THE FIRE SAFETY AND ADMINISTRATION MANAGER WAS INFORMED BY LONG ISLAND LIGHTING COMPANY HUMAN RESOURCES

ADMINISTRATOR THAT A SHOREHAM NON-LICENSED SUPERVISOR WAS FOUND POSITIVE FOR MARIJUANA IN A FITNESS FOR DUTY RANDOM TEST. THE SAMPLE WAS TAKEN ON 9/3/92. THE INDIVIDUAL WAS NOT INVOLVED IN DIRECT SAFETY RELATED WORK AND HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. THE LICENSEE HAS TERMINATED UNESCORTED ACCESS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: GEORGIA POWER CO.

SITE: VOGTLE 1 2

DOCKET: 05000424 05000425

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EN NUMBER: 24228

EVENT DATE: 09-14-92

EVENT TIME: 15:07

NOTIFY DATE: 09-14-92

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 15:50

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR DRUGS.

A REACTOR OPERATOR TESTED POSITIVE FOR DRUG USAGE UPON FOLLOWUP TESTING. THE TYPE OF DRUG WAS NOT IDENTIFIED. THIS WAS THE SECOND POSITIVE FOR THE OPERATOR WHO WAS ALREADY IN THE EMPLOYEE ASSISTANCE PROGRAM FOR A PREVIOUS POSITIVE RESULT. THE EMPLOYEE WAS IN TRAINING AND NOT ACTUALLY PERFORMING WORK ON SHIFT AT THE TIME OF THE TEST. THE EMPLOYEE HAS BEEN TERMINATED. THE RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 24255

DOCKET: 05000341 EVENT DATE: 09-17-92

RX TYPE: BWR EVENT TIME: 13:47

VENDORS: GE-4 NOTIFY DATE: 09-18-92

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 09:17

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM PX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N N O REFUELING O REFUELING

REACTOR OPERATOR TRAINING SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A REACTOR OPERATOR TRAINING SUPERVISOR (NON-LICENSED) TESTED POSITIVE FOR ALCOHOL DURING ROUTINE FOLLOWUP DRUG TESTING. THE EMPLOYEE'S PROTECTED AREA ACCESS WAS IMMEDIATELY SUSPENDED. A WORK REVIEW REVEALED THAT THE EMPLOYEE HAD NOT BEEN INVOLVED IN ANY SAFETY RELATED ACTIVITIES. THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM FOR FURTHER EVALUATION.

THIS WAS THE EMPLOYEE'S FIRST POSITIVE TEST. HE WAS IN A FOLLOWUP

PROGRAM DUE TO SELF-REFERRAL IN JUNE OF 1992.

THE RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: GEORGIA POWER CO.

SITE: HATCH 1 2 EN NUMBER: 24291 DOCKET: 05000321 05000366 EVENT DATE: 09-22-92 VENDORS: GE-4 GE-4 EVENT TIME: 22:30 NOTIFY DATE: 09-23-92

EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 15:40

OPS OFFICER: GREG SCARFO

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N 0 REFUELING 0 REFUELING

A WORKER TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG TEST.

THE RESULTS OF A RANDOM DRUG TEST ON A NON-LICENSED SUPERVISOR INDICATED POSITIVE FOR ALCOHOL. THE LICENSEE ESCORTED WORKER OFFSITE AND REVOKED HIS ACCESS. THE WORKER HAD ACCESS TO VITAL AREAS AND SAFETY EQUIPMENT BEFORE THE RANDOM DRUG TEST. A WORK REVIEW IS ONGOING. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: PHILADELPHIA ELECTRIC CO.

SITE: PEACH BOTTOM 2 3
DOCKET: 05000277 05000278
RX TYPE: BWR BWR EN NUMBER: 24301 EVENT DATE: 09-23-92 EVENT TIME: 17:24 NOTIFY DATE: 09-24-92 VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 15:37 OPS OFFICER: GREG SCARFO 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

2 N N 0 REFUELING 0 REFUELING
3 N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED EMPLOYEE TESTED POSITIVELY FOR MARIJUANA DURING A RANDOM DRUG TEST.

THE EMPLOYEE TESTED POSITIVELY FOR MARIJUANA DURING A RANDOM DRUG TEST. THIS RESULT WAS CONFIRMED VIA GAS CHROMATOGRAPHY/MASS SPECTROMETRY TESTING. THE EMPLOYEE'S SITE ACCESS HAS BEEN REVOKED PENDING COMPLETION OF A CORPORATE REVIEW. A WORK REVIEW IS ALSO UNDERWAY WITH PRELIMINARY RESULTS INDICATING THAT THE EMPLOYEE DID NOT EXERCISE HIS LICENSE DURING THE CURRENT REFUELING OUTAGE. THIS REPORT ALSO APPLIES TO THE LIMERICK FACILITY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CONNECTICUT YANKEE ATOMIC POWER CO.

SITE: HADDAM NECK 1

DOCKET: 05000213 RX TYPE: PWR

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 10:56

OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR
N Y 100 POWER OPERATION 100

1 N

PWR POWER OPERATION

EN NUMBER: 24322

EVENT DATE: 09-28-92

EVENT TIME: 10:15 NOTIFY DATE: 09-28-92

FITNESS FOR DUTY

CURR CURRENT MODE

THE LICENSEE WAS REPORTING A CONFIRMED POSITIVE TEST UNDER RANDOM SAMPLING FOR A CONTROLLED SUBSTANCE (TYPE OF SUBSTANCE WAS NOT REVEALED) BY A LICENSED OPERATOR. THE SUBSTANCE ABUSE DID NOT ADVERSELY AFFECT THE INDIVIDUAL'S

PERFORMANCE RESULTING IN THE ACTUAL OR POTENTIAL DEGRADATION OF THE LEVEL OF PLANT SAFETY. MANAGEMENT IMMEDIATELY PULLED HIS BADGE AND DENIED HIS ACCESS. FOLLOWUP MANAGEMENT ACTIONS (COUNSELLING, INTERVIEWS, REFERRAL TO THE EMPLOYMENT SYSTEMS PROGRAM, ETC.) WILL BE INITIATED. STATE & LOCAL AUTHORITIES AND RI WERE NOTIFIED. THE LICENSEE MAY ISSUE A PRESS RELEASE.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1

DOCKET: 05000331

RX TYPE: BWR

EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 13:59 OPS OFFICER: MARK MILLER

10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODF CRIT PWR N

Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY

EVENT TIME: 17:30

NOTIFY DATE: 09-29-92

EN NUMBER: 24332 EVENT DATE: 09-28-92

REACTOR OPERATOR TESTED POSITIVE FOR COCAINE.

A REACTOR OPERATOR TESTED POSITIVE FOR COCAINE. THE TEST WAS FOR-CAUSE AND WAS ASSOCIATED WITH A PREVIOUS POSITIVE TEST RESULT. THE OPERATOR WAS NOT PERFORMING LICENSED ACTIVITIES PRIOR TO THIS POSITIVE TEST RESULT AND HIS UNESCORTED ACCESS TO THE PROTECTED AREA HAS BEEN DENIED. THE CASE IS UNDER MANAGEMENT REVIEW.

THE RESIDENT INSPECTOR AND THE REGIONAL OFFICE HAVE BEEN INFORMED.

LICENSEE: VIRGINIA POWER CO.

SITE: SURRY 1 2

RX TYPE: PWR PWR

EN NUMBER: 24365 EVENT DATE: 10-02-92

VENDORS: W-3-LP W-3-LP NOTIFY DATE: 10-02-92

EMERGENCY CLASS: N/A REGION: 2 STATE: VA TIME: 17:13

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED REACTOR OPERATOR (LRO) TESTED POSITIVE FOR AN ILLEGAL SUBSTANCE.

A LRO TESTED POSITIVE FOR AN UNSPECIFIED ILLEGAL SUBSTANCE DURING A RANDOM DRUG TEST. THE LRO'S SITE ACCESS WAS IMMEDIATELY REVOKED AND WAS SUSPENDED PENDING THE RESULTS OF FOLLOW-UP TESTING. THE LRO DID HAVE ACCESS TO VITAL AREAS AND SAFEGUARDS EQUIPMENT AND A WORK REVIEW IS IN PROGRESS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CONSUMERS POWER CO.

SITE: PALISADES 1 EN NUMBER: 24369 EVENT DATE: 10-02-92 DOCKET: 05000255 EVENT TIME: 18:06 RX TYPE: PWR NOTIFY DATE: 10-02-92 VENDORS: CE

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 19:43

OPS OFFICER: JOHN MacKINNON

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

AN OPERATIONS (SEO) WAS CONFIRMED POSITIVE FOR MARIJUANA AFTER HE TOOK A RANDOM DRUG TEST ON 09/30/92. HIS UNESCORTED ACCESS WAS REVOKED AT 1809 EDT ON 10/02/92. HE WAS ON SHIFT TODAY BUT HE WAS NOT OPERATING THE PLANT. HE WILL BE GIVEN THE OPPORTUNITY TO ENTER A REHABILITATION PROGRAM. IF HE DOES NOT ELECT TO ENTER THE REHABILITATION PROGRAM HIS EMPLOYMENT WILL BE TERMINATED. PER THE LICENSEE, THIS INDIVIDUAL CANNOT COME BACK TO THE PLANT FOR A MINIMUM OF 14 DAYS FROM TODAY.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 1 2 3 EN NUMBER: 24393 DOCKET: 05000245 05000336 05000423 EVENT DATE: 10-08-92 RX TYPE: BWR PWR PWR EVENT TIME: 08:30 VENDORS: GE-3 CE W-4-LP NOTIFY DATE: 10-08-92

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 09:04

OPS OFFICER: RUDY KARSCH

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY

APRE 50.72(b)(2)(vi) OFFSITE NOTIFICATION

UNIT	SCRAM	RX	INIT PWR	INITIAL MODE	CURR PWR	CURRENT MODE	
1	N	Y	100	POWER OPERATION	100	POWER OPERATION	
2	N	N	0	REFUELING	0	REFUELING	
3	N	N	0	COLD SHUTDOWN	0	COLD SHUTDOWN	

CONTRACT SUPERVISOR FAILED A DRUG TEST.

THE INDIVIDUAL TESTED POSITIVE FOR ALCOHOL. SITE ACCESS WAS TERMINATED AND THE INDIVIDUAL WAS ESCORTED OFF THE SITE. THE INDIVIDUAL HAD VITAL AREA BUT NOT PROTECTED AREA ACCESS. THE LICENSEE IS REVIEWING THE INDIVIDUALS WORK. THE LICENSEE INFORMED STATE AND LOCAL AUTHORITIES AND THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO. EN NUMBER: 24406 SITE: QUAD CITIES 1 2 EVENT DATE: 10-12-92 DOCKET: 05000254 05000265 EVENT TIME: 07:20 RX TYPE: BWR BWR NOTIFY DATE: 10-12-92 VENDORS: GE-3 GE-3 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 13:32 OPS OFFICER: RUDY KARSCH 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N N 0 REFUELING 0 REFUELING
N Y 100 POWER OPERATION 100 POWER OPERATION CODE CRIT PWR

CONTRACTOR SUPERVISOR, FIELD ENGINEERING SUPERVISOR, TESTED POSITIVE FOR ALCOHOL IN A RANDOM SCREENING. THE INDIVIDUAL'S VITAL AREA ACCESS HAS BEEN REVOKED AND THE LICENSEE IS EVALUATING HIS WORK PERFORMANCE. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 24427 EVENT DATE: 10-14-92 DOCKET: 05000331 EVENT TIME: 11:00 RX TYPE: BWR NOTIFY DATE: 10-15-92 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 3 STATE: IA TIME: 10:01 OPS OFFICER: GREG SCARFO UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

A SUPERVISORY EMPLOYEE'S PLANT ACCESS WAS SUSPENDED WHEN A LOCAL

Y 100 POWER OPERATION 100 POWER OPERATION

NEWSPAPER PUBLISHED ALLEGATIONS IMPLICATING THE EMPLOYEE IN A LOCAL DRUG INVESTIGATION.

ON 10/14/92, THE CEDAR RAPIDS GAZETTE PUBLISHED A REPORT IMPLYING THAT A SUPERVISOR AT THE PLANT HAD TIES WITH HIS BROTHER IN THE

SALE/TRAFFICKING OF DRUGS BEING INVESTIGATED BY A MULTIAGENCY TASK FORCE. THE LICENSEE SUSPENDED THE SUPERVISOR'S ACCESS AND PERFORMED A FOR-CAUSE DRUG TEST. THE RESULTS OF THE DRUG TEST ARE STILL PENDING. THE LICENSEE IS CONTINUING A FACT-FINDING INVESTIGATION. NO INDICTMENTS HAVE BEEN ISSUED AT THIS TIME. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO. SITE: ROBINSON 2 DOCKET: 05000261 EN NUMBER: 24459 RX TYPE: PWR EVENT DATE: 10-20-92 VENDORS: W-3-LP EVENT TIME: 10:00 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 12:54 NOTIFY DATE: 10-20-92 OPS OFFICER: GREG SCARFO 10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE FITNESS FOR DUTY
CODE CRIT PWR CURRENT MODE N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR SUPERVISOR TESTED POSITIVE DURING A RANDOM DRUG TEST. THE LICENSEE REVOKED HIS UNESCORTED ACCESS AND WAS TERMINATED. A WORK REVIEW IS IN PROGRESS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: INDIANA & MICHIGAN ELECTRIC CO.

SITE: COOK 1 2 DOCKET: 05000315 05000316
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP EN NUMBER: 24529 EVENT DATE: 10-28-92 EVENT TIME: 13:12 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:57 NOTIFY DATE: 10-29-92 OPS OFFICER: THOMAS ANDREWS 10 CFR SECTION: HFIT 26.73
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N Y 3 STARTUP
2 N N 0 COLD SHUTDOWN
0 COLD SHUTDOWN

ON 10/28/92, A CONTRACT SUPERVISOR WITH UNESCORTED ACCESS WAS RANDOMLY SELECTED FOR CHEMICAL TESTING IN ACCORDANCE WITH THE FITNESS FOR DUTY PROGRAM. THE CONTRACTOR WAS CONFIRMED POSITIVE FOR ALCOHOL BASED ON RESULTS OF FOUR TESTS CONDUCTED WITH TWO SEPARATE INTOXIMETERS. THESE TESTS INDICATED A BLOOD ALCOHOL CONTENT (BAC) IN EXCESS OF 0.04 BAC AT THE TIME THE TEST BEGAN AT

INTERVIEWS WITH COGNIZANT PLANT EMPLOYEES REVEALED THAT THE CONTRACTOR DID NOT ENTER THE PLANT PROTECTED AREA AFTER ARRIVING ON SITE AT 1000 ON 10/28/92. FURTHERMORE, INVESTIGATION HAS REVEALED THAT THIS INDIVIDUAL HAS NOT BEEN INVOLVED WITH ANY WORK ON SAFETY RELATED SYSTEMS DURING THE PAST 30 DAYS. ALL WORK PERFORMED ON 10/28/92 WHILE ON SITE HAS BEEN VERIFIED BY THE

IN ACCORDANCE WITH THE FITNESS FOR DUTY PROGRAM, THE CONTRACTOR'S UNESCOPTED ACCESS WAS IMMEDIATELY SUSPENDED AND WILL NOT BE REINSTATED FOR A MINIMUM OF 14 DAYS.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED. NO OTHER NOTIFICATIONS ARE PLANNED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2

DOCKET: 05000254 05000265

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN

2 N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACT FOREMAN TESTED POSITIVE FOR DRUGS ON A FOLLOW UP TEST. A WORK PERFORMANCE EVALUATION IS IN PROGRESS. THE FINAL DISPOSITION OF THIS EMPLOYEE IS NOT CERTAIN AT THIS TIME SINCE THE INDIVIDUAL IS COVERED BY THE CONTRACTOR'S FITNESS FOR DUTY PROGRAM. THE INDIVIDUAL'S PLANT ACCESS HAS BEEN PULLED.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. NO OTHER NOTIFICATIONS ARE ANTICIPATED OR REQUIRED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 1 2 3

DOCKET: 05000205 05000361 05000362

RX TYPE: PWR PWR PWR

VENDORS: W-3-LP CE CE

EMERGENCY CLASS: N/A REGION: 5 STATE: CA

EN NUMBER: 24619

EVENT DATE: 11-17-92

EVENT TIME: 11:19

NOTIFY DATE: 11-18-92

OPS OFFICER: TIM MCGINTY

10 CFR SECTION: HFIT 26.73							FITNESS FOR DUTY		
UNIT	SCRAM	RX	INIT	INITIAL MODE		CURR CURRENT MODE PWR			
1	N	Y	92	POWER	OPERATION	92	POWER	OPERATION	
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION	
3	N	Y	65	POWER	OPERATION	65	POWER	OPERATION	

CONTROLLED SUBSTANCE FOUND IN SWITCH GEAR ROOM.

A SUSPECT MATERIAL WAS DISCOVERED IN THE PROTECTED AREA AT 0330 PST ON 11/11/92. IT WAS FOUND ON AN "I" BEAM APPROXIMATELY 6 FEET ABOVE THE FLOOR IN SWITCH GEAR ROOM "AC-504" AT THE 85' LEVEL IN UNIT 2. THE MATERIAL WAS DISCOVERED BY A CONTROL OPERATOR WHILE HE WAS PERFORMING ROUTINE SURVEILLANCE TASKS.

AT 1119 PST, NOVEMBER 17, 1992, AN OFF-SITE LABORATORY CONFIRMED THAT IT WAS A CONTROLLED SUBSTANCE, MARIJUANA (THE REMAINS OF ONE MARIJUANA CIGARETTE). THERE HAVE BEEN NO INDIVIDUALS IDENTIFIED AS BEING RESPONSIBLE FOR THE MATERIAL. THE RESIDENT INSPECTORS WILL BE NOTIFIED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3

DOCKET: 05000237 05000249

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EWENT DATE: 11-20-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

TIME: 14:49

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

EVENT TIME: 09:20

NOTIFY DATE: 11-20-92

FITNESS FOR DUTY

CURR CURRENT MODE

PWR

2 N Y 83 POWER OPERATION 83 POWER OPERATION 3 N Y 86 POWER OPERATION 86 POWER OPERATION

DURING A RANDOM DRUG / ALCOHOL TEST, A CONTRACTOR EMPLOYEE TESTED POSITIVE FOR ALCOHOL. LICENSEE TERMINATED THE INDIVIDUAL'S ACCESS AUTHORIZATION TO THE PLANT. SEE HOO LOG FOR DETAILS.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BRAIDWOOD 1 2 EN NUMBER: 24634

DOCKET: 05000456 05000457 EVENT DATE: 11-20-92

RX TYPE: PWR PWR EVENT TIME: 09:30

VENDORS: W-4-LP NOTIFY DATE: 11-20-92

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 16:55

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 HOT STANDBY 0 HOT STANDBY
2 N Y 97 POWER OPERATION 97 POWER OPERATION

LICENSEE DISCOVERED A SMALL AMOUNT OF MARIJUANA OUTDOORS WITHIN THE

PLANT PROTECTED AREA. LICENSEE SEARCHED THE SURROUNDING AREA WITH DRUG SNIFFING DOGS; NO ADDITIONAL DRUGS WERE FOUND. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CAROLINA POWER & LIGHT CO.

SITE: ROBINSON 2

DOCKET: 05000261

RX TYPE: PWR

VENDORS: W-3-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: SC

EN NUMBER: 24644

EVENT DATE: 11-23-92

EVENT TIME: 11:00

NOTIFY DATE: 11-23-92

OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED CONTRACT SECURITY SUPERVISOR TESTED POSITIVE FOR ALCOHOL

DURING A RINDOM DRUG TEST ON 11/14/92. THE TEST WAS CONFIRMED ON 11/23/92.

THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. THE LICENSEE HAS INFORMED THE CONTRACTOR THAT THIS INDIVIDUAL'S SERVICES WILL NO LONGER BE REQUIRED ON SITE. THE LICENSEE HAS CHANGED SECURITY LOCK KEYS AND CORES.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: GEORGIA POWER CO.

N

EN NUMBER: 24703 SITE: HATCH 1 2 DOCKET: 05000321 05000366 RX TYPE: BWR BWR VENDORS: GE-4 GE-4 EVENT DATE: 12-04-92 EVENT TIME: 14:25 NOTIFY DATE: 12-04-92 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 15:26 OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED OPERATOR (NOT A SUPERVICE) TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG TESTED THE EMPLOYEE'S UNESCORTED ACCESS HAS BEEN SUSPENDED AND THE . NSEE IS CURRENTLY PERFORMING A WORK REVIEW OF THE EMPLOYEE'S MOST RECENT WORK. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1 EN NUMBER: 24735 DOCKET: 05000271 EVENT DATE: 12-11-92 RX TYPE: BWR EVENT TIME: 15:28 VENDORS: GE-4 NOTIFY DATE: 12-11-92

EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 16:09 OPS OFFICER: DICK JOLLIFFE

OPS OFFICER: DICK JOLLIFFE
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST. LICENSEE WITHDREW THE EMPLOYEE'S PLANT ACCESS AUTHORIZATION. SEE HOO LOG FOR DETAILS. LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

SITE: HOPE CREEK 1 EN NUMBER: 24770

DOCKET: 05000354 EVENT DATE: 12-16-92

RX TYPE: BWR EVENT TIME: 09:18

VENDORS: GE-4 NOTIFY DATE: 12-16-92

EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 16:34

OPS OFFICER: GREG SCARFO

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

A MAINTENANCE SUPERVISOR TESTED POSITIVELY FOR ALCOHOL DURING A RANDOM DRUG TEST. THE SUPERVISOR'S UNESCORTED ACCESS HAS BEEN SUSPENDED. A WORK REVIEW WAS COMPLETED AND NO PLANT EQUIPMENT APPEARS TO BE AFFECTED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 2

DOCKET: 05000313 05000368

RX TYPE: PWR PWR

VENDORS: B&W-L-LP CE

EMERGENCY CLASS: N/A REGION: 4 STATE: AR

OPS OFFICER: THOMAS ANDREWS

EN NUMBER: 24808

EVENT DATE: 12-29-92

NOTIFY DATE: 12-29-92

TIME: 16:'3

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

ON DECEMBER 1, 1992, A CONTRACT FOREMAN REPORTED TO THE FITNESS FOR DUTY / MEDICAL OFFICE DUE TO APPARENT ILLNESS. THE INDIVIDUAL STATED THAT HE SUSPECTED THAT HE HAD EATEN A CUPCAKE THAT WAS LACED WITH AN UNIDENTIFIED DRUG AND REQUESTED THAT A DRUG SCREEN BE PERFORMED. THE SPECIMEN WAS COLLECTED AND SUBSEQUENTLY TESTED POSITIVE FOR THC (ACTIVE INGREDIENT IN MARIJUANA).

ON DECEMBER 7, THE DRUG SCREENING RESULTS WERE CONFIRMED POSITIVE AND THE INDIVIDUAL'S ACCESS WAS TERMINATED.

THREE WRAPPERS AND ONE WHOLE CUPCAKE WERE RETRIEVED FROM THE INDIVIDUAL'S WORK AREA WITHIN THE PROTECTED AREA AND SENT TO LABS FOR TESTING. ON DECEMBER 29, 1992, THE LICENSEE WAS NOTIFIED BY THE LABS THAT THE WRAPPERS AND CUPCAKES CONTAINED THC. THE LICENSEE'S INVESTIGATION IS STILL ONGOING.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. NO OTHER

NOTIFICATIONS HAVE BEEN MADE NOR ARE ANY PLANNED AT THIS TIME. SEE HOO LOG FOR ADDITIONAL DETAILS.

* * * UPDATE AT 1603 EST ON 12/31/92 FROM SCHEIDE TAKEN BY KARSCH

THE LICENSEE HAS DETERMINED ON 12/30/92 AT 1630 CST THAT THE INDIVIDUAL MEETS THE DEFINITION OF SUPERVISORY PERSONNEL, AND THEREFORE, THIS EVENT ALSO MEETS THE REPORTING CRITERIA OF 26.73(a)(2)(i). THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUOUESNE LIGHT CO.

EN NUMBER:24811 SITE: BEAVER VALLEY 1 2 DOCKET: 05000334 05000412 EVENT DATE: 12-30-92 VENDORS: W-3-LP W-3-LP EMERGENCY CLASS. W/ EVENT TIME: 09:50 NOTIFY DATE: 12-30-92 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 14:46

OPS OFFICER: THOMAS ANDREWS

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 89 POWER OPERATION 89 POWER OPERATION N Y 47 POWER OPERATION 47 POWER OPERATION 2 N

A NON-LICENSED EMPLOYEE TESTED POSITIVE FOR ALCOHOL DURING RANDOM DRUG TESTING. THE EMPLOYEE'S ACCESS TO THE STATION HAS BEEN SUSPENDED. THE EMPLOYEE WILL BE REFERRED TO THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM.

THE EMPLOYEE ONLY ENTERED THE PROTECTED AREA FOR DRUG TESTING. THE INDIVIDUAL WAS NOT INVOLVED IN ANY SAFETY RELATED ACTIVITIES TODAY.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED. NO OTHER NOTIFICATIONS ARE PLANNED.

Query: 1993 EVENT REPORTS: hfit

LICENSEE: DUKE POWER CO.

SITE: MCGUIRE 1 2 EN NUMBER: 24863 DOCKET: 05000369 05000370 EVENT DATE: 01-11-93 RX TYPE: PWR PWR EVENT TIME: 11:38
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 01-12-93 EVENT TIME: 11:38 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 10:14 OPS OFFICER: GREG SCARFO FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR 1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N Y 100 POWER OPERATION 100 POWER OPERATION

THE RESULTS OF AN INITIAL POSITIVE RANDOM DRUG TEST (RDT) ON A MAINTENANCE SUPERVISOR WERE CONFIRMED. THE SUPERVISOR'S PLANT ACCESS HAS BEEN REVOKED AND HE HAS BEEN REFERRED TO AN EMPLOYEE ASSISTANCE PROGRAM. THE SUPERVISOR HAS NOT BEEN IN A PROTECTED AREA SINCE THE DATE OF HIS INITIAL RDT ON 1/05/93.

LICENSEE: TENNESSEE VALLEY AUTHORITY SITE: BROWNS FERRY 1 2 3 EN NUMBER: 24874

DOCKET: 05000259 05000260 05000296 IVENT DATE: 01-12-93

RX TYPE: BWR BWR BWR RX TYPE: BWR BWR BWR VENDORS: GE-4 GE-4 GE-4 NOTIFY DATE: 01-13-93 EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 12:57 OPS OFFICER: JOSEPH SEBROSKY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWP 1 N N O REFUELING O REFUELING
2 N Y 69 POWER OPERATION 69 POWER OPERATION
3 N N O REFUELING

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR A DRUG DURING A RANDOM DRUG TEST. THE TEST WAS PERFORMED ON 1/4/93 AND THE RESULTS WERE CONFIRMED ON 1/12/93. THE EMPLOYEE'S UNESCORTED ACCESS HAS BEEN REVOKED AND THE EMPLOYEE HAS BEEN REFERRED TO THE MPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

* * * UPDATE 1635EDT 4/12/93 FROM PAM HAMILTON BY S.SANDIN * * * AT 0930CDT A SHIFT SUPERVISOR IN THE RADIOLOGICAL CONTROLS ORGANIZATION AT BROWNS FERRY TESTED POSITIVE (COCAINE) ON A FOLLOWUP TEST. 1HE INDIVIDUALS UNESCORTED ACCESS HAS BEEN REVOKED AND THE EMPLOYEE WILL BE TERMINATED. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR. NOTIFIED R2DO (BARR).

HOONOTE: THIS IS THE SAME INDIVIDUAL THAT WAS REFERRED TO THE EAP AS REPORTED ABOVE.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 24972 SITE: LASALLE 1 2 DOCKET: 05000373 05000374
RX TYPE: BWR BWR
VENDORS: GE-5 GE-5 EVENT DATE: 01-29-93 EVENT TIME: 11:45 NOTIFY DATE: 01-29-93 VENDORS: GE-5 GE-5 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:26

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR
N Y 15 STARTUP 15

Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR SUPERVISOR INVOLVED IN NON-SAFETY RELATED WORK ACTIVITIES

TESTED POSITIVE FOR AN ILLEGAL SUBSTANCE DURING A RANDOM DRUG

LICENSEE TERMINATED THE CONTRACTOR'S SITE ACCESS AUTHORIZATION REFERRED THE CONTRACTOR TO HIS COMPANY FOR CORRECTIVE ACTION.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: BOSTON EDISON CO.

EN NUMBER: 24973 SITE: PILGRIM 1 EVENT DATE: 01-29-93 DOCKET: 05000293 EVENT TIME: 08:50 RX TYPE: BWR VENDORS: GE-3 NOTIFY DATE: 01-29-93 EMERGENCY CLASS: N/A REGION: 1 STATE: MA TIME: 15:34

OPS OFFICER: DICK JOLLIFFE

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR SUPERVISOR INVOLVED IN NON-SAFETY RELATED WORK ACTIVITIES TESTED POSITIVE FOR ALCOHOL DURING A RANDOM ALCOHOL TEST.

LICENSEE TERMINATED THE CONTRACTOR'S SITE ACCESS AUTHORIZATION AND REFERRED THE CONTRACTOR TO HIS COMPANY FOR CORRECTIVE ACTION.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 2 EN NUMBER: 24986 EVENT DATE: 01-30-93 DOCKET: 05000247 EVENT TIME: 17:53 RX TYPE: PWR

VENDORS: W-4-LP NOTIFY DATE: 01-31-93

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 10:00

OPS OFFICER: TIM McGIATY

10 CFR SECTION: HFIT 26.73 FITNE3S FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N N O HOT SHUTDOWN O HOT SHUTDOWN

A RADWASTE CONTRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL AS FOUND

VIA RANDOM TESTING. THE INDIVIDUAL HAS REQUESTED A BLOOD TEST.
THE INDIVIDUAL'S UNESCORTED ACCESS HAS BEEN PULLED PENDING
EVALUATION

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: CAROLINA POWER & LIGHT CO.

SIT: ROBINSON 2 EN NUMBER: 25000

DOCKET: 05000261 EVENT DATE: 02-02-93

RX TYPE: PWR EVENT TIME. 13:30

VENDORS: W-3-LP NOTIFY DATE: 02-03-93

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 10:18

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N Y 100 POWER OPERATION 100 POWER OPERATION

A SUPERVISOR TESTED POSITIVELY DURING A RANDOM DRUG TEST.

THE FOLLOWING IS THE TEXT OF A FACSIMILE SUBMITTED BY THE LICENSEE:

"AT 1330 HOURS ON FEBRUARY 2, 1993, THE MEDICAL REVIEW OFFICER FOR THE H.B. ROBINSON PLANT DETERMINED THAT THE RESULTS OF A RANDOM DRUG AND ALCOHOL TEST OF A CP&L SUPERVISOR, WHICH WAS TAKEN ON JANUARY 20, WAS POSITIVE FOR DRUGS, AND DECLARED A FITNESS FOR DUTY VIOLATION IN ACCORDANCE WITH 10CFR26.73(a)(2)(ii). UNESCORTED ACCESS TO THE PROTECTED AREA HAS BEEN RESCINDED. BECAUSE THE INDIVIDUAL HAD ACCESS TO AREAS CONTAINING SAFETY RELATED EQUIPMENT, A REVIEW OF THE INDIVIDUAL'S WORK HAS BEEN INITIATED."

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1 EN NUMBER: 25003 DOCKET: 05000528 EVENT DATE: 02-03-93

RX TYPE: PWR EVENT TIME: 08:10 VENDORS: CE80 NOTIFY DATE: 02-03-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 12:17

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE REPORTED THAT A QUALITY CONTROL WORK GROUP FOREMEN TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG SCREEN MADE ON 01/27/93.

THE INDIVIDUAL'S ACAD (ACCESS CONTROL AUTHORIZATION DEVICE) WAS TERMINATED AT 08:19MST. THE INDIVIDUAL WAS NOT IN THE PROTECTED AREA AT THE TIME FOLLOWING THE REVIEW EVALUATION. THE INDIVIDUAL'S WORK AREA WAS IN THE PROTECTED AREA AND HIS WORK SCOPE WAS SUPERVISION OF QC PERSONNEL. THE INDIVIDUAL WAS TERMINATED BY THE LICENSEE ON 2/3/93. THE RI WAS INFORMED.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 2

DOCKET: 05000247

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NY

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

NO COLD SHUTDOWN

COLD SHUTDOWN

LICENSED REACTOR OPERATOR FAILED A RANDOM ALCOHOL TEST.

"A CON-ED STAFF LICENSED SRO FAILED A RANDOM ALCOHOL TEST. THE INDIVIDUAL WAS SELECTED RANDOMLY PRIOR TO ENTRY TO THE PROTECTED AREA. AT APPROXIMATELY 0615 EST, POSITIVE RESULTS OF > 0.04% BLOOD ALCOHOL WERE OBTAINED ON THE ALCOHOL BREATHALYZER TEST. BASED ON THE RESULTS OF THE TEST, THE INDIVIDUAL WAS DENIED ACCESS TO THE PROTECTED AREA. ALTHOUGH A LICENSED REACTOR OPERATOR, THE INDIVIDUAL HAS NOT PERFORMED LICENSED DUTIES FOR AN EXTENDED PERIOD OF TIME AND WAS NOT SCHEDULED TO PERFORM LICENSED DUTIES."

THE INDIVIDUAL HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. IT HAS NOT BEEN DETERMINED WHETHER A WORK REVIEW WILL BE PERFORMED.

THE LICENSEE NOTIFIED THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY
SITE: BROWNS FERRY 1 2 3

DOCKET: 05000259 05000260 05000296 EVENT DATE: 02-25-93

RX TYPE: BWR BWR BWR VENDORS: GE-4 GE-4 GE-4 EN NUMBER:25141 EVENT DATE: 02-25-93 EVENT TIME: 13:00 NOTIFY DATE: 02-26-93 EMERGENCY CLASS: N/A REGION: 2 STATE: AL

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 REFUELING 0 REFUELING
2 N N 0 REFUELING 0 REFUELING
3 N N 0 REFUELING 0 REFUELING

A LICENSEE EMPLOYEE TESTED POSITIVE ON A RANDOM DRUG TEST PROGRAM.

A FOREMAN HAD A CONFIRMED POSITIVE DRUG TEST FOR MARIJUANA. HIS UNESCORTED ACCESS CLEARANCE WAS REVOKED AND HE WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. THERE WAS NO POTENTIAL FOR HIS WORK COMPROMISING PLANT SAFETY. THE RI WILL BE INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: BYRON 1 2

DOCKET: 05000454 05000455

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EVENT TIME: 00:45

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: CHAUNCEY GOULD

OPS OFFICER: CHAUNCEY GOULD

OFFICER: OFFICER: CHAUNCEY GOULD

OFFICER: OF

THE LICENSEE REPORTED THAT A CONTRACT EMPLOYEE TESTED POSITIVE FOR ALCOHOL.

A FOREMAN, WHO WAS WORKING WITH THE TURBINE, WAS ASKED TO TAKE AN ALCOHOL TEST AFTER HIS SUPERVISOR NOTICED THE ODOR OF ALCOHOL COMING FROM HIS PERSON. FOUR TEST WERE MADE FOR ALCOHOL AND THEY TESTED POSITIVE AT >.04 BREATH ALCOHOL CONTENT. A RANDOM DRUG TEST WAS ALSO PERFORMED, BUT THE RESULTS ARE NOT COMPLETE. THE EMPLOYEE WAS DENIED SITE ACCESS AND THE LICENSEE WILL REVIEW HIS WORK. THE RI WAS INFORMED.

LICENSEE: COMMONWEALT: EDISON CO.

SITE: DRESDEN 2 3

DOCKET: 05000237 05000249

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

OPS OFFICER: RUDY KARSCH
10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

2 N N 0 REFUELING

EN NUMBER: 25144

EVENT DATE: 02-26-93

EVENT TIME: 11:10

NOTIFY DATE: 02-26-93

FITNESS FOR DUTY

CURR CURRENT MODE

PWR

0 REFUELING

CONTRACT SUPERVISOR CONFIRMED POSITIVE FOR ILLEGAL SUBSTANCE USE. THE INDIVIDUAL'S CARD HISTORY SHOWED PROTECTED AREA ACCESS, BUT NO VITAL AREA ENTRY. THE INDIVIDUAL WAS ESCORTED OFF SITE AND HIS NUCLEAR SITE ACCESS HAS BEEN PERMANENTLY REVOKED. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 2 EN NUMBER: 25155 DOCKET: 05000247 EVENT DATE: 02-27-93 RX TYPE: PWR EVENT TIME: 07:16 NOTIFY DATE: 02-27-93 VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 22:31

OPS OFFICER: RUDY KARSCH

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR

N N O REFUELING O REFUELING

CONTRACTOR EMPLOYEE SUPERVISOR TESTED POSITIVE FOR ALCOHOL IN A RANDOM SCREENING WHILE ENTERING THE SITE. SITE ACCESS HAS BEEN SUSPENDED. THE LICENSEE DETERMINED THAT THE INDIVIDUAL'S VITAL AREA ACCESS WAS LIMITED TO 3 MINUTES ON 2/24/93. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: ZION 1 2 EN NUMBER: 25288 DOCKET: 05000295 05000304 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT DATE: 03-22-93 EVENT TIME: 10:15 NOTIFY DATE: 03-22-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 11:55 OPS OFFICER: JOHN MacKINNON

FITNESS FOR DUTY CURR CURRENT MODE 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 90 POWER OPERATION 90 POWER OPERATION

CONTRACT SUPERVISOR TESTED POSITIVE ON A RANDOM DRUG TEST. TEST WAS ADMINISTERED ON 03/18/93.

CONTRACT (CHICAGO BRIDGE IRON & STRUCTURAL CO.) SUPERVISOR TESTED POSITIVE ON A RANDOM DRUG TEST WHICH WAS GIVEN ON 03/18/93. SUPERVISOR WAS INVOLVED IN CHANGING OUT BORIC ACID TANKS IN THE AUXILIARY BUILDING. SUPERVISOR HAD VITAL ACCESS. THIS PERSON TESTED POSITIVE FOR DRUGS (DID NOT KNOW WHAT TYPE OF DRUGS HE TESTED POSITIVE FOR). SUPERVISOR WAS PLACED ON LICENSEES' DENIED ACCESS LIST AND HIS BADGE WAS TERMINATED. THIS PERSON HAD WORKED ON SITE FOR LESS THAN SIXTY DAYS.

RESIDENT INSPECTOR WILL BE IN. MED BY THE LICENSEES.

LICENSEE: DUKE POWER CO.

EN NUMBER: 25307 SITE: CATAWBA 1 2 DOCKET: 05000413 05000414 EVENT DATE: 03-24-93

RX TYPE: PWR PWR EVENT TIME: 14:09 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP NOTIFY DATE: 03-24-93

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 17:30

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N N 0 REFUELING 0 REFUELING

2

THE LICENSEE CONFIRMED A POSITIVE TEST RESULTS FOR DRUGS ON A PLANT EMPLOYEE.

A RANDOM SCREEN FOR DRUGS WAS MADE ON A LICENSED EMPLOYEE AND IT WAS CONFIRMED POSITIVE FOR COCAINE. THE EMPLOYEES ACCESS HAS BEEN DENIED AND THE EMPLOYEE HAS BEEN REFERRED TO THE LICENSEES EMPLOYEES ASSISTANCE PROGRAM. HIS WORK PERFORMANCE DID NOT ADVERSELY AFFECT PLANT SAFETY OR STATUS. WORK THAT THE EMPLOYEE HAD PERFORMED IS BEING VERIFIED BY OTHER PERSONNEL. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE RI WAS INFORMED AND NO OTHER OUTSIDE AGENCIES WILL BE NOTIFIED.

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1 EN NUMBER: 25314 DOCKET: 05000346 EVENT DATE: 03-25-93 EVENT TIME: 15:00 RX TYPE: PWR

VENDORS: B&W-R-LP NOTIFY DATE: 03-26-93

EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 11:09

OPS OFFICER: JOSEPH SEBROSKY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N N O REFUELING 0 REFUELING

A LICENSED EMPLOYEE WAS DETERMINED TO BE UNDER THE INFLUENCE OF ALCOHOL DURING A PHYSICAL.

THE INDIVIDUAL WAS ABOVE THE CUTOFF LEVEL OF 0.040% BLOOD ALCOHOL CONTENT (BAC). THE INDIVIDUAL'S TEST RESULTS WERE AS FOLLOWS: AT 15:00 BAC WAS 0.042, AT 15:02 BAC WAS 0.046, AT 15:33 BAC WAS 0.038, AT 15:36 BAC WAS 0.037. THE INDIVIDUAL WAS NOT PERFORMING LICENSED ACTIVITIES AT THE TIME. THE INDIVIDUAL'S ACCESS HAS BEEN DENIED AND THE INDIVIDUAL HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: TOLEDO EDISON CO.

SITE: DAVIS BESSE 1 EN NUMBER: 25315 DOCKET: 05000346 EVENT DATE: 03-26-93 RX TYPE: PWR EVENT TIME: 08:00 VENDORS: B&W-R-LP NOTIFY DATE: 03-26-93 EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 11:15

OPS OFFICER: JOSEPH SEBROSKY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

1 N

CODE CRIT PWR
1 N N 0 REFUELING 0 REFUELING

A SUSPECTED CONTROL SUBSTANCE WAS FOUND IN THE PROTECTED AREA.

DURING A ROUTINE DRUG SEARCH BY A K-9 DRUG DOG THE FOREIGN SUBSTANCE WAS FOUND. FIELD TEST INDICATED THE SUBSTANCE TO BE HASHISH. THE LICENSEE IS CONTINUING TO INVESTIGATE. THE HASHISH WAS APPROXIMATELY 1/4 INCH BY 1/2 INCH AND WAS FOUND IN AN OPEN

THE LICENSE HAS INFORMED THE RESIDENT INSPECTOR AND WILL NOTIFY THE LOCAL LAW ENFORCEMENT AGENCY (OTTAWA COUNTY SHERIFF) .

LICENSEE: TENNESSEE VALLEY AUTHORITY

EN NUMBER: 25361 SITE: BROWNS FERRY 1 2 3 EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 10:15 OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR		PWR		
1	N	N	0	REFUELING	0	REFUELING	
2	N	N	0	REFUELING	0	REFUELING	
3	N	N	0	REFUELING	0	REFUELING	

⁻ LICENSEE SUPERVISOR EMPLOYEE TESTED POSITIVE FOR MARIJUANA -

A LICENSEE SUPERVISOR EMPLOYEE WITHOUT UNESCORTED PLANT ACCESS AUTHORIZATION TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG TEST.

THIS WAS THE EMPLOYEE'S FIRST OFFENSE.

LICENSEE REMOVED THE EMPLOYEE FROM WORK STATUS AND REFERRED HIM TO THE EMPLOYEE ASSISTANCE PROGRAM.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: BROWNS FERRY 1 2 3

EN NUMBER: 25365

DOCKET: 05000259 05000260 05000296 EVENT DATE: 04-06-93 NOTIFY DATE: 04-07-93 RX TYPE: BWR BWR BWR VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 2 STATE: AL TIME: 09:29 OPS OFFICER: JOHN MacKINNON 10 CFR SECTION. HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR 0 REFUELING N 0 REFUELING N 0 REFUELING O REFUELING O REFUELING N N O REFUELING N

LICENSEE EMPLOYEE TESTED POSITIVE FOR MARIJUANA ON A RANDOM DRUG TEST.

INDIVIDUAL WITH SUPERVISORY RESPONSIBILITIES TOOK A RANGE DRUG TEST ON 04/02/93. AT 0945 CDT 04/06/93 HIS RESULTS CANDERS OF THE STATE OF THE STATE

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORP.

SITE: VERMONT YANKEE 1 EN NUMBER: 25366

DOCKET: 05000271 EVENT DATE: 04-07-93

RX TYPE: BWR EVENT TIME: 10:15

VENDORS: GE-4 NOTIFY DATE: 04-07-93

EMERGENCY CLASS: N/A REGION: 1 STATE: VT TIME: 11:22

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N O HOT SHUTDOWN O HOT SHUTDOWN

MAINTENANCE FOREMAN TESTED POSITIVE FOR ALCOHOL FOR THE SECOND TIME IN LESS THAN ONE YEAR.

AT 0950 EDT A MAINTENANCE FOREMAN TESTED POSITIVE FOR ALCOHOL DURING A RANDOM ALCOHOL/DRUG TEST. HE WAS ADMINISTERED A SECOND TEST AT 1015 EDT AND HE RECEIVED A 0.05% ON THE ALCOHOL TEST (LIMIT IS 0.04%). LICENSEE WILL REVIEW HIS PAST WORK (THIS PERSON WAS INVOLVED MAINLY IN SCHEDULING). THIS FOREMAN WAS IN LICENSEE'S ALCOHOL/DRUG TESTING PROGRAM BECAUSE LAST MAY (1992) HE TESTED POSITIVE FOR ALCOHOL. LICENSEE SAID THAT THE FOREMAN WAS PLACED UNDER ESCORT, ESCORTED OFFSITE AT 1045 EDT. HIS ACCESS WAS TERMINATED AND HE HAS A RIGHT TO APPEAL. LICENSEE IS IN PROCESS OF TERMINATING THIS PERSON'S EMPLOYMENT.

RESIDENT INSPECTOR WAS INFORMED BY THE LICENSEE.

LICENSEE: HOUSTON LIGHTING & POWER CO.

SITE: SOUTH TEXAS 1 2

DOCKET: 05000498 05000499

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EN NUMBER: 25404

EVENT DATE: 04-15
EVENT TIME: 23:57

NOTIFY DATE: 04-16-EN NUMBER: 25404 EVENT DATE: 04-15-93 NOTIFY DATE: 04-16-93 EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:29 OPS OFFICER: TIM McGINTY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 REFUELING 0 REFUELING

A CONTRACT SUPERVISOR WAS CALLED TO REPORT TO WORK, AND HE DID NOT INFORM THE CALLER THAT HE HAD CONSUMED ALCOHOL. HE ARRIVED

AT APPROXIMATELY 2245 CDT AND ALCOHOL WAS DETECTED AND ACCESS WAS DENIED. AT 2357 CDT HE WAS TESTED AND CAME UP WITH A 0.12% BLOOD ALCOHOL CONTENT. HE WAS DENIED ACCESS AND HIS BADGE WAS PLACED ON HOLD. MANAGEMENT WILL REVIEW THE CASE TO DETERMINE HIS DISPOSITION.

THE LICENSEE INFORMED THE RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

EN NUMBER: 25456 SITE: MILLSTONE 1 2 3 SITE: MILLSTONE 1 2 3

DOCKET: 05000245 05000336 05000423

RX TYPE: BWR PWR

VENDORS: GE-3 CE W-4-LP

EN NUMBER: 25456

EVENT DATE: 04-28-93 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 13:34 OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
N 100 POWER OPERATION 100 POWER OPERATION
N 120 POWER CREENTION 100 POWER OPERATION

A CONSTRUCTION FOREMAN TESTED POSITIVE FOR ALCOHOL DURING A RANDOM SCREENING. HE HAD NOT BETW WORKING WITHIN THE PROTECTED AREA. THE LICFNSEE WILL TAKE COMPENSATORY MEASURES. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: SAINT LUCIE 1 2 EN NUMBER: 25478 DOCKET: 05000335 05000389
RX TYPE: PWR PWR EVENT DATE: 05-03-93

EVENT TIME: 00:00 VENDORS: CE CE NOTIFY DATE: 05-03-93

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 14:09

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION

AN ENGINEERING SUPERVISOR TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG TEST.

AN OFFSITE ENGINEERING SUPERVISOR TESTED POSITIVE FOR MARIJUANA DURING

A CONFIRMATORY RANDOM DRUG TEST. THE SUPERVISOR MANAGED IN-SERVICE INSPECTION CONTRACTORS AND HAD ACCESS TO VITAL AREAS OF THE PLANT. THE INITIAL TEST OCCURRED ON 04/27/93 AND THE CONFIRMATORY TEST TOOK PLACE ON 05/03/93. THE SUPERVISOR HAS BEEN TERMINATED AND A WORK REVIEW OF HIS ACTIVITIES OVER THE LAST NINETY DAYS HAS COMMENCED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

EN NUMBER: 25480 SITE: CATAWBA 1 2 DOCKET: 05000413 05000414 EVENT DATE: 05-03-93
RX TYPE: PWR PWR EVENT TIME: 00:00
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 05-03-93

EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 17:49

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED REACTOR OPERATOR WAS SUSPENDED WHEN HE ADMITTED BEING ARRESTED FOR POSSESSION OF A CONTROLLED SUBSTANCE.

WHILE IN COUNSELING AT A REHABILITATION CENTER, A LICENSED REACTOR OPERATOR ADMITTED TO A REHAB COUNSELOR THAT HE HAD BEEN ARRESTED FOR POSSESSION OF AN UNSPECIFIED CONTROLLED SUBSTANCE DURING REHABILITATION. THE REHAB COUNSELOR INFORMED A PLANT EMPLOYEE ASSISTANCE PROGRAM (EAP) COUNSELOR WHO, IN TURN, NOTIFIED THE FITNESS-FOR-DUTY OFFICER. THE LICENSED REACTOR OPERATOR HAS BEEN SUSPENDED AND SCHEDULED TO REPORT TO THE EAP COUNSELOR. AT THAT TIME, A FORMAL INTERVIEW OF THE EMPLOYEE WILL BE CONDUCTED AND FURTHER INFORMATION WILL BE AVAILABLE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

EN NUMBER: 25505 TE: DRESDEN 2 3 DOCKET: 05000237 05000249 EVENT DATE: 05-11-93 EVENT TIME: 11:30 RX TYPE: BWR BWR VENDORS: GE-3 GE-3 NOTIFY DATE: 05-11-EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 14:19 NOTIFY DATE: 05-11-93

OPS OFFICER: CHAUNCEY GOULD FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73

UNIT	SCRAM	RX		INITIAL MODE	CURR	CURRENT MODE
2	N	N	0	COLD SHUTDOWN	0	COLD SHUTDOWN
3	N	Y	100	POWER OPERATION	100	POWER OPERATION

THE LICENSEE REPORTED THAT AN ACTING DESIGN SUPERVISOR FOR THE SITE ENGINEERING GROUP TESTED POSITIVE FOR ALCOHOL DURING A RANDOM TEST.

THE EMPLOYEE TESTED ABOVE THE LICENSEE'S LIMITS (.04 BLOOD ALCOHOL CONTENT) BUT HE WAS UNDER THE STATE'S LIMITS OF .1 FOR DRIVING. HE HAS BEEN DENIED ACCESS TO THE SITE AND WILL BE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. HIS WORK GROUP WILL BE PERFORMING A WORK PERFORMANCE INVESTIGATION OVER JOBS HE HAS BEEN INVOLVED WITH TO MAKE SURE THAT HIS WORK WAS NOT AFFECTED. THE RI WAS INFORMED.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

EN NUMBER: 25568 SITE: SEABROOK 1 EVENT DATE: 05-26-93 DOCKET: 05000443 RX TYPE: PWR EVENT TIME: 09.11 NOTIFY DATE: 05-26-93 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 13:39 OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG TEST.

THE PERSON HAD A 0.04 BLOOD ALCOHOL CONTENT (BAC) AT 08:39 5/26/93 AND THE TEST WAS CONFIRMED POSITIVE AT 09:11. THE LICENSEE LIMIT IS 0.04 (BAC). THE PERSON HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. IN ADDITION THE EMPLOYEES ACCESS HAS BEEN REMOVED AND THE EMPLOYEE HAS BEEN GIVEN A 14 DAY SUSPENSION. THE LICENSEE HAS PERFORMED A WORK REVIEW OF THE EMPLOYEES PAST 30 DAYS. THE EMPLOYEE HAS NOT HAD VITAL ACCESS FOR THE LAST 30 DAYS. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES SITE: MILLSTONE 1 2 3 EN NUMBER: 25569 EVENT DATE: 05-26-93 DOCKET: 05000245 05000336 05000423 VENDORS: GE-3 CE W-4-LP EVENT TIME: 13:47 NOTIFY DATE: 05-26-93 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 13:56 OPS OFFICER: JOSEPH SEBROSKY
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
2	N	Y	70	POWER	OPERATION	70	POWER	OPERATION
3	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG TEST.

THE TEST WAS PERFORMED ON 5/20/93 AND CONFIRMED POSITIVE ON 5/26/93. THE EMPLOYEE'S ACCESS TO THE PROTECTED AREA HAS BEEN REVOKED AND THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE WILL INFORM STATE AND LOCAL OFFICIALS AND THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: CONSUMERS POWER CO.

SITE: PALISADES 1

DOCKET: 05000255

RX TYPE: PWR

VENDORS: CE

EN NUMBER: 25636

EVENT DATE: 06-10-93

EVENT TIME: 20:50

NOTIFY DATE: 06-11-93

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 09:06

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR
1 N N 0 REFUELING 0 REFUELING

A PLANT SUPERVISOR TESTED POSITIVELY ON A RANDOM DRUG TEST.

AT 2050 EDT ON 06/10/93, THE RESULTS OF A RANDOM DRUG TEST INDICATED THE USE OF COCAINE BY A PLANT SUPERVISOR. AT 2055 EDT, SECURITY DEPARTMENT

WAS NOTIFIED AND THE EMPLOYEE'S ACCESS TO ROTECTED AREAS WAS REVOKED.

THE SUPERVISOR WAS REFERRED TO THE PLANT EMPLOYEE ASSISTANCE PROGRAM.

THE EMPLOYEE CLAIMS NOT TO HAVE ACCESSED PROTECTED AREAS OF THE PLANT WITHIN THE LAST SIX MONTHS. A REVIEW OF HIS WORK IS IN PROGRESS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: MCGUIRE 1 2

DOCKET: 05000369 05000370

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EN NUMBER: 25653

EVENT DATE: 06-15-93

EVENT TIME: 08:42

NOTIFY DATE: 06-15-93

EMERGENCY CLASS: N/A REGION: 2 STATE: NC

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1	N	Y	23	POWER	OPERATION	23	POWER	OPERATION
2	N	Y	97	POWER	OPERATION	97	POWER	OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR ALCOHOL.

AN LICENSED OPERATOR TESTED POSITIVE FOR ALCOHOL ON A RANDOM FOLLOWUP TEST. HIS PROTECTED AREA ACCESS HAS BEEN SUSPENDED AND CIRCUMSTANCES OF THIS INFRACTION WILL BE EVALUATED BY THE EMPLOYEE ASSISTANCE PROGRAM. HE HAD NOT BEEN INTO THE PROTECTED AREA DURING THE DAY. THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. SEE HOO LOG BOOK FOR FURTHER DETAILS.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2

DOCKET: 05000334 05000412

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

VENDORS: W-3-LP W-3-LP

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 30 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR MARIJUANA. THE TEST RESULTS WERE CONFIRMED TODAY. THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE RESIDENT INSPECTOR WILL BE INFORMED.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI

SITE: SAN ONOFRE 2 3 EN NUMBER: 25698

DOCKET: 05000361 05000362 EVENT DATE: 06-24-93

RX TYPE: PWR PWR EVENT TIME: 15:17

VENDORS: CE CE NOTIFY DATE: 06-25-93

EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 16:01

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N N 0 REFUELING 0 REFUELING

3 N Y 100 POWER OPERATION 100 POWER OPERATION

FITNESS FOR DUTY REPORT PER 10CFR26.73.a.2.ii.
A NUCLEAR OVERSITE SUPERVISOR AT UNITS 2 & 3 CONFIRMED POSITIVE ON A RANDOM SCREENING TEST. ACCESS WAS TERMINATED WITHIN 15 MINUTES OF NOTIFICATION. LAST ENTRY INTO THE VITAL AREA BY THIS INDIVIDUAL WAS ON 6/18/93. WORK PERFORMED BY THIS INDIVIDUAL IS

UNDERGOING REVIEW. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2 EN NUMBER: 25768 SITE: LASALLE 1 2 DOCKET: 05000373 05000374 RX TYPE: BWR BWR EVENT DATE: 07-09-93 EVENT TIME: 08:15 VENDORS: GE-5 GE-5 NOTIFY DATE: 07-09-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 15:28 OPS OFFICER: JOSEPH SEBROSKY 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 97 POWER OPERATION 97 POWER OPERATION N Y 99 POWER OPERATION 99 POWER OPERATION

A NON-LICENSED CONTRACTOR SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM TEST. THE ORIGINAL TEST WAS GIVEN AT 08:15 7/9/93 AND CONFIRMED POSITIVE AT 09:00 7/9/93. THE RESULTS WERE JUST ABOVE THE LICENSEE'S LIMIT OF 0.04 PERCENT BLOOD ALCOHOL CONTENT. THE LICENSEE HAS TERMINATED THE INDIVIDUALS ACCESS TO THE PROTECTED AREA AND IS PERFORMING A REVIEW OF THE INDIVIDUAL'S WORK.

THE LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

LICENSEE: NORTHERN STATES POWER CO.

SITE: PRAIRIE ISLAND 2 EN NUMBER: 25868 DOCKET: 05000306 EVENT DATE: 08-02-93 EVENT TIME: 10:15 RX TYPE: PWR NOTIFY DATE: 08-02-93 VENDORS: W-2-LP EMERGENCY CLASS: N/A REGION: 3 STATE: MN TIME: 17:48 OPS OFFICER: STEVE SANDIN FITNESS FOR DUTY CURR CURRENT MODE 10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR
2 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR TESTED POSITIVE FOR ALCOHOL DURING RANDOM DRUG TESTING.

A LICENSED OPERATOR TESTED POSITIVE IN TWO BREATHALYZER TESTS ADMINISTERED WITHIN 10 MINUTES OF EACH OTHER AT 1015CDT. A VOLUNTARY BLOOD SAMPLE WAS DRAWN AS PART OF AN EMPLOYEE APPEAL AND FORWARDED TO A FORENSIC LAB FOR ANALYSIS. A SEARCH OF THE AREA FOR CONTRABAND WAS PERFORMED WITH NOTHING FOUND. THE INDIVIDUAL WAS ESCORTED FROM THE PA AFTER REVOKING ACCESS. THE INDIVIDUAL HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO. SITE: MCGUIRE 1 2

EN NUMBER: 26033

DOCKET: 05000369 05000370 EVENT DATE: 09- .-93
RX TYPE: PWR PWR EVENT TIME: 13:30
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 09-08-93
EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 11:13
OPS OFFICER: GREG SCARFO
10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 HOT STANDBY 0 HOT STANDBY

A DUKE POWER SUPERVISOR TESTED POSITIVELY DURING A CONFIRMATORY DRUG TEST.

A CIVIL MAINTENANCE SUPERVISOR TESTED POSITIVELY DURING A CONFIRMATORY DRUG TEST FOR COCAINE. THE CONFIRMATORY DRUG TEST WAS THE RESULT OF A POSITIVE RANDOM DRUG TEST PERFORMED ON 09/01/93. THE SUPERVISOR'S ACCESS TO THE PROTECTED AREA WAS REVOKED AND HE HAS BEEN REFERRED TO AN EMPLOYEE ASSISTANCE PROGRAM (EAP). A WORK REVIEW IS IN PROGRESS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

SITE: SALEM 1 2

DOCKET: 05000272 05000311

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: NJ

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

EN NUMBER: 26036

EVENT DATE: 09-08-93

EVENT TIME: 14:25

NOTIFY DATE: 09-08-93

FITNESS FOR DUTY

CURR CURRENT MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

-PLANT ACCESS DENIED DUE TO UNFITNESS FOR DUTY DUE TO PRESENCE OF ALCOHOL-

A PRE-PLANT-ACCESS PHYSICAL EXAMINATION OF A CONTRACTOR SUPERVISOR RESULTED IN A DETERMINATION OF UNFITNESS FOR SCHEDULED WORK DUE TO THE CONSUMPTION OF ALCOHOL.

THE INDIVIDUAL HAS NEVER BEEN ONSITE AND HIS PLANT ACCESS AUTHORIZATION HAS BEEN DENIED.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 2

DOCKET: 05000410 RX TYPE: BWR EN NUMBER:26111 EVENT DATE: 09-23-93 EVENT TIME: 13:00 VENDORS: GE-5 NOTIFY DATE: 09-24-93

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 08:01

OPS OFFICER: DICK JOLLIFFE

FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION

- NEW CONTRACTOR SUPERVISOR TESTED POSITIVE FOR THE PRESENCE OF ALCOHOL -

A NEW CONTRACTOR SUPERVISOR WHO HAD NEVER BEEN ON SITE WAS ATTENDING A LICENSEE SPONSORED BEHAVIORAL OBSERVATION TRAINING CLASS.

ONE OF THE CLASS INSTRUCTORS SMELLED ALCOHOL ON THE SUPERVISOR'S BREATH AND NOTIFIED ONE OF THE LICENSEE'S FITNESS FOR DUTY DEPARTMENT REPRESENTATIVES AND THE SUPERVISOR'S SUPERVISOR.

THE SUPERVISOR WAS TESTED FOR THE PRESENCE OF ALCOHOL. THE TEST RESULTS WERE POSITIVE.

THE SUPERVISOR'S PLANT ACCESS BADGE WAS DEACTIVATED AND THE SUPERVISOR WILL NOT BE PERMITTED TO WORK ON SITE.

THE SUPERVISOR WAS TURNED OVER TO HIS COMPANY FOR FURTHER ACTION.

LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

SITE: COMANCHE PEAK 1 2 EN NUMBER: 26162 DOCKET: 05000445 05000446 EVENT DATE: 10-04-93 VENDORS: W-4-LP W-4-LP EVENT TIME: 13:30

NOTIFY DATE: 10-04-93

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 17:09

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION N

100 POWER OPERATION 100 POWER OPERATION Y

CONTRACTOR/SUPERVISOR TESTED POSITIVE FOR MARIJUANA USE. HIS COMPANY WAS COMPLETING MODIFICATIONS TO AN OFFICE BUILDING. HE HAD PROTECTED AREA ACCESS SINCE AUGUST 8, 1993. HIS BADGE HAS BEEN PULLED AND HE WAS REMOVED FROM THE PROTECTED AREA. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: SAINT LUCIE 1 2

EN NUMBER: 26200 EVENT DATE: 10-11-93 DOCKET: 05000335 05000389

RX TYPE: PWR PWR

VENDORS: CE CE

NOTIFY DATE: 10-11-93

EMERGENCY CLASS: N/A REGION: 2 STATE: FL

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

2 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACTOR TESTED POSITIVE FOR MARIJUANA.

A CONTRACT PAINTING SUPERVISOR TESTED POSITIVE (CONFIRMED) FOR MARIJUANA. THE CONTRACTOR HAD BEEN TESTED FOR CAUSE FOLLOWING AN ALLEGATION MADE ON 10/5/93. HIS PLANT ACCESS HAS BEEN SUSPENDED SINCE THE ALLEGATION AND IS NOW TERMINATED. A 90 DAY WORK REVIEW OF THE CONTRACTOR'S TASKS ARE IN PROGRESS. HE DID NOT HAVE ACCESS TO VITAL AREAS IN THE PLANT.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1

DOCKET: 05000528

RX TYPE: PWR

VENDORS: CE80

EVENT DATE: 10-14-93

EVENT TIME: 21:53

NOTIFY DATE: 10-15-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73

EN NUMBER: 26227

EVENT DATE: 10-14-93

EVENT TIME: 21:53

NOTIFY DATE: 17:21

FITNESS FOR DUTY

OPS OFFICER: CHAUNCEI GOODD

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N N 0 REFUELING 0 REFUELING

A SUPERVISORY CONTRACTOR TESTED POSITIVE FOR ALCOHOL.

THE LICENSEE TESTED A SUPERVISORY CONTRACT PERSON (WORKED FOR CBS WHICH IS A CONTRACTOR RESPONSIBLE FOR HOUSEKEEPING) FOR ALCOHOL AFTER HE HAD ARRIVED TO WORK 4 HOURS LATE ON 10/14/93. HE WAS TESTED FOR CAUSE DUE TO ALLEGATIONS BY FELLOW EMPLOYEES. HE WAS TESTED BETWEEN 21:44 AND 21:53 MST AND A POSITIVE TEST REVEALED THAT HIS AVERAGE BLOOD ALCOHOL CONTENT INDICATED .086%. AT 22:10 @ 10/14/93 HIS PROTECTED AREA ACCESS WAS TERMINATED AND HE WAS ESCORTED OFF SITE AND TAKEN HOME. THE TYPE OF WORK HE WAS INVOLVED IN WAS NOT PLANT SAFETY RELATED. THE RI WAS INFORMED.

LICENSEE: CONNECTICUT YANKEE ATOMIC POWER CO.

SITE: HADDAM NECK 1 EN NUMBER: 26237

DOCKET: 05000213 EVENT DATE: 10-18-93

RX TYPE: PWR EVENT TIME: 12:22

VENDORS: W-4-LP NOTIFY DATE: 10-18-93

EMERGFNCY CLASS: N/A REGION: 1 STATE: CT TIME: 12:25

OPS OFFICER: JOHN MacKINNON

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

NON-LICENSED SUPERVISOR HAD A RANDOM BLOOD AND ALCOHOL TEST ADMINISTERED TO HIM THIS MORNING AND HE TESTED POSITIVE FOR ALCOHOL. TH'S SUPERVISOR HAD NOT BEEN IN ANY VITAL AREAS TODAY. HIS BADGE HAS BEEN PULLED AND HE WILL BE ESCORTED HOME LATER TODAY. HE WILL BE REFERRED TO LICENSEES EMPLOYEE ASSISTANCE PROGRAM.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2

DOCKET: 05000334 05000412

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EMERGENCY CLASS: N/A REGION: 1 STATE: PA

EMERGENCY CLASS: N/A REGION: 1 STATE: PA

OPS OFFICER: WILLIAM HUFFMAN
10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN
2 N REFUELING

EN NUMBER: 26249

EVENT DATE: 10-21-93

EVENT TIME: 09:20

NOTIFY DATE. 10-21-93

FITNESS FOR DUTY

CURRENT MODE

PWR

1 N N 0 COLD SHUTDOWN
0 REFUELING

CONTRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL.

A CONTRACT SECURITY SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM FITNESS FOR DUTY TEST. BLOOD ALCOHOL LEVEL WAS 0.04%. RESULTS WERE RECEIVED AT 09:20 EDT THIS MORNING. THE INDIVIDUAL'S SITE ACCESS HAS BEEN TERMINATED AND A WORK REVIEW IS IN PROGRESS. THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: LASALLE 1 2

DOCKET: 05000373 05000374

RX TYPE: BWR BWR

VENDORS: GE-5 GE-5

EMERGENCY CLASS: N/A REGION: 3 STATE: IL

EN NUMBER: 26254

EVENT DATE: 10-21-93

EVENT TIME: 10:00

NOTIFY DATE: 10-22-93

OPS OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION 2 N N O REFUELING 0 REFUELING

A CONTRACT EMPLOYEE TESTED POSITIVELY DURING A PRE-ACCESS RANDOM DRUG TEST.

AT 1000CDT ON 10/21/93, A CONTRACT EMPLOYEE TESTED POSITIVELY DURING A PRE- ACCESS RANDOM DRUG TEST. BETWEEN 1000CDT AND 1155CDT, THE EMPLOYEE WAS ADDED TO THE ACCESS-DENIED LIST BUT WAS INADVERTENTLY BADGED FOR ACCESS TO VITAL AND PROTECTED AREAS OF THE PLANT PRIOR TO ITS RELEASE. AT 1205CDT, THE EMPLOYEE'S ACCESS BADGE WAS RESCINDED AND HE WAS REMOVED FROM THE PROTECTED AREA. AT 1300CDT, A WORK REVIEW WAS COMPLETED WITH NO INDICATION THAT HE ACCESSED ANY VITAL AREAS OF THE PLANT. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTHERN CALIFORNIA EDISON & SAN DI SITE: SAN ONOFRE 2 3 EN NUMBER: 26276 DOCKET: 05000361 05000362 EVENT DATE: 10-27-93 RX TYPE: PWR PWR EVENT TIME: 10:30 VENDORS: CE CE NOTIFY DATE: 10-28-93 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 09:35 OPS OFFICER: JOHN MacKINNON 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION N N 0 REFUELING 0 REFUELING

SUSPECT MATERIAL FOUND (REMAINS OF ONE MARIJUANA CIGARETTE) IN REMOTE AREA OF UNIT 3. LICENSEE SUSPECTS THAT THE ABOVE CONTROLLED SUBSTANCE HAS BEEN IN THIS REMOTE LOCATION SINCE UNIT 3 CONSTRUCTION (1978 - 1981 TIME FRIME).

SUSPECT MATERIAL WAS FOUND IN PROTECTED AREA LOCATED IN A GENERALLY NON-ACCESSIBLE REMOTE AREA IN UNIT 3 CONTAINMENT. MATERIAL DISCOVERED BY CONTRACT PERSONNEL WHILE PERFORMING A POLAR CRANE MODIFICATION. THIS IS THE FIRST MODIFICATION PERFORMED ON THE POLAR CRANE SINCE INITIAL CONSTRUCTION. CONFIRMATION OF THE SUSPECT MATERIAL IS PENDING VERIFICATION BY AN OFFSITE LABORATORY (REMAINS OF ONE MARIJUANA CIGARETTE). NO INDIVIDUAL IDENTIFIED AS BEING RESPONSIBLE FOR THE MATERIAL. LICENSEE SUSPECTS THAT THE CONTROL SUBSTANCE HAS BEEN IN THIS REMOTE AREA SINCE INITIAL UNIT 3 CONSTRUCTION.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: IOWA ELECTRIC LIGHT & POWER CO.

SITE: DUANE ARNOLD 1 EN NUMBER: 26279 DOCKET: 05000331 EVENT DATE: 10-29-93 RX TYPE: BWR EVENT TIME: 10:38 VENDORS: GE-4 NOTIFY DATE: 10-29-93 EMERGENCY CLASS: N/A REGION: 3 STATE: IA

TIME: 13:44

OPS OFFICER: JACK LEWIS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

1 N Y 75 POWER OPERATION 75 POWER OPERATION

-POSITIVE RESULTS ON DRUG TEST-

THE LICENSEE RECEIVED A CONFIRMED POSITIVE DRUG TEST FOR A NON-LICENSED EMPLOYEE. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED.

SEE HOO LOG FOR DETAILS.

THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DETROIT EDISON CO.

SITE: FERMI 2 EN NUMBER: 26308

DOCKET: 05000341 EVENT DATE: 11-02-93

RX TYPE: BWR EVENT TIME: 15:20

VENDORS: GE-4 NOTIFY DATE: 11-03-93

EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 11:18

OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: HFIT 26.73

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

2 N Y 93 POWER OPERATION 93 POWER OPERATION

THE LICENSE REPORTED THAT A SUPERVISOR WITH UNESCORTED ACCESS TESTED POSITIVE DURING A RANDOM DRUG TEST.

ON 11/2/93 @15:20 THE MEDICAL REVIEW OFFICER REPORTED THAT A SUPERVISOR WITH UNESCORTED ACCESS TESTED POSITIVE DURING A RANDOM DRUG TEST. HIS PROTECTED AREA ACCESS WAS SUSPENDED AT 15:20 @ 11/2/93. THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEES ASSISTANCE PROGRAM FOR FURTHER EVALUATION. THIS WAS THE EMPLOYEE'S FIRS. POSITIVE TEST FOR DRUGS. A REVIEW OF THE EMPLOYEES ASSIGNMENTS IDENTIFIED NO POOR WORK PERFORMANCE AND NO IMPACT ON REACTOR SAFETY. THE RI WAS INFORMED.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1

DOCKET: 05000220

RX TYPE: BWR

VENDORS: GE-2

NOTIFY DATE: 11-03-93

PMERCENCY CLASS: N/A PECION: 1 STATE: NY

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 14:39

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR IN A NON-ACTIVE STATUS FAILED A BLOOD ALCOHOL TEST ADMINISTERED FOR CAUSE. THE EMPLOYEE'S UNESCORTED ACCESS HAS BEEN REVOKED WITH THE EMPLOYEE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 1 2 3

DOCKET: 05000528 05000529 05000530

RX TYPE: PWR PWR
VENDORS: CE80 CE80 CE80

EN NUMBER: 26316

EVENT DATE: 11-04-93

EVENT TIME: 14:30

NOTIFY DATE: 11-04-93

EMERGENCY CLASS: N/A REGION: 5 STATE: AZ TIME: 17:27

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: HFIT 26.73

DSAF 73.71(b)(1)

UNIT SCRAM RX INIT INITIAL MODE
CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N Y 85 POWER OPERATION
3 N N 0 HOT STANDBY 0 HOT STANDBY

TWO INDIVIDUALS WERE GRANTED UNESCORTED ACCESS BASED ON FALSIFIED RECORDS AND AN INCOMPLETE BACKGROUND INVESTIGATION.

THE LICENSEE HAS DETERMINED THAT UNESCORTED ACCESS WOULD NOT HAVE BEEN GRANTED IF A COMPLETE AND PROPER INVESTIGATION HAD BEEN COMPLETED. A PRELIMINARY INVESTIGATION BY THE LICENSEE INTO THE EMPLOYMENT CERTIFICATION PROGRAM USED BY THEIR SUBCONTRACTOR HAS REVEALED SEVERAL DISCREPANCIES. IN ADDITION, OTHER INDIVIDUALS (APPROX 15) CERTIFIED BY THE SUBCONTRACTOR HAVE HAD THEIR UNESCORTED ACCESS REVOKED AND HAVE BEEN ESCORTED OFF SITE. THESE INDIVIDUALS WERE WORKING INSIDE THE UNIT 1 CONTAINMENT ON STEAM GENERATOR TUBE PLUGGING AND REMOVAL. THE LICENSEE WILL DETERMINE THE IMPACT THESE INDIVIDUALS MAY HAVE HAD ON PLANT SAFETY SO APPROPRIATE CORRECTIVE MEASURES CAN BE TAKEN. THE LICENSEE HAS INFORMED THE REGION 5 SAFEGUARDS BRANCH INSPECTOR (SCHAEFER) AND WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: WATTS BAR 1

DOCKET: 05000390

RX TYPE: PWR

VENDORS: W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN

EN NUMBER: 26318

EVENT DATE: 11-04-93

EVENT TIME: 14:00

NOTIFY DATE: 11-05-93

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 UNDER CONSTRUCT 0 UNDER CONSTRUCT

A LICENSEE TECHNICAL SUPERVISOR TESTED POSITIVE DURING A RANDOM TEST FOR ALCOHOL.

THIS EMPLOYEE WAS ESCORTED FROM THE SITE AND WILL BE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. AS PART OF THEIR CORRECTIVE

ACTION THEY WILL REVIEW THE WORK THAT HE HAS DONE. THE RI WILL BE INFORMED.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

EN NUMBER: 26319 SITE: SALEM 1 2 DOCKET: 05000272 05000311 EVENT DATE: 11-05-93 RX TYPE: PWR PWR RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 11:40 NOTIFY DATE: 11-05-93 EMERGENCY CLASS: N/A REGION: 1 STATE · NJ TIME: 12:53 OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE OPS OFFICER: THOMAS ANDREWS

CODE CRIT PWR

1 N N 0 REFUELING 0 REFUELING
2 N Y 100 POWER OPERATION 100 POWER OPERATION

A SUPERVISOR TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST. THE RESULTS WERE CONFIRMED. THE EMPLOYEE'S ACCESS HAS BEEN PULLED AND THE EMPLOYEE HAS BEEN REFERRED TO THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM.

THE NRC RESIDENT INSPECTOR WILL BE INFORMED. NO OTHER NOTIFICATIONS ARE PLANNED AT THIS TIME.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 EN NUMBER: 26332 DOCKET: 05000220 RX TYPE: BWR EVENT DATE: 11-08-93 EVENT TIME: 08:00 NOTIFY DATE: 11-08-93 VENDORS: GE-2

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 11:43

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR
1 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR'S RANDOM DRUG TEST RESULTS WERE CONFIRMED POSITIVE FOR COCAINE AT 0800 EST TODAY. THE TEST WAS CONDUCTED ON 10/29/93. THE EMPLOYEE'S ACCESS HAS BEEN PULLED AND THE EMPLOYEE HAS BEEN REFERRED TO THE LICENSEE'S EMPLOYEE ASSISTANCE PROGRAM.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: PACIFIC GAS & ELECTRIC CO.

SITE: DIABLO CANYON 1 2 EN NUMBER: 26349 DOCKET: 05000275 05000323 EVENT DATE: 11-10-93 RX TYPE: PWR PWR EVENT TIME: 18:50 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 11-10-93 EVENT TIME: 18:50 EMERGENCY CLASS: N/A REGION: 5 STATE: CA TIME: 22:49

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

DDDD 73.71							CIFIED	PARAGRAPH
UNIT	SCRAM	RX		INITIA	AL MODE	CURR	CURRI	ENT MODE
1	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

BASED ON AN ALLEGATION REGARDING A NON-LICENSED, NON-SUPERVISORY EMPLOYEE POSSESSING AN ILLEGAL DRUG INSIDE THE DIABLO CANYON PROTECTED AREA, A CORPORATE SECURITY INVESTIGATION WAS CONDUCTED. AT APPROXIMATELY 1850 PST, THE LICENSEE DETERMINED BASED ON AN INTERVIEW WITH THE SUBJECT EMPLOYEE AND AFTER CONSULTING WITH SECURITY MANAGEMENT THAT THE ALLEGATION WAS VALID.

THE EMPLOYEE ADMITTED TO POSSESSING A PRESCRIPTION MEDICATION (DARVOCET) WHILE IN THE PROTECTED AREA AND ADMITTED TO GIVING SOME OF THE DRUG TO A CO-WORKER. DARVOCET IS A SCHEDULE 4 CONTROLLED SUBSTANCE. THE LICENSEE FURTHER ADDED THAT THE EMPLOYEE HAD MULTIPLE PRESCRIPTIONS FOR DARVOCET.

THE SUBJECT EMPLOYEE AND THE CO-WORKER WHO RECEIVED THE DRUG FROM THE SUBJECT EMPLOYEE HAVE HAD THEIR ACCESS SUSPENDED PENDING FURTHER ACTION FROM THE LICENSEE.

THE LICENSEE WILL NOTIFY THE NRC RESIDENT INSPECTOR. NO OTHER NOTIFICATIONS ARE PLANNED AT THIS TIME.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3 EN NUMBER: 26414 DOCKET: 05000286 EVENT DATE: 11-23-93 RX TYPE: PWR EVENT TIME: 11:09 VENDORS: W-4-LP NOTIFY DATE: 11-24-93

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 11:08

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

0 COLD SHUTDOWN N 0 COLD SHUTDOWN

A LICENSED SENIOR OPERATOR PROVIDED A "SUSPECT" URINE SAMPLE TO A FITNESS FOR DUTY SITE COLLECTION NURSE. THE SAMPLE WAS IDENTIFIED AS SUSPECT BECAUSE ITS TEMPERATURE WAS LESS THAN 90.5 DEGREES F. A WITNESSED SAMPLE WAS COLLECTED AND SUBMITTED. TEST RESULTS HAVE NOT BEEN RECEIVED. THE INDIVIDUAL IN QUESTION RESIGNED HIS POSITION WITH NYPA ON 1645 EST ON 11/23/93. HE MAY HAVE PERFORMED WORK WHICH WAS NOT CHECKED BY ANOTHER LICENSED OPERATOR. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: PUBLIC SERVICE ELECTRIC & GAS CO.

SITE: SALEM 1 2 EN NUMBER: 26418

DOCKET: 05000272 05000311 EVENT DATE: 11-26-93

RX TYPE: PWR PWR EVENT TIME: 10:06

VENDORS: W-4-LP W-4-LP NOTIFY DATE: 11-26-93 EMERGENCY CLASS: N/A REGION: 1 STATE: NJ TIME: 14:41 OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N O REFUELING 0 REFUELING
N Y 100 POWER OPERATION 100 POWER OPERATION CODE CRIT PWR

THE LICENSEE DISCOVERED THAT ONE OF THEIR EMPLOYEES WAS DISCOVERED DURING A RANDOM FITNESS FOR DUTY CHECK TO EE UNFIT FOR DUTY DUE TO ALCOHOL.

THIS EMPLOYEE IS A PRINCIPAL NUCLEAR TRAINING SUPERVISOR AND HIS UNFITNESS FOR DUTY WAS DETERMINED DURING A RANDOM FITNESS FOR DUTY TEST FOR ALCOHOL. HIS ACCESS HAS BEEN DENIED AND HE HAS BEEN SUSPENDED PENDING FURTHER REVIEW. HE WILL BE REFERRED TO THE EMPLOYEES ASSISTANCE PROGRAM. THE WORK HE WAS INVOLVED WITH DID NOT HAVE ANY AFFECT ON PLANT SAFETY. THE RI WILL BE INFORMED.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: WATERFORD 3 EN NUMBER: 26428 DOCKET: 05000382 EVENT DATE: 11-29-93 EVENT TIME: 14:10 RX TYPE: PWR NOTIFY DATE: 11-30-93 VENDORS: CE EMERGENCY CLASS: N/A REGION: 4 STATE: LA TIME: 09:38

OPS OFFICER: STEVE SANDIN OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED SUPERVISOR VOLUNTARILY ENTERED THE EMPLOYEE ASSISTANCE PROGRAM FOR ILLIGAL DRUG AND ALCOHOL ABUSE. SECURITY ACCESS TO THE PROTECTED AREA HAS BEEN SUSPENDED. THE LICENSEE WILL DETERMINE WHETHER A WORK REVIEW WILL BE DONE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: ILLINOIS POWER CO.

EN NUMBER: 26482 SITE: CLINTON 1 EVENT DATE: 12-08-93 DOCKET: 05000461 EVENT TIME: 11:00 RX TYPE: BWR NOTIFY DATE: 12-09-93 VENDORS: GE-6 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 11:42

OPS OFFICER: DICK JOLLIFFE 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

1 N N 0 COLD SHUTDOWN 1 STARTUP 10 CFR SECTION: HFIT 26.73

LICENSEE HAS WITHDREW THE PLANT ACCESS AUTHORIZATION OF 2 CONTRACTORS BASED UPON A REASONABLE ASSURANCE THAT THE CONTRACTORS HAD USED ILLEGAL DRUGS. LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. SEE HOO LOG FOR DETAILS.

LICENSEE: DUQUESNE LIGHT CO.

SITE: BEAVER VALLEY 1 2 EN NUMBER: 26518 DOCKET: 05000334 05000412 EVENT DATE: 12-20-93 RX TYPE PWR PWR EVENT TIME: 08:49 VENDORS W-3-LP W-3-LP NOTIFY DATE: 12-20-93 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 17:15 OPS OFFI CER: THOMAS ANDREWS FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION 2 N 100 POWER OPERATION 100 POWER OPERATION

A LICENSME EMPLOYEE (NON-LICENSED) SUPERVISOR TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG TEST. THE EMPLOYEE DID NOT PERFORM ANY SAFET! RELATED WORK BETWEEN ARRIVING ONSITE AND PARTICIPATING IN THE RANDOM DRUG TESTING.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

Query: EN1994:hfit

LICENSEE: ENTERGY OPERATIONS INC.

EN NUMBER: 26559 SITE: ARKANSAS NUCLEAR 1 2 DOCKET: 05000313 05000368 EVENT DATE: 01-03-94 EVENT TIME: 10:00 RX TYPE: PWR PWR VENDORS: B&W-L-LP CE NOTIFY DATE: 01-03-94 EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 15:27

OPS OFFICER: GREG SCARFO 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N N Y 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION 100 POWER OPERATION

A CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST.

ON 12/21/93, A CONTRACT SUPERVISOR TESTED POSITIVE FOR COCAINE DURING A RANDOM DRUG TEST. THE RESULTS OF A CONFIRMATORY TEST, AVAILABLE ON 01/03/94, SUBSTANTIATED THE PREVIOUS RESULTS. THE CONTRACT SUPERVISOR'S PLANT ACCESS WAS REVOKED IMMEDIATELY AND HE WAS TERMINATED. EMPLOYEES UNDER HIS SUPERVISION DID HAVE ACCESS TO SAFETY EQUIPMENT. HOWEVER, THE LICENSEE BELIEVES THAT A WORK REVIEW IS UNNECESSARY BECAUSE ALL WORK PERFORMED BY THIS GROUP WAS INDEPENDENTLY REVIEWED PER PROCEDURE. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: GEORGIA POWER CO.

SITE: HATCH 1 EN NUMBER: 26678 DOCKET: 05000321 EVENT DATE: 01-25-94 RX TYPE: BWR EVENT TIME: 16:25 NOTIFY DATE: 01-25-94 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 17:45

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CRIT PWR CODE PWR

Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED OPERATOR FAILED A RANDOM DPUG TEST FOR ALCOHOL ADMINISTERED ON 1/21/94.

"TODAY AT 1625EST IT WAS REPORTED TO THE CONTROL ROOM THAT A LICENSED EMPLOYEE VIOLATED THE FITNESS FOR DUTY RULE. THIS WAS DETECTED BY A RANDOM DRUG ALCOHOL TEST THAT WAS CONFIRMED POSITIVE. THE EMPLOYEE'S UNESCORTED ACCESS HAS BEEN SUSPENDED, SECURITY BADGE REVOKED AND A WORK REVIEW WILL BE CONDUCTED TO DETERMINE IF WORK WAS SAFETY-RELATED."

THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM (EAP). THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: FLORIDA POWER & LIGHT CO.

SITE: TURKEY POINT 3 4

DOCKET: 05000250 05000251

RX TYPE: PWR PWR

VENDORS: W-3-LP W-3-LP

EN NUMBER: 26727

EVENT DATE: 02-02-94

RVENT TIME: 08:15

NOTIFY DATE: 02-02-94 SITE: TURKEY POINT 3 4 EN NUMBER: 26727

EMERGENCY CLASS: N/A REGION: 2 STATE: FL TIME: 13:50

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR

N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 85 POWER OPERATION 85 POWER OPERATION

4 N

A NON-LICENSED SUPERVISOR TESTED POSITIVE FOR MARIJUANA.

AT 0815 ON 2/2/94, A FP&L NON-LICENSED SUPERVISOR WAS CONFIRMED POSITIVE FOR MARIJUANA BY A RANDOM TEST WHICH WAS CONDUCTED ON 1/38/94. THE INDIVIDUALS GAS CHROMATOGRAPHY MASS SPEC (GCMS) LEVEL WAS 20 NANOGRAMS/ML, AND THE CUTOFF FOR MARIJUANA IS 10 NANOGRAMS/ML. THERE ARE NO INDICATIONS OF ON-SITE USAGE. THE INDIVIDUALS ACCESS TO TURKEY POINT AND SAINT LUCIE HAS BEEN DENIED, AND THE INDIVIDUAL IS APPEALING THE RESULTS. THE LICENSEE WILL BE CONDUCTING A REVIEW OF THE INDIVIDUALS WORK ACTIVITIES FOR THE PAST 90 DAYS. THE LICENSEE INFORMED THE RESIDENT INSPECTOR.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 2
DOCKET: 05000220 05000410
RX TYPE: BWR BWR
VENDORS: GE-2 GE-5 EN NUMBER: 26738 EVENT DATE: 02-04-94 EVENT TIME: 08:45 NOTIFY DATE: 02-04-94 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 13:11

OPS OFFICER: TIM MCGINTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N CODE CRIT PWR
N Y 100 POWER OPERATION 100 POWER OPERATION
N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISOR WAS OBSERVED THIS MORNING TO HAVE ALCOHOL ON HIS BREATH. THE PERSON WAS THEN TESTED FOR CAUSE AND FOUND TO BE POSITIVE FOR ALCOHOL. THE INDIVIDUALS UNESCORTED ACCESS HAS BEEN REMOVED, AND HAS BEEN ENTERED INTO THE EMPLOYEE ASSISTANCE PROGRAM. THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

DOCKET: 05000445 05000446
RX TYPE: PWR PWR
VENDORS: W-4 LD EN NUMBER: 26750 EVENT DATE: 02-08-94 EVENT TIME: 11:00

NOTIFY DATE: 02-08-94 VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 14:17

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 58 POWER OPERATION 58 POWER OPERATION

A NON-LICENSED CONTRACT SUPERVISOR TESTED POSITIVE FOR AMPHETAMINES DURING A RANDOM DRUG TEST.

THE RANDOM TEST WAS ADMINISTERED ON 2/3/94 AND CONFIRMED POSITIVE ON 2/8/94 AT 11:00 CST. THE INDIVIDUALS PROTECTED AREA ACCESS HAS BEEN REVOKED. THE LI ENSEE WILL INFORM THE RESIDENT INSPECTOR. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: DUKE POWER CO. EN NUMBER: 26792 SITE: MCGUIRE 1 2 DOCKET: 05000369 05000370 EVENT DATE: 02-14-94 RX TYPE: PWR PWR VENDORS: W-4-LP W-4-LP EVENT TIME: 13:35 NOTIFY DATE: 02-15-94 EMERGENCY CLASS: N/A REGION: 2 STATE: NC TIME: 13:05 OPS OFFICER: GREG SCARFO FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN Y 100 POWER OPERATION 100 POWER OPERATION 2 N

A NON-LICENSED CONTRACT SUPERVISOR TESTED POSITIVELY DURING A RANDOM DRUG TEST. HIS ACCESS HAS BEEN DENIED AND HIS BADGE WAS TERMINATED. A WORK REVIEW HAS BEEN COMPLETED AND NO SAFETY EQUIPMENT WAS AFFICTED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: SOUTH CAROLINA ELECTRIC & GAS CO. SITE: SUMMER 1 EN NUMBER: 26840 DOCKET: 05000395 EVENT DATE: 02-23-94 RX TYPE: PWR EVENT TIME: 16:00 VENDORS: W-3-LP NOTIFY DATE: 02-24-94 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 13:28 OPS OFFICER: GREG SCARFO FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR 1 N Y 65 POWER OPERATION 65 POWER OPERATION

A LICENSED REACTOR OPERATOR (LRO) TESTED POSITIVELY DURING A RANDOM DRUG TEST.

AN LRO, REPORTING FOR TRAINING AT AN TISITE FACILITY, TESTED POSITIVELY FOR ALCOHOL DURING A CONFIRMATORY DRUG TEST. THIS

TEST WAS THE RESULT OF A POSITIVE RANDOM DRUG TEST. AT THE TIME, THE LRO DID NOT HAVE ANY RESPONSIBILITIES OR DUTIES IN THE PROTECTED AREA OF THE PLANT. THE LRO WAS SUSPENDED FOR 24 HOURS AND ACCESS TO THE PLANT REVOKED. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

ARKANSAS NUCLEAR 1 2 26876 03-03-94 PCW LICENSEE: ENTERGY OPERATIONS INC. EN NUMBER: 26876 SITE: ARKANSAS NUCLEAR 1 2 EVENT DATE: 03-03-94 DOCKET: 05000313 05000368 EVENT TIME: 09:24 RX TYPE: PWR PWR NOTIFY DATE: 03-03-94 VENDORS: B&W-L-LP CE EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 16:27 OPS OFFICER: GREG SCARFO FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR N Y 100 POWER OPERATION 100 POWER OPERATION 95 POWER OPERATION 95 POWER OPERATION

A CONTRACT SUPERVISOR TESTED POSITIVELY FOR ALCOHOL DURING A RANDOM DRUG TEST.

A CONTRACT SUPERVISOR TESTED POSITIVELY FOR ALCOHOL DURING A RANDOM DRUG TEST. THE BLOOD-ALCOHOL LEVEL WAS MEASURED AT 0.04. A CONFIRMATORY URINALYSIS YIELDED NEGATIVE RESULTS. THE CONTRACTOR IS A NON-LICENSED EMPLOYEE WHO WORKS IN THE TOOL SHOP. THE CONTRACTOR EXERCISES HIS SUPERVISORY RESPONSIBILITIES IN THE TOOL SHOP ONLY DURING OUTAGES. THE LICENSEE WILL NOT PERFORM A WORK REVIEW ON THE BASIS OF THE CONTRACTOR'S RESPONSIBILITIES AND LIMITED SUPERVISORY ROLE. THE CONTRACTOR'S UNESCORTED ACCESS HAS BEEN SUSPENDED PENDING THE RECEIPT OF A CONFIRMATORY BLOOD-ALCOHOL TEST. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

* * * UPDATE 03/04/94 1709EST FROM: SCHEIDE BY: SCARFO * * * THE FOLLOWING IS THE TEXT OF A FACSIMILE SUBMITTED BY THE LICENSEE:

"AT 0924CST ON 03/03/94, AN ENTERGY OPERATIONS SUPERVISOR TRAINED INDIVIDUAL TESTED AT 0.04% ALCOHOL VIA A BREATHALYZER DURING A RANDOM DRUG SCREENING. THE INITIAL TEST INDICATED 0.035%; HOWEVER, TWO SUBSEQUENT TESTS INDICATED 0.04%. A BLOOD ALCOHOL SAMPLE WAS COLLECTED AT 0950 AND SENT OFFSITE FOR ANALYSIS. A DRUG SCREEN URINE SAMPLE WAS COLLECTED AT 1000. THE RESULTS OF THAT TEST WERE NEGATIVE. THE SUBJECT INDIVIDUAL WORKS IN THE ANO TOOL ROOM. HIS ONLY JOB RESPONSIBILITIES ARE LIMITED TO ISSUING AND COLLECTING TOOLS. HE PERFORMS SUPERVISOR DUTIES DURING OUTAGES. DUE TO THE NATURE OF THE INDIVIDUAL'S DUTIES, ANO DOES NOT BELIEVE IT IS NECESSARY TO REVIEW HIS PAST WORK PERFORMANCE. THE INDIVIDUAL'S UNESCORTED ACCESS HAS BEEN TERMINATED PENDING RECEIPT OF THE RESULTS OF THE BLOOD ALCOHOL TEST. IF THE BLOOD ALCOHOL TEST RESULT IS POSITIVE, THE INDIVIDUAL'S ACCESS WILL

REMAIN TERMINATED FOR 14 DAYS AND HE WILL BE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM."
END OF TEXT.

THE LICENSEE SUBMITTED THIS FACSIMILE AS A CLARIFICATION OF THE ORIGINAL REPORT. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR. R4DO (HARRELL) NOTIFIED.

UPDATE ON 3/8/94 @ 13:44 BY SCHEIDE TO GOULD THE LICENSEE IS RETRACTING THIS EVENT SINCE THE BLOOD ALCOHOL TEST WAS BELOW THE THRESHOLD OF 0.04 BLOOD ALCOHOL ANALYSIS FOR BEING REPORTABLE. THE MEASURED BLOOD ALCOHOL LEVEL WAS 0.038. SINCE BLOOD ALCOHOL LEVEL TAKES PRECEDENCE OVER THE BREATHALYZER TEST, THIS EVENT WAS DETERMINED NOT TO BE REPORTABLE. THE INDIVIDUAL WAS RETURNED TO DUTY. THE RI WILL BE INFORMED. REG 4 WESTERMAL NOTIFIED.

LICENSEE: CLEVELAND ELECTRIC ILLUMINATING CO.

SITE: PERRY 1 EN NUMBER: 26914 DOCKET: 05000440 EVENT DATE: 03-10-94 EVENT TIME: 00:36 RX TYPE: BWR NOTIFY DATE: 03-10-94 VENDORS: GE-6 EMERGENCY CLASS: N/A REGION: 3 STATE: OH TIME: 14:12 OPS OFFICER: GREG SCARFO FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N O REFUELING O REFUELING

A CONTRACT SUPERVISOR TESTED POSITIVELY DURING A FOR-CAUSE DRUG TEST.

A CONTRACT SUPERVISOR TESTED POSITIVELY DURING A FOR-CAUSE DRUG TEST. THE REGISTERED BLOOD-ALCOHOL LEVEL WAS 0.014. THE TEST WAS CONDUCTED APPROXIMATELY SIX HOURS INTO THE SUPERVISOR'S SHIFT. AN ANALYSIS INDICATED THAT HIS BLOOD-ALCOHOL LEVEL AT THE TIME HE REPORTED TO WORK WAS ABOUT 0.04. ACCESS TO THE PROTECTED AREA WAS REVOKED AND HE WAS SENT HOME. A WORK REVIEW IS UNDERWAY. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: BROWNS FERRY 1 2 3

DOCKET: 05000259 05000260 05000296

EVENT DATE: 03-11-94

RX TYPE: BWR BWR BWR

VENDORS: GE-4 GE-4 GE-4

EMERGENCY CLASS: N/A REGION: 2 STATE: AL

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

CODE CRIT PWR

1 N N 0 REFUELING

2 N Y 100 POWER OPERATION 100 POWER OPERATION

APPROXIMATELY 2 OUNCES OF A SUSPECT WHITE POWDER SUBSTANCE WAS FOUND IN THE PROTECTED AREA.

A JANITOR WHO WAS SWEEPING IN A PASSAGEWAY AREA ADJACENT TO THE EAST ACCESS BUILDING DISCOVERED THE SUBSTANCE UNDERNEATH A FREEZER USED FOR STORAGE OF ICE. SITE SECURITY TOOK CUSTODY OF THE SUBSTANCE AND THE SUBSTANCE HAS BEEN SENT TO A FORENSIC LABORATORY FOR ANALYSIS. THE LICENSEE ESTIMATES RESULTS OF THE ANALYSIS WILL NOT BE AVAILABLE FOR A WEEK TO 10 DAYS.

THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 3 EN NUMBER: 27027 DOCKET: 05000423 EVENT DATE: 03-31-94 RX TYPE: PWR VENDORS: W-4-LP EVENT TIME: 21:20 NOTIFY DATE: 03-31-94 EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 21:36

OPS OFFICER: RUDY KARSCH UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N N O COLD SHUTDOWN O COLD SHUTDOWN

RANDOM SCREENING IDENTIFIED AN INDIVIDUAL WHO TESTED POSITIVE FOR

THE INDIVIDUAL WAS NOT LICENSED. SEE HOO LOG FOR FURTHER DETAILS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: TEXAS UTILITIES ELECTRIC CO.

SITE: COMANCHE PEAK 1 2
DOCKET. 05000445 05000446
RX TYPE: PWR PWR
VENDORS: W-4-LP W-4-LP EN NUMBER: 27042 EVENT DATE: 04-04-94 EVENT TIME: 14:23 NOTIFY DATE: 04-05-94

EMERGENCY CLASS: N/A REGION: 4 STATE: TX TIME: 11:43

OPS OFFICER: STEVE SANDIN OPS OFFICER: STEVE SANDIN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 73 POWER OPERATION 73 POWER OPERATION

CONTRACT SECURITY GUARD CONFIRMED POSITIVE FOR RANDOM DRUG TEST GIVEN ON 3/22/94. COMPENSATORY MEASURES TAKEN. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: ARIZONA PUBLIC SERVICE CO.

SITE: PALO VERDE 3 EN NUMBER: 27095 DOCKET: 05000530 EVENT DATE: 04-13-94 RX TYPE: PWR EVENT TIME: 19:39

VENDORS: CE80 NOTIFY DATE: 04-14-94 EMERGENCY CLASS: N/A REGION: 4 STATE: AZ TIME: 13:53 OPS OFFICER: CHAUNCEY GOULD FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR CODE CRIT PWR N O REFUELING O REFUELING N

THE LICENSEE REPORTED THAT A REACTOR OPERATOR WAS TESTED POSITIVE FOR ALCOHOL.

THIS OCCURRED FOLLOWING AN OBSERVED BEHAVIOR INDICATING POSSIBLE SUBSTANCE ABUSE AND SUBSEQUENT TEST FOR CAUSE. A POSITIVE AND CONFIRMATORY TEST FOR ALCOHOL INDICATED THAT THE OPERATOR HAD A BLOOD ALCOHOL LEVEL OF 0.042% BAC (THE LICENSEES CUT OFF LEVEL IS 0.04%). THE INDIVIDUAL DECLINED THE BLOOD CONFIRMATORY TEST AND WAS ESCORTED OFF SITE. THE OPERATOR STATED THAT HE DID NOT VIOLATE THEIR 5 HR ABSTENTION POLICY. THE OPERATOR HAS BEEN SUSPENDED W/O PAY FOR 40 CONSECUTIVE STRAIGHT TIME HOURS AND WAS ALSO SUSPENDED FROM UNESCORTED ACCESS WITH THE KEY CARD BEING EXPIRED. THE OPERATOR WAS IN THE PROTECTED AREA AT THE TIME THE CONDITION WAS DETERMINED, BUT THAT OCCURRED DURING SHIFT TURNOVER AND NO LICENSED DUTIES WHERE PERFORMED. THE SUSPENSION IS PENDING THE OUTCOME OF A SUBSTANCE ABUSE EVALUATION AND/OR REHABILITATION. THE OPERATOR WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. THE RI WAS INFORMED.

LICENSEE: ENTERGY OPERATIONS INC.

SITE: ARKANSAS NUCLEAR 1 2 EN NUMBER: 27123 DOCKET: 05000313 05000368 EVENT DATE: 04-19-94 EVENT TIME: 10:30 RX TYPE: PWR PWR NOTIFY DATE: 04-19-94 VENDORS: B&W-L-LF CE

EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 17:25

OPS OFFICER: CHAUNCEY GOULD 10 CFR SECTION: HFIT 26.73

FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR Y 100 POWER OPERATION 100 POWER OPERATION N

N 0 HOT SHUTDOWN 0 HOT SHUTDOWN

THE LICENSEE REPORTED THAT ONE OF THEIR EMPLOYEES TESTED POSITIVE DURING A RANDOM DRUG SCREEN.

THE EMPLOYEE TESTED POSITIVE FOR ALCOHOL ON TWO CONSECUTIVE TESTS WITH A BREATHALIZER READING OF 0.058% (10:38 CT) AND 0.050% (10:40 CT). THE LIMIT IS 0.04%. THE INDIVIDUAL IS QUALIFIED TO PERFORM SUPPERVISORY DUTIES, BUT HAS NOT PERFORMED ANY SINCE 10/93. THE INDIVIDUAL IS CURRENTLY AN INSTRUCTOR AND THE LICENSEE IS PERFORMING A QUALITY REVIEW OF THE EMPOLYEE'S WORK. THE EMPLOYEE'S ACCESS AUTHORIZATION HAS BEEN TERMINATED AND THE INDIVIDUAL WILL BE REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

THE RI WILL BE INFORMED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2 DOCKET: 05000254 05000265 BX TYPE: BWR BWR EN NUMBER: 27154 EVENT DATE: 04-24-94 EVENT TIME: 02:01 RX TYPE: BWR BWR NOTIFY DATE: 04-24-94 VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 19:14

OP3 OFFICER: GREG SCARFO

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR
N 0 REFUELING 0 REFUELING
N Y 100 POWER OPERATION 100 FOWER OPERATION

2

A SENIOR-LEVEL MANAGER FAILED A RANDOM DRUG TEST FOR ALCOHOL.

AFTER BEING CALLED IN TO THE PLANT, A SENIOR-LEVEL MANAGER FAILED A RANDOM DRUG TEST FOR ALCOHOL. THE MANAGER HAD BEEN CALLED IN TO ATTEND TO A TRANSIENT (LOSS OF COOLING TO THE MAIN TRANSFORMER). A BREATHALYZER TEST YIELDED A READING OF 0.075. AT THAT TIME, HE WAS ESCORTED FROM THE PROTECTED AREA AND HIS ACCESS WAS REVOKED. HE HAD BEEN ON SITE FOR ABOUT TWO HOURS TO OBSERVE PLANT RECOVERY OPERATIONS IN THE CONTROL ROOM BEFORE BEING TESTED AND HE DID NOT AFFECT THE STATUS OF ANY SAFETY EQUIPMENT. THE MANAGER DID NOT ISSUE ANY ORDERS WHILE IN THE CONTROL ROOM. A BLOOD SAMPLE WAS TAKEN TO PERFORM A CONFIRMATORY BLOOD-ALCOHOL TEST. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: CONNECTICUT YANKEE ATOMIC POWER CO.

SITE: HADDAM NECK 1 EN NUMBER: 27237 DOCKET: 05000213 EVENT DATE: 05-11-94 RX TYPE: PWR EVENT TIME: 15:30 VENDORS: W-4-LP NOTIFY DATE: 05-12-94

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 09:43

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

CONTRACTOR TESTED POSITIVE FOR A CONTROLLED SUBSTANCE.

THE LICENSEE REPORTED THAT A CONTRACTOR SUPERVISOR OF INDIVIDUALS WITH UNESCORTED ACCESS TESTED POSITIVE FOR USE OF A CONTROLLED SUBSTANCE DURING PRE-ACCESS TESTING. THE INDIVIDUALS ACCESS HAS BEEN REVOKED (HE HAD BEEN IN THE PROTECTED AREA, WITH A VISITORS BADGE AND ESCORTED). THE INDIVIDUALS HE SUPERVISED HAD ALREADY CLEARED THE SCREENING AND HAD BEEN CLEARED FOR UNESCORTED ACCESS. THE LICENSEE IS PERFORMING A REVIEW OF THE ACTIVITIES IN THE AREAS THAT THE PERSON HAD ESCORTED ACCESS TO. THE LICENSEE INFORMED THE STATE AND LOCAL AUTHORITIES, AND THE RESIDENT

INSPECTOR.

LICENSEE: CONSOLIDATED EDISON CO. OF N.Y./NEW

SITE: INDIAN POINT 3 EN NUMBER: 27238 DOCKET: 05000286 EVENT DATE: 05-12-94 RX TYPE: PWR EVENT TIME: 09:00 VENDORS: W-4-LP NOTIFY DATE: 05-12-94

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 12:20

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR PWR

3 N N O COLD SHUTDOWN O COLD SHUTDOWN

A RANDOM DRUG TEST OF A NON-LICENSED CONTRACT SUPERVISOR WAS CONFIRMED POSITIVE FOR COCAINE ON 5/12/94 AT 09:00. THE INDIVIDUAL'S UNESCORTED ACCESS HAS BEEN REVOKED. THE LICENSEE PERFORMED A WORK REVIEW OF THE INDIVIDUAL AND HAS DETERMINED THAT THERE WAS NO IMPACT ON PLANT OPERATIONS. THE TEST WAS ORIGINALLY ADMINISTERED ON 5/4/94.

SEE HOO LOG FOR ADDITIONAL DETAILS. THE LICENSEE HAS INFORMED THE RESIDENT INSPECTOR.

LICENSEE: LONG ISLAND LIGHTING CO

EN NUMBER: 27247 SITE: SHOREHAM 1 EVENT DATE: 05-13-94 DOCKET: 05000322 EVENT TIME: 05:00 RX TYPE: BWR NOTIFY DATE: 05-13-94 VENDORS: GE-4 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 14:39

OPS OFFICER: JOSEPH SEBROSKY

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

PWR

CODE CRIT PWR
1 N 0 DECOMMISSIONED 0 DECOMMISSIONED

A NON-LICENSED CONTRACT SUPERVISOR TESTED POSITIVE FOR ALCOHOL. THE EMPLOYEE WAS TESTED FOR CAUSE. ACCESS TO THE SITE HAS BEEN TERMINATED. SEE HOO LOG FOR DETAILS.

THE LICENSEE HAS INFORMED THE LOCAL NRC INSPECTOR (MIMITZ) OF THE EVENT.

LICENSEE: GEORGIA POWER CO.

SITE: HATCH 1 2 EN NUMBER: 27302 DOCKET: 05000321 05000366

RX TYPE: BWR BWR

VENDORS: GE-4 GE-4 EVENT DATE: 05-26-94 EVENT TIME: 10:20 NOTIFY DATE: 05-26-94 VENDORS: GE-4 GE-4 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 11:52

OPS OFFICER: STEVE SANDIN

OPS OFFICER: STEVE SANDIN

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

	CODE	CRIT	PWR			PWR		
1		Y	100	POWER	OPERATION	100		OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

A NON-LICENSED SUPERVISOR WAS CONFIRMED POSITIVE FOR A RANDOM DRUG TEST (ALCOHOL). THE LICENSEE HAS SUSPENDED UNESCORTED ACCESS AND REFERRED HIM TO THE EMPLOYEE ASSISTANCE PROGRAM. A WORK REVIEW WILL BE PERFORMED. SEE HOO LOG FOR DETAILS. THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

LICENSEE: ENTERGY OPERATIONS INC. EN NUMBER: 27327 SITE: ARKANSAS NUCLEAR 1 EVENT DATE: 06-01-94 DOCKET: 05000313 EVENT TIME: 08:45 RX TYPE: PWR NOTIFY DATE: 06-01-94 VENDORS: B&W-L-LP EMERGENCY CLASS: N/A REGION: 4 STATE: AR TIME: 14:33 OPS OFFICER: CHAUNCEY GOULD FITNESS FOR DUTY 10 CFR SECTION: HFIT 26.73 UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N Y 100 POWER OPERATION 100 POWER OPERATION

THE LICENSEE REPORTED THAT ONE OF THEIR EMPLOYEES WHO IS SUPERVISOR QUALIFIED TESTED POSITIVE IN A RANDOM DRUG TEST.

ON 5/27/94 A LICENSEE EMPLOYEE WHO IS QUALIFIED TO PERFORM SUPERVISORY DUTIES TESTED POSITIVE FOR MARIJUANA DURING A RANDOM DRUG SCREEN. THE INDIVIDUAL IS NOT A FULL TIME SUPERVISOR AND HAS LAST PERFORMED SUPERVISORY DUTIES FROM 3/21/94 - 3/23/94. THE INDIVIDUAL PROVIDED A URINE SAMPLE FOR TESTING 5/27/94 @ 10:41CT WHICH WAS SENT TO THE SITE LAB AND SCREENED POSITIVE FOR MARIJUANA. SOME OF THAT SAMPLE WAS ALSO SENT TO AN OFF SITE LAB AND THE RESULTS RECEIVED 6/1/94 CONFIRMED THE POSITIVE READING. PLANT ACCESS FOR THE INDIVIDUAL HAS BEEN TERMINATED UNTIL 6/15/94. IN ADDITION, THE EMPLOYEE HAS BEEN REFERRED TO THE EMPLOYEES ASSISTANCE PROGRAM. A QUALITY REVIEW OF THE INDIVIDUAL'S WORK HAS BEEN CONDUCTED. THE RI WILL BE INFORMED.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA EN NUMBER: 27392 SITE: SEABROOK 1 EVENT DATE: 06-14-94 DOCKET: 05000443 EVENT TIME: 09:03 RX TYPE: PWR NOTIFY DATE: 06-14-94 VENDORS: W-4-LP EMERGENCY CLASS: N/A REGION: 1 STATE: NH TIME: 12:31 OPS OFFICER: THOMAS ANDREWS 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR N O REFUELING O REFUELING N

LICENSED OPERATOR WAS DETERMINED TO BE UNDER THE INFLUENCE OF ALCOHOL DURING A RANDOM DRUG TEST. THE EMPLOYEE'S ACCESS TO THE

PLANT HAS BEEN PULLED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED.

LICENSEE: GEORGIA POWER CO.

EN NUMBER: 27407 SITE: HATCH 1 2 DOCKET: 05000321 05000366 EVENT DATE: 06-16-94 RX TYPE: BWR BWR VENDORS: GE-4 GE-4 EVENT TIME: 14:13 NOTIFY DATE: 06-16-94 EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 16:53 OPS OFFICER: WILLIAM HUFFMAN OPS OFFICER: WILLIAM HOFFMAN

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

LICENSED OPERATOR VIOLATED FITNESS FOR DUTY REQUIREMENTS.

A LICENSED REACTOR OPERATOR (NON-SUPERVISORY) ADMITTED TO VIOLATING HFIT REQUIREMENTS. THE EMPLOYEE SELF-ADMITTED DRUG AND ALCOHOL ABUSE DURING A PSYCHOLOGICAL EVALUATION. A DRUG TEST WAS ADMINISTERED BUT RESULTS WERE NEGATIVE. THE INDIVIDUAL'S UNESCORTED ACCESS TO THE SITE HAS BEEN SUSPENDED. A REVIEW OF THE INDIVIDUAL'S SAFETY RELATED WORK ACTIVITIES IS IN PROGRESS. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

LICENSEE: PHILADELPHIA ELECTRIC CO.

EN NUMBER: 27442 SITE: LIMERICK 1 2 DOCKET: 05000352 05000353 RX TYPF: BWR BWR VENDORS: GE-4 GE-4 EVENT DATE: 06-23-94 EVENT TIME: 14:50 NOTIFY DATE: 06-23-94 EMERGENCY CLASS: N/A REGION: 1 STATE: PA TIME: 17:22

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

A LICENSED PLANT EMPLOYEE TESTED POSITIVE FOR ILLEGAL RUGS DURING A RANDOM DRUG TEST. THE EMPLOYEE'S UNESCORTED ACCESS TO THE PLANT HAS BEEN REVOKED. SEE HOO LOG FOR DETAILS.

LICENSEE: GEORGIA POWER CO.

SITE: HATCH 1 2 EN NUMBER: 27456 DOCKET: 05000321 05000366 RX TYPE: BWR BWR EVENT DATE: 06-27-94 RX TYPE: BWR BWR VENDORS: GE-4 GE-4 EVENT TIME: 19:00 VENDORS: GE-4 GE-4
EMERGENCY CLASS: N/A REGION: 2 STATE: GA TIME: 20:04 NOTIFY DATE: 06-27-94

OPS OFFICER: CHAUNCEY GOULD

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT	SCRAM			INITI	AL MODE	CURR	CURRI	ENT MODE
1	N	Y	100	POWER	OPERATION	100	POWER	OPERATION
2	N	Y	100	POWER	OPERATION	100	POWER	OPERATION

THE LICENSEE REPORTED A CONFIRMED POSITIVE DRUG TEST FOR A LICENSED REACTOR OPERATOR.

A LICENSED REACTOR OPERATOR HAD A CONFIRMED POSITIVE TEST FOR COCAINE AND WAS PLACED ON ADMINISTRATIVE LEAVE WITH HIS PLANT ACCESS BEING LIFTED. HIS OPERATORS LICENSE WAS WITHDRAWN AND HE HAS BEEN REFERRED TO THE EMPLOYEES ASSISTANCE PROGRAM. HIS MOST RECENT WORK HISTORY WILL ALSO BE REVIEWED, BUT FOR THE LAST 30 DAYS HE HAS BEEN ON ADMINISTRATIVE LEAVE. THE RI WILL BE NOTIFIED.

LICENSEE: NORTH ATLANTIC ENERGY SERVICE COMPA

SITE: SEABROOK 1 EN NUMBER: 27470

DOCKET: 05000443 EVENT DATE: 06-30-94

RX TYPE: PWR EVENT TIME: 07:35

VENDORS: W-4-LP NOTIFY DATE: 06-30-94

EMERGENCY CLASS: N/A REGION: 1 STATE. NH TIME: 15:42

OPS OFFICER: DOUG WEAVER

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 REFUELING 0 REFUELING

A CONTRACTOR EMPLOYEE INFORMED SUPERVISION THAT HE HAD INADVERTENTLY TRANSPORTED A SMALL (187ml) BOTTLE OF WINE INTO THE PROTECTED AREA. THE BOTTLE WAS SEALED. THE EMPLOYEE WAS TESTED FOR ALCOHOL USE AND THE RESULTS WERE NEGATIVE. THE EMPLOYEE WAS SUSPENDED AND HIS BADGE PULLED PENDING FURTHER INVESTIGATION.

LICENSEE: NIAGARA MOHAWK POWER CORP.

SITE: NINE MILE POINT 1 EN NUMBER: 27628

DOCKET: 05000220 EVENT DATE: 08-03-94

RX TYPE: BWR EVENT TIME: 15:30

VENDORS: GE-2 NOTIFY DATE: 08-04-94

EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 15:30

OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR SUPERVISOR WHO HAD NEVER BEEN ON SITE FAILED A PRE-ACCESS DRUG TEST. LICENSEE DENIED THE CONTRACTOR ACCESS TO THE SITE.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE: DUKE POWER CO.

SITE: CATAWBA 1 2 EN NUMBER: 27710 DOCKET: 05000413 05000414 EVENT DATE: 08-25-94 RX TYPE: PWR PWR EVENT TIME: 14:16 VENDORS: W-4-LP W-4-LP NOTIFY DATE: 08-25-94 EMERGENCY CLASS: N/A REGION: 2 STATE: SC TIME: 16:58

OPS OFFICER: THOMAS ANDREWS

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

N Y 100 POWER OPERATION 100 POWER OPERATION N Y 100 POWER OPERATION 100 POWER OPERATION

A CONTRACTOR EMPLOYEE PERFORMING SUPERVISORY RESPONSIBILITIES AS IDENTIFIED IN 10 CFR 26.73 TESTED POSITIVE FOR MARIJUANA DURING A RANDOM TEST. THIS WAS A CONFIRMED POSITIVE TEST RESULT.

THE EMPLOYEE HAS NOT PERFORMED DUTIES IN THE PROTECTED AREA SINCE THE INITIAL TEST ON AUGUST 22. THE EMPLOYEE'S ACCESS HAS BEEN TERMINATED AT THE CATAWBA STATION AND THE EMPLOYEE WILL BE DENIED ACCESS AT ALL DUKE POWER FACILITIES.

THE NRC RESIDENT INSPECTOR WILL BE NOTIFIED.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: DRESDEN 2 3 EN NUMBER: 27792 DOCKET: 05000237 05000249
RX TYPE: BWR BWR
VENDORS: GE-3 GE-3 EVENT DATE: 09-16-94 EVENT TIME: 14:10 VENDORS: GE-3 GE-3 NOTIFY DATE: 09-16-94 EMERGENCY CLASS: N/A REGION: 3 STATE: IL TIME: 16:56 OPS OFFICER: DICK JOLLIFFE

10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY
UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE CODE CRIT PWR PWR

2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN 3 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

A LICENSEE MAINTENANCE SUPERVISOR TESTED POSITIVE FOR THE PRESENCE OF DRUGS. THE EMPLOYEE'S ACCESS AUTHORIZATION TO THE PLANT WAS WITHDRAWN AND THE EMPLOYEE WAS REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM.

LICENSEE IS INVESTIGATING THE EMPLOYEE'S RECENT PAST WORK PERFORMANCE.

LICENSEE INFORMED THE NRC RESIDENT INSPECTOR.

LICENSEE NOTIFIED R3 JIM BELANGER.

SEE HOO LOG FOR DETAILS.

LICENSEE: CONSUMERS POWER CO.

SITE: PALISADES 1 EN NUMBER: 27896 DOCKET: 05000255 EVENT DATE: 10-13-94 RX TYPE: PWR EVENT TIME: 09:25 VENDORS: CE NOTIFY DATE: 10-13-94 EMERGENCY CLASS: N/A REGION: 3 STATE: MI TIME: 10:16 OPS OFFICER: DOUG WEAVER 10 CFR SECTION: HFIT 26.73 FITNESS FOR DUTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE PWR CODE CRIT PWR 1 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON LICENSED EMPLOYEE WAS DETERMINED TO BE UNDER THE INFLUENCE ON AN ILLEGAL DRUG DURING FOLLOWUP TESTING. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS.

LICENSEE: TENNESSEE VALLEY AUTHORITY EN NUMBER:27917 SITE: WATTS BAR 1 2 DOCKET: 05000390 05000391 EVENT DATE: 10-18-94
RX TYPE: PWR PWR EVENT TIME: 00.00
VENDORS: W-4-LP W-4-LP NOTIFY DATE: 1J-18-94 EMERGENCY CLASS: N/A REGION: 2 STATE: TN TIME: 14:31 OPS OFFICER: BOB STRANSKY UNIT SCRAM RX INIT INITIAL MODE CUER CURRENT MODE
CODE CRIT PWR
N N 0 1 N N O O O N O 0

A SUPERVISOR WAS FOUND TO BE UNDER THE INFLUENCE OF ALCOHOL DURING A RANDOM TEST. THE EMPLOYEE HAS BEEN REMOVED FROM THE SITE, AND HAS BEEN REFERRED TO THE EMPLOYEE ASSISTANCE PROGRAM. SEE HOO LOG FOR ADDITIONAL DETAILS. THE RI WILL BE INFORMED.

LICENSEE: ROCHESTER GAS & ELECTRIC CORP.

SITE: GINNA 1 EN NUMBER: 28019 DOCKET: 05000244 EVENT DATE: 11-11-94 EVENT TIME: 10:40 RX TYPE: PWR VENDORS: W-2-LP NOTIFY DATE: 11-11-94 EMERGENCY CLASS: N/A REGION: 1 STATE: NY TIME: 12:16 OPS OFFICER: TIM McGINTY UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE
CODE CRIT PWR

N Y 98 POWER OPERAT 98 POWER OPERATION

A NON-LICENSED CONTRACTOR EMPLOYEE WAS CONFIRMED TO HAVE TESTED POSITIVE FOR COCAINE UNDER THE RANDOM DRUG TESTING PROGRAM. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS.

THE LICENSEE INFORMED THE RESIDENT INSPECTOR.

LICENSEE: COMMONWEALTH EDISON CO.

SITE: QUAD CITIES 1 2

DOCKET: 05000254 05000265

RX TYPE: BWR BWR

VENDORS: GE-3 GE-3

EMERGENCY CLASS: N/A REGICN: 3 STATE: IL

OPS OFFICER: WILLIAM HUFFMAN

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

EN NUMBER: 28078

EVENT DATE: 11-28-94

EVENT TIME: 11:12

NOTIFY DATE: 11 28-94

FITNESS FOR DUTY

CURRENT MODE

CODE CRIT PWR

1 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN
2 N N 0 COLD SHUTDOWN 0 COLD SHUTDOWN

EMPLOYEE TESTED POSITIVE FOR ALCOHOL.

A STAFF EMPLOYEE AT THE SUPERVISORY LEVEL TESTED POSITIVE FOR ALCOHOL DURING A RANDOM DRUG TEST. THIS INDIVIDUAL IS NOT LICENSED AND IS NOT CURRENTLY SUPERVISING ANYONE.

THE INDIVIDUAL'S SITE ACCESS HAS BEEN SUSPENDED.

THE NEED FOR A SAFETY WORK REVIEW IS BEING EVALUATED.

THE NRC RESIDENT INSPECTOR WAS INFORMED.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: WATTS BAR 1 2

DOCKET: 05000390 05000391

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN

OPS OFFICER: JOHN MacKINNON

EN NUMBER: 28147

EVENT DATE: 12-13-94

EVENT TIME: 15:08

NOTIFY DATE: 12-14-94

TIME: 13:10

OPS OFFICER: JOHN MACKINNON

10 CFR SECTION: **HFIT** 26.73 FITNESS FOR DUTY

UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

1 N N 0 UNDER CONSTRUCT 0 UNDER CONSTRUCT 2 N N 0

CONTRACT SUPERVISOR TESTED POSITIVE FOR MARIJUANA

CONTRACT SUPERVISOR (MECHANICAL ENGINEER) TESTED POSITIVE FOR MARIJUANA ON 12/13/94. CONTRACTOR WAS REMOVED FROM TVA PROPERTY AND HIS ACCESS WAS RESTRICTED FOR THREE YEARS. CONTRACT SUPERVISOR HAD JUST BEEN HIRED AND WAS IN THE CHECK IN PHASE AT THE PLANT (TAKING SITE ACCESS TRAINING COURSE, etc). ALSO HE DID NOT HAVE UNESCORTED ACCESS PRIVILEGES.

RESIDENT INSPECTOR WILL BE INFORMED BY THE LICENSEE.

LICENSEE: TENNESSEE VALLEY AUTHORITY

SITE: SEQUOYAH 1 2

DOCKET: 05000327 05000328

RX TYPE: PWR PWR

VENDORS: W-4-LP W-4-LP

EMERGENCY CLASS: N/A REGION: 2 STATE: TN

OPS OFFICER: TIM McGINTY

10 CFR SECTION: HFIT 26.73

UNIT SCRAM RX INIT INITIAL MODE

EN NUMBER: 28156

EVENT DATE: 12-17-94

EVENT TIME: 09:00

NOTIFY DATE: 12-17-94

FITNESS FOR DUTY

CURR CURRENT MODE

CODE CRIT PWR PWR

1 N Y 100 POWER OPERATION 100 POWER OPERATION
2 N Y 100 POWER OPERATION 100 POWER OPERATION

A NON-LICENSED SUPERVISORY EMPLOYEE TESTED POSITIVE DURING A "FOR CAUSE" TEST FOR ALCOHOL. THE EMPLOYEE'S ACCESS TO THE PLANT HAS BEEN TERMINATED. SEE HOO LOG FOR ADDITIONAL DETAILS. LICENSEE WILL INFORM THE RESIDENT INSPECTOR.

POWER REACTOR

EVENT NUMBER: 21121

FACILITY: PALO VERDE REGION: 5 UNIT: [1] [] STATE: AZ RX TYPE: [1] CE, [2] CE, [3] CE						NOTIFICATION DATE: 05/31/91 NOTIFICATION TIME: 22:54 [E EVENT DATE: 05/31/91 EVENT TIME: 18:49 [MS				
	OTIFIED BY:						-	T UPDATE		
								NOTI	FICATIO	ONS
	ENCY CLASS: R SECTION:		INFORMATI	ON ONL	Y		ROB	ERT PATE		RDO
UNIT	SCRAM CODE	RX CRIT	INIT PWR	INIT	RX	MODE		CURR PWR	CURR	RX MODE
	According to the second	Accessor	the same of the same of the same of	-	NAME OF TAXABLE PARTY.		ON	100		OPERATION

EVENT TEXT

FBI ARREST OF A CONTRACT EMPLOYEE AT PLANT SITE.

THE FBI ARRESTED A CONTRACT I&C TECHNICIAN ON A FEDERAL WARRANT FOR CONSPIRACY TO COMMIT FRAUD, BANKRUPTCY, AND TAX EVASION. THE EMPLOYEE WAS ARRESTED AT THE SITE GATE WHEN HE REPORTED TO WORK THIS EVENING AT 18:49MST. THE LICENSEE HAS TERMINATED HIS PLANT ACCESS. THE LICENSEE DOES NOT CONSIDER THIS A MATTER CONCERNING SAFE OPERATION OF THE PLANT, HOWEVER, THERE IS A POTENTIAL FOR MEDIA INTEREST. THE NRC RESIDENT INSPECTOR HAS BEEN INFORMED.

POWER REACTOR

UNIT: [1] [2] []

APRE 50.72(b)(2)(vi) OFFSITE NOTIFICATION

RX TYPE: [1] GE-4, [2] GE-4

HO OPS OFFICER: GREG SCARFO

FACILITY: SUSQUEHANNA

NRC NOTIFIED BY: SMITH

10 CFR SECTION:

EVENT NUMBER: 23057

REGION: 1 NOTIFICATION DATE: 03/20/92 NOTIFICATION TIME: 11:56 [ET] STATE: PA

> EVENT DATE: 03/20/92 EVENT TIME: 08:54 [EST]

LAST UPDATE DATE: 03/20/92

RDO

NOTIFICATIONS

EMERGENCY CLASS: NOT APPLICABLE GLENN MEYER

UNIT	SCRAM C	CODE RX	CRIT	INIT PWR	INIT RX MODE	CURR PWR	CURR RX MODE
1	N		N	0	REFUELING	0	REFUELING
2	N		N	0	COLD SHUTDOWN	0	COLD SHUTDOWN

EVENT TEXT

THE LICENSEE ISSUED A PRESS RELEASE ABOUT THE PLANT'S DRUG & ALCOHOL TESTING PROGRAM IN RESPONSE TO A RECENT ARTICLE IN A LOCAL NEWSPAPER.

THE LICENSEE PROVIDED A FACSIMILE TO THE OPERATIONS CENTER: "PP&L MADE A PRESS RELEASE CONCERNING THE NUCLEAR DEPARTMENT'S DRUG AND ALCOHOL FREE WORK PLACE SCREENING PROGRAM. THE PROGRAM WAS IMPLEMENTED IN 1990 AND CONSISTS OF A TRE-ACCESS DRUG AND ALCOHOL SCREENING ALONG WITH RANDOM TESTING. SINCE 1990, 3300 PRE-ACCESS SCREENING HAVE BEEN PERFORMED RESULTING IN 11 POSITIVE TESTS. UNDER RANDOM TESTING PORTION OF THE PROGRAM MORE THAN 3200 TESTS HAVE BEEN COMPLETED WITH 10 POSITIVE RESULTS." END OF FACSIMILE TEXT.

THE LICENSEE WILL INFORM THE NRC RESIDENT INSPECTOR.

POWER REACTOR

EVENT NUMBER: 25789

FACILITY: COMANCHE PEAK REGION: 4
UNIT: [1] [2] [] STATE: TX

REGION: 4

NOTIFICATION DATE: 07/16/93

RX TYPE: [1] W-4-LP, [2] W-4-LP

NOTIFICATION TIME: 08:48 [ET]

NRC NOTIFIED BY: M SMITH

EVENT DATE: 07/16/93 EVENT TIME: 06:58[CDT] LAST UPDATE DATE: 07/16/93

NOTIFICATIONS

HO OPS OFFICER: JOHN MacKINNON

EMERGENCY CLASS: NOT APPLICABLE

JIM GAGLIARDO

RDO

10 CFR SECTION:

NINF

INFORMATION ONLY

SCRAM CODE RX CRIT INIT PWR INIT RX MODE CURR PWR CURR RX MODE UNIT Y 100 POWER OPERATION 100 POWER OPERATION 1 N Y 90 POWER OPERATION 90 POWER OPERATION 2 N

EVENT TEXT

NEW EMPLOYEE UNINTENTIONALLY ATTEMPTED TO ENTER PROTECTED AREA WITH A WEAPON. IMMEDIATE COMPENSATORY MEASURES WERE TAKEN ON DISCOVERY. LICENSEE DOES NOT CONSIDER THIS A CREDIBLE THREAT. NEW EMPLOYEE ACCESS WAS PULLED AND LICENSEE WILL PERFORM MORE CHECKS ON THIS PERSON BACKGROUND AND THIS EMPLOYEE WILL BE RETRAINED. SEE HOO LOG BOOK FOR FURTHER DETAILS.

RESIDENT INSPECTOR WAS INFORMED BY LICENSEE.

POWER REACTOR

EVENT NUMBER: 27364

FACILITY: SAN ONOFRE UNIT: [] [2] [3] STATE: CA RX TYPE: [1] W-3-LP, [2] CE, [3] CE					A NO	NOTIFICATION DATE: 06/07/94 NOTIFICATION TIME: 17:00 [ET EVENT DATE: 06/06/94 EVENT TIME: 14:00[PD		
	OTIFIED BY: S OFFICER:					ST UPDATE		
	ENCY CLASS:				-	NOTI	FICATIO	ONS
10 CF NLTR	R SECTION:		LICENSEE	24 HR REPORT	GA	LRY SANBORN		RDO
UNIT	SCRAM CODE	RX CRIT	INIT PWR	INIT RX MOI	DE .	CURR PWR	CURR	RX MODE

EVENT TEXT

LICENSEE IS MAKING A 24 HOUR NOTIFICATION UNDER LICENSE CONDITION 2.G.

"THIS IS A NON-EMERGENCY 24 HOUR NOTIFICATION."

"ON JUNE 6, 1994, AT APPROXIMATELY 1400 HOURS DURING THE PERFORMANCE OF A JOINT COMPUTER GROUP SECURITY INVESTIGATION TO DETERMINE ACTIVE OR DEACTIVE SECURITY EQUIPMENT, EDISON DISCOVERED A CABINET WITHIN A VITAL AREA OF UNIT 3 THAT CONTAINED WIRING FOR THE SECURITY COMPUTER SYSTEM. THE CABINET WAS NOT FASTENED CLOSED IN ACCORDANCE WITH THE REQUIREMENTS OF THE PHYSICAL SECURITY PLAN. WHILE THIS CABINET WAS LOCKED CLOSED WITH A FILE PANEL KEY, THE PHYSICAL SECURITY PLAN FOR UNITS 1, 2 AND 3 REQUIRES CABINETS CONTAINING SECURITY RELATED WIRING TERMINATIONS TO BE EITHER:

- 1. ARMED WITH TAMPER SWITCHES,
- 2. WELDED CLOSED, OR
- 3. SECURED WITH "1A" FASTENERS.

THEREFORE, EDISON CONCLUDED THAT THIS CONDITION WAS NOT IN CONFORMANCE WITH THE DESCRIPTION OF THE PHYSICAL SECURITY PLAN. WITHIN 10 MINUTES OF THIS DISCOVERY, EDISON INITIATED A COMPENSATORY 1 HOUR PATROL OF THE AFFECTED CABINET. DISON HAS EVALUATED THIS CONDITION AND HAS DETERMINED THAT UNAUTHORIZED OR UNDETECTED ACCESS TO PLANT PROTECTED OR VITAL AREAS COULD NOT HAVE OCCURRED DUE TO THIS CONDITION. THE SECURITY EQUIPMENT VENDOR (ELECTRONICS SYSTEMS, USA) HAS INDEPENDENTLY AGREED WITH OUR FINDINGS. THEREFORE, THERE WAS NO SAFETY SIGNIFICANCE TO THIS CONDITION. WE ARE IN THE PROCESS OF INITIATING SYSTEM WALKDOWNS TO VERIFY SYSTEM INTEGRITY. UNIT 2 WAS OPERATING AT APPROXIMATELY 98% POWER AND UNIT 3 WAS OPERATING AT APPROXIMATELY 97% POWER WHEN THIS CONDITION WAS IDENTIFIED. IN ACCORDANCE

PAGE # 2 OF EVENT NUMBER: 27364

FACILITY: SAN ONOFRE

WITH THE REQUIREMENTS OF LICENSE CONDITION 2.G OF LICENSE NO. NPF-10 AND NPF-15 FOR SAN ONOFRE UNITS 2 AND 3, RESPECTIVELY, A COPY OF THIS NOTIFICATION WILL BE FAXED TO THE NRC REGIONAL ADMINISTRATOR AT APPROXIMATELY 1600 HOURS JUNE 7, 1994. A WRITTEN FOLLOWUP REPORT WILL BE SUBMITTED WITHIN 14 DAYS."

THE LICENSEE WAS UNABLE TO DETERMINE HOW LONG THIS CONDITION EXISTED OR WHAT THE LONG TERM CORRECTIVE ACTIONS WOULD BE. THE LICENSEE INFORMED THE NRC (WONG, ERNST AND YANDELL).

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

APR 0 5 1994

IA 94-004

Mr. Douglas D. Preston (Address deleted Under 10 CFR 2.790)

Dear Mr. Preston:

SUBJECT: ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES

(EFFECTIVE IMMEDIATELY) (NRC INSPECTION REPORT NO. 50-

331/93020)

The enclosed Order Prohibiting Involvement in NRC-Licensed Activities is being issued as a consequence of your deliberately providing false information on applications you made for access authorization at the Iowa Electric Light and Power Company's (licensee) Duane Arnold Energy Center. On or about June 19, 1990, and on June 23, 1993, you indicated on your access authorization applications that you had not been arrested or convicted of a criminal offense other than minor traffic violations. The licensee subsequently learned that you had been arrested and convicted several times for crimes other than traffic violations and that you were incarcerated for some of those offenses. As a result of your deliberate false statements, you were granted unescorted access to the Duane Arnold facility in 1990 and again in 1993. A licensee investigator interviewed you about the false information at which time you indicated that you had lied on your applications in 1990 and 1993 and that you would lie again about your criminal record. The deliberate false information on your criminal history in your June 23, 1993 application caused you to be personally in violation of 10 CFR 50.5, "Deliberate Misconduct".

While you deliberately made the same false statements on your access authorization application of June 19, 1990, that instance is not being cited in the enclosed Order because it occurred prior to September 16, 1991, the date that 10 CFR 50.5 became effective.

Failure to comply with the provisions of the enclosed Order may result in civil or criminal sanctions.

Questions concerning the Order may be addressed to James Lieberman, Director, Office of Enforcement. Mr. Lieberman can be reached at telephone number (301) 504-2741.

060000

9404070041 94040

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice", a copy of this letter and the enclosure with your home address removed will be placed in the NRC's Public Document Room.

Sincerely,

Sames Lieberman, Director Office of Enforcement

Enclosure:

Order Prohibiting Involvement in NRC-Licensed Activities (Effective Immediately)

cc w/enclosure:

L. Liu, Chairman of the Board and Chief Executive Officer D. Wilson, Plant Superintendent

Nuclear Licensing

K. Young, Manager, Nuclear Licensing

Resident Inspector, RIII

Stephen Brown, Iowa Department

of Commerce

Licensing Project Manager, NRR Berry Construction Company

UNITED STATES NUCLEAR REGULATORY COMMISSION

In the Matter of MR. DOUGLAS D. PRESTON

IA 94-004

ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES (EFFECTIVE IMMEDIATELY)

I

Mr. Douglas D. Preston was employed by the Berry Construction Company at the Iowa Electric Light and Power Company's (IELPC or Licensee) Duane Arnold Energy Center where he was granted unescorted access. IELPC holds Facility License DPR-49, issued by the Nuclear Regulatory Commission (NRC or Commission) pursuant to 10 CFR Part 50 on February 22, 1974. The license authorizes IELPC to operate the Duane Arnold Energy Center located near Cedar Rapids, Iowa, in accordance with the conditions specified therein.

II

Mr. Preston first applied for employment with Berry Construction Company and was subsequently granted unescorted access to the Diane Arnold Energy Center on or about June 19, 1990, based in part on the representations he made on his access authorization applications. One of the representations was that he had not been arrested and convicted for any criminal offense other than minor traffic violations. The Licensee submitted fingerprint cards to the Federal Bureau of Investigations (FBI) and subsequently was

informed that Mr. Preston had a record of arrests, convictions, and imprisonments prior to 1978. However, while waiting for the results of the FBI fingerprint check, Mr. Preston's employment at the Duane Arnold Energy Center was terminated for a lack of work. Mr. Preston's deliberate false statements on his access authorization application on or about June 19, 1990 were essentially the same as his 1993 false statements (addressed below), but are not being cited in this Order as a violation because they were made before the effective date of 10 CFR 50.5.

On June 21, 1993, Mr. Preston again applied for a position at the Duane Arnold Energy Center and was hired on June 21, 1993 by the Berry Construction Company as a laborer with responsibilities involving NRC-licensed activities. On June 23, 1993, Mr. Preston filled cut an access authorization application and again denied having a criminal history. The Licensee granted Mr. Preston temporary unescorted access to the plant on or about July 15, 1993. On or about August 13, 1993, the Licensee received the results of a second FBI fingerprint check which again detailed Mr. Preston's criminal history. Mr. Preston, when questioned by an IELPC investigator on August 13, at first denied having a criminal history and then admitted that he had lied about his criminal history to gain employment in 1990 and again in 1993. He further stated that he would lie again to gain employment in the future. The Licensee then revoked Mr. Preston's unescorted access based on the deliberately false information regarding his criminal history

on his access authorization application.

III

Based on the above, Mr. Preston engaged in deliberate misconduct on or about June 23, 1993, by deliberately falsely stating on the access authorization application that he had no criminal history for crimes other than minor traffic offenses. The Commission's regulations in 10 CFR 50.5, in part, prohibit any employee of a contractor of a licensee from deliberately submitting to the licensee information that the employee knows to be incomplete or inaccurate in some respect material to the NRC. Mr. Preston's actions constitute a violation of 10 CFR 50.5(a). Information concerning criminal history is material to the determination the licensee must make to meet 10 CFR 73.56(b)(2).

IV

The NRC must be able to rely on the Licensee, its contractors, and the licensee and contractor employees to comply with NRC requirements, including the requirement to provide information that is complete and accurate in all material respects. Mr. Preston's actions in deliberately providing false information to the Licensee constitute deliberate violations of Commission regulations and his statement to the Licensee that he would do it again have raised serious doubt as to whether he can be relied upon to comply with

NRC requirements and to provide complete and accurate information to the NRC in the future.

Consequently, I lack the requisite reasonable assurance that nuclear safety activities within NRC jurisdiction can be conducted in compliance with the Commission's requirements and that the health and safety of the public would be protected if Mr. Preston were permitted to be engaged in the performance of licensed activities. Therefore, the public health, safety and interest require that Mr. Preston be prohibited from being involved in the performance of activities licensed by the NRC for a five year period. In addition, Mr. Preston is required to notify the NRC, for an additional five year period, of his acceptance of employment in NRC-licensed activities so that appropriate inspections can be performed. Furthermore, pursuant to 10 CFR 2.202, I find that the significance of the deliberate misconduct described above is such that the public health, safety and interest require that this order be immediately effective.

IV

Accordingly, pursuant to sections 103, 161b, 161i, 182 and 186 of the Atomic Energy Act of 1954, as amended, and the Commission's regulations in 10 CFR 2.202 and 10 CFR 50.5, IT IS HEREBY ORDERED, EFFECTIVE IMMEDIATELY, THAT:

- A. Mr. Douglas D. Preston is prohibited from engaging in activities licensed by the NRC for five years from the date of this Order. For the purposes of this Order, licensed activities include the activities licensed or regulated by: (1) NRC; (2) an Agreement State, limited to the Licensee's conduct of activities within NRC jurisdiction pursuant to 10 CFR 150.20; and (3) an Agreement State where the licensee is involved in the distribution of products that are subject to NRC jurisdiction.
- B. After the five year prohibition has expired as described in paragraph A above, Mr. Preston shall provide notice to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555, for acceptance of any employment in licensed activity for an additional five year period.

The Regional Administrator, Region III, may, in writing, relax or rescind any of the above conditions upon demonstration by Mr. Preston of good cause.

V

In accordance with 10 CFR 2.202, Mr. Preston must, and any other person adversely affected by this Order may, submit an answer to

this Order, and may request a hearing within 30 days of the date of this Order. The answer may consent to this Order. Unless the answer consents to this Order, the answer shall, in writing and under oath or affirmation, specifically admit or deny each allegation or charge made in this Order and shall set forth the matters of fact and law on which Mr. Preston or other person adversely affected relies and the reasons as to why the Order should not have been issued. Any answer or request for a hearing shall be submitted to the Secretary, U. S. Nuclear Regulatory Commission, ATTN: Chief, Docketing and Service Section, Washington, DC 20555. Copies also shall be sent to the Director, Office of Enforcement, U. S. Nuclear Regulatory Commission, Washington, DC 20555, to the Assistant General Counsel for Hearings and Enforcement at the same address, to the Regional Administrator, Region III, U. S. Nuclear Regulatory Commission, 801 Warrenville Road, Lisle, Illinois 60532-4351, and to Mr. Preston, if the answer or hearing request is by a person other than Mr. Preston. person other than Mr. Preston requests a hearing, that person shall set forth with particularity the manner in which his interest is adversely affected by this Order and shall address the criteria set forth in 10 CFR 2.714(d).

If a hearing is requested by Mr. Preston or a person whose interest is adversely affected, the Commission will issue an Order designating the time and place of any hearing. If a hearing is held, the issue to be considered at such hearing shall be whether

this Order should be sustained.

Pursuant to 10 CFR 2.202(c)(2)(i), Mr. Preston, or any person adversely affected by this Order, may in addition to demanding a hearing, at the time that answer is filed or sooner, move the presiding officer to set aside the immediate effectiveness of the Order on the ground that the Order, including the need for immediate effectiveness, is not based on adequate evidence but on mere suspicion, unfounded allegations, or error.

In the absence of any request for a hearing, the provisions specified in Section IV above shall be final 20 days from the date of this Order without further order or proceedings. AN ANSWER OR A REQUEST FOR A HEARING SHALL NOT STAY THE IMMEDIATE EFFECTIVENESS OF THIS ORDER.

FOR THE NUCLEAR REGULATORY COMMISSION

James Lieberman, Director Office of Enforcement

Dated at Rockville, Maryland this that of April 1994

DISTRIBUTION

SECY

CA

JTaylor, EDO

HThompson, DEDS

JMilhoan, DEDR

JLieberman, OE

LChandler, OGC

JGoldberg, OGC

TMurley, NRR

JRoe, NRR

Enforcement Coordinators

RI, RII, RIV, RV

Resident Inspector FIngram, GPA/PA

DWilliams, OIG

BHares, OI

EPawlik, OI:RIII

EJordan, AEOD

JCreed, RIII

DFunk, RIII

Licensing Project Manager, NRR

PRosano, OE

EA File (2)

State of Iowa

RAO:RIII

SLO:RIII

PAO:RIII

IMS:RIII

DCS: x Yes
PDR: x Yes

OEAD Hileberman 444 /94

per April 1,94 som Timo pared with

and flownisms

DOCUMENT: G:\OECASES\DAECREV.DR

DEOR

4/

JM1 lhoan

1/94

20-5

OFFICE OF ENFORCEMENT NOTIFICATION OF SIGNIFICANT ENFORCEMENT ACTION

Licensee: Douglas D. Preston (IA 94-004)

Subject: ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES (EFFECTIVE IMMEDIATELY)

This is to inform the Commission that, in accordance with Commission approval, an Order Prohibiting Involvement in NRC-Licensed Activities (Effective Immediately) will be is used today to Douglas D. Preston. The Order provides that Mr. Preston is prohibited from involvement in licensed activities for five years. For an additional five years he is to provide notice to NRC of involvement in licensed activities to permit NRC inspections. This action is based on Mr. Preston's falsification of information on his application for unescorted access at Iowa Electric Light and Power Company's Duane Arnold Energy Center. When interviewed by licensee investigators, Mr. Preston admitted that he had lied about his criminal history and indicated that he would lie again.

It should be noted that the individual has not been specifically informed of the enforcement action. The schedule of issuance and notification is:

Mailing of Notice Telephone Notification

April 5, 1994 April 5, 1994

The individual has thirty days from the date of the Notice in which to respord.

Contact. D. Rosano, OE, 504-3282 J. Lieberman, OE, 504-2741

Distribution:

OWFN 12:00	OWFN /2	00 MNBB /2 000	PHIL /2 00
Chairman Selin	EDO	oc	IRM .
Comm. Rogers	DEDR	AEOD	
Comm. Remick	DEDS	Op Ctr	NL /2 0 0
Comm. de Planque	OE		RES
SECY	NMSS	Regional Office	MAIL
OCA	NRR	RI 12:00 RIV /2:00	
OSP	OI	RII (2 00 RV /2:00	PDR
GPA	OGC	RIII /2,00	OIG

PRELIMINARY INFORMATION - NOT FOR PUBLIC DISCLOSURE UNTIL VERIFICATION THAT LICENSEE HAS RECEIVED ACTION

A-2

9404140237 940405 PDR 1&E EN-94-035 PDR

1E:37

OFFICE OF ENFORCEMENT NOTIFICATION OF SIGNIFICANT ENFORCEMENT ACTION

Licensee: Iowa Electric Light and Power Company (EA 93-276)

(Duane Arnold)
Docket No. 50-331

Subject: PROPOSED IMPOSITION OF CIVIL PENALTY - \$12,500

This is to inform the Commission that, in accordance with Commission approval, a Notice of Violation and Proposed Imposition of Civil Penalty in the amount of \$12,500 will be issued coday to Iowa Electric Light and Power Company. This action is based on a violation involving the granting of unescorted access to an individual without first evaluating or considering derogatory information received from the FBI as a result of an earlier request for access authorization for the individual. The civil penalty adjustment factors were considered and the civil penalty was mitigated by 25% due to the self-disclosing nature of the event and by 50% due to the licensee's corrective actions.

It should be noted that the licensee has not been specifically informed of the enforcement action. The schedule of issuance and notification is:

Mailing of Notice April 5, 1994
Telephone Notification of Licensee April 5, 1994

The State of Towa will be notified.

The licensee has thirty days from the date of the Notice in which to respond. Following NRC evaluation of the response, the civil penalty may be remitted, mitigated, or imposed by Order.

Contact: D. Rosano, OE, 504-3282 J. Lieberman, OE, 504-2741

Distribution:

OWFN	OWFN	MNBB	PHIL
Chairman Selin	EDO		IMI
Comm. Rogers	DEDR	AEOD	
Comm. Remick	DEDS	op Ctr	NL
Comm. de Planque	OE		RES
SECY	NMSS	Regional Office	MAIL
OCA	NRR	RI RIV	ADM: Doc. Mgt.
OSP	OI	RII RV	PDR
GPA	OGC	RIII	OIG

PRELIMINARY INFORMATION - NOT FOR PUBLIC DISCLOSURE UNTIL VERIFICATION THAT LICENSEE HAS RECEIVED ACTION

A-3

Ace# 9404140242 940405 Liche 78925:038
PDR 18E
EN-94-036 PDR

0/1

IA 94-004

MEMORANDUM FOR: Michael T. Lesar, Acting Chief

Rules Review Section

Regulatory Publication Branch

FROM:

James Lieberman, Director

Office of Enforcement

SUBJECT:

ORDER FROHIBITING INVOLVEMENT IN NRC-LICENSED

ACTIVITIES (EFFECTIVE IMMEDIATELY)

(Mr. Douglas D. Preston)

A signed original of the subject order is enclosed for your transmittal to the Office of the <u>Federal Register</u> for publication. Additional conformed copies (5) of the Order are enclosed for your use.

Original Signed By James Lieberman

James Lieberman, Director Office of Enforcement

Enclosure: As Stated

cc: J. Goldberg, OGC

DISTRIBUTION:
JLieberman, OE
DROSano
Day File
IA File
DCS

OE &	D:01
DRosano	Jijaberman
4/6/94	4/ 1/94

Doc Name: G:\IA94004.dr



NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20956-0001

. JUL 1 2 1994

IA 94-004

Mr. Douglas D. Preston (Address deleted Under 10 CFR 2.790)

Dear Mr. Preston:

SUBJECT: ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES (EFFECTIVE IMMEDIATELY)

This is in reference to the subject Order issued by the Nuclear Regulatory Commission on April 5, 1994. The Order prohibited you from engaging in NRC-licer.sed activities for a period of five years from the date of the Order and required you to notify the NRC of your acceptance of any employment in NRC-licensed activities for an additional five-year period. Further, the Order provided you an opportunity to request a hearing on the Order on or before May 5, 1994. Your opportunity to request a hearing has expired.

The order also required you to submit an answer to the Order. As of this date, we have not received your answer. This is to advice that, in the absence of the response from you on the is: as described in the Order, the NRC assumes that you consent to, and agree to fully comply with, the provisions in Section IV of the Order. Note that the provisions specified in Section IV of the Order are now final and will be enforced by the NRC.

Sincerely,

James Luke

dames Lieberman, Director Office of Enforcement

cc: L. Liu, Chairman of the Board
and Chief Executive Officer
D. Wilson, Plant Superintendent
Nuclear Licensing
K. Young, Manager, Nuclear Licensing
Resident Inspector, RIII
Stephen Brown, Iowa Department
of Commerce
Licensing Project Manager, NRR
Berry Construction Company

9407140016 940712 PDR DRO NE SEN PDR IE14

A-5

Mr. Thomas E. Tipton Vice President and Director Operations, Management, and Support Services Division Nuclear Energy Institute Suite 300 1/76 Eye Street, N.W. Washington, DC 20006-2496

Dear Mr. Tipton:

Robert Whitesel's March 23, 1994, letter forwarded the Nuclear Energy Institute's draft "Access Authorization (AA) Program Issues and Responses." dated March 23, 1994, for our review and comment. It was specifically requested that we review the document to ensure that the guidance does not conflict with the intent of applicable regulations.

Except as noted in our comments, we find that the guidance does not conflict with the intent of 10 CFR Parts 26, 73.56 and 73.57.

Our comments are summarized in Enclosure 1 and there are some annotations on the attached copy of the draft (Enclosure 2). If these are incorporated, the NEI document should not conflict with the applicable regulations. If you have any questions on the enclosed, please let us know. The staff content is N. Ervin. (301) 504-2946.

> Sincerely. Original signed by R. Lee Spessard, Director Div., ion of Technical Support Office of Nuclear Reactor Regulation

Enclosures: 1. Detailed NRC Comments

JLieberman

2. Annotated NEI Draft Guidance

Distribution:

Central Files PDR

RFonner LBush PSGB r/f NErvin Alhadani PMckee . L S CLERICE HADI JCalvo

DOCUMENT NAME: g:Berney\AANE1.DOC

*SEE PREVIOUS CONCURRENCE

"C" a Cupy without attachment/enclusive "E" a Copy with attachment/enclusive "N" x his copy *30 OGC* BC: PSGB: NRRI PSGH: NRB2 = OFFICE PSGB: NRR* JLieberman L JC bon trigham RFonner LI Bush Co NAME HIErvin 09/26/94 10/04/94 10/17/94 10/6 /94 69/26/94 DATE U:DOIS:NER A / D: DRSS: NRR . OFFICE RESpessard MAME Jacalvo 134 10/ 94 10/ 194 194 10/ 10/14/94 DATE

OFFICIAL RECORD COPY

end trail

NRC COMMENTS ON NEI DRAFT "ACCESS AUTHORIZATION (AA) PROGRAM ISSUES AND RESPONSES," DATED MARCH 23, 1994

1. Response A.I. would be enhanced if you address licensee responsibility with respect to review of contractor/vendor/subcontractor programs prior to approval, contractual agreements regarding the use of subcontractors and notification responsibilities when discovered problems affect other licensees or when incomplete in estimations are discovered.

The second paragraph implies that only the program-approving licensee is responsible for additing a contractor/vendor program. Each licensee accepting a contractor/vendor program has an audit responsibility, to include a responsibility to audit any portions of the program that the contractor/vendor subcontracts (See 10 CFR 7s.56(g)(2)). The regulation allows licensees to accept audits completed by other 11 ensees providing the receiving licensee fulfills the requirements of 10 CFR 73.56, which include obtaining the audit reports, corrective actions, etc., reviewing them for adequacy, and taking appropriate actions. Appropriate actions may include additic 11 audit by the receiving licensee if agrificant problems were identified that may affect its program. The response should be revised to properly reflect the regulation.

row may want to expand that portion of the response that addresses a recent citation to include orders recently issued by the NRC to contractors for acts of wrongdoing. Also, the response refers to 10 CFR 50.5 and provides an example of an "ir electron" faciling of a contractor/vendor program; 10 CFR 50.5 applies to deliberate acts.

- 2. Response B.I. states that a criminal history check "should" not be closed out without classifiable fingerpring of the reison for the print being unclassifiable is poor printing technique. The fingerprint rule requires that a "legible" print be submitted (See 10 CFR 73.57(d)(1)). In cases where two sets of completes, legible prints are submitted and returned as unclassifiable, a best effort can be satisfied with a name check from the FEI. The response should be revised to properly reflect the regulation.
- 3. Response B.2. would be enhanced by inclusion of examples of cases in which best effort would be would not be satisfied. For example, an unacceptable best effort would be if, in completing an employment check, a licensee just calls a general number for a listed place of employment, asks anyone who answers to address its specific questions, and then just annotates that the person talked to refused to provide any information. As another example, an acceptable best effort would be more aggressive pursuit of persons who can answer questions when the individual initially contacted cannot answer them and advising the individuals that the licensee has a signed release that can be forwarded if recessary.

Another example you may want to include is that it would be unacceptable for a licensee to just close out a <u>developed</u> reference check, required for temporary access, as best effort using a <u>listed</u> reference or an individual who has not had frequent and direct association with the applicant. If a developed reference cannot be obtained by contacting listed references initially provided, the limitable may want to contact the applicant's coworkers to try to locate a reference may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the applicant of the limitable may be a reference of the first the contact the contact the limitable may be a reference of the first the contact the limitable may be a reference of the first the contact the contact the limitable may be a reference of the first the limitable may be a reference of the first the contact the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a reference of the first the limitable may be a

- 89-01. Another approach would be to obtain additional listed references from the individual being processed and try again.
- 4. Response B.3. could be expanded to alert licensees to the importance of specifically requesting "character of service" information. If not requested, information about drug, alcohol, emotional problems, etc., may not be identified. Also, paragraph 6.2.4 of NUMARC 89-01 specifies if records are not forwarded by the NPRC, the temporary access period may be extended provided that reasonable, documented attempts are made every six months until a response from NPRC is received. Licensees are expected to make appropriate additional inquiries as necessary based on the response. If a written response is not received after several documented attempts, licensees should attempt telephonic contact and document the effort.
- 5. Response 8.4. could be expanded to provide some of the tactics used by licensees to ensure that individuals are aware of their responsibilities to report arrests, such as signed acknowledgement documents, training (to include test questions), signs, bulletins, etc.
- 6. Festionse B.S. addresses methods of identity verification that are identified as acceptable under NUMARC 89-01 when conducting a full backgroun! investigation, yet the question appears to be directed at what might be acceptable for verifying identification when conducting "temporary" background investigation. Temporary access is granted based on a very limited background investigation, and accurate verification of identity is a significant element of the process. Paragraph 6.4 of NUMARC 89-01 allows licensees to grant temporary access based on satisfactory photo identification, along with satisfactory completion of certain other elements. In credit card, would not meet the intent of photo identification. If photo identification cannot be obtained, visual identification by a supervisor, or if a supervisor is completely unattrinable, by coworkers (preferably ones who have been granted unescorted access) would meet the intent of photo identification. If visual verification is also not attainable, telephonic identification can be used. It can be accomplished by obtaining a verbal description from a secretar or coworkers and by the person(s) providing the description also , rounding voice identification by talking to the applicant.
- Mesopouse 8.6. Should be expanded to address proper actions to be taken when derogatory information is developed that may not have been identified by an applitant on a clearance application form, as required by the licensee. Actions would include licensee review of the form or interface with its self-screening contractor or screening agent to determine if the applicant identified the information. If it was now identified, the licensee would need to determine if the applicant deliberately omitted it. In these cases, the possible act of smission, as well as the significance of the derogatory information, is "smallable information" to be considered before authorizing or continuing unexisted access. Willful omission or falsification of material information submitted in support of a request for unescorted access is one of the factors identified in paragraph relia, of NUMARC 89-01 that "must" be essented access in paragraph relia, of NUMARC 89-01 that "must" be

we recovered the response be expanded to advise licensees that, if unexported acceptance to already tree greated, derogatory information should be evaluable as a contact tree greated, along with other information already developed.

Seemingly minor adverse information previously developed can become much more significant when coupled with new information. A decision should be made promptly to suspend, terminate, or continue unescorted access. In some cases the licensee may decide to place an individual under escort pending resolution of the issue.

A case has been identified where a licensee took a position that, because 10 CFR 73.57(e) gives an individual at least 10 days to challenge results of an FBI criminal history records check, it did not have to consider suspending or terminating a temporary unescorted access for 10 days following receipt of derogatory criminal history infortation, regardless of its significance. The licensee's position was not correct. The requirement in 10 CFR 73.57 to allow individuals 10 days to challenge information is only directed at a licensee's final adverse determination. The requirement does not relieve the licensee of its responsibility to review and evaluate pertinent information developed and to make a decision to revoke or continue the individual's unescorted access authorization until the matter is resolved (See 10 CFR 73.56(b)(3)).

cases have also been identified in which licensees took an individuals word initially that a criminal history record was incorrect, that they were innucent, or that the charges were dropped, only to find out later during routing inquiries, that the individual misled them in order to retain unescorted access. In some cases, if the licensees had <u>initially</u> verified the information through appropriate sources (law enforcement agencies, official court records, etc.) they would have terminated the unescorted access authorization much sooner.

8. Response 8.7. states that "There is no regulatory requirement to maintain checklists or field notes." 10 CFR 73.56(h)(l) requires licensees to retain the records on which access authorizations are based. Also, 10 CFR 73.56(b)(3) requires that "The licensee shall base its decision to grant, deny, revoke, or continue an unescorted access authorization on review and evaluation of all pertinent information developed." If a summary sheet contains all pertinent information developed, then we agree that it would meet the review and retent on requirements of the rule. For example, it would need to contain information such as responses to questions asked during the background investigation about employment history or about an applicant's reputation for emotional stability, trustworthiness and reliability, etc. Instant and of information is considered "pertinent", and its significance is altressed in paragraph 6.2.5 of NUMARC 89-01. If the summary sheet does not call all pertinent information, then the documents containing it must be evaluated and resistance whether they are checklists, field notes, or other discurents.

It is acceptable for the licensees to rely on an investigative agency to evaluate, somerive, and retain any or all information as long as it is completed in accordance with the licensee's commitments to the NFC. Also, if the information is evaluated and retained by the investigative agency with the information is evaluated and retained by the investigative agency with the information is the licensee which does not contain all of the required plants such as answers to the questions referenced above, the licensee's religious such as answers to the questions referenced above, the licensee's problem of the investigation of the required plants of the contractors should cover those elements (e.g., and the investigation, protection of actionation, reference, reference, etc.).

- 9. Response B.8. should include some discussion on the importance of "frequent" and "direct" association wher conducting an investigation for granting a temporary access. Such an investigation is limited at best and only one developed reference is relied on, which is why the NRC and the industry a reed that the association must be frequent and direct (see paragraph 6.4.d. of NUMARC 89-01). Licensees would benefit by development of guidance as to what constitutes "frequent" and "direct" contact. Further, industry guidance would be of benefit. Also, investigators should determine during interviews if developed references have sufficient knowledge based on the licensee's established, documented parameters. In responding to the question of how frequent must the association be, you may want to point out that frequent, by definition, occurs "often", and often, by definition, occurs many times, not occasionally. We have observed that licensees use varying definitions of "frequent" and "direct" and require varying durations for such associations.
- 10. Response C.I. should indicate "full" proctoring or acceptable partial proctoring (e.g., via CCIV, observation through glass, etc). We have observed that summa incensees have implemented a good practice of documenting proctoring in some mission to assist in ensuring proper implementation of the procedure.
- 11. Aespanse 1.2. would be enhanced by providing a medical definition of "clinical". One standard dictionary definition of "clinical" is "of or based on observed signs and symptoms" (1980 Oxford American Dictionary). Abother is "involving direct observation of the patient" (Webster's Ninth New College be Dictionary, 1985).

In addition, we recommend that the orment regarding NRC's consideration of current technology to revised to clearly state that technology to cransmit these signs and symptoms in sufficient quality to provide adequate sensor, class has not been demonstrated to the NRC as yet.

- 12. Response 0.1. is somewhat confusing. If it is industry's position that the trunsfer form or certification letter cannot be submitted unless the contractor's entire program is approved, to include the behavioral observation briggam, it should be clearly stated as a requirement that must by met in order to utilize the transfer system for contractors or to certify and request access. Otherwise, when only "certain" elements have been approved, it should be so stated on the form or letter. The initial NRC AA inspections determined that the above position was jot understood by all licensees.
- 13. Pesponse E.1. should be expanded to state that access is considered interrupted when an individual is away from a licensee or licensee-approved behavioral observation program (80P) for more than 30 days, regardless of whether the units inted access is active or has been terminated and that the licensee must ascertain that the activitie—the individual engaged in during the absence did not have the potential to affect his or her trustworthiness and reliability. We note that 10 CFR 73.56(b)(2)(iii) requires behavioral observation conducted by supervisors and management personnel for individuals granted unescented access and that the NRC elected to clarify to industry that it expects licensees to ascertain an individual's activities if there is a break in the EOP (See paragraph 8.3. of RG 5.66). Industry proposed, in NUMARC 91-03, "Nuclear fower Plant Personnel Access Authorization Data Exchange Guidelines", that this action should only have to be taken if the

break is more than 30 days. The NRC subsequents, great with that time frame when it advised NUMARC that the Guidelines met the intent of 10 CFR 73.56 and RG 5.56.

- 14. Response E.2. should reference the 30-day criteria in r spanse E.1.
- 15. Response i 1. should clarify that NUMARC 91-03 allows the use of the Transfer form as an enclosure to a Contractor Certification Letter only to provide informat on on the individual for those elements covered by the contractor's program, not to transfer another licensee's unescorted access authorization or i 1 criminal check completion. 10 CFR 73.56 and 73.57 only allow licensees to transfer data of this nature. Lack of clarity in the response to this question may result in contractors entering licensee data if they are aware of it, which could result in misinformation or unauthorized actions by contractors.
- 16. Fisponse F.2. should caution licensees that it is the receiving licensee's responsibility to ensure that computer-faxed access transfer copies are truly from a licensee. If the receiving licensee has requested the transfer using fax numbers established with the other licensee, then it would have adequate assurance that the fax it receives is from that licensee. However, if a transfer is received that was not requested, verification would be in order. For example, a fax may indicate that a licensee is transferring an access at the request of its contractor. The verification should be accomplished through established verification numbers. Fax transmission headers footers are intered by the sender, who may not be a licensee.

Single insider concerns and protective measures should be considered and addressed, to include situations where individuals are allowed to authoriz-/certify access, fax or receive transfer forms, enter authorization data into computers, manufacture badges, etc.

- 17. Response F.6.: The appropriate response for the question addressed here appears to be addressed in Response A.I. You may want to combine the questions. If you keep them separate, our A.I. comments apply here, as appropriate.
- 18. Response is should be expanded to include information on record retention/update responsibility when the initial five years is exceeded.
- 19. Response G 2. may give the wrong implication if it starts with "No".
 Licensees may see the "No" and not review the qualifiers in the response. We recommend that you advise licensees that "in most cases" the delays are caused by either the fBI criminal or military records check not being returned, etc., which does not necessitate withdrawal of the unescored access as long as proper actions are taken to attempt to obtain in the sing information. However, it should be made clear that if the delay the result of failure to complete other elements of the background investigation within the control of the first processing licensee, the unascorted access authorization must be withdrawn at the 180 day point for those licensees who commit to implementing all elements of PG 5.66 (See para 8.2 of RG 5.66).
- 20. Personne 6.3. should point out that if the receiving license is not not feel prior to the 180 day limit, the unescorted AA must be terminated.

- 21. Response G.4. should emphasize that the check itself must still be completed on a best effort basis and cannot be closed out as best effort just because it cannot be completed in a couple of days. The licensee would need to make contact with the employer and get some kind of a response, unless, for example, the licensee verifies that the employer went out of business and could not be contacted.
- 22. Response I.I. would be enhanced by referencing your response to A.I.. which addresses acceptance of a contractor certification vice a licensee transfer of access. Also, if a receiving licensee is aware of audit findings that place doubt on the quality of the contractor program, it has a responsibility to contact other licensees or the contractor, as appropriate, to ensure that the identified discrepancies do not affect its program or the transferred access authorization. This should be accomplished prior to authorizing unescorted access based on the transfer when the receiving licensee is aware of unresolved issues that could affect the quality of the transfer. The transferring licensee may not have conducted the audit and may not be aware of the discrepancies. It may even be necessary for the receiving licensee to audit the contractor's program if its concerns cannot be resolved initially.

We are aware of cases where contractors did not take immediate steps to ensure that major program discrepancies discovered by one licensee did not affect background investigations the contractor conducted for other licensees. In some cases, discrepancies in background investigations conducted for the other licensee were not addressed until that licensee inquired or audited and found the same problems.

Ine response should focus on more than just obtaining a copy of audit reports. Emphasis should be placed on proper review for adequacy of the audit. evaluation of findings, corrective actions, etc. and appropriate follow up actions. Also, as stated in our comments on Response A.l, althous 10 CFR actions. Also, as stated in our comments on Response by other licensees, 73.56(g)(2) allows licensees to accept audits conducted by other licensees, each licensee retains responsibility for the effectiveness of any contractor and vendor program it accepts and the implementation of appropriate corrective action.

23. Response J.1.: The appropriate response for this question appears to be addressed in part, in Response B.7. You may want to combine the questions. If you do not, our applicable B.7. comments apply here. Also, if service with a BI contractor is discontinued and the contractor has the records that the licensee's access authorizations were based on, they should be retrieved or there should be a contractual agreement for the contractor to maintain them. If the contractor maintains the records, the licensee would have audit responsibilities to ensure that the records are properly maintained. If individuals are in the data transfer system, their records need to be maintained for five years after final termination of access. Once the records are destroyed, another five year investigation and a psychological evaluation would have to be instituted and evaluated prior to authorizing or continuing access (for 10 fix 73.56(h)(1).

24 Fig. to a 12 states that "current procedures" should be followed the requirements here also.



March 23, 1994


Mr Frank J Congel, Director Division of Radiation Safety and Safeguards Office of Nuclear Reactor Regulation 1. S. Nuclear Regulatory Commission One White Flint North Hees Rockville Pike Property MID 20852

Dear tit Congel

The purpose of this letter is to request an NRC staff review of the enclosed draft Access Authorization (AA) Program Issues and Responses." We request NRC review to ensure that our responses to the industry on these access authorization issues are not in centiles with the intent of applicable regulations. On two prior occasions, we have used this process to efficiently provide information to licensees that helped to refine and improve access authorization programs. The main sources for these issues are previous NI MARC Workshops on Fitness-for-Duty and Access Authorization and the results of the NRC's recent prior inspection program for licensee implementation of the Access Authorization Pule

Because this information is of generic interest to the nuclear power industry and the 1.PC it is a r understanding that no special fees will be assessed for the NRC review If this is incorrect, please contact us prior to beginning your review.

For your information. NEI is continuing a NUMARC project aimed at identifying the required elements of a standardized behavioral observation program. Guidelines for a program that satisfies the behavioral observation requirements of both the Access Auth. rization and the Fitness-for-Duty Rules are being developed. After industry review we will forward a copy to the NRC.



Mr. Frank J. Congel, Director March 23, 1994 Page 2

Thank you for your support of our efforts to provide assistance to the industry in these draft documents, please call Rich Enkeboll or me.

Sincerely.

Box 11. Italian

Robert N. Whitesel, Manager Operations, Management

and Support Services

PROGRAM ISSUES AND RESPONSES

A. ACCESS AUTHORIZATION PROGRAM ORGANIZATION AND ADMINISTRATION

Some licensees are apparently not looking closely at how their approved contractor verifors (self-screening contractors) are complying with regulation and accesses commuments. One contractor vendor neglected to audit its sub-contractors. This was not noticed by the licensee in its audits: a falsification described in the situation to light. Another contractor vendor was followed. That was full but not the clarifications imposed by Reg. Guide 5.66. It has a marked made clear that all licensees had committed to the use of NIMA. The contractors of the contractors. The contractors of the contractors. The contractors of the contractors o

Comprehensive oversight of contractor/vendor programs to ensure understanding and compliance would alleviate the root cause of this observation. Specific provisions should be included in the contract. The contract should stipulate notification responsibilities for discovery of inaccurate or falsified information. If the discovery would affect other licensees, a procedure for their prompt notification should be included. Records ownership and retention responsibilities should be specified. Copies of all pertinent licensee procedures and regulatory documents need to be provided to the contractor/vendor. For instance, IN 91-59 ("to alert addressees to two areas of continuing problems with access authorization programs...falsifying records...improper administration or compromise of psychological tests.") should be included. The procedures should explain the action to be taken and what the liability is for stillful withholding of information.

The program-approving licensee is responsible for auditing the contractor/vencor program. Follow-up on deficiencies identified in audits must be documented and made available to other requesting licensees in support of their access determinations that are made based on the expectation that the provided information is correct. It is essential that contractor/vendor programs meet the standards imposed by regulation

An NRC comment in a public meeting indicated that there is concern that a nonlicensed individual could violate § 50.5 by failing to follow the licensee's procedures or policies and cause the licensee to be in violation of NRC requirements. An inadvertent failing of a contractor/vendor in following a licensee's procedure has recently resulted in a citation for lack of compliance. to a quinst the contractor or licensee? This program recas add

classification. See and Comment #1.

BACKGROUND INVESTIGATION ELEMENTS 13.

in unconstitute fingerprint issue is not well understood. Some licensees believe the conference have been submitted twice, regulatory requirements have been mes there do not always determine and correct the cause of a pour print " " " " uni may accept a "name check" as sufficient. The NRC cited a n where a felon was able to fabricate a background with a false identit. and each temporary unescorted access. He was only caught when the fingery to with a resulted in receipt of a criminal record concerning the individual's the diletions

Veriminal history check-should not be closed without classifiable fingerprints if the reason for the print being unclassifiable is poor printing technique. The resultant search by name. FBI check result may not provide the needed result. Licensee personnel performing the fingerprinting should be properly trained for the task, or the use of a technician from a law enforcement agency should be considered. In the rure case where the individual's finger ridges have been worn away or disfigured, the fingerprints should be identified as the "best set obtainsble" prior to submission. The I BI may then be able to perform an approximate classification. All attempts to obtain classifiable prints should be documented; rejected prints should be retained to serify "best effort." Even with this guidance, a case should not be closed with less than two attempts (one \$24 fee provides for this) to obtain classifiable prints.

One licensee has expressed concern about temporarily cleared individuals when the fingerprints are returned without being classified. If the individual has completed work and departed the site, the licensee obligation to complete the process for a full clearance is stifled until the individual becomes available for re-fingerprinting. Item (. 3. talem provides further discussion of this issue.

. the to are a ceral levels of interpretation of what constitutes a "best off in an value, their interest information. What is considered an acceptable level or at what form and an all of the investigative effort?

Best effort" is not amenable to quantification - there is no set formula or check lost for a background investigation that can be used to determine when the effort has

been sufficient. The NUMARC 89-01/91-03 intent was that the investigator make a thorough attempt to collect the required information, doing as complete an investigation as can be done under the circumstances. If one avenue was unsuccessful, may be another would lead to the information required. If sufficient information can be pieced together to accomplish the objective, the "best effort" will have been successful. If, in spite of using all normal avenues available, the information collected is still incomplete, a narrative of the effort and results achieved should be documented to show the basis to evaluate the attempt as "best effort."

What constitutes a "best effort" in submitting SF 180 request forms to the National ters and Records Center to obtain a DD-214? Some licensees report that save the Forms have been submitted with no response or, in some cases the character of service" has been deleted.

It is important to recognize that the National Personnel Records Center (NPRC) is only one place that military records are filed. If no response is received within two months, you may have requested the information from the wrong agency. The location of the record will depend on the branch of service, the time period since separation and whether the individual has remained in the Reserves. It is recommended that the licensee review information provided by the candidate, then review Appendix C of NUMARC 91-03, specifically referring to the chart on the back of S1 180, to determine the most likely location of the service record. If this research indicates that the record should be located at NPRC, but the record is not forthcoming within two months, you may wish to contact NPRC (Army Reference Branch number: 314-538-4145 or 4131; Navy 4200). NPRC advises they will provide a postcard response if they refer the submitted SF 180 request to another agency. If there is still no success, further submissions of SF 180 will not alleviate the situation. The licensee should record a "best effort" that is properly supported by narrative and close out the search.

The "character of service" will be provided by NPRC only if specifically requested, and the individual authorizes its release by signature (see Appendix C of NLNIRC 91-03).

Rest Guide 5.66. § 9.0, requires employees "to report any arrest that may impact upon his her trustworthiness." How is this determined unless all arrests are restented.

It is necessary that all persons subject to the rule be made aware of their individual responsibility under the licensee's physical security plan commitment to Reg. Guide

5.66. Many licensees have established procedures that include training the individual on the purpose, process to be followed and the potential ramifications of this requirement. These programs provide awareness of two individual responsibilities:

- . Report all convictions as part of the security clearance process; and
- · Promptly report arrests or when charged with a crimonal offense.

Some programs establish specific criteria for reporting arrests rather than relying on the Reg. Guide 5.66 phraseology to report any arrest that may impact upon his/her trustworthiness. For example, some licensees require the reporting of any arrest that results in being taken into custody by an authority of the law, incarcerated (i.e., taken to jail/court), or charged with a criminal offense but not taken into custody. This enables the licensee to evaluate its impact upon the individual's reliability and trustworthiness related to unescorted access authorization or access to Safeguards Information. Considering state law categorizations, licensees should determine whether non-custodial, misdemeanor arrests (e.g., a routine traffic ticket) are required to be reported.

same accesses apparently accept two credit cords as sufficient evidence to some acceptances apparently accept two credit cords as sufficient evidence to some acceptances advantages when a photo identification is unavailable -- is the acceptance procedure.

No. it is not an accepted practice to use commercial forms of identification with the possible exception of a credit card imprinted with a photo of the card user. The significance of "verification of identity" is to ensure that the individual in question is whom he or she purports to be. Reg. Guide 5.66, § 6.2.6, requires identity to ". he verified through means such as photograph, social security number, date of hirth, or comparison of applicant's physical characteristics with employment, education, military, and other records, and/or employer and character references who have a personal acquaintance with the applicant." Identity should normally be verified through the use of applicant issued by a municipal. State, or Federal agency to g., check by name and social security number). An acceptable alternative is to have the person identified by a supervisor/manager that is acquainted with the individual.

tulis, discument their review and adjudication of potentially derogators

In order to show that potentially derogatory information has been satisfactorily checked, the disposition of derogatory information should be documented. An interview with the applicant should be conducted in order to allow explanation or refutation of any potentially derogatory information.

opener's elegrance summary sheets is sufficient or whether all of the actual energy clearance summary sheets is sufficient or whether all of the actual energy tield notes, etc., must be reviewed, please clarify.

The purpose of the licensee review is to look at all elements of the investigation to ensure that the Andividual meets the requirements of the rule before being granted unescerted access authorization. If the summary sheets provide that information, that is sufficient. There is no regulatory requirement to maintain checklists or field

m profes have interpreted the "frequent contact" requirement for personal references to mean contact with the subject every two months over the course of a reference to mean must personal contact be with the access applicant for an individual to count as a personal reference?

No set frequency has been, nor should be, established. The licensee makes the judgment on the issue of whether the personal reference has had sufficient contact with the subject to provide adequate responses to the investigator. Each relationship with the subject to provide adequate responses to the investigator. Each relationship has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather than on a minimum frequency has to be evaluated on a case by case basis rather tha

PSYCHOLOGICAL EVALUATIONS

and that fact documented?

Yes. Information Notice 88-91, "Improper Administration and Control of Prochological Jests," explains why proctoring is necessary to ensure proper administration and control of psychological test materials and testing environments. Information Notice 91-59 (see A.1. above) also alerted addressees to improper administration or compromise of psychological tests. If a utility's procedure explains

the psychological testing process and meets regulatory intent, no further documentation should be necessary.

Procedures do not aiways define requirements for a psychological interview the necessity of which is determined after review of the MMPI results. Some necessity of which is determined after review of the MMPI results. Some necessity of which is determined after review of the MMPI results. Some necessity of which is determined by telephone. Some licensees have asked about the use of a video-phone hookup to enable remote interviewing. What is expected

The NRC has taken the position that face-to-face interviews are necessary to reveal sufficient sensory clues to the interviewer. During a face-to-face interview, a psychologist who has knowledge of an individual's background and understands the meaning of the MMPI indicators can lead the interview in a way that brings out subtle clues unavailable by other means. Abnormal psychological symptoms (e.g., subtle clues unavailable by other means. Abnormal psychological symptoms (e.g., subtle clues movement, skin flushing, unusual body language, etc.) may be subtle but can be significant in the interview/observation process. The NRC does not consider current technology video-phones to be of sufficient quality to transmit these subtle clues.

D. BEHAVIORAL OBSERVATION PROGRAM

nemized in licensee approval of unescented access authorization programs.

Hemized in licensee approval of unescented access authorization programs.

Here there this aspect was not necessarily being audited. Licensees receiving there they this aspect was not necessarily being audited. Licensees receiving a license data from approved contractor vendors in the past have expected that the access data from approved contractor vendors in the past have expected that the approved program automatically included behavioral observation. What can we expect?

Licensees are authorized to approve any or all aspects of a contractor/vendor program. When a program is approved, the approving document (contract or equivalent) should state which program elements are to be the responsibility of the contractor/vendor. When a NUMARC Transfer Form or Certification Letter contractor/vendor employee is provided to a receiving licensee, it is concerning a contractor/vendor employee is provided to a receiving licensee, it is expected that the contractor/vendor's CBOP is approved (and therefore audited) or that the individual has been under the transferring licensee's behavioral observation program.

L. UPDATING AND REINSTATEMENT

If an individual met all requirements for unescorted access but has been away from a Continual Rehavioral Observation Program (CBOP) for more than 30 days the licensee must ascertain that the activities of the individual during the second host impact his or her trustworthiness and reliability. What is considered to be an appropriate process for this determination?

The rule, \$73.56(C)(1), states: "The access authorization program may specify conditions for reinstating an interrupted access authorization..." Reg. Guide 5.66. Clarification 3., states: "...prior to reinstatement of the access authorization, it is reasonable to expect that the licensee will ascertain that whatever activities the employee engaged in during his or her absence would not have the potential to affect the completee's trustmorthiness and reliability." NUMARC 91-03, III.B.4., notes that the absence ascribed in Reg. Guide 5.66 has to have been more than 30 consecutive days. Further, this section advises that this determination can take place by any process suitable to this end. It allows the licensee to make a determination based on individual circumstances. The intent is to assess how much re-investigation should be conducted based on specific circumstances. Ascertaining what activities the individual was engaged in since he or she last held an unescorted access authorization could utilize some combination of several techniques. This could include the use of a questionnaire, an interview of the individual, or contact with employers or associates re.g., listed or developed references) of the individual during the period of absence, a check of local union halls or unemployment agencies, etc. It is appropriate to use any follow-up investigative technique that would obtain the necessary information.

the companies with approved access authorization programs (e.g., INPO) required to have their personnel updated or reinstated if they have been in the companies continuous employ and under its random testing and behavioral observation programs?

No. provided that the company's approved FFD and access authorization (including behavioral observation) programs meet all requirements as determined by periodic behavioral observation) programs meet all requirements for because audits. Personnel covered by such a program meet all requirements for unescorted access authorization at all sites and would need only site specific training prior to being badged. (See F.8. below.)

F. TRANSFER OF ACCESS

Lines the Cerufication Letter serve a different purpose than the NUMARC 91-03

Transfer Form'

Yes, although the process ("I MARC 91-03, II B.) allows the use of the Transfer form as an enclosure to a Certification Letter. With the individual's consent, licensees use the Transfer Form to provide access authorization information about an individual to whom they have granted unescorted access and who was terminated without disqualification. Contractor/vendors are to use a Certification Letter to provide all information associated with their employees, except the criminal history details that they are not authorized to have by regulation. The Certification Letter makes an obvious distinction between a licensee access authorization clearance transfer and a contractor/vendor access information document. It provides a vehicle to identify the licensee that approved the access authorization program and adjudicated the individual's criminal history.

Must the person who signs the NUMARC y1-03 Transfer Form be listed on the state of contact (CPOC) list? Transfer Forms ma, i. automatically computer-faxed without a signature; does this present a problem?

No, the CPOC list was established by position, not by name, to be a ready point of contact. More than one person working with access control information may be authorized by the company to officially transmit Transfer Forms. Also, there is no requirement for a computer generated NUMARC 91-03 Transfer Form to be signed. If the transmission header/footer specifying the transmitting company name or phone number provides reasonable assurance that the transmission originated at the specified source. If this is not the case, further communication is appropriate.

Authorization on the NI MARC 91-03 Transfer Form (Section 6 -- Access Authorization History Audit Irail) to indicate an individual's access authorization audit transfer free sites. What should we do if the individual has been at more time tax vites.

Individuals who have an extensive work history in the nuclear industry will have a lengthy unescorted access authorization audit trail. Because this is a series transfer process, a satisfactory practice is to maintain the first entry (initial access granted) and then access location entries for the last four. This practice is considered preferable to attaching a page of access authorization history to the Transfer Form.

In the unusual circumstance that it becomes necessary to obtain information associated with the period of the "gap," the audit trail can be retrieved by starting with the first entered company.

Does the NUMARC process require that a Transfer Form be sent by the receiving the sent by the receiving the sent to the transferring licensee to initiate a transfer of information? Is it required that a consent form be provided concurrently by the transferring the ensect

No is the answer to both questions. As described in NUMARC 91-03, it is only necessary to furnish the transferring licensee with the name(s) and social security number(s) of the individual(s) on whom information is being requested. No consent form is required. The Transfer Form is not sent unless the individual has provided this consent to the first transferring licensee. The request for transfers is made by this consent to the transferring licensee. The transferring licensee then provides a telephone fax to the transferring licensee. The transferring licensee then provides a telephone fax to the transferring licensee. The transferring licensee then provides a telephone fax to the transferring licensee. The transferring licensee then provides a telephone fax to the transferring licensee. The transferring licensee then provides a telephone fax to the transferring licensee individuals. If some information is not filled in Transfer Form for each of the listed individuals. If some information is not being provided, the applicable line should not be left blank out annotated to advise the receiving licensee of the fact that the omission was not alroversight.

and some covers all FFD training in GET (General Employee Training). The training covers all FFD training in GET (General Employee Training). The training to the security used to the second to track initial and annual retraining for these subscales of the second to track initial and annual retraining for these subscales of the second to track initial and annual retraining for these subscales of the second to track initial and annual retraining for these subscales of the second to the second to track initial and annual retraining for these subscales of the second to track initial and annual retraining for these subscales of the second to the second to track initial and annual retraining for the second to track initial and annual retraining for the second to the s

In this case, it would be appropriate to use the most accent date that the GET training or retraining was accomplished. This date should be inserted in all applicable blanks on the form. There is no reason to indicate when the initial training was completed unless it was the last training provided.

Mr. E. m. thod is used to ensure a contractor vendor access authorization programs
me a metastr, xercening standards?

The Incensee who approves a contractor/vendor program must first ensure that company has a program and process that meet regulatory requirements, which are normally specified in the contract. The approving licensee's annual audit then ensures that the contractor/vendor is complying with the contract.

explain where data responsibility lies.

The NUMBE process provides for transfer of access data to the next licensee in a series trail. The initiating licensee retains the responsibility for maintaining records of the clearance for five years after transferring the individual (see J.3 below). Data to support continuation of the clearances are maintained by each licensee in the transfer chain, all a transferring licensee subsequently receives another transfer transfer that the individual in question deliberately neglected to advise this requesting that the individual in question deliberately neglected to advise this requesting licensee that he/she had been at another plant in the interim, possibly fearing that derogatory information could be found in his/her record. To minimize opportunities for such deception, a receiving licensee should inform the transferring licensee if the individual fails to appear at the site as expected. Responsibility for the individual sector requests a data transfer.

to the second to the licensee'

Such extra requirements reduce the efficiency of the transfer process. NUMARC 91.
03. II.C.2., provides a description of the clearance status. (authorized for unescorted access." An individual maintained in this status meets alls equirements (completed of the convered by random testing and CBOP within the last 30 days, current in training.

1. Covered by random testing and CBOP within the last 30 days, current in training. etc.) and can be granted immediate unescorted access, after completion of site specific training, without any updating or verifying of activities. (See E.2. above.)

G. TEMPORARY ACCESS AUTHORIZATION

The service with the accept the transfer of a temporary clearance if the service within a short period of time?

No be ensee is required to accept a temporary transfer. Experience has shown that, even if there is only a little time left before the 180-day deadline arrives, the only residual information needed will either be criminal history or military history most other transferable information will be available and useful. The transferring because when the transfer Form (or by CPOC call) the expectations for

providing the incomplete items. The transferring licensee continues to be responsible for notifying the receiving licensee regarding BI completion and/or emergent disqualifying information, if any.

In the situation where a licensee transfers a temporary clearance but is unable to make the transfer to the transfer to within the 180 day period, does the receiving licensee have to withdraw the access authorization?

No. NI MARC 91-03 establishes the first processing licensee as the agent responsible for completing the Bl. Delays in completion of either the criminal history or military background checks can be used to extend the clearance beyond the 180-day period. A criminal history delay may be the result of multiple re-submissions of fingerprints (see B.1. above and G.3. below). A military nistory delay may occur because the applicable record retention agency was not contacted (see B.3. above). The special circumstances that must be addressed in order to complete the full clearance process can usually be accomplished within the 180 day period with a "best affort" pursuit. However, if the delay is the result of failure to complete other elements of the trackground investigation within the control of the first processing licensee, then the temporary clearance should be withdrawn at the 180-day point.

an the receiving licensee expect to receive notification when fingerprint at a transfer is acceptable upon its return from the FBI? If fingerprint results are not received prior to an individual leaving the site, and reprinting is required, but the transferring licensee is unable to make subsequent contact with the individual what needs to be done for closure of the background investigation?

st 20

Yes, the receiving licensee can expect to be notified when a temporary clearance has been upgraded to a full clearance after the residual requirements (including criminal history) have been completed by the process initiating licensee (see G.1. and G.2. above). When providing a NUMARC 91-03 Transfer Form for a temporary clearance the transferring licensee should advise the receiving licensee of remaining requirements. If the residual requirements are not completed within the 180-day period, the transferring licensee would advise the receiving licensee of the potential delay in a timely manner. If the incomplete information concerns military history or criminal history, the clearance period can be extended while those aspects are completed. If the fingerprint submittal has not resulted in the return of a criminal history from the FBI because of poor quality prints (see B.1. above), the receiving licensee should then obtain the best possible reprint and submit it via the NRC for another FBI check.

Many licensees report that their experience has shown that the verification of employment for a temporary clearance provides no added value. One example cited way "Of v63 personnel badged during the outage 180 were delayed flower productivity of more than three days each) while trying the previous year." What purpose does this or imployment check

Reg. Guide 5.66 NI MARC 89-01, § 6.4.f., specifies those Items (a psychological evaluation, a credit check, a developed reference and the one year employment check) to be completed for a temporary clearance. This is considered to be an acceptable expedient while finishing the full clearance requirements (five-year background investigation and military history as well as an adult criminal history). Elimination of the employment check could weaken the temporary clearance basis. Some licensees obtain an additional character reference to supplement the paucity of meaningful information from the one-year employment check. The goal of the checks for temporary clearance is to collect sufficient information that a reasoned unescorted access decision can be made.

II. PROTECTION OF PERSONAL INFORMATION

and employment information to others as required by 10 CFR § 73.56 (f)(2), even when such requests have been accompanied by a signed release from the information the requirement

This may be a result of procedures in place prior to the Access Authorization Rule. As long as the information is only used for the purpose of determining an access clearance and is properly protected, the rule requires that it be provided. The information would be obtained from access authorization records, not from the information would be obtained from access authorization records, not from the personnel employment file (see J.2. below). If not already included in the initial consent Form, the clearance initiating licensee needs to obtain a signed release consent that authorizes the transfer of the collected information to other companies that may be asked to allow the individual unescorted access to protected areas or to safeguards information. In Section 1 of the NUMARC 91-03 Transfer Form there is the statement: "Subject individual has provided written consent for the release of any information or documentation pertinent to evaluation for unescorted access authorization at any nuclear power plant." No other consent forms need to be requested or provided when transferring access information

I. AUDITS

If hen a receiving licensee is provided information on a contractor/vendor employee is a required that a copy of the last audit be provided at the same time. If has if there were audit findings that placed doubt on the quality of the program; as has been the case with a few self-screening contractor/vendor programs)?

No, the Rule does not require that the audit results be obtained prior to granting unescorted access to a transferred individual but the Rule (paragraph 73.56(g)(2)) does require licensees who share audits of contractor/vendo. It obtain a copy of the applicable audit report. The responsibility for the quality of the program, including resolution of audit findings, remains with the licensee or the Euraudit company of a group of licensees (such as the Integrated Nuclear Data Exchange (INDEX), the Shared Nuclear Access Authorization Audit Group (SNAAAG), or the Nuclear Procurement Issues Committee (NUPIC)) that approved the contractor/vendor program. Receiving licensees trust that the program approving licensee(s) ensures the quality of the contractor/vendor's program. If a receiving licensee is not comfortable with this practice, further communication with the applicable auditors may be appropriate.

J. RECORDS

Man, it enversevaluate a synopsis thrief summary of the background elements examined and an indication of their acceptability) instead of the detailed checkins provided by a background investigative agency as the basis for access authorization decision, can it be used in place of original background investigation data to g. field notes) to satisfy record retention requirements? Is the livensee required to obtain original screening records when they have decontinued services with a BI contractor?

If the synopsis is structured to provide the information required by regulation, field notes are not required. NUMARC 91-03, III.F., states that it is necessary to obtain and maintain records that support continued unescorted access for clearances initiated and granted by that licensee. Licensees should be able to retrieve the records for the BI contracted services. Subsequent receiving licensees are dependent upon this information being available to support program audits and NRC inspections.

Is it acceptable to have Human Resources information (e.g., employment records, and access authorization data stored in the same file or data base?

It is not a good practice to do so. Employment records serve a different purpose from acress authorization records, and each is normally managed by a different group.

Limployment records are also considered to be 'confidential,' while access records must be 'made available' for requests provided for in § 73.56 f(2). There may be some information overlap in the two files (e.g., associated with a combined employment and suitable inquiry request). For these reasons, maintaining separate employment and access records may reduce exposure to potential discrimination FEO issues, co-employment issues, etc. (Also see H.1. above.)

A land the status of finding a solution to the five year record retention issue!

The solution resides in the establishment of a central records repository system (authorized by the NUMARC Board of Directors on March 1994). However, until this system is in place current procedures should be followed. The central records repository is expected to be in operation by 1996, within the tre year period after access authorization rule implementation.



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20656-0001

December 12, 1994

Mr. Rex Allen Werts (Address deleted under 10 CFR 2.790)

SUBJECT:

ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES

AND UNESCOPTED ACCESS (EFFECTIVE IMMEDIATELY)
OI INVESTIGATION REPORT YNOPSIS (2-93-052R)

Dear Mr. Werts:

The enclosed Order Prohibiting Involvement in NRC-Licensed Activities and Unascorted Access (Effectively Immediately) is being issued as a consequence of the deliberate false statements you made on an application for access authorization at the Carolina Power and Light Company's (Licensee) Brunswick Nuclear Plant. On or about March 11, 1993, you used an alias on your access authorization application and indicated on the application that you had not been arrested or convicted of any criminal offense. As a result of your deliberate false statements, you were granted unescorted access to the Brunswick Nuclear Plant on March 24, 1993. The Licensee subsequently learned of your use of an alias and that you had been arrested and convicted several times for crimes and were incarcerated for some of those offenses. A licensee supervisor interviewed you about your application, at which time you admitted that you had submitted false information on your application.

10 CFR 50.5(a)(2), "Deliberate misconduct," prohibits an employee of an NRC licensee or licensee contractor from deliberately submitting information to the licensee or licensee contractor that the employee knows to be incomplete or inaccurate in some respect material to the NRC. 10 CFR Part 2, Appendix C, "General Statement of Policy and Procedures for NRC Enforcement Actions," in particular Section VIII, "Enforcement Action Involving Individuals," provides guidance and considerations for enforcement sanctions against individuals who deliberately violate NRC requirements.

The NRC Office of Investigations (OI) conducted an investigation (2-93-052R) to determine whether you committed a willful violation in connection with your making false statements regarding your criminal background. The OI investigation concluded that you had deliberately provided false information concerning your criminal arrest and conviction record in order to gain unescorted access to the site protected area. By letter dated September 14, 1994, the NRC attempted to provide you with a copy of the OI investigation synopsis and afford you an opportunity for an enforcement conference prior to making a final decision regarding escalated enforcement action in your case. The latter has been returned by the post office as undeliverable and we have been unable to locate you. A copy of the September 14, 1994, letter with the OI synopsis attached is enclosed (inclosure 1). If attempts to deliver this letter and the enclosed Order are not successful, it will not delay the effective date of the anclosed Order nor the placement of this letter and enclosed Order in the Public Document Room.

Acc# 9412130295-

identity. The Licensee submitted fingerprint cards completed by Mr. Werts to the Federal Bureau of Investigation (FBI) and subsequently was informed that Mr. Werts (alias Mr. Hunter) had a record of arrests, convictions, and imprisonments prior to 1990.

III

Based on the above, Mr. Werts engaged in deliberate misconduct in violation of 10 CFR 50.5(a)(2) which prohibits any employee of a licensee or licensee contractor from deliberately submitting to the licensee or licensee's contractor information the employee knows to be incomplete or inaccurate in some respect material to the NRC. Information concerning an individual's true identity and criminal history is material in that it is used by the Licensee to make determinations relative to the grant or denial of access authorization. If the Licensee had been given accurate information regarding Mr. Werts' criminal record, the Licensee would not have granted unescorted access to Mr. Werts.

The NRC must be able to rely on the Licensee, its contractors, and licensee and contractor employees to comply with NRC requirements, including the requirement to provide information that is complete and accurate in all material respects. Mr. Werts' actions have raised serious concerns as to whether he can be relied upon to comply with NRC requirements and to provide complete and accurate information to the NRC or to NRC licensees in the future.

Consequently, I lack the requisite reasonable assurance that nuclear safety activities can be conducted in compliance with the Commission's requirements

and that the health and safety of the public would be protected if Mr. Werts were permitted at this time to be involved in the performance of licensed activities or were permitted unescorted access to protected or vital areas of NRC-licensed facilities. Therefore, the public health, safety and interest require that Mr. Werts be prohibited from being involved in the performance of activities licensed by the NRC and be prohibited from obtaining unescorted access for a period of three years from the date of this Order. For a period of five years from the date of this Order, Mr. Werts is required to inform the NRC of his acceptance of employment with any employer whose operations he knows or has reason to believe involve NRC-licensed activities. Furthermore, pursuant to 10 CFR 2.202, I find that the significance of the deliberate misconduct described above is such that the public health, safety and interest require that this Order be immediately effective.

IV

Accordingly, pursuant to sections 103, 161b, 161i, 182 and 186 of the Atomic Energy Act of 1954, as amended, and the Commission's regulations in 10 CFR 2.202, 10 CFR 50.5, and 10 CFR 150.20, IT IS HEREBY ORDERED, EFFECTIVE IMMEDIATELY, THAT:

A. For a three-year period from the date of this Order, Mr. Rex Allen Werts is prohibited from engaging in activities licensed by the NRC and is prohibited from obtaining unescorted access to protected and vita? areas of facilities licensed by the NRC. For the purposes of this Order, licensed activities include the

activities licensed or regulated by: (1) NRC; (2) an Agreement State, limited to the Licensee's conduct of activities within NRC jurisdiction pursuant to 10 CFR 150.20; and (3) an Agreement State where the licensee is involved in the distribution of products that are subject to NRC jurisdiction.

B. For a five-year period from the date of this Order, Mr. Werts is required to provide notice to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555, of his acceptance of employment with any employer whose operations he knows or has reason to believe involve NRC-licensed activities.

The Director, Office of Enforcement, may, in writing, relax or rescind any of the above conditions upon demonstration by Mr. Werts of good cause.

V

In accordance with 10 CFR 2.202, Mr. Werts must, and any other person adversely affected by this Order may, submit an answer to this Order, and may request a hearing on this Order, within 20 days of the date of this Order. The answer may consent to this Order. Unless the answer consents to this Order, the answer shall, in writing and under oath or affirmation, specifically admit or deny each allegation or charge made in this Order and shall set forth the matters of fact and law on which Mr. Werts or other person adversely affected relies and the reasons as to why the Order should not have been issued. Any answer or request for a hearing shall be submitted to the

Secretary, U.S. Nuclear Regulatory Commission, ATTN. Chief, Docketing and Services Section, Washington, DC 20555. Copies also shall be sent to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555, to the Assistant General Counsel for Hearings and Enforcement at the same address, to the Regional Administrator, Region II, U.S. Nuclear Regulatory Commission, 101 Marietta St. N.W., Atlanta, Georgia 30323, and to Mr. Werts, if the answer or hearing request is by a person other than Mr. Werts. If a person other than Mr. Werts requests a hearing, that person shall set forth with particularity the manner in which his interest is adversely affected by this Order and shall address the criteria set forth in 10 CFR 2.714(d).

If a hearing is requested by Mr. Nerts or a person whose interest is adversely affected, the Commission will issue an Order designating the time and place of any hearing. If a hearing is held, the issue to be considered at such hearing shall be whether this Order should be sustained.

Pursuant to 10 CFR 2.202(c)(2)(i), Mr. Werts, or any other person adversely affected by this Order, may, in addition to demanding a hearing, at the time the answer is filed or sooner, move the presiding officer to let aside the immediate effectiveness of the Order on the ground that the Order, including the need for immediate effectiveness, is not based on adequate evidence but on mere suspicion, unfounded allegations, or error.

In the absence of any recommon a hearing, the provisions specified in Section IV above shall be final 20 days from the date of this Order without

further order or proceedings. AN ANSWER OR A REQUEST FOR A HEARING SHALL NOT STAY THE IMMEDIATE EFFECTIVENESS OF THIS ORDER.

FOR THE NUCLEAR REGULATORY COMMISSION

Dames L. Milhoan Deputy Execution Deputy Executive Director for Nuclear Reactor Regulation, Regional Operations and Research

Dated at Rockville, Maryland this Thay of December 1994

cc w/encls: Carolina Power and Light Company ATTN: Mr. R. A. Anderson Vice President Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461

State of North Carolina All States PUBLIC DOCUMENT ROOM

Distribution w/encl: LPDR SECY CA JTaylor EDO HThompson, DEDS SEbneter, RII RZimmerman, NRR RBernero, NMSS LChandler, OGC JGoldherg, OGC Enforcement Coordinators RI, RIII, RIV JLieberman, OE JGray, OE RRosano, CF EHayden, OPA HHiller, OC ODandois, OC LTremper, OC JFitzgerald, OI EJordan, AEOU DWilliams, OIG OE: EA (2) DCollins, RII DMcGuire, RII PMilano, NRR HChristensen, RII CEvans, RII Burys, RII KClark, RII PLohaus, OSP RTrojanowski, RII IMS:RII NUDOCS

DOCUMENT: 6:\OECASES\94163RE4.DR

SYNOPSIS

On August 20, 1993, the U.S. Nuclear Regulatory Commission (NRC) licensee. Carolina Power and Light Company, submitted a Security Event Report to the NRC regarding an event at the licensee's Brunswick Nuclear Plant (BNP). The event described by the licensee involved an employee of a contractor who was granted unescorted access to the BNP vital and protected areas based on falsified employment and background information. This matter was referred to the NRC Office of Investigations (OI) Region II Field Office on September 1, 1993, for evaluation.

Based on OI review of the documentation and evidence obtained in this investigation, it is concluded that the subject deliberately falsified personal identification and background information to deceive the contractor, PPM, the licensee and the NRC in order to fraudulently obtain employment and unescorted access at the BNP.

NOTIFICATION OF SIGNIFICANT ENFORCEMENT ACTION

Individual: Rex Allen Werts (1A 94-035)

Subject: ORDER PROHIBITING INVOLVEMENT IN NRC-LICENSED ACTIVITIES AND

UNESCORTED ACCESS (EFFECTIVE IMMEDIATELY)

This is to inform the Commission that, in accordance with SECY-94-287 (November 23, 1994) and the Commission's approval of the recommended action dated December 9, 1994, an Order Prohibiting Involvement in NRC-Licensed Activities and Unescorted Access (Effective Immediately) was issued December 12, 1994 to Rex Allen Werts. The action was based on an OI investigation which concluded that Mr. Werts had deliberately falsified his identity to gain employment and unescorted access to Carolina Power & Light's Brunswick facility. The Order prohibits Mr. Werts from engaging in NRC-licensed activities and from gaining unescorted access to protected and vital areas of NRC-licensed facilities for a period of three years. In addition, for a period of five years from the date of the Order, Mr. Werts is required to provide notification to the Director, Office of Enforcement, of his acceptance of employment with any employer whose operations he knows or has reason to believe involve NRC-licensed activities.

It should be noted that the individual has not been specifically informed of the enforcement action. The schedule of issuance and notification is:

Mailing of Notice December 12, 1994
Telephone Notification of Individual December 12, 1994

The individual has twenty days from the date of the Order in which to request a hearing.

Contacts: D. Rosano, OE, 504-3282 J. Lieberman, OE, 504-2741

Distribution

OWFN D.40 Chairman Selin Comm. Rogers Comm. de Planque SECY OCA GPA	EDO DEDR	TWFN 12:40 OC AEOD OP CTR NMSS IRM OIG RES ACRS	Regional Offices RI 2:40 RIV 2:40 RII 2:40 WCFO 13:40 RIII 2:40 WCFO 13:40 RIII DCS PDR
---	-------------	---	---

PRELIMINARY INFORMATION - NOT FOR PUBLIC DISCLOSURE UNTIL VERIFICATION THAT INDIVIDUAL HAS RECEIVED ACTION

Acc#9412220164

A-9