## UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

In the Matter of

MISSISSIPPI POWER & LIGHT COMPANY MIDDLE SOUTH ENERGY, INC., AND SOUTH MISSISSIPPI ELECTRIC POWER ASSOCIATION (Grand Gulf Nuclear Station) Docket No. 50-416

## ORDER REQUIRING DIESEL GENERATOR INSPECTION (EFFECTIVE IMMEDIATELY)

Ι.

Mississippi Power & Light Company, Middle South Energy, Inc., and South Mississippi Electric Power Association (the licensees) are the holders of Facility Operating License No. NPF-13, which authorizes the operation of the Grand Gulf Nuclear Station, Unit 1 (the facility) at steady-state reactor power levels not in excess of 191 megawatts thermal. The facility consists of a boiling water reactor (BWR/6) with a Mark III containment located in Claiborne County, Mississippi.

II.

On August 12, 1983, the main crankshaft on one of the three emergency diesel generators (EDGs) at the Shoreham Nuclear Power Station, which were manufactured by Transamerica Delaval, Inc. (TDI), broke into two pieces during a load test. During the course of the evaluation of the failure, information related to the operating history of TDI engines has been identified which calls into question the reliability of all TDI diesels. The operational problems associated with TDI diesels have significantly reduced the staff's level of confidence in the reliability of all TDI diesel generators. As a result of the above, there is a question concerning the reliability of the TDI diesel generators installed at the Grand Gulf facility. Staff analysis (Attachment 1) indicates that the total loss of diesels at 5% power would not significantly increase the risk of low-power operation. Nevertheless, one of the contributors to that risk is some very low probability environmental events. That risk is reduced if the reliability of the TDI diesel generator is enhanced. Consequently, it is appropriate to have increased assurance as to reliable onsite power. Moreover, for full-power operation, a high degree of reliability is required for the diesel generators. The most appropriate method to obtain information about the specific conditions of the diesel generators at Grand Gulf is to disassemble and inspect the diesel generator which has been operating the longest. The public interest requires that the questions about the reliability of the Grand Gulf diesel generators be resolved promptly. While these questions are being resolved, there is a need to enhance the availability of other sources of power supplied to the macility.

Therefore, the public health, safety and interest require that the diesel generator with the most hours of operation be inspected prior to proceeding above 5% power and that while this diesel is disassembled, the licensees provide additional power supplies and compensatory actions set forth in this order. Attachment 4 is the staff's safety evaluation for operation under the present low power license with one diesel generator undergoing inspection.

IV.

Accordingly, pursuant to sections 103, 161i, 161o, 182 and 186 of the Atomic Energy Act of 1954, as amended, and the Commission's regulations

- 2 -

III.

in 10 CFR Parts 2 and 50, it is hereby ordered, effective immediately, that:

- A. 1. The Division 1 TDI diesel generator shall be disassembled for inspection within 10 days of the date of this Order in accordance with Attachment 2 which describes the components to be inspected and the inspections to be performed.
  - 2. All defective parts found shall be replaced prior to declaring the engine operable. The engine block and engine base may be excepted if indications are non-critical. Non-critical indications are defined as not causing oil or water leakage, not propagating, or not adversely affecting cylinder liners or stud holes.
  - 3. Preoperational testing must be performed on the inspected engine prior to declaring it operable. This phase of testing shall include the manufacturer's preoperational test recommendations and the following elements, if they are not already included in the manufacturer's recommendations, unless they would not be recommended by the manufacturer in order to satisfy operability requirements.
    - 10 modified starts to 40% load
    - 2 fast starts to 70% load
    - 1 24-hour run at 70% load

A modified start is defined as a start including a prelube period as recommended by the manufacturer and a 3 to 5 minute loading to the specified load level and run for a minimum of one hour. The fast starts are "black starts" conducted from the control room on simulation of an ESF signal with the engine on ready standby status. The engine shall be loaded to 70% and run for 4 hours at this load on each fast start

- 3 -

test. The 24-hour performance run is required to detect abnormal temperatures and/or temperature excursions that might indicate abnormal engine behavior. Either a modified or quick start may be utilized.

Should these tests not be performed satisfactorily at the first attempt, i.e., the 10 modified starts shall be performed successively with no failure, the NRC shall be notified within 24 hours. A failure is defined as an inability of the engine to start, or an abnormal condition during the respective run which would ultimately preclude the engine from continuing to operate.

- B. The licensees shall not operate the Grand Gulf facility under the terms of License No. NPF-13 unless such operation is in conformance with the revised interim technical specifications appended to this Order. (Attachment 3)
- C. The Director, Division of Licensing may terminate in writing any of the preceding conditions for good cause.

٧.

Within 20 days of the date of this Order, the licensees may request a hearing on this Order. Any request for a hearing on this Order must be filed within 20 days of the date of the Order with the Director, Office of Nuclear Reactor Regulation, U.S. Nuclear Regulatory Commission, Washington, D. C. 20555. A copy of the request shall also be sent to the Executive Legal Director at the same address. A request for a hearing shall not stay the immediate effectiveness of Section IV of this Order.

- 4 -

If the licensee requests a hearing on this Order, the Commission will issue an order designating the time and place of hearing. If a hearing is held, the issue to be considered at such a hearing shall be whether this Order should be sustained.

FOR THE NUCLEAR REGULATORY COMMISSION

Original Steward Mil

Harold R. Denton, Director Office of Nuclear Reactor Regulation

Attachments: (1) Staff Analysis (2) Inspection Description (3) Interim Technical Specifications (4) Safety Evaluation

Dated at Bethesda, Maryland this day of May, 1984.

	LB#4:DL MMiller:pob 5/ /84	LB#4:DL MDuncan 5/21/84	DHouston 5/21/84	SSPB:DL DHoffman 5/2/84	LB#47DL EAdensam 5/2 V84	ADTD-DL TNovak 562/84	-	
or	AD/SA:TDIPG:DL CBerlinger 5/2/84	AD754590 FMfrag11a 5/22/84	OELDCd Cyr JLiebermar 5/J2/84	0304 0415 5/20	enhut 18	D:NPB HDenton 5/22/84		
	D: DSI Harrightsen							

# ATTACHMENT 2

: ,

Inspection Plan for Division I Diesel Generator

ë

đ

TDI		Drawing										
Comp. #	Part Name	Part Number	Number	item /	Task Descriptions	Visual	Desn	NDE	Hdns	Torque C	omp.	Notes
02-360A	Cylinder Heads	03-360-03-0F	03-360-04		Inspect Valve Seating Surfaces and Fire Deck	x		UT* LP** MT***				Fire Deck & Nozzel Cavity Wall Thickness Valve Seats & Fire Deck Area
02-305 <b>A</b>	Engine Base Assembly	02-305-05-AA			LP Main Bearing Saddle Area and Visually Inspect Mating Surfaces	x		LP				Assemble Documentation, See Note 1
02-39 <b>0</b> 6	Rocker Arm Capscrews	02-390-01-0B	02-390-04	3	Verify Torque M.T. Capscrews & Verify Material			М.Т.	x	365 X ft-1bs		
02-315A	Lylinder Block	02-315-03-AE	02-315-500	1 1	Visual NDE Map for Baseline	x		LP*				Cylinder Block Mating Surface Bolt Hole Area See note 1
02-315E	Cylinder Head Studs	03-315-01-0A	02-315-500	1 8	Visually Inspect Head Studs, Material Hardness & Torque Verifi- cation on Studs	x			Х*	3600 X ft/1bs		* One Stud * Four Studs
02-3150	Cylinder Liners	02-315-02-0G	02-315-500	14	Visually Inspect Dimensional Material Verification	X*	X*		Х*	,	•	Cylinder Liners, See note 1
	Landing Area					X**	X**	LP**			•	* Landing Area

PROPOSED CGNS INSPECTION PLAN, DIV I D/G (See Note 1)

1

-

TDI			Drawing					Inspect			
Comp. Ø	Part Name	Part Number	Number	Item /	Task Descriptions	Visual	Dusn	NDE	Hdns	Torque Comp	. Notes
02-475C	Turbocharger Welds		02-475-22		Visual	x					Assemble Documentation
	Bracket-Bolting See note 1	GB-001-143 GB-001-117	02-475-22	3 13	Verify Torque Material	x				x x	Assemble Documentation See note 1
02-340A	Connecting Rod Boxes	02-340-05-AG	02-340-4780	19	Rod Box (out-of∽engine)	x	x	мт	x	x	<ul> <li>Female Thread: in Rod Box 6</li> <li>External Machined Surface, See note 1</li> </ul>
		02-340-04-AB		5	Rod Box Bolts (out-of-engine)			HT**		2600*** ft/lbs	** Conn Rod Bolt *** At Disassembly & Reassembly
02-340A	Connecting Rod Bushing (Wrist Pin)	R-3195	62-340-4780	10	NDE & Material Verification		x	I.P		x	
02-3408	Connecting Rod Bearing Shells	02-340-04-AU	02-340-05	3	RT Shells, Visual Inspection, & Dimensional Check	x	x	RT		2600* ft/1bs	RT to ASTM Standards * At Disassembly 6 Reassembly
02-340C	Pistons - Crowes Studs	03-341-04-AE 03-340-04-AE 03-341-04-AB		10	MT Skirts, Crowns á Studs		x	мт			
02-310A	Crankshaft	1A-5445	02-310-09	1	Torsiograph Deflection Test		x				Torsiograph
02-386B	Crankcase Covers: Gaskets & Bolting		02-386-01		Visual Inspect Verify Torque	x				x	N III

TABLE 1 PROPOSED GCNS INSPECTION PLAN, DIV I D/G (See Note 1)

-

TDI											
Com: 1	Part Name	Part Number	Number	Item #	Task Descriptions	Visual	Dmsn	NDE	anbh	Torque Comp.	Notes
02-365C	Fuel Oil Injection Tube	1A-2600	02-365-01	•	Visual Inspection for Leaks	x					Assemble Documentation
02-390C	Intake Exhaust Push Rods	02-390-06-AB	02-390-04	4	Visual	x					Friction Weld Assemble Documentation
02-390D	Connector Push Rods	02-390-07-AG	02-390-04	5	Visual	x					Fricition Weld Assemble Documentation
02-359	Air Start Valve Capscrews	GB-032-114	02-359-03	19	Visual		x				Assemble Docomentation, See note 1

PROPOSED CGNS INSPECTION PLAN, DIV I D/G (See note 1)

Note: 1. The NRC requires additional inspections for these components as identified in Table 2.

٩.

۹. .

## TABLE 2

## Additional Inspections Required by NRC

## Additional Inspection Required

Engine Base Assembly

Cylinder Block

· · · · ·

Cylinder Liners

Turbocharger Thrust Bearings

Air Start Valve Capscrews

Fastener torques should also be checked.

Visual and LP Inspection should also include liner lands of engine block.

LP inspection should also be performed. In addition, lightly hone any glazed areas of liners in accordance with the manufacturers recommendations.

Inspect for wear, check motor assembly axial clearances, check bearing oil flow rates per criteria employed by TDI Owners Group.

Torques should also be checked.

## ATTACHMENT 3 TO ORDER REQUIRING DIESEL GENERATOR INSPECTION FACILITY OPERATING LICENSE NO. NPF-13 Docket No. 50-416

: .

Replace the following pages of the appendix A Technical Specifications with the enclosed pages. The revised pages are identified by date of Order and contain a vertical line indicating the area of change. The corresponding reverse pages are also provided to maintain document completeness.

	nded age					verse age
3/4	8-1					
3/4	8-2					
3/4	8-2a					
3/4	8-3					
3/4	8-4					
3/4	8-5					
3/4	8-6					
3/4	8-7					
3/4	8-7a	(new	page)		3/4	8-8
3/4	8-9					
3/4	8-9a					
B3/4	8-1				B3/4	8-2

3/4.8.1 A.C. SOURCES

÷ .

A.C. SOURCES - OPERATING

## LIMITING CONDITION FOR OPERATION

3.8.1.1 As a minimum, the following A.C. electrical power sources shall be OPERABLE:

- a. Three physically independent circuits between the offsite transmission network and the onsite Class 1E distribution system, and
- b. Two separate and independent diesel generators, each with:
  - Separate day fuel tanks containing a minimum of 220 gallons of fuel.
  - 2. A separate fuel storage system containing a minimum of:
    - a) 48,000 gallons of fuel for diesel generator 12, and
    - b) 39,000 gallons of fuel for diesel generator 13.
  - A separate fuel transfer pump.
- c. The 6200 kW gas turbine generator system consisting of 3 gas turbines, with:
  - A separate day fuel tank containing a minimum of 300 gallons of fuel for each gas turbine, and
  - 2. A fuel storage system consisting of:
    - A makeup fuel tank containing a minimum of 300 gallons of fuel, and
    - b) A fuel storage tank containing a minimum of 52,000 gallons of fuel, and
    - c) A fuel transfer pump.

APPLICABILITY: OPERATIONAL CONDITIONS 1, 2, and 3.

#### ACTION:

a. With one offsite circuit of the above required A.C. electrical power sources inoperable, demonstrate the OPERABILITY of the remaining A.C. sources by performing Surveillance Requirements 4.8.1.1.1.a within two hours and 4.8.1.1.2.a.4, for one diesel generator at a time, within two hours and at least once per 8 hours thereafter, and 4.8.1.1.4.b.1 within two hours and at least once per 8 hours thereafter; restore all three offsite circuits to OPERABLE status within 72 hours or be in at least HOT SHUTDOWN within the next 12 hours and in COLD SHUTDOWN within the following 24 hours.

Order

#### LIMITING CONDITION FOR OPERA: ION (Continued)

## ACTION (Continued)

- b. With diesel generator 12 of the above required A.C. electrical power sources inoperable, demonstrate the OPERABILITY of the remaining A.C. sources by performing Surveillance Requirements 4.8.1.1.1.a within one hour and 4.8.1.1.2.a.4, for one diesel generator at a time, within two hours and at least once per 8 hours thereafter and 4.8.1.1.4.b.1 within 2 hours and at least once per 8 hours thereafter; restore diesel generator 12 to OPERABLE status within 72 hours or be in at least HOT SHUTDOWN within the next 12 hours and in COLD SHUTDOWN within the following 24 hours.
- c. With either diesel generator 12 or the gas turbine generator system of the above required A.C. electrical power sources imperable, in addition to ACTION b or d, above as applicable, verify within 2 hours that all required systems, subsystems, trains, components and devices that depend on diesel generator 12 or the gas turbine generator system as a source of emergency power are also OPERABLE; otherwise, be in at least HOT SHUTDOWN within the next 12 hours and in COLD SHUTDOWN within the following 24 hours.
- d. With the gas turbine generator system of the above required A.C. electrical power sources inoperable, demonstrate the OPERABILITY of the remaining A.C. sources by performing Surveillance Requirements 4.8.1.1.1.a and 4.8.1.1.2.a.4 within two hours and at least once per 8 hours thereafter; restore the gas turbine generator system to OPERABLE status within 72 hours or be in at least HOT SHUTDOWN within the next 12 hours and in COLD SHUTDOWN within the following 24 hours.
- e. With diesel generator 13 of the above required A.C. electrical power sources inoperable, demonstrate the OPERABILITY of the remaining A.C. sources by performing Surveillance Requirements 4.8.1.1.1.a within one hour and 4.8.1.1.2.a.4, for diesel generator 12, within two hours and at least once per 8 hours thereafter and 4.8.1.1.4.b.1 for the gas turbine generator system within two hours and at least once per 8 hours thereafter; restore the inoperable diesel generator 13 to OPERABLE status within 72 hours or declare the HPCS system inoperable and take the ACTION required by Specification 3.5.1.
- f. With a tornado or hurricane warning in effect:
  - Diesel generator 13 shall be demonstrated to be OPERABLE per Specification 4.8.1.1.2.a.4 within two hours and at least once per eight hours thereafter until the adverse weather condition warning has cleared.

#### LIMITING CONDITION FOR OPERATION (Continued)

## ACTION (Continued)

- Diesel generator 12 shall be started, brought to operating voltage and speed, and maintained running until the adverse weather condition warning has cleared.
- All three gas turbine generators shall be started, brought to rated voltage and speed, and maintained running until the adverse weather condition warning has cleared.
- g. With a tornado or hurricane watch in effect:
  - Diesel generator 13 shall be demonstrated to be OPERABLE per Specification 4.8.1.1.2.a.4 within two hours and at least once per eight hours thereafter until the adverse weather condition watch has cleared.
  - Diesel generator 12 shall be demonstrated to be OPERABLE per Specification 4.8.1.1.2.a.4 within two hours and at least once per eight hours thereafter until the adverse weather condition watch has cleared.
  - All three gas turbine generators shall be demonstrated to be OPERABLE per Specification 4.8.1.1.4.b.1 within two hours and at least once per 8 hours thereafter until the adverse weather condition watch has cleared.

Order

#### SURVEILLANCE REQUIREMENTS

4.8.1.1.1 Each of the above required independent circuits between the offsite transmission network and the onsite Class 1E distribution system shall be:

- a. Determined OPERABLE at least once per 7 days by verifying correct breaker alignments and indicated power availability, and
- b. Demonstrated OPERABLE at least once per 18 months during shutdown by manually transferring unit power supply from the normal circuit to the alternate circuit.

4.8.1.1.2 Each of the above required diesel generators shall be demonstrated OPERABLE:

- In accordance with the frequency specified in Table 4.8.1.1.2-1 on a STAGGERED TEST BASIS by:
  - 1. Verifying the fuel level in the day tank.
  - 2. Verifying the fuel level in the fuel storage tank.
  - 3. Verifying the fuel transfer pump starts and transfers fuel from the storage system to the day tank.
  - 4. Verifying the diesel starts from ambient condition and accelerates to at least 441 rpm for diesel generator 12 and 882 rpm for diesel | generator 13 in less than or equal to 10 seconds. The generator voltage and frequency shall be 4160 ± 416 volts and 60 ± 1.2 Hz within 10 seconds after the start signal. The diesel generator shall be started for this test by using one of the following signals:
    - a) Manual.
    - b) Simulated loss of offsite power by itself.
    - c) Simulated loss of offsite power in conjunction with an ESF actuation test signal.
    - d) An ESF actuation test signal by itself.
  - 5. Verifying the diesel generator is synchronized, loaded to greater than or equal to 7000 kW for diesel generator 12 and 3300 kW for diesel generator 13 in less than or equal to 60 seconds, and operates with these loads for at least 60 minutes.
  - Verifying the diesel generator is aligned to provide standby power to the associated emergency busses.
  - Verifying the pressure in all diesel generator air start receivers to be greater than or equal to:
    - a) 160 psig for diesel generator 12, and
    - b) 175 psig for diesel generator 13.
- b. At least once per 31 days and after each operation of the diesel where the period of operation was greater than or equal to 1 hour by checking for and removing accumulated water from the day fuel tanks.

## SURVEILLANCE REQUIREMENTS (Continued)

- c. At least once per 92 days and from new oil prior to addition to the storage tanks by verifying that a sample obtained in accordance with ASTM-D270-1975 has a water and sediment content of less than or equal to .05 volume percent and a kinematic viscosity @ 40°C of greater than or equal to 1.9 but less than or equal to 4.1 when tested in accordance with ASTM-D975-77, and an impurity level of less than 2 mg. of insolubles per 100 ml. when tested in accordance with ASTM-D2274-70, except that the test of new fuel for impurity level shall be performed within 7 days after addition of the new fuel to the storage tank.
- d. At least once per 18 months, during shutdown, by:
  - Subjecting the diesel to an inspection in accordance with procedures prepared in conjunction with its manufacturer's recommendations for this class of standby service.
  - 2. Verifying the diesel generator capability to reject a load of greater than or equal to 550 kW (RHR B/C Pump) for diesel generator 12, and greater than or equal to 2180 kW (HPCS Pump) for diesel generator 13 while maintaining less than or equal to 75% of the difference between nominal speed and the overspeed trip setpoint, or 15% above nominal, whichever is less.
  - Verifying the diesel generator capability to reject a load of 7000 kW for diesel generator 12 and 3300 kW for diesel generator 13 without tripping. The generator voltage shall not exceed 5000 volts during and following the load rejection.
  - 4. Simulating a loss of offsite power by itself, and:
    - a) For Division 2:
      - Verifying deenergization of the emergency busses and load shedding from the emergency busses.
      - 2) Verifying the diesel generator starts on the auto-start signal, energizes the emergency busses with permanently connected loads within 10 seconds, energizes the auto-connected shutdown loads through the load sequencer and operates for greater than or equal to 5 minutes while its generator is loaded with the shutdown loads. After energization, the steady state voltage and frequency of the emergency busses shall be maintained at 4160  $\pm$  416 volts and 60  $\pm$  1.2 Hz during this test.
    - b) For Division 3:
      - 1) Verifying de-energization of the emergency bus.
      - 2) Verifying the diesel generator starts on the auto-start signal, energizes the emergency bus with the loads within 10 seconds and operates for greater than or equal to 5 minutes while its generator is loaded with the shutdown loads. After energization, the steady state voltage and frequency of the emergency bus shall be maintained at 4160  $\pm$  416 volts and 60  $\pm$  1.2 Hz during this test.

Order

#### SURVEILLANCE REQUIREMENTS (Continued)

- 5. Verifying that on an ECCS actuation test signal, without loss of offsite power, the diesel generator starts on the auto-start signal and operates on standby for greater than or equal to 5 minutes. The generator voltage and frequency shall be 4160  $\pm$ 416 volts and 60  $\pm$  1.2 Hz within 10 seconds after the auto-start signal; the steady state generator voltage and frequency shall be maintained within these limits during this test.
- Verifying that on a simulated loss of the diesel generator, with offsite power not available:
  - a. For Division 2:
    - 1. The loads are shed from emergency busses associated with Diesel Generator 12.
    - 2. Subsequent loading of the diesel generators is in accordance with design requirements.
  - b. For Division 3:
    - The associated output breaker for Diesel Generator 13 opens automatically.
    - Subsequent loading of the diesel generator is in accordance with design requirements.
- Simulating a loss of offsite power in conjunction with an ECCS actuation test signal, and:
  - a) For Division 2:
    - Verifying deenergization of the emergency busses and load shedding from the emergency busses.
    - 2) Verifying the diesel generator starts on the auto-start signal, energizes the emergency busses with permanently connected loads within 10 seconds, energizes the autoconnected shutdown loads through the load sequencer and operates for greater than or equal to 5 minutes while its generator is loaded with the emergency loads. After energization, the steady state voltage and frequency of the emergency busses shall be maintained at 4160 ± 416 volts and 60 ± 1.2 Hz during this test.
  - b) For Division 3:
    - 1) Verifying de-energization of the emergency bus.
    - 2) Verifying the diesel generator starts on the auto-start signal, energizes the emergency bus with the permanently connected loads within 10 seconds and the autoconnected emergency loads within 20 seconds and operates for greater than or equal to 5 minutes while its generator is loaded with the emergency loads. After energization, the steady state voltage and frequency of the emergency bus shall be maintained at 4160  $\pm$  416 volts and 60  $\pm$  1.2 Hz during this test.

#### SURVEILLANCE REQUIREMENTS (Continued)

- Verifying that all automatic diesel generator trips are automatically bypassed upon an ECCS actuation signal except:
  - For Division 2, engine overspeed, generator differential current, low lube oil pressure, and generator ground overcurrent.
  - For Division 3, engine overspeed and generator differential current.
- 9. Verifying the diesel generator operates for at least 24 hours. During the first 2 hours of this test, the diesel generator shall be loaded to greater than or equal to 7700 kW for diesel generator 12 and 3630 kW for diesel generator 13 and during the remaining 22 hours of this test, the diesel generator shall be loaded to 7000 kW for diesel generator 12 and 3300 kW for diesel generator 13. The generator voltage and frequency shall be 4160 ± 416 volts and 60 ± 1.2 Hz within 10 seconds after the start signal; the steady state generator voltage and frequency shall be maintained within these limits during this test. Within 5 minutes after completing this 24-hour test, perform Surveillance Requirement 4.8.1.1.2.d.7.a).2) and b).2)\*.
- Verifying that the auto-connected loads to each diesel generator do not exceed the continuous rating of 7000 kW for diesel generator 12 and 3300 kW for diesel generator 13.
- 11. Verifying the diesel generator's capability to:
  - Synchronize with the offsite power source while the generator is loaded with its emergency loads upon a simulated restoration of offsite power,
  - b) Transfer its loads to the offsite power source, and
  - c) Be restored to its standby status.
- 12. Verifying that with the diesel generator operating in a test mode and connected to its bus that a simulated ECCS actuation signal:
  - a) For Division 2, overrides the test mode by returning the diesel generator to standby operation.
  - b) For Division 3, overrides the test mode by bypassing the diesel generator automatic trips per Surveillance Requirement 4.8.1.1.2.d.8.b).
- 13. Verifying that with all diesel generator air start receivers pressurized to less than or equal to 256 psig and the compressors secured, the diesel generator starts at least 5 times from ambient conditions and accelerates to at least 441 rpm for diesel generator 12 and 882 rpm for diesel generator 13 in less than or equal to 10 seconds.

GRAND GULF-UNIT 1

<sup>\*</sup>If Surveillance Requirement 4.8.1.1.2.d.4.a)2) or b)2) are not satisfactorily completed, it is not necessary to repeat the preceding 24 hour test. Instead, the diesel generator may be operated at rated load for one hour or until operating temperatures have stabilized.

: .

## SURVEILLANCE REQUIREMENTS (Continued)

- Verifying that the fuel transfer pump transfers fuel from each fuel storage tank to the day tank of each diesel via the installed lines.
- 15. Verifying that the automatic load sequence timer is OPERABLE with the interval between each load block within ± 10% of its design interval for diesel generator 12.
- 16. Verifying that the following diesel generator lockout features prevent diesel generator starting and/or trip the diesel generator only when required:
  - a) Generator loss of excitation.
  - b) Generator reverse power.
  - c) High jacket water temperature.
  - d) Generator overcurrent with voltage restraint.
  - e) Bus underfrequency (12 only).
  - f) Engine bearing temperature high (12 only).
  - g) Low turbo charger oil pressure (12 only).
  - h) High vibration (12 only).
  - i) High lube oil temperature (12 only).
  - j) Low lube oil pressure (13 only).
  - k) High crankcase pressure.
- e. At least once per 10 years or after any modifications which could affect diesel generator interdependence by starting all three diesel generators simultaneously, during shutdown, and verifying that the three diesel generators accelerate to at least 441 rpm for diesel generator 12 and 882 rpm for diesel generator 13 in less than or equal to 10 seconds.
- f. At least once per 10 years by:
  - 1. Draining each fuel oil storage tank, removing the accumulated sediment and cleaning the tank using a sodium hypochlorite or equivalent solution, and
  - Performing a pressure test of those portions of the diesel fuel oil system designed to Section III, subsection ND of the ASME Code in accordance with ASME Code Section 11, Article IWD-5000.

4.8.1.1.3 <u>Reports</u> - All diesel generator failures, valid or non-valid, shall be reported to the Commission pursuant to Specification 6.9.1. Reports of diesel generator failures shall include the information recommended in Regulatory Position C.3.b of Regulatory Guide 1.108, Revision 1, August 1977. If the number of failures in the last 100 valid tests, on a per nuclear unit basis, is greater than or equal to 7, the report shall be supplemented to include the additional information recommended in Regulatory Position C.3.b of Regulatory Guide 1.108, Revision 1, August 1977.

#### SURVEILLANCE REQUIREMENTS (Continued)

- 4.8.1.1.4 The gas turbine generator system shall be demonstrated OPERABLE:
  - a. At least once per 15 days by verifying that all three gas turbine generators start and attain rated speed and voltage in less than or equal to 25 minutes and can be run for at least 60 minutes.
  - b. At least once per 31 days by verifying:
    - 1. that all three gas turbine generators start and attain rated speed and voltage in less than or equal to 25 minutes, and
    - that the gas turbine system can be synchronized and loaded to greater than or equal to 4700 kW and can operate with this load for at least 60 minutes.
  - c. At least once per 31 days by verifying:
    - the fuel level in each of the three gas turbine generator day tanks,
    - the fuel level in the fuel storage tank supplying make-up to the gas turbine generator system, and
    - the OPERABILITY of the fuel transfer pump between the gas turbine generator system make-up tank and the fuel storage tank supplying make-up to the gas turbine generator system.
  - d. At least once every 60 days and prior to the addition of fuel to the fuel storage tank supplying make-up to the gas turbine generator system, fuel oil samples shall be drawn from the fuel storage tank supplying make-up to the gas turbine generator system and analyzed to verify that the makeup fuel oil meets the standards set forth in Specification 4.8.1.1.2.c.

1520

## TABLE 4.8.1.1.2-1

#### DIESEL GENERATOR TEST SCHEDULE

		Test	Freque	ency			
1	At	least	once	per	31	days	
2	At	least	once	per	14	days	
3	At	least	once	per	7 (	days	
4	At	least	once	per	3 (	days	
	ilures in <u>lid Tests*</u> 1 2 3 4	id Tests* 1 At 2 At 3 At	id Tests*Test I1At least2At least3At least	id Tests*Test Frequence1At least once2At least once3At least once	id Tests*Test Frequency1At least once per2At least once per3At least once per	id Tests*Test Frequency1At least once per 312At least once per 143At least once per 7 of	id Tests*Test Frequency1At least once per 31 days2At least once per 14 days3At least once per 7 days

\*Criteria for determining number of failures and number of valid test shall be in accordance with Regulatory Position C.2.e of Regulatory Guide 1.108, Revision 1, August 1977, where the last 100 tests are determined on a per nuclear unit basis. For the purposes of this test schedule, only valid tests conducted after the OL issuance date shall be included in the computation of the "last 100 valid tests." Entry into this test schedule shall be made at the 31 day test frequency.

## A.C. SOURCES - SHUTDOWN

#### LIMITING CONDITION FOR OPERATION

3.8.1.2 As a minimum, the following A.C. electrical power sources shall be OPERABLE:

- a. One circuit between the offsite transmission network and the onsite Class IE distribution system, and
- b. Diesel generator 12, and diesel generator 13 when the HPCS system is required to be OPERABLE, with each diesel generator having:
  - 1. A day tank containing a minimum of 220 gallons of fuel.
  - 2. A fuel storage system containing a minimum of:
    - a) 48,000 gallons of fuel each for diesel generator 12.
    - b) 39,000 gallons of fuel for diesel generator 13.
  - 3. A fuel transfer pump.
- c. The 6200 kW gas turbine generator system consisting of 3 gas turbines, with:
  - A separate day fuel tank containing a minimum of 300 gallons of fuel for each gas turbine, and
  - 2. A fuel storage system consisting of:
    - A makeup fuel tank containing a minimum of 300 gallons of fuel, and
    - b) A fuel storage tank containing a minimum of 52,000 gallons of fuel, and
    - c) a fuel transfer pump.

APPLIC^BILITY: OPERATIONAL CONDITIONS 4, 5 and \*.

#### ACTION:

- a. With all offsite circuits inoperable and/or with diesel generator 12 or the gas turbine generator system of the above required A.C. electrical power sources inoperable, suspend CORE ALTERATIONS, handling of irradiated fuel in the primary or secondary containment, operations with a potential for draining the reactor vessel and crane operations over the spent fuel storage pool when fuel assemblies are stored therein. In addition, when in OPERATIONAL CONDITION 5 with the water level less than 23 feet above the reactor pressure vessel flange, immediately initiate corrective action to restore the required power sources to OPERABLE status as soon as practical.
- b. With diesel generator 13 of the above required A.C. electrical power sources inoperable, restore the inoperable diesel generator 13 to OPERABLE status within 72 hours or declare the HPCS system inoperable and take the ACTION required by Specification 3.5.2 and 3.5.3.
- c. The provisions of Specification 3.0.3 are not applicable.

\*When handling irradiated fuel in the primary or secondary containment. GRAND GULF-UNIT 1 3/4 8-9

Order

\* •

## SURVEILLANCE REQUIREMENTS (Continued)

4.8.1.2 At least the above required A.C. electrical power sources shall be demonstrated OPERABLE per Surveillance Requirements 4.8.1.1.1, 4.8.1.1.2, 4.8.1.1.3 and 4.8.1.1.4, except for the requirement of 4.8.1.1.2.a.5.

MAY 2 2 1984

#### BASES

### 3/4.8.1, 3/4.8.2 and 3/4.8.3 A.C. SOURCES, D.C. SOURCES and ONSITE POWER DISTRIBUTION SYSTEMS

(The following bases are developed for low power operation while diesel generator 11 is out of service for disassembly and inspection.)

The OPERABILITY of the A.C. and D.C. power sources and associated distribution systems during operation ensures that sufficient power will be available to supply the safety related equipment required for (1) the safe shutdown of the facility and (2) the mitigation and control of accident conditions within the facility. The minimum specified independent and redundant A.C. and D.C. power sources and distribution systems satisfy these systems requirements for capacity, capability, and redundancy needed for safe plant shutdown.

The ACTION requirements specified for the levels of degradation of the power sources provide restriction upon continued facility operation commensurate with the level of degradation. The OPERABILITY of the power sources are consistent with the initial condition assumptions of the accident analyses and are based upon maintaining at least Division 2 of the onsite A.C. or the gas turbine generator system and D.C. power sources and associated distribution systems OPERABLE during accident conditions coincident with an assumed loss of offsite power and single failure of the other onsite A.C. source. Division 3 supplies the high pressure core spray (HPCS) system only.

The A.C. and D.C. source allowable out-of-service times are based on Regulatory Guide 1.93, "Availability of Electrical Power Sources", December 1974. When diesel generator 12 or gas turbine generator system is inoperable, there is an additional ACTION requirement to verify that all required systems, subsystems, trains, components and devices, that depend on the remaining OPERABLE diesel generator 12 or gas turbine generator system as a source of emergency power, are also OPERABLE. This requirement is intended to provide assurance that a loss of offsite power event will not result in a complete loss of safety function of critical systems during the period diesel generator 12 or gas turbine generator system is inoperable. The term verify as used in this context means to administratively check by examining logs or other information to determine if certain components are out-of-service for maintenance or other reasons. It does not mean to perform the surveillance requirements needed to demonstrate the OPERABILITY of the component.

The OPERABILITY of the minimum specified A.C. and D.C. power sources and associated distribution systems during shutdown and refueling ensures that (1) the facility can be maintained in the shutdown or refueling condition for extended time periods and (2) sufficient instrumentation and control capability is available for monitoring and maintaining the unit status.

The surveillance requirements for demonstrating the OPERABILITY of the diesel generators are in accordance with the recommendations of Regulatory Guide 1.9, "Selection of Diesel Generator Set Capacity for Standby Power Supplies", March 10, 1971, Regulatory Guide 1.108, "Periodic Testing of Diesel Generator Units Used as Onsite Electric Power Systems at Nuclear Power Plants", Revision 1, August 1977 and Regulatory Guide 1.137" Fuel-Oil Systems for Standby Diesel Generators", Revision 1, October 1979.

GRAND GULF-UNIT 1

B 3/4 8-1

Order

#### BASES

## A.C. SOURCES, D.C. SOURCES and ONSITE POWER DISTRIBUTION SYSTEMS (Continued)

The surveillance requirements for demonstrating the OPERABILITY of the unit batteries are in accordance with the recommendations of Regulatory Guide 1.129 "Maintenance Testing and Replacement of Large Lead Storage Batteries for Nuclear Power Plants," February 1978, and IEEE Std 450-1980, "IEEE Recommended Practice for Maintenance, Testing, and Replacement of Large Lead Storage Batteries for Generating Stations and Substations.".

Verifying average electrolyte temperature above the minimum for which the battery was sized, total battery terminal voltage onfloat charge, connection resistance values and the performance of battery service and discharge tests ensures the effectiveness of the charging system, the ability to handle high discharge rates and compares the battery capacity at that time with the rated capacity.

Table 4.8.2.1-1 specifies the normal limits for each designated pilot cell and each connected cell for electrolyte level, float voltage and specific gravity. The limits for the designated pilot cells float voltage and specific gravity, greater than 2.13 volts and 0.015 below the manufacturer's full charge specific gravity or a battery charger current that had stabilized at a low talue, is characteristic of a charged cell with adequate capacity. The normal limits for each connected cell for float voltage and specific gravity, greater than 2.13 volts and not more than J.020 below the manufacturer's full charge specific gravity with an average specific gravity of all the connected cells not more than 0.010 below the manufacturer's full charge specific gravity, ensures the OPERABILITY and capability of the battery.

Operation with a battery cell's parameter outside the normal limit but within the allowable value specified in Table 4.8.2.1-1 is permitted for up to 7 days. During this 7 day period: (1) the allowable values for electrolyte level ensures no physical damage to the plates with an adequate electron transfer capability; (2) the allowable value for the average specific gravity of all the cells, not more than 0.020 below the manufacturer's recommended full charge specific gravity, ensures that the decrease in rating will be less than the safety margin provided in sizing; (3) the allowable value for an individual cell's specific gravity ensures that an individual cell's specific gravity will not be more than 0.040 below the manufacturer's full charge specific gravity and that the overall capability of the battery will be maintained within an acceptable limit; and (4) the allowable value for an individual cell's float voltage, greater than 2.07 volts, ensures the battery's capability to perform its design function.

## SAFETY EVALUATION REPORT RELATED TO ORDER REQUIRING DIESEL GENERATOR INSPECTION

GRAND GULF UNIT 1

#### 1.0 Introduction

As a basis for operation of Grand Gulf Unit 1 at full power, Mississippi Power & Light (MP&L) submitted reports dated February 20 and April 17, 1984, concerning the MP&L program to verify and enhance the reliability of the TDI diesel generators at Grand Gulf Unit 1. These submittals were in response to the NRC questions on the TDI issue and are supplemental to other MP&L responses to the NRC requests contained in letters to J. P. McGaughy dated October 31, 1983 and December 27, 1983. Additional actions taken by MP&L to verify and enhance the reliability of onsite/offsite AC power systems were documented by letter dated February 26, 1984.

Based on a review of this information and additional information provided during meetings between the NRC staff and MP&L, the staff informed MP&L by letter dated April 25, 1984, that the staff was unable to conclude that the proposed MP&L program for ensuring adequate TDI diesel engine reliability would be sufficient to support operation of Grand Gulf Unit 1 at power levels in excess of 5% of full power. The staff proposed additional actions to ensure adequate reliability of the TDI diesels including disassembly and inspection of at least one TDI diesel, subsequent preoperational testing of that engine, and additional maintenance and surveillance actions pertaining to the TDI diesels.

By letter dated May 6, 1984, MP&L submitted additional information to support its conclusions that there is little if any justification to require a disassembly inspection of a TDI diesel engine prior to the first refueling outage, and that adequate basis exists to support 100% power operation of Grand Gulf Unit 1 until the first refueling outage. The MP&L submittal also included an alternative proposal to disassemble and inspect the Division 1 TDI diesel generator in parallel with the conduct of the plant's power ascension program.

In their submittal of February 26, 1984, the licensee proposed to use gas turbines as supplemental AC sources to the onsite distribution systems. Therefore, during the period of time when one TDI diesel generator (Division 1) is unavailable due to disassembly and inspection of diesel engine components, the available AC power sources will be the offsite systems (115 KV and 500 KV networks), one TDI diesel generator (Division 2) and the gas turbine generators. Although the Division 2 TDI diesel generator will be maintained with current Technical Specifications, our review conservatively assumed both TDI diesel generators were not available.

This safety evaluation is based on the assumption that the reactor thermal power level will not exceed 5% power while one TDI diesel generator is un-available.

#### 2.0 Engine Disassembly, Inspection and Pre-Operational Testing

## 2.1 Discussion

Concerns regarding the reliability of large bore, medium speed diesel generators of the type supplied by TDI at Grand Gulf Unit 1 and 15 other domestic nuclear plants were first prompted by a crank shaft failure at Shoreham on September 1983. However, a broad pattern of deficiencies in critical engine components have since become evident at Shoreham, Grand Gulf Unit 1, and at other nuclear and non-nuclear facilities employing TDI diesel generators. These deficiencies stem from inadequacies in design, manufacture and QA/QC by TDI.

In response to these problems, eleven U.S. nuclear utility owners, including MP&L, formed a TDI diesel generator owners group to address operational and regulatory issues relative to diesel generator sets used for standby emergency power. The Owners Group program, which was initiated in October 1983, embodies three major efforts.

- Resolution of 16 known generic problem areas (Phase I program) intended by the Owners Group to serve as an interim basis for the licensing of plants
- Design review of important engine components and quality revalidation of important attributes for selected engine components (Phase II program)
- 3) Expanded engine testing and inspection

Pending the completion of the Owners Group program, MP&L has submitted a description of its program to enhance the reliability and performance of the two TDI diesel generators. This includes engineering evaluations, testing, and corrective actions taken in response to problems experienced during the startup testing phase of the plant, and other potential generic problems identified by the TDI Owners Group (i.e., the 16 known problem areas).

#### 2.2 Evaluation

Problems to date with TDI diesel generators stem from a broad pattern of design, manufacturing, and QA/QC inadequacies by TDI. For this reason the staff believes that the comprehensive approach of the Owners Group program to go beyond problems known to exist and to include a systematic review of critical engine components is essential for purposes of reestablishing full confidence in the reliability of the diesel engines.

Pending completion of the TDI Owners Group program, and the staff's review of the recommendations stemming from this program, the staff concludes that additional information is needed regarding the present condition of critical engine components to support interim operation of Grand Gulf Unit 1 at power levels in excess of 5% power. An engine disassembly and inspection in accordance with Section 2.2.1 below is needed to obtain the required information, and subsequent preoperational testing in accordance with Section 2.2.2 below is needed to verify that the engine has been properly reassembled. The staff's findings regarding the need for these actions are generally based on the following:

- Phase I of the Owners Group program which addresses the 16 known problems has not been completed. To date, the Owners Group has submitted reports addressing 8 of these potential problem areas for DSRV-16 engines. However, the staff review of the available Owners Group Reports has not yet been completed, and therefore the staff is unable to conclude that a final resolution to these potential problem areas is available. In addition, some of the Owners Group reports call for NDE inspections of components which have not yet been performed for GGNS (See Item 4 below).
- Owners Group Phase I reports still outstanding on the DSRV engines include reports on the connecting rods and the cylinder block. Little information has been provided to date regarding the specific causes of failures and/or cracks of these components.
- The Owners Group has not completed Phase II of its program consisting of a comprehensive design review and quality reverification of important engine components.
- 4) Verification (post-operational) NDE inspections have not been performed on a number of critical components originally included in the list of 16 known potential problems. These include:
  - pistons

· · . ·

- connecting rod bearings
- connecting rods
- wrist pin bushing
- engine block
- turbocharger thrust bearing

To date, these and other important engine components have experienced between 200 and 800 hours of service (for Div. 1 engine). Confirmation that these components are presently in an acceptable condition will provide needed confidence that these components will not cause an engine failure during the next 50 to 200 hours of anticipated engine running time before the first refueling outage. (It is anticipated that the Owners Group program and the staff findings stemming from its review of the program results will be complete by that time.) 5) Because of QA/QC deficiencies at TDI, the staff believes there may be significant differences in the "as manufactured" quality of engine components between the TDI engines at Grand Gulf and those of other plants with similarly designed engines. Therefore, it is difficult to draw conclusion relative to the Grand Gulf engines based on inspection results from other plants (e.g., Catawba).

## 2.2.1 Engine Disassembly and Inspection

The Division 1 engine (which has accumulated the most operating hours to date) should be disassembled for inspection of key components (identified below), prior to plant operation above 5% power. Action to be taken on the Division 2 engine would be contingent upon the results of the inspections conducted on the Division 1 engine and MP&L's ability to demonstrate, through a review of the manufacturer's QA records, that the two engines have similar "as-manufactured" quality.

The types of inspections to be performed should be similar to those conducted at Shoreham and Catawba (e.g., dye penetrant, eddy current, ultrasonic, radiography, etc.) as appropriate for each component based on the kinds of problems (e.g., cracks, abnormal wear or other distress, inadequate assembly or torquing) which have previously been experienced on these components at Grand Gulf Unit 1, Shoreham or other TDI engines. The staff concludes that the type and scope of inspections proposed by MP&L in their May 6, 1984 submittal (Table 1 of Attachment 2 to the Order) would be acceptable subject to the changes in Table 2 of Attachment 2 to the Order. All defective parts found shall be replaced prior to declaring the engine operable. The engine block and engine base may be excepted if indications are non-critical. Noncritical indications are defined as not causing oil or water leakage, not propagating, or not adversely affecting cylinder liners or stud holes.

A description of the inspections performed and the results should be submitted for NRC staff review prior to plant operation above 5% power. This report should address all indications found and the engineering basis for acceptance or rejection of the subject components.

2.2.2 Preoperational Testing Subsequent to Engine Disassembly and Inspection

Preoperational testing must be performed on the Division 1 engine following its disassembly, inspection and reassembly. In addition to adhering to the manufacturer's preoperational test recommendations, this phase of testing should include the elements listed below, if they are not already included in the manufacturer's recommendations, unless they would not be recommended by the manufacturer in order to satisfy operability requirements.

- 10 modified starts to 40% load
- 2 fast starts to 70% load
- 1 24-hour run at 70% load

A modified start is defined as a start including a prelube period as recommended by the manufacturer and a 3 to 5 minute loading to the specified load level and run for a minimum of one hour. The fast starts are "black starts" conducted from the control room on simulation of an ESF signal with the engine on ready standby status. The engine should be loaded to 70% and run for 4 hours at this load on each fast start test. The 24-hour performance run is suggested to detect abnormal temperatures and/or temperature excursions that might indicate engine distress. Either a modified or fast start may be utilized.

Should these tests not be performed satisfactorily at the first attempt, i.e., the 10 modified starts should be performed with no failure, the NRC staff will review the need for additional testing requirements. A failure is defined as an inability of the engine to start, or an abnormal condition during the respective run which would ultimately preclude the engine from continuing to operate.

2.2.3 Engine Maintenance and Surveillance Program

The staff will review MP&L's proposed maintenance, surveillance and inspection program as identified in MP&L's May 6, 1984 submittal prior to the issuance of a license for plant operation in excess of 5% power.

#### 2.3 Conclusion

· .

Pending the completion of the TDI Owners Group Program and the staff review of recommendations stemming from this program as they apply to Grand Gulf Unit 1, the staff concludes that a TDI diesel generator disassembly and inspection in accordance with Section 2.2.1 of this SER and subsequent preoperational testing of the affected engine(s) in accordance with Section 2.2.2 of this SER is needed to support operation of Grand Gulf Unit 1 at power levels in excess of 5% of full power. The staff will review MP&L's proposed maintenance, surveillance and inspection program and any needed license conditions prior to issuance of a full power license.

3.0 Interim Technical Specifications for AC Power Systems

3.1 Review Scope

We have reviewed the description of the 500 KV and 115 KV transmission lines, and the gas turbine generator set connected to the offsite system and evaluated their capacity, capability, reliability and redundancy. We have also reviewed the proposed technical specifications for AC power systems.

#### 3.2 Offsite Power

The offsite power system has previously been reviewed in the Safety Evaluation Report of the FSAR and was found to satisfy the capacity, capability, reliability and redundancy requirements and, therefore, is acceptable.

#### 3.3 Gas Turbine Generator

. .

The gas turbine generators (GTG) are presently installed at Grand Gulf near the Unit 2 diesel fuel oil storage tanks. This location will provide an advantageous electrical connection to the non-Class IE portion of the Unit 1 plant distribution system. The three units are connected in parallel through their associated circuit breaker to the non-Class IE 4160-volt distribution system which in turn feeds the Class IE 4160-volt buses. In view of the physical location of the gas turbines surrounded by large substantial structures it is highly unlikely that a tornado would damage the gas turbine simultaneously with both the 115 KV and the 500 KV offsite power sources. Therefore the gas turbine power source is expected to be available to the onsite distribution system to provide power to the safe shutdown loads for a tornado event which may damage the offsite power sources. Also, the location will prevent unavailability of the gas turbines due to flooding and normal standing water conditions.

The gas turbine generator set consists of three units. Two units have a capacity of 2000 KW each and third unit has a capacity of 2200 KW. Our review found that, of the three units, the combined two units, aggregate rating of 4000 KW, are sufficient to provide power to safe shutdown divisional loads of 3200 KW for long term cooling.

Each gas turbine has a separate auxiliary power unit (APU) for starting. A single APU can be used to start any one of the gas turbines. The gas turbine is designed for manual dead-line starting capability: i.e., the gas turbine is capable of starting and accelerating to rated speed and voltage by using an APU. After bringing all three units up to rated speed and voltage, the first unit's circuit breaker closes to a dead bus and the second and third units are synchronized in sequence to the first unit and thus become ready to provide power to the bus.

To demonstrate this capacity and starting capability following initial testing, the licensee will perform periodic tests which require that (1) at least once every 15 days, each GTG will be started, brought to rated speed and voltage, and run for at least 60 minutes; (2) at least once every 31 days, two of the GTG will be started, synchronized and loaded to 4700 KW in less than or equal to 25 minutes and operated with a load greater than or equal to 4700 KW for at least 60 minutes. The periodic tests and the interim surveillance requirement for the gas turbine generator in the proposed technical specification are equivalent to those for the emergency standby power supplies. We believe that these surveillance requirements on the gas turbine power supply are adequate for the period of time when one of TDI diesel generators is being inspected.

#### 3.4 Technical Specifications

 The current surveillance requirements and limiting conditions for operation (LCOs) for the offsite power sources and diesel generator No. 12 (DG #12) and diesel generator No. 13 (DG#13) remain the same.

- Surveillance requirements as stated in Section 3.3 of this evaluation and LCOs for the gas turbine generators are included in the interim technical specifications. (Attachment 3 to this Order)
- iii) Additional operability requirements for DGs #12, #13, and GTGs during tornado warning and watch conditions are also included in the interim technical specifications.

## 4.0 Overall Conclusion

The NRC staff, in attachment 1 to this Order, had concluded that total failure of the TDI diesels at Grand Gulf would not significantly increase the risk of the low power operation and that the risk is acceptably small. Nevertheless, the licensee has provided gas turbine generators to substitute for the out-of-service diesel generator during the period of inspection and subsequent preoperational testing.

Based on our evaluation of the available power sources and in view of the minimum power needs for low power operation, the staff finds that these sources (offsite, one TDI diesel and gas turbine generators) together with the specified surveillance requirements, represent a power system which has the capacity, capability, reliability, and redundancy for this low power level and that the health and safety of the public will not be endangered by implementation of this Order.