


POST OFFICE BOX 2951 \* BEAUMONT, TEXAS 77704

May 25, 1984 RBG-17920 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-453 Final Report/DR-147



Gulf States Utilities Company has completed its investigation of DR-147 concerning the end attachment of a pipe support component supplied by Bergen-Paterson and has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

J. E. Booker

Manager-Engineering,

L.a. Englandyor

Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site