

AREA CODE 409 838 6631

May 23, 1984 RBG-17900 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-108

Gulf States Utilities Company has completed its investigation of DR-108 concerning Bergen-Paterson supplied pipe support components and has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

L.G. Englandyn

J. E. Booker Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

IE-27

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

