## DUDIDUBURIDS

DEC 1 3 1991

Docket No. 50-346

Centerior Service Company ATTN: Mr. Donald Shelton Vice President Nuclear - Davis Besse c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652

Dear Mr. Shelton:

This refers to the routine safety inspection conducted by Messrs. W. Levis, R. K. Walton, and A. Dunlop of this office on October 29, 1991, through November 30, 1991, of activities at Davis-Besse Nuclear Power Station authorized by Facility Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Storz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by R. D. Lankebury Richard C. Knop, Chief Reactor Projects Branch 3

Enclosure: Inspection Report No. 50-346/91018(DRP)

See Attached Distribution

9112240126 911213 PDR ADOCK 05000346 9 PDR

## Centerior Service Company

DEC 1 3 1991

10

## Distribution:

CO W/enclosures: L. Storz, Plant Manager DCD/DCB (RIDS) OC/LFDCB Resident Inspector, RIII James R. Williams, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission

RII	I	
	lop	/pb

RIII Jackiw RIII Schumacher UN

2

RIII RDJ Knop LJBRI