

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201


BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

May 29, 1984
TXX-4178

Mr. E.H. Johnson, Chief
Reactor Project Branch 1
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket Nos.: 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
UNAUTHORIZED THERMOLAG INSTALLATION
QA FILE: CP-84-11, SDAR-135
FILE NO.: 10110



Dear Mr. Johnson:

On May 2, 1984, we verbally notified your Mr. D. Hunnicutt of a condition wherein additional thermolag was found in cable trays, between the cables and fire barrier envelope.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

Billy R. Clements

BRC:tlg

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8406050401 840529
PDR ADOCK 05000445
S PDR