Arizona Public Service Company P.O. BOX 21666 . PHOENIX, ARIZONA 85036 May 25, 1984 U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park

ANPP-29603-TDS/TRB

1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director Division of Resident Reactor Projects and Engineering Programs

Time Extension For Report - DER 84-11 Subject: A 50.55(e) Potentially Reportable Deficiency Relating To Conduit Used In PVMP Instrumentation Is Contaminated. File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Johnson and T. Bradish on March 8, 1984. (B) ANPP-29213, dated April 3, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by May 29, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by August 31, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director

EEVB/TRB:db

cc: See Page Two

15-2710

Mr. T. W. Bishop DER 84-11 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

B. S. Kaplan

L. A. Souza

D. E. Fowler

J. Vorees

J. R. Bynum

J. M. Allen

P. P. Klute

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

S. R. Frost

J. Self

D. Canady

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339