

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 215 327 1200 Ext. 2000

10CFR 50.73

August 18, 1995 Docket Nos. 50-352 50-353 License Nos. MPF-39 NPF-85

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Licensee Event Report SUBJECT:

Limerick Generating Station - Units 1 and 2

This LER reports actuations of the Unit 1 and Unit 2 Primary Containment and " actor Vessel Isolation Control Systems, reatures, resulting from the inadvertent Engineered Safe grounding of an ectrical lead during replacement of a keyswitch. The cause was due to unclear management expectations surrounding work activities having the potential of creating a ground or short circuit condition.

Reference:

Docket Nos. 50-352 50-353

Report Number:

2-95-007

Revision Number:

00

Event Date: Report Date:

July 20, 1995 August 18, 1995

Facility:

Limerick Generating Station P.O. Box 2300, Sanatoga, PA

19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(iv).

Very truly yours, www Boyce DMS: cah

T. T. Martin, Administrator Region I, USNRC N. S. Perry, USNRC Senior Resident Inspector, LGS 250022

PDR ADDCK 05000353