Docket Mos. 50-338, 50-339 License Nos. NPF-4, NPF-7

Virginia Electric and Power Company ATTN: Mr. W. L. Stewart Senior Vice President - Nuclear 5000 Dominion Boulevard Glen Allen, VA 23060

Gentlemen:

SUBJECT: NORTH ANNA SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (NRC INSPECTION REPORT NOS. 5U-338/91-25 AND 5C-339/91-25)

The KRC Systematic Assessment of Licensee Performance (SALP) has been completed for your North Anna facility. The facility was evaluated for the period September 1, 1990, through November 2, 1991. The results of the evaluation are documented in the enclosed Initial SALP Report. This report will be discussed at a public meeting to be held at the North Anna facility on January 27, 1992, at 1:00 p.m.

North Anna's performance was evaluated in the functional areas of Plant Operations, Radiological Controls, Maintenance/Surveillance, Emergency Preparedness, Security, Engineering/Sechnical Support and Safety Assessment/Quality Verification.

Activities at your North Anna facility were characterized by overall excellent safuty performance during the assessment period. Performance in the Engineering/Technical Support area declined, due in large measure to the level of technical support provided to procedures used in the Plant Operations and Maintenance/Surveillance areas. Although the Maintenance/Surveillance area did not change in overall performance rating, improved maintenance and outage performance was contrasted by procedure deficiencie; and missed tests. Overall performance in Plant Operations remained at an excellent level and resulted in no operational events of major significance. However, this area showed a decrining trend in performance as demonstrated primarily by in increase in the number of personnal errors and procedure deficiencies.

Several functional areas improved or remained at a superior level. The Radiological Controls area continued to improve, demonstrating that the program effectively controlled personnel exposure and protected the health and safety of the station workers and the general public. The Security area also improved, reflecting your efforts to upgride the security systems and your continued strong corporate and statio: support for the program. Two functional areas, Emergency Preparedness and Safety Assessment/Quality Verification maintained their superior level of performance. Improved performance in several activities was influenced significantly by initiatives implemented during the assessment period, such as the self-assessment programs, the upgrading of equipment material condition, and strong management trending programs.

Any comments you have concerning this evaluation should be submitted to this office by February 10, 1992. Your comments will be considered in the development of the Final SALP Report and will be issued, along with summary of our meeting, as an appendix to the Final SALP Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Original signed by

Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report - North Anna

c: w/encl: E. W. Harrell Vice President - Nuclear Operations Virginia Electric & Power Company 5000 Dominion Boulevard Glen Allen, VA 23060

J. P. O'Hanlon Vice President - Nuclear Services Virginia Electric & Power Company 5000 Dominion Boulevard Glen Allen, VA 23060

M. L. Bowling, Jr., Manager Nuclear Licensing Virginia Electric & Power Company 5000 Dominion Boulevard Glen Allen, VA 23060

G. E. Kane, Station Manager North Anna Power Station P. O. Box 402 Mineral, VA 23117

(cc w/encl cont'd - See page 3)

(cc w/encl cont'd)
Executive Vice President
Old Dominion Electric Cooperative
4201 Dominion Boulevard
Glen Allen, VA 23060

W. T. Lough Virginia Corporation Commission Division of Energy Regulation P. O. Box 1197 Richmond, VA 23209

William C. Porter, Jr. County Administrator Louisa County P. O. Box 160 Louisa, VA 23093

Michael W. Maupin, Esq. Hunton and Williams P. O. Br. 35 Richard L. 4 3212

Patrick A. O'r re
Office or the ttorney General
Supreme Court wilding
101 North Str. treet
Richmond, 5 23219

C. M. G. Buttery, M.D., M.P.H. Department of Health 109 Governor Street Richmond, VA 23219

Commonwealth of \ ginia

bcc w/encl:
The Chairman
K. C. Regers. Commissioner
J. R. Curtiss Commissioner
F. J. Remick, Commissioner
E. G. de Planque, Commissioner
J. M. Taylor, EDO
H. L. Thompson, Jr., EDO
J. F. Wechselberger, Regional
Coordinator, EDO
T. E. Murley, NRR
S. Varga, NRR
L. Engle, NRR

bcc w/encl cont'd: (See page 4)

bcc w/encl cont'd:
H. Berkow, NRR
F. Allenspach, SALP Coordinator, MRR
Regional Admini trators, RI, RIII
RIV, and RV
K. Clark, RII, PAO
M. Sinkule, DRP, RII
K. P. Fredrickson DRP, RII
J. Johnson, DEP, RII
INPO
L. Watson, Chief, TSS
NRC Resident Inspector
DRS and DRSS Branch Chiefs,
and Section Chiefs
Document Control Desk

NRC Resident Inspector U.S. Nuclear Regulatory Commission Route 2, Box 78-A Mineral, VA 23117

NRC Resident Inspector U.S. Nuclear Regulatory Commission Routes 1, Box 166 Surry, VA 23883

RII:DRP AVO PFredrickson 01/,0/91 RII: DRP

M. lesser

RII: DRP

W19

MSinkule

01/(0/91

RII:DBP RJIADAS
Johnson AGidson
01/0/91 01/0/91

Engle.

PS phr 01 N /91

HQ:NRR RII:ORA

MUSKOZ

HBerkow JMilhoan

01/0/91 01/ /91