## BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475 BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT CALVERT CLIPPS NUCLEAR POWER PLANT LUSBY, MARYLAND 20657

January 24, 1983

Office of Environmental Programs Waste Management Administration 201 West Preston Street Baltimore, Maryland 21201

Attention: Mr. Ronald Parise

Re: Maryland State Discharge Permit No. 74-DP-0187 and NPDES Permit No. MD 0002399

Dear Mr. Parise:

On January 12, 1983, outfall 001, monitoring point 101 experienced a total residual chlorine of about 3.0 ppm which is greater than the specification of 0.5 ppm. This condition existed for about 4 hours due to failure of a pump used to add the dechlorinating agent. Spare pumps are kept on site and allowed rapid corrective action once the problem was identified.

This matter had been communicated to you by telephone on January 13, 1983. Please feel free to call if you have any further questions.

Very truly yours,

L. B. Russell ' Plant Superintendent

LBR/EME/fcb

01270291 920116 R ADUCK 05000317