



PECO ENERGY

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
215 327 1200 Ex. 2000

10CFR50.73

August 28, 1995
Docket Nos. 50-352
50-353
License Nos. NPF-39
NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Units 1 and 2

This LER reports the inadvertent actuation of the Unit 1 and Unit 2 Primary Containment and Reactor Vessel Isolation Control Systems (PCRVICS), Engineered Safety Features, as a result of a blown Unit 1 PCRVICS fuse which occurred when a technician inadvertently grounded a starter screwdriver.

Reference:	Docket Nos. 50-352 50-353
Report Number:	1-95-004
Revision Number:	00
Event Date:	July 28, 1995
Report Date:	August 28, 1995
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(iv).

Very truly yours,

DMS:cah

cc: T. T. Martin, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

010045

9509010005 950828
PDR ADOCK 05000352
S PDR