

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

June 8, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-362
Licensee Event Reports Nos. 84-013, Revision 1 and 84-015, Revision 1
San Onofre Nuclear Generating Station, Unit 3

References: (1) Letter, J. G. Haynes (SCE) to USNRC Document Control Desk,
dated April 26, 1984, Licensee Event Report No. 84-013
(2) Letter, J. G. Haynes (SCE) to USNRC Document Control Desk,
dated May 29, 1984, Licensee Event Report No. 84-015

The referenced letters provided the required Licensee Event Reports (LER's) for occurrences involving the Reactor Coolant System (RCS) specific activity. In our continuing review of these events, a clerical error, which resulted in the omission of certain RCS chemistry data, was discovered. Please find enclosed LER 3-84-013, Revision 1 and LER 3-84-015, Revision 1, which have been revised to include all pertinent data.

If there are any questions regarding these revisions, please so advise.

Sincerely,

Enclosures: LER 84-013 Revision 1
LER 84-015 Revision 1

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

8406130182 840608
PDR ADDCK 05000362
S PDR

IE22
/1