

Meeting: 950167

Contact: Monte Phillips

Phone: 7088299637

Fax:

Date	Time
03/08/95- / /	02:30 PM-
/ / - / /	-
/ / - / /	-

Location: NRC Region III
801 Warrenville Road

City/ST.: Lisle IL

[Purpose of Meeting]

Discuss licensee's corrective action process: identify & address long-standing deficien-

[Comments]

cies; fix deficiencies; & identify, investigate & set priorities. Confirm mtg day before.

Docket/Facility: 050-00341/FERMI 2

[Offices]

RIII NRR

[Outside Organizations]

Detroit Edison Company

[N]ext Record or [Q]uit

Alt-Z FOR HELP | ANSI

| FDX | 9600 N81 | LOG CLOSED | PRINT OFF | ON-LINE

A/1

Meeting: 950294

Contact: Monte Phillips

Phone: 7088299637

Fax: 7085151102

Date	Time
04/07/95- / /	10:00 AM-12:00 PM
/ / - / /	-
/ / - / /	-

Location: NRC Region III
801 Warrenville Road

City/ST.: Lisle IL

[Purpose of Meeting]

Open enforcement conference to discuss apparent violations resulting in inoperable high pres-

[Comments]

sure coolant injection & reactor core isolation cooling high level trip functions.

Docket/Facility: 050-CJ341/FERMI 2
/
/

[Offices]

RIII
NRR
OE

[Outside Organizations]

Detroit Edison Company

[P]revious Record or [Q]uit

Alt-Z FOR HELP | ANSI

| FDX | 9600 N81 | LOG CLOSED | PRINT OFF | ON-LINE

A/2