

APPENDIX A

NOTICE OF VIOLATION

Kansas Gas and Electric Company
Wolf Creek Generating Station

Docket: 50-482/83-18
Permit: CPPR 147

Based on the results of an NRC investigation conducted during the period of November 30, 1982-January 14, 1983, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987, dated March 9, 1982, the following violation was identified:

Improper Substitution of Material in Safety-Related Pipe Hanger

10 CFR 50, Appendix B, Criterion VIII requires that, "Measures shall be established for the identification and control of materials, parts, and components, including partially fabricated assemblies. These measures shall assure that identification of the item is maintained by heat number, part number, serial number, or other appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item. These identification and control measures shall be designed to prevent the use of incorrect or defective material, parts, and components."

Contrary to the above, Piece 2 of Hanger BG04-C033 was removed on March 16-17, 1981, and replaced with scrap material which had been stamped with a heat number and hanger number to duplicate the numbers on the original piece.

This is a Severity Level IV Violation. (Supplement II) (482/8318-01)

Pursuant to the provisions of 10 CFR 2.201, Kansas Gas and Electric Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: June 23, 1983