RICHARD E. NEAL

COMMITTEE ON SMALL BUSINESS SUBCOMMITTEE ON REGULATION. BUSINESS OPPURTUNITIES AND ENERGY



COMMITTEE ON BANKING FINANCE AND URBAN AFFAIRS

SUBCOMMITTEE ON FINANCIAL INSTITUTIONS SUPERVISION, REGULATION AND INSURANCE

SUBCOMMITTEE ON INTERNATIONAL DEVELOPMENT FINANCE TRADE AND MONETARY POLICY

SUBCOMMITTEE ON HOUSING AND COMMUNITY DEVELOPMENT

Congress of the United States House of Representatives

Washington, DC 20515

December 18, 1991

Mr. Ivan Selin Chairman Nuclear Regulatory Commission Washington, D.C. 20555

Dear Chairman Selin:

I am writing to formally request an investigation by the Nuclear Regulatory Commission (NRC) into the accident that occurred on Interstate 91 in Springfield, Massachusetts, on December 16, 1991, in which a vehicle transporting radioactive uraniur dioxide pellets from Wilmington, Delaware, to the Vermont Yankee nuclear power plant in Vernon, Vermont, was completely destroyed.

While there was no apparent release of radiation from the collision, the accident did raise serious concerns about the transportation of radiocative nuclear materials on our nation's highways. Furthermore, the accident emphasizes the need for a re-examination of the advance notification policy for vehicles carrying nuclear cargo on public roadways.

The frequency with which radioactive nuclear material is transported on our nation's roads is increasing each year. Therefore, in an effort to prevent this type of accident from happening again, I urge you to initiate an investigation into the cause of the accident, and what implications it will have on future transportation of radioactive nuclear materials. I look forward to your response.

Sincerely,

RICHARD E. NEAL Member of Congress

CANNON HOUSE OFFICE BUILDING WASHINGTON DC 20515 (202) 225-5601

9202050437 920117 PDR COMMS NRCC CORRESPONDENCE PDR 1550 MAIN STREET FEDERAL BUILDING SPRINGFIELD, MA 01103 (413) 785-0325

PRINTED ON RECYCLED PAPER

881 MAIN STREET PHILBIN BUILDING FITCHBURG MA 01420 (508) 342-7822