DUDIDUB (REDS)

JAN 3 1 1992

Docket No. 50-461

Illinois Power Company ATTN: Mr. J. S. Perry Vice President Clinton Power Station Mail Code V-275 Post Office Box 678 Clinton, IL 61727

SUBJECT: NRC INSPECTION REPORT NO. 50-461/91023(DRP) AND NOTICE OF VIOLATION

Dear Mr Perry:

This refers to the routine safety inspection conducted by Messrs. P. G. Brochman, F. L. Brusn, J. A. Hopkins, and J. M. Ulie of this office from November 19 through December 30, 1991, of activities at Clinton Power Station, authorized by NRC Operating License No. NPF-62, and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required. Additi ally, we request that you supplement your response to the Notice of Violation with the results of your study to improve the reliability of the reactor coolant leakage detection system's fission product monitor (FPM). We would appreciate this submittal by June 1, 1992.

NRC is concerned with your overall performance on this particular issue, especially with the repeat occurrence on December 31, 1991. The fact that on numerous instances over the last 4 years, when the paper was found immobile or the maintenance task was performed on a periodicity in excess of the design capabilities of the FPM, the FPM was not recognized as being inoperable and the fact that the corrective action program failed to resolve this longstanding issue are of particular concern. We also believe that the performance by your engineering and maintenance staffs in understanding the design of the FPM and in creating, JEOL 1

9202060004 920131 PDR ADDCK 05000461 PDR

Illinois Power Company

16.1

JAN 3 1 1992

scheduling, and performing this preventative maintenance tasks was less than adequate.

2

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the *Paperwork Reduction Act* of 1980, Public Law 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by E. G. Greenzan

Edward G. Greenman, Director Division of Reactor Projects

Enclosures:

- 1. Notice of Violation
- Inspection Report No. 50-461/91023(DRP)

See Attached Distribution

RIII RIII RIII RIII RIII RIII ROFL RM ECK 260 Gregor Hopkins Lanksbury Creed Gardner Knop Enman 13992

Illinois Power Company

JAN 3 1 1992

3)

Distribution

cc w/enclosures: J. Cook, Manager - Clinton Power Station F. (pangenberg, III, Manager - Licensing and Safety DCD/DCB (RIDS) OC/LFDCB Clinton SRI A. Gody, Jr., NRR PM J. McCaffrey, Chief, Public Utilities Division Patricia O'Brien, Governor's Office of Consumer Services K. K. Berry, Licensing Services Manager General Electric Company S. Zabel, Esquire, Schiff, Hardin, & Waite Chairman, DeWitt County Board Illinois Department of Nuclear Safety Perry SRI Robert Newmann, Office of Public Counsel State of Illinois Center TSS, RIII

ø

3