

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01VP)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 Fax



DUKE POWER

DATE: August 31, 1995

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station Unit 1 and 2
Docket No. 50-369

Licensee Event Report 369/95-03, Revision 1
Problem Investigation Process No.: 2-M95-1225

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 369/95-03, Revision 1, concerning Failure Of The Turbochargers Associated With The Emergency Diesel Generators. This revision is being submitted to clarify corrective actions as discussed in the pre-decisional enforcement conference held on August 14, 1995. This event is assigned an NRC cause code of Design Oversight. This report is being submitted in accordance with 10 CFR 50.73 (a)(2)(i) and 10 CFR 50.73 (a)(2)(v). This report also satisfies the reporting requirements of 10 CFR 21 and Special Reporting requirements of Technical Specification 3.8.1.1.

Very truly yours,

T.C. McMeekin

RJD/bcb

Attachment

cc: Mr. S.D. Ebnetter
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. George Maxwell
NRC Resident Inspector
McGuire Nuclear Station

050040
9509080047 950831
PDR ADDCK 05000369
S PDR

bx: B.L. Walsh (EC11C)
Zack Taylor (CNS)
G.A. Copp (EC050)
J.I. Glenn (MG02-ME)
P.R. Herran (MG01VP)
Cindy Davis (MG01CP)
J. E. Burchfield (ONS Reg Compliance)
G.H. Savage (EC06E)
G.B. Swindlehurst (EC11-0842)
M.S. Tuckman (EC07H)
R.F. Cole (EC05N)
John Frye (EC05N)
Tim Becker (PB02L)
P.M. Abraham (EC08I)
Ronnie White (MG01VP)
L.V. Wilkie (ON03SR)
D.P. Kimball (CN05SR)
NSRB Support Staff (EC05N)
Kay Crane (MG01RC)
Rich Casler (EC05N)
Stuart Lindsey (MG02PE)