

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 18, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4


Re: Catawba Nuclear Station
Docket Nos. 56-413 and 50-414

Dear Mr. Denton:

Section 13.5.3 of the Catawba Safety Evaluation Report discusses License Condition 26, Modifications to Emergency Operating Instructions. On April 14, 1983, Duke Power provided a response to Supplement 1 to NUREG-0737 which included a description of the Emergency Procedure Upgrade Program for Catawba. Section 6.2.1 of that response described Duke Power's plans for incorporating the Westinghouse Emergency Response Guidelines (ERGs) into the Catawba Emergency Procedures.

On March 29, 1984, representatives from the Westinghouse Owners Group made a presentation to the NRC Staff describing the differences between the Basic and Revision 1 ERGs. The attached document describes and justifies the safety-significant deviations between the Catawba plant-specific Emergency Procedure Guidelines (ERGs) and Revision 1 of the Westinghouse Owners Group ERGs.

Very truly yours,



Hal B. Tucker

ROS/php

Attachment

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

NRC Resident Inspector
Catawba Nuclear Station

8406200036 840618
PDR ADOCK 05000413
F PDR

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

A003
11

Mr. Harold R. Denton, Director
June 18, 1984
Page 2

cc: Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207