



Donald C. Shelton
Vice President - Nuclear
Davis-Besse

300 Madison Avenue
Toledo, OH 43652-0001
(419) 249-2300

Document Number 50-346

License Number NPF-3

Serial Number 2012

February 6, 1992

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Summary Report for Seventh Refueling Outage Inservice
Inspection Activities
Davis-Besse Nuclear Power Station - Unit 1

Gentlemen:

In accordance with the 1986 Edition of the American Society of
Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section XI,
IWA-6000, enclosed is the subject report covering inservice inspection
activities and repairs and replacements completed through the end of
the Davis-Besse Nuclear Power Station, Unit 1 seventh refueling outage.

Should you have any questions regarding the enclosed reports, please
call Mr. R. W. Schrauder, Manager - Nuclear Licensing, at (419)
249-2366.

Very truly yours,

PWS/dlm

Enclosure

cc: A. B. Davis, Regional Administrator, NRC Region III
J. B. Hopkins, NRC Region III, DB-1 NRC Senior Project Manager
W. Levis, NRC Region III, DB-1 Senior Resident Inspector
Hartford Steam Boiler and Insurance Company (2)
State of Ohio
Utility Radiological Safety Board

9202110060 920206
PDR ADOCK 05000346
PDR

Operating Companies
Cleveland Electric Illuminating
Toledo Edison

AO47