FEB 0 4 1992

Docket No. 50-282 Docket No. 50-306

Northern States Power Company ATTN: Mr. L. R. Eliason Vice President, Nuclear Generation 414 Nicollet Mall Minneapolis, MN 55401

Dear Mr. Eliason:

This rc rs to the inspection conducted by Mr. G. L. Pirtle of this office between September 6 and December 27, 1991. The inspection included a review of activities authorized for your Prairie Island Nuclear Plant facility.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection. However, the NRC is continuing to review deficiencies noted in a contractor health physics security screening program, as noted in Sections 3 and 5.b of the Report Details.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Publi Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

L. Robert Greger, Chief Reactor Programs Branch

Enclosure: Inspection Reports No. 50-282/91021(DRSS); No. 50-306/91021(DRSS)

133

Belanger

See Attached Distribution

tie/da Madeda

RILL



Dibler Pawlik 2/4/92

FEB 0.4 1992

2

Northern States Power Company

Distribution

ġ.

cc w/enclosure: E. L. Watzl, Site Manager, Prairie Island S M. Sellman, Plant M ager DCD/DCB (RIDS) OC/LFDCB Resident Inspector, RIII Prairie Island Resident Inspector, RIII Monticello John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State of Minnesota Prairie Island, LPM, NRR Robert M. Thompson, Administrator Wisconsin Division of Emergency Government