83 DEC 12 P Becember 8, 1983

NUCLEAR PRODUCTION DEPARTMENT

U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0200/15525/15526 I.E. Report 416/83-38 of August 15-19 and August 30 -

September 1, 1983

AECM-83/0776

References:

- 1) MAEC-83/0317, September 30, 1983
- 2) AECM-83/0694, October 13, 1983

The following information is provided to supplement out previous response (Reference 2) to I.E. Report 83-38 (Reference 1).

Response to Violation 83-38-10:

Paragraph IV: Add the following:

"...and it is MP&L's philosophy that the activities stated be performed prior to the fire barriers being blocked open or removed.

Response to Violation 83-38-13:

Paragraph I: Insert the following before the last sentence:

"Subsequent inspection by MP&L of PQDR 00055-81 revealed that this PQDR was delinquent. During MP&L's inspection, it was verified that this PQDR had been responded to and verified closed."

8406220071 840330 PDR ADDCK 05000416 G PDR

MISSISSIPPI POWER & LIGHT COMPANY

Paragraph II: Delete all and replace with:

Plant Administrative Procedure 01-S-03-2, "Plant Quality Deficiency Reports," failed to provide guidance for escalation of PQDR's to plant management which were not being responded to in a timely manner.

Yours truly,

L. F. Dale

Manager of Nuclear Services

PRH: 1m

cc: Mr. J. B. Richard

Mr. R. B. McGehee

Mr. T. B. Conner

Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555