Hicial JAN 16 1992 Docket Nos. 50-335, 50-389 License Nos. DPR-67, NPF-16 Fiorida Power and Light Company ATTN: Mr. J. H. Goldberg President - Nuclear P. O. Box 14000 Juno Beach, FL 33408-0420 Gentlemen: SUBJECT: CORRECTED COPY NRC INSPECTION REPORT NOS. 50-335/91-26 AND 50-389/91-26 This refers to our inspection report which was issued on January 14, 1992. Due to an administrative error, the Report Numbers listed on the cover letter were incorrect and should have been 50-335/91-26 and 50-389/91-26 versus 50-369/91-26 and 50-370/91-26. Please replace with the enclosed corrected copy. We are sorry for the inconvenience. Sincerely, Douglas M. Collins, Chief Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards Enclosure: Cover Letter cc w/encl: D. A. Sager, Vice President St. Lucie Nuclear Plant P. O. Box 128 Ft. Pierce, FL 34954-0128 R. E. Grazio, Director Nuclear Licensing Florida Power and Light Co. P. O. Box 14000 Juno Beach, FL 33408-0420 cc w/encl: (Cont'd on page 2)

9202140173 920116 PDR ADOCK 05000335

IE04

cc w/encl: (Cont'd) G. J. Boissy, Plant Manager St. Lucie Nuclear Plant P. O. Box 128 Ft. Pierce, FL 34954-0128

cc w/Inspection Summary: Harold F. Reis, Esq. Newman & Holtzinger 1615 'Street, NW Washington, D. C. 20036

John T. Butler, Esq. Steel, Hector and Davis 400 Southeast Financial Center Miami, FL 33131-2398

Jacob Daniel Nash Office of Radiation Control Department of Health and Rehabilitative Services 1317 Winewood Boulevard Tallahassee, FL 32399-0700

Administrator Department of Environmental Regulation Power Plant Siting Section State of Florida Twin Towers 2600 Blair Stone Road Tallalissee, FL 32301

Jack Shreve Public Counsel Office of the Public Counsel c/o The Forida Legislature 111 West Madison Ave., Room 812 Tallahassee, FL 32399-1400

Robert G. Nave, Director Emergency Management Department of Community Affairs 2740 Centerview Drive Tallahassee,FL 32399-2100

cc w/encl: (Cont'd on page 3)

cc w/encl: (Cont'd) James V. Chisholm County Administrator St. Lucie County 2300 Virginia Avenue, Fort Pierce, FL 34982

Charles B. Brinkman Washington Nuclear Operations ABB Combustion Engineering, Inc. 12300 Twinbrook Parkway, Suite 3300 Rockville, MD 20852

State of Florida

bcc w/encl: NRR/DRIS/SB

Document Control Desk (RIDS 1E04), 016 KLandis

U. S. Nuclear Regulatory (ission Senior Resident Inspector 7585 South Highway AlA Jensen Beach, FL 33457

RII: DRSS On My KStansberry 51 NG92

Der DMcGuire 1 /16/92

RII: DRSS RIL: DRP

SAFEGUARDS INFORMATION

JAN 1 4 1992

Docket Nos. 50-335, 50-389 License Nos. DPR-67, NPF-16

Florida Power and Light Company ATTN: Mr. J. H. Goldberg President - Nuclear P. O. Box 14000 Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS, 50-335/91-26 AND 50-389/91-26

This refers to the inspection conducted by W. W. Stansberry of this office on December 16-20, 1991. The inspection included a review of activities authorized for your St. Lucie facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observation of activities in progress.

Within the scope of the inspection, violations or deviations were not identified.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will \underline{not} be placed in the Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

151

Douglas M. Collins, Chief Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

Enclosure: (See page 2)

9201210085

SAFEGUARDS INFORMATION

Document transmitted horavith contains sensitive unclassified information. When separated from enclosures, this document is decontrolled.