

GPU Nuclear Corporation
Post Office Box 480
Route 441 South
Middletown, Pennsylvania 17057-0191
717 944-7621
TELEX 84-2386
Writer's Direct Dial Number:

(717) 948-8005

February 13, 1992
C311-92-2014

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
Inservice Inspection (ISI) Data Reports

In accordance with 10CFR 50.55a(g) and TMI-1 Technical Specifications, enclosed are GPU Nuclear's Forms NIS-1, "Owner's Data Report for Inservice Inspection" and NIS-2 "Owner's Data Report for Repairs or Replacements."

Two NIS-1 Forms are enclosed. One NIS-1 Form covers ISI first interval examinations conducted between March 5, 1990 and November 15, 1991 which were conducted in accordance with the ASME Code, Section I, 1974 Edition through Summer 1975 Addenda. The second NIS-1 Form covers ISI second interval examinations conducted between April 19, 1991 through November 15, 1991 in accordance with the ASME Code, Section XI, 1986 Edition with no Addenda. Table 1 of the NIS-1 provides an abstract of the examinations performed. Table 2 provides an abstract of the corrective measures recommended and taken. All conditions listed on Table 2, where Code acceptance criteria were exceeded, were determined to be operable upon inspection and evaluation. Repairs were performed as indicated in the table to meet Code requirements. These reports are being submitted in compliance with Subarticle IWA-6220 of the Code.

The enclosed NIS-2 reports cover those repairs or replacements where the documentation was completed between April 4, 1990 and January 10, 1992. In accordance with Subarticle IWA-6220, only the NIS-2 reports describing Class 1 or 2 component repairs or replacements need be submitted.


9202200044 920213
PDR ADOCK 05000289
Q PDR

AD-47 1/1

Document Control Desk
C311-92-2014
Page 2

Reports completed after January 10, 1992 will be included with our next submittal after the Cycle 10 refueling outage.

Sincerely,



T. G. Broughton
Vice President and Director, TMI-1

Enclosures
MRK

cc: Region I Administrator
TMI-1 Senior Project Manager
TMI Senior Resident Inspector
PA DOLI
Hartford Steam Boiler I&I Co.