

APPENDIX A

NOTICE OF VIOLATION

Arkansas Power & Light Company
Arkansas Nuclear One, Units 1 and 2 (ANO)

Dockets: 50-313/84-09
50-368/84-09

Licenses: DPR-51
NPF-6

Based on the results of an NRC inspection conducted during the period of March 26-April 6, 1984, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 49 FR 8583, dated March 8, 1984, the following violation was identified:

Procedure Compliance

Both Unit 1 (50-313) Technical Specification 6.10 and Unit 2 (50-368) Technical Specification 6.11, "Radiation Protection Program," require that: "Procedures for personnel radiation protection shall be prepared . . . and adhered to for all operations involving . . . exposure."

Additionally, ANO Health Physics Operating Procedure 1632.021, "TLD Calibration and Performance Certification," Revision 3, requires that upon completion of the performance test for the fourth quarter of the current calendar year, an annual performance test should be made.

Contrary to the above, the fourth quarter performance test was completed on November 21, 1983, and as of April 6, 1984, the annual performance test had not been made.

This is a Severity Level V Violation. (Supplement IV) (313/8409-01; 368/8409-01)

Pursuant to the provisions of 10 CFR 2.201, Arkansas Power and Light Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: MAY 10 1984

8406250107 840510
PDR ADDCK 05000313
G PDR