Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

10

.

License No. CPPR-132; CPPR-133

As a result of the inspection conducted on April 9-13, 18-20 and 24-26, 1984, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, Criterion XVII as implemented by CE-1-A Corporate Nuclear Quality Assurance Manual Section 17, (and by Hatfield Procedures #1 and #1?) require that inspection records shall identify the Sargent & Lundy drawings used by the inspectors to inspect for proper equipment installation.

Contrary to the above, Hatfield Electric Company (HECo) equipment installation inspection reports 1 thru 100 had no reference to S&L drawings and revisions used to perform inspections of electrical equipment installation.

This is a Severity Level V violation (Supplement IID).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUN 1 2 1984

Dated

treater For

R. L. Spessard, Director Division of Engineering

B406260207 B40612 PDR ADOCK 05000454 0 PDR