

September 21, 1995

Mr. Ross P. Barkhurst  
Vice President Operations  
Entergy Operations, Inc.  
P.O. Box B  
Killona, LA 70066

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION (RAI) - GENERIC LETTER (GL) 95-03  
"CIRCUMFERENCIAL CRACKING OF STEAM GENERATOR TUBES" (TAC NO. M92288)

Dear Mr. Barkhurst:

On April 28, 1995, the U.S. Nuclear Regulatory Commission issued GL 95-03 "Circumferential Cracking of Steam Generator Tubes" which requested addressees to evaluate recent operating experience related to circumferential cracking, justify continued operation until the next scheduled steam generator tube inspections, and to develop plans for the next steam generator tube inspections. After reviewing your response dated June 27, 1995, the staff requested additional information by letter dated August 31, 1995. The staff has identified additional areas for which additional information and/or clarification is needed. The enclosure to this letter contains the information needed for the staff to complete its review of your response to GL 95-03. Please provide your response within 30 days from the receipt of this letter.

This request is within the original reporting burden for information collection covered by the Office of Management and Budget clearance number 3150-0011, which expires July 31, 1997.

Sincerely,

Original Signed By:

Chandu P. Patel, Project Manager  
Project Directorate IV-1  
Division of Reactor Projects III/IV  
Office of Nuclear Reactor Regulation

Docket No. 50-382

Enclosure: Request for Additional  
Information

cc w/encl: See next page

DISTRIBUTION

Docket File	PUBLIC	PD4-1 r/f	C. Patel
W. Beckner	T. Clark	ACRS (4)	OGC (15B18)
J. Roe	E. Adensam	J. Dyer, RIV	D. McDonald

J. Karwoski (07D4)

Document Name: WAT00000.LTR

OFC	LA:PD4-1	PM:PD4-1 <i>CP</i>
NAME	TClark <i>TC</i>	CPatel:sw
DATE	9/21/94	9/21/94

200000

9509260206 950921  
PDR ADOCK 05000382  
P PDR

NRG FILE CENTER COPY

*DFOI 1/0*