Georgia Power Company Route 2. Box 299A Waynesboro Georgia 30830 Telephone 404 554-9961, Ext. 3360 404 724-8114, Ext. 3360

OFFICIAL COPY



D. O. Foster Vice President and Preject General Manager Vugtle Project

18 P2:02

the southern electric system

June 11, 1984

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

File: X7BG03-M36 GN-374 Log:

Reference:

Vogtle Electric Generating Plant-Units 1 and 2; 50(424, 50-425; Delaval Diesel Generator-Piston Skirt Cracking; Letter GN-219

dated March 1, 1983.

Attention: Mr. James P. O'Reilly

Gentlemen:

In the evaluation summary attached to the referenced letter, Georgia Power Company indicated that the piston skirts in the Vogtle diesel generators would be removed from the engines, returned to Transamerica Delaval for inspection and stress relief annealing, and then replaced in the engines.

Georgia Power Company has reevaluated this corrective action and has elected to replace the piston skirts currently in its diesel generators (Type "AN" skirts) with piston skirts of a later design (Type "AE" skirts). The Type "AE" piston skirts have been properly heat treated and are not susceptible to the problems reported for the currently installed skirts. Georgia Power Company expects to have the new Type "AE" piston skirts installed by September 1, 1984.

This response contains no proprietary information and may be placed in the NRC Public Document Room.

REF/DOF/tdm

U. S. Nuclear Regulatory Commission Document Control Desk

Washington, D. C. 20555

R. J. Kelly D. E. Dutton

R. E. Conway W. F. Sanders R. H. Pinson G. F. Head P. D. Rice W. T. Nickerson

R. A. Thomas

O. Batum G. Bockhold B. M. Guthrie E. D. Groover

J. A. Bailey

L. T. Gucwa M. Malcom

H. H. Gregory, III J. T. Beckham, Jr.

J. L. Vota

8406290355 84061 PDR ADOCK 05000424

D. N. MacLemore

OFFICIAL COPY