57-346



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20555-0001

September 26, 1995

Mr. John P. Stetz Vice President - Nuclear, Davis Besse Centerior Service Company c/o Toledo Edison Company Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, OH 43449

200040

9509290033 950926 PDR ADDCK 05000346

SUBJECT: LESSONS LEARNED FROM NUCLEAR REGULATORY COMMISSION OPERATIONAL SAFEGUARDS RESPONSE EVALUATIONS

Dear Mr. Stetz:

The Nuclear Regulatory Commission (NRC) Operational Safeguards Response Evaluation (OSRE) program has noted a variety of weaknesses and strengths associated with licensees' contingency response capabilities in relation to their ability to protect their plant(s) against a design-basis threat for sabotage [10 CFR 73.1(a)]. In addition, the NRC investigation of the unauthorized forced entry to the protected area at the Three Mile Island Nuclear Station on February 7, 1993, prompted an evaluation of the need for guidance in response to unauthorized forced entry into a licensee's protected area. This letter is to inform you that information is being provided to your plant security manager, Mr. Gary Skeel, that could assist in your efforts to protect your plant(s) against a design-basis threat for sabotage. This information is (1) applicable sections of NUREG/CR-5172, "Tactical Training Reference Manual", dated April 1989, which could be used in plant tactical security training programs, and (2) lessons learned in plant contingency responses identified through OSREs. Because this information contains Safeguards Information, it is being withheld from public disclosure and will be forwarded with this letter only to your plant security manager.

Plant security managers have previously been forwarded a copy of NUREG/CR-5172. This document is oriented primarily toward fuel cycle facilities and incorporates guidance from a similar U.S. Department of Energy (DOE) program; however, it contains useful information for nuclear power plants. This manual addresses skills that armed response personnel could employ to ensure personal safety and effective response to adversary actions and provides guidance in the general factors that could be considered. The manual is, however, for reference purposes only and its contents should not be construed as acceptance criteria or as regulatory requirements.

The OSRE lessons learned provide the weaknesses and strengths identified during OSREs pertaining to licensees' capability to cope with an adversary with the characteristics specified in NRC's design-basis threat. It is

NRC FILE CENTER COP

Mr. Stetz

suggested that the information be reviewed for applicability to your plant and actions be considered, as appropriate. However, the solutions and approaches contained in these OSRE lessons learned do not constitute NRC requirements, and it should not be inferred that these are the only acceptable solutions for a plant.

No specific action or written response to this letter is required.

Sincerely,

ORIGINAL SIGNED BY: Linda L. Gundrum

Linda L. Gundrum, Project Manager Project Directorate III-3 Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION: Docket File GMarcus PUBLIC PD III-3 R/F DCrutchfield/BGrimes LCunningham DOrrik MWarren EKoup 0-9-G-22

DOCUMENT NAME: G:\DAVISBES\SECURITY.LTR

OFFICE	LA: PDIII-3 QC	PM:PDIII-3	D.PDIII-3
Contraction of the local division of the	Droster-Curseen	LGundrum RRY	GMareus
DATE	09/25/95	09/26/95	09/ 195

Mr. Stetz

3

suggested that the information be reviewed for applicability to your plant and actions be considered, as appropriate. However, the solutions and approaches contained in these OSRE lessons learned do not constitute NRC requirements, and it should not be inferred that these are the only acceptable solutions for a plant.

No specific action or written response to this letter is required.

Sincerely,

Linda Lundrum

Linda L. Gundrum, Project Manager Project Directorate III-3 Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

Mr. John P. Stetz Toledo Edison Company

١

cc: Mary E. O'Reilly Centerior Energy Corporation 300 Madison Avenue Toledo, Ohio 43652

Mr. William T. O'Connor, Jr. Manager - Regulatory Affairs Toledo Edison Company Davis-Besse Nuclear Power Plant 5501 North State - Route 2 Oak Harbor, Ohio 43449

Gerald Charnoff, Esq. Shaw, Pittman, Potts and Trowbridge 2300 N Street, N.W. Washington, D.C. 20037

Regional Administrator U.S. NRC, Region III 801 Warrenville Road Lisle, Illinois 60523-4351

Mr. Robert B. Borsum Babcock & Wilcox Nuclear Power Generation Division 1700 Rockville Pike, Suite 525 Rockville, Maryland 20852

Resident Inspector U. S. Nuclear Regulatory Commission 5503 N. State Route 2 Oak Harbor, Ohio 43449

Mr. John K. Wood, Plant Manager Toledo Edison Company Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, Ohio 43449

Mr. Gary Skeel, Manager of Security Mail Stop 4000, Route #2 Oak Harbor, Ohio 43449 Davis-Besse Nuclear Power Station Unit No. 1

Robert E. Owen, Chief Bureau of Radiological Health Service Ohio Department of Health P. O. Box 118 Columbus, Ohio 43266-0118

Attorney General Department of Attorney General 30 East Broad Street Columbus, Ohio 43216

Mr. James W. Harris, Director Division of Power Generation Ohio Department of Industrial Regulations P. O. Box 825 Columbus, Ohio 43216

Ohio Environmental Protection Agency DERR--Compliance Unit ATTN: Zack A. Clayton P. O. Box 1049 Columbus, Ohio 43266-0149

State of Ohio Public Utilities Commission 180 East Broad Street Columbus, Ohio 43266-0573

Mr. James R. Williams State Liaison to the NRC Adjutant General's Department Office of Emergency Management Agency 2825 West Granville Road Columbus, Ohio 43235-2712

President, Board of County Commissioners of Ottawa County Port Clinton, Uhio 43452