



Donald C. Shelton
Vice President - Nuclear
Davis-Besse

300 Madison Avenue
Toledo, OH 43652-0001
(419) 249-2300

Docket Number 50-346

License Number NPP-3

Serial Number 2000

February 24, 1992

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Fire Protection - Completion of Electric Fire Pump Controller
Installation

Gentlemen:

Toledo Edison's (TE) October 11, 1989 letter (Serial Number 1718) committed to implement a modification to the electric fire pump controller. As documented in the Nuclear Regulatory Commission's (NRC) May 30, 1991 letter which contained the Safety Evaluation of Fire Protection Measures at the Davis-Besse Nuclear Power Station, Unit Number 1, per Appendix B to 10 CFR Part 50 (TE Log Number 3480), TE committed to complete installation of the new controller by the end of the seventh refueling outage. The new controller has been installed and either complies with the applicable National Fire Protection Association (NFPA) Code requirements or complies with the intent of these requirements. The detailed NFPA Code review is available onsite for NRC review.

If you have any questions, please contact Mr. R. W. Schrauder, Manager - Nuclear Licensing, at 419-249-2366.

Very truly yours,

KBR/dlm

cc: A. B. Davis, Regional Administrator, NRC Region III
J. B. Hopkins, NRC/NRR DB-1 Senior Project Manager
W. Levis, NRC Region III, DB- Senior Resident Inspector
Utility Radiological Safety Board

9202280076 920224
PDR ADOCK 05000346
F PDR

Operating Companies
Cleveland Electric Illuminating
Toledo Edison

A006 1/0