




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704  
AREA CODE 713 838-6631

June 25, 1984  
RBG- 18081  
File Nos. G9.5, G9.25.1.1

Mr. John T Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-198

An interim or final status report concerning welds made on  
unscheduled conduit supports in the Control Building will be provided by  
September 27, 1984.

Sincerely,

*L. A. England jr*

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/PJD/lp

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

*12-27-84*

8407050088 840625  
FDR ADOCK 0500458  
S PDR