

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

84 MAR 2 March 1984

NUCLEAR PRODUCTION DEPARTMENT

U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Units 1 and 2

Docket Nos. 50-416 and 50-417

License No. NPF-13 File 0260/15524/0310

Report Nos. 50-416/84-01 and

50-417/84-02, dated February 29, 1984 (MAEC-84/0076)AECM-84/0181

This is in response to your letter to Mississippi Power & Light Company from Richard C. Lewis, dated February 29, 1984.

Attached is the response to the violation cited in the report.

Should you have any questions, please contact my office.

Yours truly,

L. F. Dale

Manager of Nuclear Services

RLS/PRH: 1m Attachment

cc: Mr. J. B. Richard (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

8407060052 840619 PDR ADOCK 050004

NRC VIOLATION IN REPORT MOS. 50-416/84-01 AND 50-417/84-C2

ADMISSION OR DENIAL OF THE ALLEGED VIOLATION

The violation is admitted; however, there was no effect on the health and safety of the public.

II. REASON FOR THE VIOLATION IF ADMITTED

The violation was the result of personnel oversight.

III. CORRECTIVE STEPS WHICH HAVE BEEN TAKEN AND THE RESULTS ACHIEVED

Emergency Plan Procedure 10-S-01-05, "General Emergency," was revised January 26, 1984, and submitted February 27, 1984, as an enclosure to AECM-84/0109. Guidance has been incorporated into the implementing procedure (10-S-01-05) for determining offsite protective action recommendations.

- IV. CORRECTIVE STEPS WHICH WILL BE TAKEN TO AVOID FURTHER VIOLATION

 No further action is required.
- V. DATE WHEN FULL COMPLIANCE WILL BE ACHIEVED

 Full compliance was achieved January 26, 1984.