


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

July 2, 1984
TXX-4214



Mr. E.H. Johnson, Chief
Reactor Project Branch 1
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket Nos.: 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
ROCKBESTOS CABLE DEFICIENCY
QA FILE: CP-84-14, SDAR-138
FILE NO.: 10110

Dear Mr. Johnson,

On June 6, 1984 we verbally contacted your Mr. D. Hunnicutt of a deficiency regarding possible insulation damage in certain reels of Rockbestos Class 1E multi-conductor cable.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

A handwritten signature in cursive script that reads "Billy R. Clements".

BRC/tlg

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8407090186 840702
PDR ADOCK 05000445
S PDR

Ik-27 1/0