



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

OCT 5 1995

TU Electric
ATTN: C. L. Terry, Group Vice President
Nuclear Production
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

SUBJECT: NRC INSPECTION REPORT 50-445/95-17; 50-446/95-17 AND NOTICE OF VIOLATION

This refers to the inspection conducted by Messrs. A. T. Gody, Jr., H. F. Freeman, and Ms. V. L. Ordaz of this office on July 30 through September 9, 1995, at the Comanche Peak Steam Electric Station, Units 1 and 2, facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, the NRC has determined that one violation of NRC requirements occurred. The violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding it are described in detail in the subject inspection report. The violation involves a failure to follow operating procedures which resulted in lowering the refueling water storage tank level to below the minimum Technical Specification level for operability and is of concern because it reflects a weakness in operations self-verification. We note your aggressive and self-critical investigation of the event. We are concerned that your findings reflect poor engineering followup in their failure to develop adequate corrective actions from the December 1992 recognition of a spent fuel pool high level alarm setpoint discrepancy.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not


9510110125 951005
PDR ADOCK 05000445
Q PDR

include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



J. E. Dyer, Director
Division of Reactor Projects

Dockets: 50-445
50-446
Licenses: NPF-87
NPF-89

Enclosures:

1. Notice of Violation
2. NRC Inspection Report
50-445/95-17; 50-446/95-17

cc w/enclosures:

TU Electric
ATTN: Roger D. Walker, Manager of
Regulatory Affairs for Nuclear
Engineering Organization
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

Juanita Ellis
President - CASE
1426 South Polk Street
Dallas, Texas 75224

TU Electric
Bethesda Licensing
3 Metro Center, Suite 610
Bethesda, Maryland 20814

Morgan, Lewis & Bockius
ATTN: George L. Edgar, Esq.
1800 M. Street, NW
Washington, D.C. 20036

Texas Department of Licensing & Regulation
ATTN: G. R. Bynog, Program Manager/
Chief Inspector
Boiler Division
P.O. Box 12157, Capitol Station
Austin, Texas 78711

Honorable Dale McPherson
County Judge
P.O. Box 851
Glen Rose, Texas 76043

Texas Radiation Control Program Director
1100 West 49th Street
Austin, Texas 78756

Office of the Governor
ATTN: Susan Rieff, Director
Environmental Policy
P.O. Box 12428
Austin, Texas 78711

OCT 5 1995

TU Electric

-4-

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01) - DRS, DRP, and Decommissioning

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
MIS System
RIV File
Branch Chief (DRP/TSS)

Resident Inspector (2)
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRSS-FIPB
Project Engineer (DRP/B)

DOCUMENT NAME: R:/_CP/CP517RP.ATG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP\B	AC:DRP\B	D:DRP			
ATGody <i>HAP</i>	DFKirsch <i>K</i>	JEDyer <i>VJD</i>			
09/25/95	09/25/95	09/25/95	09/ /95	09/ /95	

OFFICIAL RECORD COPY

100693

OCT 5 1995

TU Electric

-4-

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01) - DRS, DRP, and Decommissioning

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
MIS System
RIV File
Branch Chief (DRP/TSS)

Resident Inspector (2)
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRSS-FIPB
Project Engineer (DRP/B)

DOCUMENT NAME: R:/_CP/CP517RP.ATG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP\B	AC:DRP\B	D:DRP			
ATGody <i>HP</i>	DFKirsch <i>K</i>	JEDyer <i>W</i>			
09/25/95	09/25/95	09/25/95	09/ /95	09/ /95	

OFFICIAL RECORD COPY