



Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

TELEPHONE
714 368-6255

October 4, 1995

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362
Licensee Event Report No. 95-011
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter from Edison (R. W. Krieger) to NRC Document
Control Desk dated July 5, 1995; Subject: Licensee
Event Report 95-011

In accordance with the requirements of 10 CFR 50.73(d), by the
referenced letter, Edison provided Licensee Event Report (LER)
95-011 for an occurrence involving inoperable fire dampers. When
the LER was submitted, Edison had not completed evaluation of the
cause(s), and the LER indicated that Edison planned to submit a
revision by October 5, 1995 reporting the results of our evaluation.

While conducting the evaluation, Edison determined that additional
factors required evaluating and additional time would be necessary
to conduct a thorough review. Edison plans to submit a revision to
LER 95-011 by November 3, 1995.

If you require any additional information, please so advise.

Sincerely,

- cc: L. J. Callan, Regional Administrator, NRC Region IV
- T. P. Gwynn, Director, Division of Reactor Safety, Region IV
- K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC
Region IV
- J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units
2 and 3
- M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
Institute of Nuclear Power Operations (INPO)

10-

9510110214 951004
PDR ADOCK 05000361
S PDR

IFR 2
1/0