




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-5631



September 19, 1984
RBG- 18942
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76001

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-188

An interim or final status report concerning the hubs on socket-weld flanges supplied by Guyon Alloys for the instrument lines on the Main Steam Isolation System will be provided by November 21, 1984.

Sincerely,

J. E. Booker
Manager - Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

^{PJD}
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

NRC Resident Inspector - Site

IS-27

8410100303 840919
PDR ADOCK 05000458
S PDR

1/0