



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

October 1, 1984

Director  
Office of Nuclear Reactor Regulation  
U S Nuclear Regulatory Commission  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60


Steam Generator Tube Plugging

In accordance with Technical Specification 4.12.E.1, the following steam generator tube plugging information is provided for the information of the NRC Staff.

Following the recent inservice inspection of the Unit 2 steam generators, thirty-three tubes were plugged. Nineteen tubes were plugged in steam generator 21 and fourteen in steam generator 22. The percentage of tubes plugged is 1.4% and 2.8% in steam generators 21 and 22, respectively.

This information will be expanded upon in the Inservice Inspection Report for each unit. Also Tables 4.3-13 and 14 of the Prairie Island Updated Safety Analysis Report will be updated in the next revision.

If you have any questions concerning this information please call.

  
David Musolf  
Manager-Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III  
NRR Project Manager, NRC  
Resident Inspector, NRC  
G Charnoff

B410100370 B41001  
PDR ADOCK 05000282  
Q PDR

Ac47  
/0