SAFEGUARDS INFORMATION

JUL 1 1 1984

Docket No. 50-256 Docket No. 50-301

Wisconsin Electric Power Company ATTN: Mr. Sol Burstein Vice Chairman of the Board 231 West Michigan Milwaukee, WI 53201

Gentlemen:

This refers to the safeguards inspection conducted by Messrs. G. L. Pirtle and J. L. Belanger of this office on June 11-15, 1984, of activities at print Beach Nuclear Plant authorized by NRC Operating Licenses No. DPR-24 and No. DPR-27, and to the discussion of our findings with Mr. J. Zach and other members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required. Additionally, a concern has developed regarding written guidance provided by the security contractor in reference to reporting possible violations to the NRC. Our concerns are addressed in paragraph 6.b of the Report Details. We request that you advise us in writing, within 30 days of your receipt of this letter, of actions taken to resolve these concerns.

Four commitments were made to resolve concerns noted during the inspection and are described in paragraph 3 of the Report Details. Please advise us if our understanding of your proposed actions is incorrect.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter, our report of this inspection, and your response to the noncompliance identified in the enclosure to this letter will not be placed in the Public Document Room. Therefore, your statement of corrective action regarding the noncompliance identified in the enclosure should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

AFEGUARDS INFORMATION

IEOH

8407160183 840711 PDR ADDCK 05000266

SAFEGUARDS INFORMATION

Wisconsin Electric Power Company 2

JUL 1 1 1994

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. A. Hind, Director Division of Radiation Safety and Safeguards

Enclosures:

Appendix, Notice of Violation

Violation

Inspection Reports
 No. 50-266/84-08(DRSS);
 No. 50-301/84-06(DRSS)

UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/encls: J. J. Zach, Plant Manager IE File IE/DQASIP/ORPB IE/ES NMSS/SGPL NRR/DL/SSPB ACRS

cc w/encls, w/o UNCLASSIFIED
SAFEGUARDS INFORMATION
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
John J. Duffy, Chief
Boiler Section
Peter Anderson, Wisconsin's
Environmental Decade
Ness Flores, Chairperson
Wisconsin Public Service
Commission

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

RIII 1 (1) (b) 1 (02) 84 RIII

RILI

Axenson

RIII

RIII Schultz RIII Hind 7/11/89