NRC FORM 591M PART 1 (07-2012) 10 CFR 2,201			U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY	INSPECTION REPOR	T AND COMPLIA	ANCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED		2. NRC/REGIONAL OFFICE		
Tunnel Ridge, LLC		Region 1		
LICENSEE'S FACILITIES		2100 Renaissance Blvd		
1901 SHORT CREEK ROAD WHEELING, WV 26003		Suite 100 King of Prussia, PA 19406-2713		
		King of Plussia, Pr	19400-2713	
REPORT NUMBER(s) 2020001		<u> </u>		
3. DOCKET NUMBER(S) 030-38733	4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-30733	47-35142-01		03/01/2020 - 03/23/2020	
LICENSEE: The inspection was an examination of the activing Nuclear Regulatory Commission (NRC) rules a procedures and representative records, interviews. 1. Based on the inspection findings, no views. 2. Previous violation(s) closed. 3. The violations(s), specifically described non-repetitive, and corrective action was satisfied.	and regulations and the conditions was with personnel, and observational olations were identified. to you by the inspector as non-ci	of your license. The inspons by the inspector. The	ection consisted of selective examinations of	
4. During this inspection, certain of your	cement Policy. This form is a NOT	/or attached, were In viol	ation of NRC requirements and are being ch may be subject to posting in accordance	
 A. 10 CFR 20.1101(c) states that licensimplementation. 	sees shall periodically (at least an	nually) review the radiation	on protection program content and	
Contrary to the above, as of March 3, 20, content and implementation. Specifically 2016, 2017, 2018, or 2019.	20, the licensee failed to periodica , the licensee failed to perform an	illy (at least annually) revi d document any annual p	iew the radiation protection program program reviews for calendar years	
As corrective action, the licensee perform inform the licensee when the annual prog	ned a program review on March 5, Iram reviews are due moving forw	2020 and established a ard.	recurring computer-based task to	
This is a Severity Level IV violation (Enfo	rcement Policy 6.3.d.3).			
B. License Condition 24 of NRC Licens statements, representations, and procedu	e 47-35142-01 states, in part, tha ures contained in the documents,	t the licensee shall condi including any enclosures	uct its program in accordance with the , listed under License Condition 24,	
In the letter dated April 30, 2014, as listed documentation demonstrating that unmor the allowable limits in 10 CFR Part 20.	I under License Condition 24, the hitored individuals are not likely to	licensee committed to ma receive, in one year, a ra	aintain, for inspection by the NRC, diation dose in excess of 10 percent of	
Contrary to the above, as of March 3, 202 unmonitored individuals are not likely to r 20. Specifically, the licensee failed to eith	eceive, in one year, a radiation do	se in excess of 10 perce	nt of the allowable limits in 10 CFR Part	
As corrective action, the licensee contrac likely to receive, in one year, a radiation of	ted a service provider to produce lose in excess of 10 percent of the	a calculation demonstrati e allowable limits in 10 Cl	ing that unmonitored individuals are not FR Part 20.	
This is a Severity Level IV violation (Enforcement Policy 6.3.d.3).				

NRC FORM 591M PART 1

(07-2012) 10 CFR 2.201 U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED

Tunnel Ridge, LLC LICENSEE'S FACILITIES 1901 SHORT CREEK ROAD WHEELING, WV 26003 2. NRC/REGIONAL OFFICE

Region 1

2100 Renaissance Blvd

Suite 100

King of Prussia, PA 19406-2713

REPORT NUMBER(s) 2020001

3. DOCKET NUMBER(S) 030-38733

4. LICENSE NUMBER(S)

47-35142-01

5. DATE(S) OF INSPECTION

03/01/2020 - 03/23/2020

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	Troy Gussler	Try And	3-30-20
NRC INSPECTOR	Jonathan Pfingsten	Jonathan Pfingsten	3/30/2020
BRANCH CHIEF	Chrisopher Cahill		