

JUN 21 1984

Docket No. 50-286

Power Authority of the State of New York
Indian Point 3 Nuclear Power Plant
ATTN: Mr. J. C. Brons
Resident Manager
P. O. Box 215
Buchanan, New York 10511

Gentlemen:

Subject: Inspection Report No. 50-286/84-11

This refers to the routine safety inspection conducted by Mr. Nemen M. Terc of this office on April 30 through May 4, 1984, at the Indian Point 3 Nuclear Power Plant and your corporate office in White Plains, New York, of activities authorized by NRC License No. DPR-64, and to the discussions of our findings held by Mr. Terc with Mr. J. Russell and other members of your staff at the conclusion of the inspection, and to a subsequent telephone discussion between Dr. R. R. Bellamy and others of my staff with Mr. J. Brons on May 9, 1984.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of this inspection, no violations were observed. However, the inspector identified two areas of concern that need improvement: upgrading and implementation of the training program and description of the emergency organization as it appears in the Emergency Plan. Based on the telephone conversation of May 9, 1984, we understand that you will implement corrective actions as follows:

1. The training program description will be clarified, expanded, and formalized to include more detailed lesson plans and a means for qualifying all personnel responsible for emergency response. We believe that implementation of the training program should be achieved by November 1, 1984. In addition, you are requested to provide us with a monthly progress report (see Appendix A).
2. The description of your emergency response organization in the Emergency Plan will be clarified, including all augmentation phases, and showing lines of command as well as relationships between successive stages. This description should include, but will not be limited to, block diagrams. This change to your Emergency Plan will be implemented by June 15, 1984 (see Appendix A).

8407170417 840621
PDR ADOCK 05000286
PDR
Q

OFFICIAL RECORD COPY

DL50-286/84-11 - 0001.0.0
06/07/84

IE06
%

JUN 21 1984

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 10 CFR 2.790(b)(1). The telephone notification of your intent to request withholding, or any request for an extension of the 10-day period which you believe necessary, should be made to the Supervisor, Files, Mail and Records, USNRC Region I, at (215) 337-5223.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us in this matter is appreciated.

Sincerely,

Original signed by

H. CROCKER

for Thomas T. Martin, Director
Division of Engineering and
Technical Programs

Enclosure:

1. Appendix A
2. NRC Region I Inspection Report Number 50-286/84-11

cc w/encl:

L. W. Sinclair, President and Chief Operating Officer
J. P. Bayne, Executive Vice President-Nuclear Generation
C. M. Pratt, Assistant General Counsel
A. Klausmann, Vice President - Quality Assurance
J. Cirilli, Quality Assurance Superintendent
G. M. Wilverding, Chairman, Safety Review Committee
M. Blatt, Director, Regulatory Affairs (Con Ed)
NRC Licensing Project Manager
Dept. of Public Service, State of New York
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New York

bcc w/encl:

Region I Docket Room (with concurrences)
Senior Operations Officer (w/o encls)
DPRP Section Chief

D RI:DETP
Berc/lp
6/7/84

RI:DETP *ELG*
Gordon
6/8/84

RI:DETP *H. Crocker*
Crocker
6/15/84

RI:DETP *Bellamy*
Bellamy
6/18/84

RI:DETP *Martin*
Martin
6/ /84

APPENDIX A

Power Authority of the State of New York
Indian Point 3 Nuclear Power Plant

Docket No. 50-286
License No. DPR-64

As a result of the inspection conducted on April 30 - May 4, 1984, the inspectors identified several areas of concern related to the emergency preparedness program. These items are described below.

(286/84-11-01): Review your emergency organization and revise it as needed to clarify all emergency functions required during initial, intermediate and final phases of augmentation and recovery. Your site Emergency Plan (and implementing procedures) shall be updated as necessary to be consistent with the revised organization. The updated description in the Plan shall include a sufficient level of detail to: completely and unambiguously delineate the command hierarchy; clearly specify its structure, reporting chains and inter-relationships at any phase of augmentation and include supervisory as well as non-supervisory elements.

(286/84-11-02): Complete the development and implement a formal, centralized training/retraining program for all individuals within the revised emergency organization. This training shall focus on the specific functional duties assigned to each individual. This training program shall include approved lesson plans, performance objectives, practical exercises, tests, qualification criteria, and records of attendance as needed to ensure effective emergency response training.