Docket No. 50-397

Washington Publ Power Supply System P. O. Box 968 Richland, Washington 99352

Attention: Mr. G. C. Sorensen, Manager

Regulatory Programs

Gentlemen:

Subject: NRC Inspection of WNP-2

This refers to the routine inspection conducted by inspectors D. J. Willett and L. R. Kanow of this office, during the period of August 20-24, 1984, of activities authorized by NRC License No. NPF-21, and to the discussion of our inspectors findings with Mr. J. D. Martin and members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspections consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

No violations with NRC requirements were identified within the scope of this inspection.

Should you have any questions concerning this inspection, do not hesitate to contaci us.

Sincerely,

1/ signed //

T. W. Bishop, Director Division of Reactor Safety and Projects

Enclosure: Inspection Report No. 50-397/84-24

B410120198 B40921 PDR ADDCK 05000397

IEO1

cc w/enclosure:

J. D. Martin, WNP-2 Plant Manager

P. L. Powell, WNP-2 Licensing Manager

R. B. Glasscock, Director, Assurance & Licensing

N. S. Reynolds,

Bishop, Liberman, Cook, Purcell & Reynolds 1200 Seventeenth Street, N.W. Suite 700, Washington, DC 20036 State of Washington

bcc: RSB/Document Control File (RIDS)

Distributed by RV: Mr. Martin, RV (w/enclosure) Pink/Green (w/o enclosure) Docket File Copy (w/enclosure)

RV/jk

9/19/84

KANOW YRK 9/19/84 DODDS

9/14/84

BISHOP

9/28/84