



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 11, 1984

NUCLEAR LICENSING & SAFETY DEPARTMENT

U. S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D. C. 20555

Attention: Mr. Harold R. Denton, Director

Dear Mr. Denton:

SUBJECT: Grand Gulf Nuclear Station
Units 1 and 2
Docket Nos. 50-416 and 50-417
License No. NPF-13
File: 0260/0272/L-860.0
Humphrey Containment Concerns
AECM-84/0484

Mississippi Power & Light Company (MP&L) transmitted letter AECM-84/0476 to the Nuclear Regulatory Commission on October 10, 1984. Note 11 in Attachment 1 of that letter has been discovered to contain an error. That note states:

This thermocouple is not safety related and is not required to function following an accident.

The note should read:

This thermocouple is safety related but is not required to function following an accident.

The correction of this error does not change the basic conclusion of letter AECM-84/0476.

Yours truly,

L. F. Dale
Director

SHH:rg

cc: See next page

8410150069 841011
PDR ADOCK 05000416
PDR

B021
1/0

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. N. S. Reynolds
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. P. O'Reilly, Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30323