



GULF STATES UTILITIES COMPANY


POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713-838-6631

September 27, 1984
RBG-19021
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76001

Dear Mr. Collins:



River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-182

An interim or final status report concerning a Limitorque motor operator failure on a Feedwater isolation valve will be provided by November 8, 1984.

Sincerely,

J. E. Booker

J. E. Booker
Manager - Engineering
Nuclear Fuels & Licensing
River Bend Nuclear Group

^{REN}
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

NRC Resident Inspector - Site

8410150488 840927
PDR ADOCK 05000458
S PDR

IE-27

1/0