Arizona Public Service Company

984 OCT -2 AM 8 OF

September 26, 1984
ANPP-30666-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oals Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director Division of Resident

Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-45

A 50.55(e) Potentially Reportable Deficiency Relating To Spot

Welding On Skid Mounted Indication And Control.

File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between D. Hollenbach and T. Bradish on July 17, 1984

(B) ANPP-30260, dated August 16, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by September 28, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by October 24, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director

E & Van Bour

EEVB/TRB/nj

cc: See Page Two

8410160146 840926 PDR ADOCK 05000528 F DR

75-2710

Mr. T. W. Bishop DER 84-45 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

R. P. Zimmerman

L. Lyde

M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339