

July 27, 1984
501 Vine Street
Middletown, PA 17057

Mr. Harold Denton, Director
Nuclear Reactor Regulation
U.S. NRC
Washington, DC 20555

Dear Mr. Denton:

I'm requesting answers to several questions I have related to TMI #1.

1. Please identify the locations of all vents/discharge stacks that do or could release gaseous/particulates radioactivity to the environment from TMI #1 containment building and auxilliary fuel handling building.
2. Which vents/discharge stacks do not have "filters"?
3. How often is the efficiency of such "filters" reviewed?
4. Please list the dates the action described in question #3 was accomplished for each vent/discharge stack in TMI #1?
5. What considerations determine that a "filter" should/must be replaced?
6. Please describe the manner in which gaseous effluent could be released from TMI #2, when it originated in TMI #1.

Thank you for taking the time to respond to my questions.

Sincerely,

Donald E. Hossler

Donald E. Hossler

8407310360 840727
PDR ADOCK 05000289
H PDR

YE03
1/0