NRC Form (9-63)			LICENSEE EVENT REPORT (LER)												U.S. NUCLEAR REGULATORY COMMISSION APPROVED OM& NO. 3150-0104 EXPIRES. 8/31/85							
FACILITY	NAME (1														DOCK	KET NUMBER (2)				PAG	E (3)	
Brunswick Steam Electric Plant Unit									it 1	r 1						0.151010101312			15 1 OF 011			
TITLE (4)		and the second second		and the second se	Contractor of the	statistics of grant states of	and the second second		and the second se	ing	E IIe		0 1 0	nd 2 Com	-	-		advanced in succession of the			011	
																		Gas	ole.	ICK		
-			Rad					ent				ec	ified	Samplin	FI	eque	1CY	0 (8)				
EVENT DATE (5)			LER NUMBER (6)						MONTH DAY YEAR				OTHEN FACILITIES INVO					DOCKET NUMBER(S)				
MONTH	DAY	DAY YEAR		NUMBER				UMBER	MONTH	DAY	YEA	-	Brunswick Unit 2			100	0 15 0 0 0 0 3 1 2 14					
			1.1								1	1				0						
0 9	1 3	84	8	4-	0	2 4	-	00	40	1	0 8	4						0 15 10 10 101 1				
DPS	RATING		THIS	REPORT	T 15 5	BMITTE	D PUR	SUANT	TO THE	REQUIRE	MENTS C	OF 10	CFR 5: 10	Check one or mor	re of the	following	/ (11)			-		
MODE (9) 4				20.402(b)					20.405(c)				50.73(a)(2)(iv)				73,71(b)					
POWER				20.406(a)(1)(i)				50.36(e)(1)			50.73(a)(2)(v)				73.71(c)							
LEVEI (10)	0,0		20.408(a)(1)(II)				50.36(e)(2)				50.73(a)(2)(vil)				-	OTHER (Specify in At						
	_	20.406(s)(1)(iii) X 20.405(s)(1)(iv)					60.73(a)(2)(i) 60.73(a)(2)(ii)				50.73(a)(2)(viii)(A) 50.73(a)(2)(viii, 8)			Γ	below and in Taxt, NRC Form 366AJ							
			20.405(a)(1)(v)					50.73(a)(2)(iii) 50.73(a)					50.73(a)(2)(x))(x)								
								1	ICENSE	CONTA	T FOR	THIS	LER (12)									
NAME																		EPHONE N	UAIB	ER		
																AREA CO	e					
		Μ	J. I	Past .	'a,	Jr.,	Re	gula	tory	Tech	mici	ian				9111	9 4	1517 1	- 1	915	1211	
					co	MPLETE	ONE L	INE FOI	EACH	OMPONE	NT FAIL	URE	DESCRIBE	D IN THIS REP	ORT (1)	and the second						
CAUSE	MUSE SYSTEM		ONEN	T MANUFAC-			REPORTABLE TO NPRDS		E		CA	USE	SYSTEM	COMPONENT	MANUFAC- TUREA		c	REPORTABLE TO NPRDS				
	1	1			1											1.1	,		T		·	
					-	ter and a second	1						1				-					
	1	1	1 1		1	1							11	1.1.1		1.1.	1					
	the second second				8	UPPLEMI	ENTAL	REPOR	T EXPEC	TED (14)						<u> </u>		Two	NTH	DAY	YEAR	
									T		-				-		ISSION				- Pon	
YE	5 /II yes, c	ampiete i	XPEC	TED SUS	MISSI	ON DAT	E)		ł	X NO							E (15)					
ABSTRA	CT filmit	0 1400 m	MCHC /		riman	ely titrae	sinaia	Cara Put	1	A											L	

On September 13, 1984, at 0838, required grab sampling of gaseous radioactive waste effluents from Units 1 and 2 common main off-gas stack was not performed until approximately two hours beyond the once per 12 hours specified sampling frequency. This sampling was necessitated due to declared inoperability of the units' common main off-gas stack noble gas radiation monitor D12-RM-4599-1. The technical specifications (T/S) required action, due to the inoperability of this monitor, is contained in Technical Specification Table 3.3.5.9-1. On August 7, 1984, the monitor was declared inoperable because of an identified deficiency of the monitor periodic surveillance test procedure. (For more information specific to the inoperability of the 4599-1 monitor, see LER 1-84-15.) At the time of this event, the Unit 1 reactor was in cold shutdown and Unit 2 was in a refueling/maintenance outage.

This event occurred as a result of inclement weather activity during the arrival of Hurricane Diana on the North Carolina seacoast. This weather activity, in the form of high winds and heavy rain, presented an unacceptable personnel safety hazard to plant technicians responsible for the subject sampling, until approximately two hours beyond the specified sampling frequency. This situation was reported to the NRC via the Emergency Notification System as a deviation from T/S requirements authorized pursuant to 10CFR50.54X.

TE22

8410180498 841010 PDR ADOCK 05000325

G



Carolina Power & Light Company

Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429

October 10, 1984

FILE: B09-13510C SERIAL: BSEP/84-2110

NRC Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

> BRUNSWICK STEAM ELECTRIC PLANT UNIT 1 DOCKET NO. 50-325 LICENSE NO. DPR-71 LICENSEE EVENT REPORT 1-84-24

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,

clint

C. R. Dietz, General Manager Brunswick Steam Electric Plant

MJP/mcg/LETCG2

Enclosure

cc: Mr. R. C. DeYoung Mr. J. P. O'Reilly

1622