




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 16, 1984
RBG- 18225
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-146

On June 13, 1984, GSU notified Region IV by telephone it had determined DR-146 concerning multipole circuit breakers manufactured by I-T-E Electrical Products Siemens - Allis, Incorporated, and supplied by Gould Incorporated to be reportable under 10CFR50.55(e). However, inspection results have revealed that none of the circuit breakers supplied to RBS are defective. Because no deficiency exists, this condition does not meet the reporting requirements of 10CFR50.55(e).

Sincerely,
J. E. Booker
J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJD
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8408010004 840716
PDR ADOCK 05000458
S PDR